

ASS. REC. BY:

REF:

CS/CT#19020471/Asd302

Special Instruction:

Surveyor: AdnanASSIGNMENT (Office)From (Person): Ben Tang

of

CTIDate/Time: 18/11/19 @ 5.14pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 1975M

Insured:

Sgk 9789H

at Workshop m/s

JEC Auto

Tel:

9232 7457

of

1 kaki Bukit Ave 6 # 02-11 Autobay

Policy No:

Claim No:

SNM19D 204748

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.17am @ 19/11/19

Person Contacted:

Ah xianVehicle IN/OUT

Date/Time

Action/Instruction

JohnyFBM1975M - WA/INC19008191/21DoA: 9/11/201920/11/19@ 14:54 pm checked with Ah Xian, got estimate.

ASS. REC. BY:

REF: CTE

ASSIGNMENT

From:

Date:

19/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBM 1975M

at Workshop m/s

JEC AUTO

of

11celki Bukit Ave. 6 # 02-11

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBM 1975M

Yr Regn:

2005/Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kawasaki KRR2X

C.C. 149

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

55535

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KR150KAS8663

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 80/80R17. R: 80/80R17.

R: 90/80R17.

BS / DUNLOP / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06 mm

R/Bal.

06 mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

19/11/19.

Survey held at

JEC

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Claim

WE Expiry: 30/04/24.

Adrian Confirmed L/S \$ 3,100/- @ 5 days with
Boss. (\$ 1,696.00 Red - 35%)

Date/Time, File Pass to?

11/12/19

1) Typ II

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

220

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Report Format:

Lump Sum / L/S: C

\$ 3,100/- L/S

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Monday, 18 November 2019 5:14 PM
To: assignments@lkkauto.com
Subject: FW: OUR REF: SNM19D204748-SGK9789H-BEN- FW: Claim Insurance for Bike FBM1975M

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP bike FBM1975M.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: autoservice Jec <jecautoservice@yahoo.com.sg>
Sent: Monday, November 18, 2019 3:53 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D204748-SGK9789H-BEN- FW: Claim Insurance for Bike FBM1975M

Hi Ben,

We opt for Adrian Ling.

Please assist to contact my mobile if you have any inquiry.

Thanks.

--

Best Regards,

Ah Xian (92327457)

1 Kaki Bukit Avenue 6
#02-11 Autobay @ Kaki Bukit
Singapore 417883

On Monday, 18 November 2019, 03:33:54 pm GMT+8, Ben Tang <ben.tang@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sirs

We refer to your email of 18.11.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

Without admission of liability, please provide our surveyor with repair estimates to facilitate direct settlement.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

Best Regards

Ben Tang

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, November 18, 2019 2:24 PM

To: Ben Tang <Ben.Tang@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; jecautoservice@yahoo.com.sg

Subject: OUR REF: SNM19D204748-SGK9789H-BEN- FW: Claim Insurance for Bike FBM1975M

Dear Ben,

Please conduct PRS for FBM1975M.

Note : officer in charge – Ben Tang 63896175.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: jecautoservice@yahoo.com.sg [<mailto:jecautoservice@yahoo.com.sg>]
Sent: Saturday, November 16, 2019 10:13 PM
To: Claims Dept of CTI
Subject: Claim Insurance for Bike FBM1975M

Hi Team,

This is direct case.

Please advice if I can do direct with your company for this case?

Kindly arrange Surveyer for bike Inspection.

Doc attached for your reference. Pls assist to contact me if you have any questions.

Thanks.

Best Regards,

Ah Xian (9232 7457)

1 Kaki Bukit Avenue 6

#02-11 Autobay @Kaki Bukit

Singapore 417883

发自 iPhone 版 Yahoo 邮箱

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	420H
Vehicle Details	
Vehicle No.:	FBM1975M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Nov 2019
Vehicle Make:	KAWASAKI
Vehicle Model:	KRRZX150 M
Primary Colour:	Blue
Manufacturing Year:	2004
Engine No.:	KR150EEA58663
Chassis No.:	KR150KA58663
Maximum Power Output:	-
Open Market Value:	\$2,974.00
Original Registration Date:	12 Jan 2005
First Registration Date:	12 Jan 2005
Transfer Count:	3
Actual ARF Paid:	\$447.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$3,256.00
COE Rebate Amount:	\$1,448.00
Total Rebate Amount:	\$1,448.00

The information contained herein is correct as at 19 Nov 2019

OK

Active Vehicle Parts Browse

Merimen e-Claims

New audi s4 Cars, Singapore Cai

Used Kawasaki KRR ZX150 bike

←

↻

sgbikemart.com.sg/Listing/usedbike/kawasaki-krr-zx150/14915/

+

☆

⌵

NEW BIKES

USED BIKES

ACCESSORIES

AUCTION

RENTAL

BOUNTY

MOTORCYCLE INSURANCE

DIRECTORY

ARTICLES

SHORTLIST

POST AD

ACCOUNT

Apply & get a free* return flight. Guaranteed.

FORWARD Your Rewards

APPLY NOW

FORWARD Your Rewards

*1000 points, 10000 miles, 10000 miles

Q SEARCH

VIEW ALL

Kawasaki KRR ZX150

Listing Type

Free Ad

Brand

Kawasaki

Model

Kawasaki KRR ZX150

Engine Capacity

148cc

Classification

Class 2B

Registration Date

31/05/2002

COE Expiry Date

30/05/2022 (2 years 6 months left)

Mileage

-

No. of owners

2

Type of Vehicle

Sport Bikes

Price: SGD\$6000

REPORT ERROR

ADD TO SHORTLIST

Like 0

SHARE

SHARE

DETAILS

Road Tax Till 16 Nov 2019, Pm For Exact Mileage.

BOON SIEW SINGAPORE

The Official Distributor of Honda Motorcycles

The Official Distributor Of Honda Motorcycles

Boon Siew Singapore Pte Ltd is the

FORMS TO DOWNLOAD

Agreement Form

Deposit Receipt

Private Settlement Form

Handing Over Form

LTA Transfer Form

SELLER INFORMATION

Contact

Bob +65 91... Click to view

Bob +65 96... Click to view

3003 PM

19/11/2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/11/2019 10:20
Date Of Accident	07/10/2019 12:30
Exact Location Of Accident	BEDOK NORTH AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBM1975M
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD HAFIZ BIN SUANDI
NRIC No	S8736420H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84813231
Alternative Phone No	OFFICE-84813231

Vehicle Particulars

Manufacturer	KAWASAKI
Model	KAWASAKI KRRZX150 M
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	VMO/P2241730
Cover Note Number	

Driver

Name of Driver	MUHAMMAD HAFIZ BIN SUANDI
NRIC No	S8736420H
Date Of Birth	09/11/1987
Occupation	INDOOR
Date Of Driving Pass	11/08/2010
Driving Experience	9 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84813231
Fax Number	
Contact Number	OFFICE-84813231
Email Address	NOEMAIL

Address	APT BLK 360 YUNG AN ROAD #02-89
Postcode	610360
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NOOR AISHAN BINTE ABDUL SHEDIK GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK DIVISION HQ
Police Station Address	ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGK9789H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD HAFIZ BIN SUANDI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBM1975M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	APT BLK 360 YUNG AN ROAD #02-89
Postcode	610360

DETAILS OF INJURED PERSON 2

Name	NOOR AISHAN BINTE ABDUL SHEDIK
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBM1975M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	APT BLK 360 YUNG AN ROAD #02-89
Postcode	610360

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:



**SINGAPORE
POLICE FORCE**



G/20191024/7026

1 of 2

POLICE REPORT (NP299)

Report No. G/20191024/7026

Police Station Of Origin
Bedok Division HQ
30 Bedok North Road SINGAPORE 469676
Tel No:1800-2440000

Date/Time Report Made 24/10/2019 12:33	Vide Report No.	Station Diary No.
Name Of Informant MUHAMMAD HAFIZ BIN SUANDI	Address APT BLK 360 YUNG AN ROAD #02-89 SINGAPORE 610360	
ID Type / ID No. NRIC NO / S8736420H	Contact No. Home/Office: Mobile: 84813231	
Nationality SINGAPORE CITIZEN	Email Address hafizsuandi@gmail.com	
Occupation Area Manager	Sex Male	Age 31
Institution/School Name	Date of Birth 09/11/1987	Race Javanese
Date/Time Of Incident 07/10/2019 12:30 - 07/10/2019 12:50	Location Of Incident BEDOK NORTH AVENUE 3	

Brief details.

RTA at Bedok North Ave 3 on 07/10/2019 12:30pm

At around 12:30pm. When i was riding my Vehicle A (FBM 1975 M) along Bedok North Ave 3 towards Upper Changi Road, at speed around 50-60km per hour few hundreds metres away after moving off from the traffic light, A Blue BMW Vehicle B (SGK 9789 H) was coming out from the carpark and turning right.

When I saw the vehicle, it was not moving at first, so I speed up to pass the car, but unfortunately the

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 24/10/2019 12:33
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



G/20191024/7026

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20191024/7026

driver did not check her right before moving off when I almost reached her car. The car collided with me she need to stop at the white line and give way to the main road.

My wife, Name:Noor Aishan Binte Abdul Shedik Nric:S8932318E, and I was conveyed to CGH, Both of us will given 5days MC (EMD2019198752) and (EMD2019198807)

Subsequently my wife went to Island Group Clinic and was given another 3days MC.

Subjects Involved			
Victim			
Person Name	MUHAMMAD HAFIZ BIN SUANDI		
ID Type	NRIC NO	ID No	S8736420H
Gender	Male	Age	31
Race	Javanese	Language	English
Occupation	Area Manager	Address Type	
Address	APT BLK 360 YUNG AN ROAD #02-89 SINGAPORE 610360	Mobile No	84813231
Is Informant A Victim?	Yes		
Person Name	MUHAMMAD HAFIZ BIN SUANDI (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 24/10/2019 12:33
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

TP Chinn.
Shirley.

FBM1975M. 2005 Jan.
Kawasaki KRRZX
KR150KAS8663.

Front Number Plate.	$\left. \begin{matrix} \text{New} \\ \text{m} \end{matrix} \right\}$	15 (SN) +
Front Windshield.		95 x
Headlamp. <i>crushed</i>		265 ✓
Headlamp Cowling <i>crushed</i>		280 ✓
Headlamp Bracket. <i>Best</i>		75 ✓
Front Wheel Fender. <i>crushed</i>		90 ✓
Front Fork Assy. <i>Best</i>		680 ✓
Front Fork Bracket. <i>Best</i>		155 ✓
Front Fork Oil	$\left. \begin{matrix} \text{New} \\ \text{m} \end{matrix} \right\}$	30 ✓
Front Fork Oil Seal		50 ✓
Steering Core and Bearing. <i>New</i>		85 ✓
Handle Bar x 02 <i>RHT Best</i>		$75 \times 2 = 150$ 75.
Clutch Lever. <i>New m</i>		35 x
Balancer <i>KT</i> x 02 <i>New m</i>		$20 \times 2 = 40$ x
Speedometer. <i>crushed</i>		385 ✓
Fuel Tank <i>Dented</i>		520 ✓
Fuel Tank Rubber Pad <i>New</i>		50 ✓
Side Fairing x 02 <i>distorted</i>		$210 \times 2 = 420$ ✓
Side Fairing Inner Garnish x 02 <i>LH crushed</i>		$45 \times 2 = 90$ 45
Side Fairing Inner Air Duct x 02 <i>New New</i>		$30 \times 2 = 60$ x

FBM1975M

Side Faring Signal Lamp x 02 ^{RIT} ~~cracked~~ $40 \times 2 = 80$ ~~80~~ 40.

Foot Brake. Best

45 ✓

Front Footrest x 02 ^{RIT} ~~cut~~

$40 \times 2 = 80$ ~~80~~ 40

Rear Footrest x 02

$40 \times 2 = 80$ ~~80~~ 40.

Wing Mirror x 02 ^{RIT} ~~cut~~

$75 \times 2 = 150$ ~~150~~ 75.

8

3445

3100.50

Panel Bending.

~~400~~ 250

Spray Painting

~~400~~ 250

Wiring.

~~50~~ 30

To straighten chassis member.

~~300~~ 200. 770

Lowing.

40 ✓

4796/-

Total: 3870.50

L/S: 3.11c.

05 Days.

5195

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Oct 2019		20 Nov 2019 18:10 Edit Adj Rpt	S\$3,100.00 Edit Estimates	S\$3,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	-, Co. Reg. No.: -	
Main Claimant:	MUHAMMAD HAFIZ BIN SUANDI	
Vehicle Reg. No.:	FBM1975M	Date of Loss: 07/10/2019 13:00 - :59 [176 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204748C01	Policy/Cover Note No.: DMPCSN1817531901 (Comprehensive)
Vehicle Reg. No. (Insured):	SGK9789H	Policy No. (Claimant):
		Excess: S\$1,500.00
Repairer:	Jec Automotive (HQ) 1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY, 417883 Kaki Bukit - Tel: 6509 6585	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 29/11/2019]	
Adj Asg. Remarks:	Please assist to arrange for PRS survey of TP bike FBM1975M.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*FBM1975M (SNM19D204748C01)
[SGK9789H]












































TP























































MUHAMMAD HAFIZ BIN SUANDI




Oct 7 2019 1:00PM

[-]

Jec Automotive

Upload Documents		Upload Photos	Compose New Letter	View View In Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
34	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
35	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
36	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
37	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
38	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
39	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
40	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
41	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
42	10/12/19 09:45	General View	 Load JPG	<input checked="" type="checkbox"/>	
43	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	10/12/19 09:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	10/12/19 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
99	10/12/19 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
100	10/12/19 09:46	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
101	10/12/19 09:46	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
102	10/12/19 09:46	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119020471/ASD3E2

Date: 17/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1817531901

Claimant
Vehicle No : FBM1975MInsured Vehicle
No : SGK9789H

Date of Loss: 07/10/2019

Nature of Claim: TP

Claim
No: SNM19D204748C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM1975M	Engine No:	KR150EEA58663
Make & Model:	KAWASAKI KRR ZX150 M, 149cc (M)	Chassis No:	KR150KA58663
Reg. Date:	12/01/2005 (Man. Year: 2004)	Odometer:	55535 km
Colour:	Blue		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/80 R17	Rear Tyre Size:	90/80 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,005.00	3,100.50	904.50	22.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,190.00	770.00	420.00	35.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,195.00	3,870.50	1,324.50	25.50
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	5,195.00	3,100.00	2,095.00	40.33

INSPECTION

Date of Assignment: 20/11/2019

Date Inspected: 19/11/2019 Inspected At:

Jec Automotive (HQ)
1 KAKI BUKIT AVENUE 6, #02-11
AUTOBAY
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Dec 2019)	
Parts:	N/A	KAWASAKI KRR ZX150 M 149cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM1975M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSHIELD	Not Necessary	95.00 F	*- FL
2	1		*HEADLAMP	Cracked	265.00 F	*265.00 FL
3	1		*HEADLAMP COWLING	Cracked	280.00 F	*280.00 FL
4	1		*HEADLAMP BRACKET	Bent	75.00 F	*75.00 FL
5	1		*FRONT WHEEL FENDER	Cracked	90.00 F	*90.00 FL
6	1		*FRONT FORK ASSY	Bent	680.00 F	*680.00 FL
7	1		*FRONT FORK BRACKET	Bent	155.00 F	*155.00 FL
8	1		*FRONT FORK OIL	Necessary	30.00 F	*30.00 FL
9	1		*FRONT FORK OIL SEAL	Necessary	50.00 F	*50.00 FL
10	1		*STEERING CONE AND BEARING	Necessary	85.00 F	*85.00 FL
11	1		*HANDLE BAR	O/S Bent	150.00 F	*75.00 FL
12	1		*CLUTCH LEVER	Not Necessary	35.00 F	*- FL
13	2		*BALANCER	Not Necessary	40.00 F	*- FL
14	1		*FUEL TANK	Dented	520.00 F	*520.00 FL
15	1		*FUEL TANK RUBBER PAD	Necessary	50.00 F	*50.00 FL
16	2		*SIDE FAIRING	Distorted	420.00 F	*420.00 FL
17	1		*SIDE FAIRING INNER GARNISH	N/S Cracked	90.00 F	*45.00 FL
18	2		*SIDE FAIRING INNER AIR DUCT	Not Necessary	60.00 F	*- FL
19	1		*SIGNAL FAIRING SIGNAL LAMP	O/S Cracked	80.00 F	*40.00 FL
20	1		*FOOT BRAKE	Bent	45.00 F	*45.00 FL
21	1		*FRONT FOOTREST	O/S Cut	80.00 F	*40.00 FL
22	1		*REAR FOOTREST	O/S Cut	80.00 F	*40.00 FL
23	1		*WING MIRROR	O/S Cut	150.00 F	*75.00 FL
24	1		*FRONT NUMBER PLATE	Not Necessary	15.00 FS	*- FS
25	1		*SPEEDOMETER	Cracked	385.00 F	*385.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,005.00	3,445.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	344.50
Total Parts (\$\$)	4,005.00	3,100.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	250.00
2	SPRAY PAINTING	New	400.00	250.00
3	WIRING	New	50.00	30.00
4	TO STRAIGHTEN CHASSIS MEMBER	New	300.00	200.00
5	TOWING	New	40.00	40.00
Gross Labour Cost (S\$)			1,190.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >