

DATE/TIME

ASS. REC. BY:

Steve

REF: 08/CTI 19020472/ Es d307

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Tan Kah Long

of CTI

Date/Time: 18/11/19 @ 4:14pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SGY 8245T

Insured:

YK 9645B

at Workshop m/s

JWG International

Tel:

6909 8882

of

Blk 10 Amk h.d. Park 2A #03-08

Policy No.:

Claim No.:

SNM19D 205446

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/1/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

5:19pm @ 1st/11/19

Person Contacted:

Jessie

Vehicle

IN OUT

Date/Time

Action/Instruction

Estimate /

SGY 8245T-X

YK 9645B - CCG / CTI 18017756 / Ajb3n2

D.O.A: 20/08/2018

ASS. REC. BY:

Steve

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 ul _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SGY 8245T Yr Regn: 9/19/97
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Accord c.c. 1998
 Colour: Yellow A/C: Insured / Std / NI / NA
 Sp. Reading: 196942 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: CL7-1301107
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/45ZR18
 R: 21
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kumho
 Front R/Bal. 5 mm Rear R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 14/11/19 D.O.I. 20/11/19
 Survey held at JWG International
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

X N/S	O/S
X	

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
2/12/19	MV-70K Final Conf \$2550, 4 days (K/ln) (\$15,871.67 Red - 86%) <i>[Signature]</i> 13/12/2019

RECEIVED 16 DEC 2019

Date/Time, File Pass to? 16/12/19
 1) Typ4
 Date/Time, File Return to? _____
 2) _____
 Prop. Formed: _____
 Lump Sum / L.B. / C. \$2,550 / 45

Days Of Repair: 4
 Resurvey No. of Trip: 1
 Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)
 Survey Fee: 220
 Transportation: _____
 S + RS, SI _____
 Photos _____
 Others _____
 TOTAL 220

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Monday, 18 November 2019 4:14 PM
To: JWG CLAIMS; assignments
Subject: RE: OUR REF: SNM19D205446-YK9645B-TKL - PRI arrangement for vehiclenumber SGY 8245T (URGENT)
Attachments: OUR REF: SNM19D205446-YK9645B-TKL - PRI arrangement for vehicle number S... (1.99 MB)

WITHOUT PREJUDICE

Dear Jessie,

We refer to your email dated 18.11.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: JWG CLAIMS [mailto:jwg.claims@yahoo.com]
Sent: Monday, November 18, 2019 3:56 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205446-YK9645B-TKL - PRI arrangement for vehiclenumber SGY 8245T (URGENT)

Dear Kah Leong,

Thanks for the email.

We are pleased to appoint Steve (LKK) to conduct this survey.
Please arrange survey on 20/11/19.

Thanks

Warmest Regard,

Jessie Ong

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H
Blk 10, Ang Mo Kio Ind Park 2A,
#03-08 AMK AutoPoint,
Singapore 568047

Tel: 6909 8882 Fax: 6909 9592 H/P: 9777 0970

E-Mail: jwg.claims@yahoo.com

From: Tan Kah Leong

Sent: Monday, November 18, 2019 3:06 PM

To: jwg.claims@yahoo.com

Subject: RE: OUR REF: SNM19D205446-YK9645B-TKL - PRI arrangement for vehiclenumber SGY 8245T (URGENT)

Without Prejudice

Dear Jessie,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, November 18, 2019 2:20 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>;
jwg.claims@yahoo.com

Subject: OUR REF: SNM19D205446-YK9645B-TKL - PRI arrangement for vehicle number SGY 8245T (URGENT)

Dear Kah leong,

Please conduct PRS for SGY8245T.

Note : officer in charge – Kah Leong 63896193.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: JWG CLAIMS [<mailto:jwg.claims@yahoo.com>]

Sent: Saturday, November 16, 2019 12:09 PM

To: Claims Dept of CTI

Subject: RE: PRI arrangement for vehicle number SGY 8245T (URGENT)

Without Prejudice

Dear Sir/Madam,

As attached, kindly send a list of survey firms to choose from.

Warmest Regard,

Jessie Ong

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

Tel: 6909 8882 Fax: 6909 9592 H/P: 9777 0970

E-Mail: jwg.claims@yahoo.com

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

Nivitha (LKK Auto)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Monday, 18 November 2019 2:20 PM
To: Tan Kah Leong; Chee So Chow; jwg.claims@yahoo.com
Subject: OUR REF: SNM19D205446-YK9645B-TKL - PRI arrangement for vehicle number SGY 8245T (URGENT)
Attachments: PRI SGY8245T.pdf; SAS2703254.PDF; FW: PRI arrangement for vehicle number SGY 8245T (URGENT) 1st Reminder (0.99 MB)

Dear Kah leong,

Please conduct PRS for SGY8245T.

Note : officer in charge – Kah Leong 63896193.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: JWG CLAIMS [mailto:jwg.claims@yahoo.com]
Sent: Saturday, November 16, 2019 12:09 PM
To: Claims Dept of CTI
Subject: RE: PRI arrangement for vehicle number SGY 8245T (URGENT)

Without Prejudice

Dear Sir/Madam,

As attached, kindly send a list of survey firms to choose from.

Warmest Regard,

Jessie Ong

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

Tel: 6909 8882 Fax: 6909 9592 H/P: 9777 0970

E-Mail: jwg.claims@yahoo.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	619J
Vehicle Details	
Vehicle No.:	SGY8245T
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	ACCORD EURO-R 2.0 M
Primary Colour:	Yellow
Manufacturing Year:	2007
Engine No.:	K20A6541187
Chassis No.:	CL71301107
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$25,980.00
Original Registration Date:	09 Oct 2007
First Registration Date:	09 Oct 2007
Transfer Count:	2
Actual ARF Paid:	\$28,578.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$50,355.00
COE Rebate Amount:	\$39,570.00
Total Rebate Amount:	\$39,570.00

The information contained herein is correct as at 21 Nov 2019

OK

Steve Chen (LKK Auto)

From: JWG CLAIMS <jwg.claims@yahoo.com>
Sent: Friday, November 29, 2019 4:06 PM
To: Steve Chen (LKK Auto)
Subject: RE: SGY8245T Finalize

Without Prejudice

Dear Sir/Madam,

We would like to accept the finalized offer of **S\$2,550.00/-** for stated vehicle with **4 repair days**.

Thanks and Best Regards,

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

Phone: 6909 8882 | Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

From: Steve Chen (LKK Auto)
Sent: Wednesday, November 27, 2019 9:36 AM
To: jwg.claims@yahoo.com
Subject: SGY8245T Finalize

Dear Kelvin,

Kindly refer our finalize \$2550 (L/S, before GST). 4 repair days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/11/2019 16:45
Date Of Accident	14/11/2019 20:10
Exact Location Of Accident	PASIR RIS DRIVE 1 ALONG LIVIA CONDO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY8245T
Insured/Policyholder	
Name Of Registered Owner	TAN WEE KIAT,EDMUND
NRIC No	S8814619J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98341403
Alternative Phone No	OTHERS-98341403

Vehicle Particulars

Manufacturer	HONDA
Model	ACCORD EURO-R 2.0 M
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA403691/1
Cover Note Number	

Driver

Name of Driver	TAN WEE KIAT,EDMUND
NRIC No	S8814619J
Date Of Birth	29/04/1988
Occupation	INDOOR
Date Of Driving Pass	23/07/2008
Driving Experience	11 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98341403
Fax Number	
Contact Number	OTHERS-98341403
EMail Address	NOEMAIL

Address	571 PASIR RIS STREET 53 #08-48 SPORE 510571
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YK9645B
Vehicle Make/Model/Colour	ISUZU / NPR71L
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

VEHICLE NO.: S677 22457
INSURER : AXA
DATE & TIME: 14 | 11 | 19 2010

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: S. K. M.
NRIC/FIN No:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(804 83253)

ON THE STATED DATE AND TIME I VEHICLE A WAS TRAVELING ALONG
 STATED LOCATION ON THE RIGHT LANE SUDDENLY VEHICLE B 4K9645B
 CMT INTO MY LANE AND HIT THE LEFT SIDE OF MY VEHICLE
 VEHICLE B DID NOT SIGNAL AND CMT INTO MY LANE THERE IS A VIDEO
 FOOTAGE FOR THIS ACCIDENT.

Note : Please note that your Insurer may have 14days Time Frame for you to submit an Own Damage Claim
 under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NR/C/FN No:

Claim Own Policy Claim Third Party Reporting Only
 Claim GO/TP at other workshop ()

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

DATE : 19/11/19

VEHICLE NO : SGY 8245 T
 MODEL : HONDA ACCORD EURO R
 CHASSIS NO : CL71301107

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	HEADLAMP LH X <i>NN</i>	1	\$ 789.70	\$ 789.70
2	HEADLAMP LOWER BRACKET LH X <i>NN</i>	1	\$ 90.00	\$ 90.00
3	FRONT BUMPER X <i>NN</i>	1	\$ 976.00	\$ 976.00
4	FRONT BUMPER SIDE RETAINER LH X <i>NN</i>	1	\$ 48.00	\$ 48.00
5	FRONT BUMPER BRACKET LH X <i>NN</i>	1	\$ 68.00	\$ 68.00
6	FRONT FENDER LH / <i>DD</i>	1	\$ 556.00	\$ 556.00
7	FRONT FENDER COWLING LH X <i>NN</i>	1	\$ 158.20	\$ 158.20
8	SIDE MIRROR ASSY COMPLETE / <i>BR</i>	1	\$ 1,485.00	\$ 1,485.00
9	FRONT DOOR LH X <i>R</i>	1	\$ 1,106.94	\$ 1,106.94
10	FRONT DOOR LOCK LH X <i>NN</i>	1	\$ 322.84	\$ 322.84
11	FRONT DOOR WEATHERSTRIP LH X <i>NN</i>	1	\$ 198.00	\$ 198.00
12	REAR DOOR LH / <i>DD</i>	1	\$ 1,186.69	\$ 1,186.69
13	REAR DOOR LOCK LH X <i>NN</i>	1	\$ 222.98	\$ 222.98
14	REAR DOOR WEATHERSTRIP LH X <i>NN</i>	1	\$ 198.00	\$ 198.00
15	REAR LOWER ARM RH X <i>NN</i>	1	\$ 371.56	\$ 371.56
16	REAR KNUCKLE ARM RH X <i>NN</i>	1	\$ 496.37	\$ 496.37
17	REAR KNUCKLE ARM BEARING RH X <i>NN</i>	1	\$ 321.64	\$ 321.64
18	REAR SHOCK ABSORBER RH X <i>NN</i>	1	\$ 457.42	\$ 457.42
19	REAR STAY ARM RH X <i>NN</i>	1	\$ 267.34	\$ 267.34
20	REAR ADJUSTABLE ARM RH X <i>NN</i>	1	\$ 291.35	\$ 291.35
21	REAR UPPER ARM RH X <i>NN</i>	1	\$ 347.56	\$ 347.56
22	REAR WHEEL RIM RH X <i>NN</i>	1	\$ 480.00	\$ 480.00

TOTAL PRICE \$ 10,439.59
 LESS 20% \$ 2,087.92
 SUB TOTAL PRICE \$ 8,351.67

2267.59
-20%
1814.07

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	SPORT RIMS X <i>NN</i>	2	\$ 1,800.00	\$ 3,600.00

2	TYRE X N/A	2	\$ 400.00	\$ 800.00
3	DOOR STICKER / MK	2	\$ 80.00	\$ 160.00
4	BRAKE FLUID X N/A	2	\$ 50.00	\$ 100.00
5	FRONT BUMPER CLIPS X N/A	1	\$ 100.00	\$ 100.00
6	FRONT FENDER COWLING CLIPS X N/A	1	\$ 100.00	\$ 100.00

TOTAL \$ 4,860.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	500
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	600 700
3	TUFF COAT	\$ 250.00	30
4	WIRING CHECK	\$ 180.00	30
5	TO RNR FRONT & REAR DOOR MECHANISM TO ASSIST WORK LOAD	\$ 450.00	30
6	TO RNR UNDERCARRIAGE SYSTEM	\$ 350.00	X
7	TO CHECK WHEEL ALIGNMENT	\$ 150.00	X
8	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	\$ 80.00	X
9	TO RNR TYRE AND WHEEL BALANCING	\$ 100.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X

TOTAL \$ 5,210.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 13,211.67
TOTAL LABOUR COST : \$ 5,210.00
TOTAL REPAIR COST : \$ 18,421.67

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

KELVIN WO

KELVIN WO

Steve (LKK)

WHL Advice
20/11/19, 11.00am

4 days

L/S

Reg AFL Spj

P- 1814.07

M- 80

L- 1290

3184.07

L/S- 2547.25

= 2550

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Nov 2019		22 Nov 2019 11:55 Edit Adj Rpt	S\$2,550.00 Edit Estimates	S\$2,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TKB C-E CONTRACTOR PTE LTD , Co. Reg. No.: 198600003M									
Main Claimant: TAN WEE KIAT, DESMOND , ID: S8814619J									
Vehicle Reg. No.:	SGY8245T	Date of Loss:	14/11/2019 20:00 - :59 [145 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205446C02	Policy/Cover Note No.:	DMCVSN17388719022						
Vehicle Reg. No. (Insured):	YK9645B	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A, #03-08 AMK AutoPoint, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 03/12/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGY8245T (SNM19D205446C02)
 [YK9645B]
 TP
 TAN WEE KIAT, DESMOND
 Nov 14 2019 8:00PM
 [TKB C-E CONTRACTOR PTE LTD]
 JWG International Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
2	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
3	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
4	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
5	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
6	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
7	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
8	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
9	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
10	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
11	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
12	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
13	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
14	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
15	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
16	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
17	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
18	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
19	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
20	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
21	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
22	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
23	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
24	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
25	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
26	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
27	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
28	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
29	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
30	29/11/19 09:03	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>						
31	29/11/19 09:03	Chassis Number		Load JPG	<input checked="" type="checkbox"/>						
32	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
33	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
34	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
35	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
36	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
37	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
38	29/11/19 09:03	General View		Load JPG	<input checked="" type="checkbox"/>						
39	29/11/19 09:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>						
40	29/11/19 09:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>						
41	29/11/19 09:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>						
42	29/11/19 09:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>						
43	29/11/19 09:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>						

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	29/11/19 09:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
45	29/11/19 09:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119020472/ESD3E2

Date: 17/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN17388719022

**Claimant
Vehicle No :** SGY8245T

**Insured
Vehicle No :** YK9645B

Date of Loss: 14/11/2019

Nature of Claim: TP

Claim
No: SNM19D205446C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY8245T**

Make & Model: HONDA ACCORD, 2.0 Euro R (CL7) (M)

Engine No: K20A6541187

Reg. Date: 09/10/2007 (Man. Year: 2007)

Chassis No: CL71301107

Colour: Yellow

Odometer: 196942 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R18

Rear Tyre Size: 225/45Z R18

Front Left Side: Kumho 5 mm

Rear Left Side: Kumho 5 mm

Front Right Side: Kumho 5 mm

Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	13,211.67	1,894.07	11,317.60	85.66	
Miscellaneous Items	0.00	0.00	0.00		
Labour	5,210.00	1,290.00	3,920.00	75.24	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	18,421.67	3,184.07	15,237.60	82.72	
Approved Total (Overridden) (S\$)		2,550.00			
	(S\$)	18,421.67	2,550.00	15,871.67	86.16
+ GST 7.00/7.00% (S\$)	1,289.52	178.50	1,111.02	86.16	
Nett Amount (S\$)	19,711.19	2,728.50	16,982.69	86.16	

INSPECTION

Date of Assignment: 22/11/2019

Date Inspected: 20/11/2019 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A, #03-
08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2019)
Parts: 143	HONDA ACCORD 2.0 Euro R (CL7) (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGY8245T)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Not Necessary	789.70 FL	*- FL
2	1		*HEADLAMP LOWER BRACKET LH	Not Necessary	90.00 FL	*- FL
3	1		*FRONT BUMPER	Not Necessary	976.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	48.00 FL	*- FL
5	1		*FRONT BUMPER BRACKET LH	Not Necessary	68.00 FL	*- FL
6	1		*FRONT FENDER LH	Dented	556.00 FL	*556.00 FL
7	1		*FRONT FENDER COWLING LH	Not Necessary	158.20 FL	*- FL
8	1		*SIDE MIRROR ASSY COMPLETE	Broken	1,485.00 FL	*524.90 FL
9	1		*FRONT DOOR LH	Repair	1,106.94 FL	*- FL
10	1		*FRONT DOOR LOCK LH	Not Necessary	322.84 FL	*- FL
11	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	198.00 FL	*- FL
12	1		*REAR DOOR LH	Dented	1,186.69 FL	*1,186.69 FL
13	1		*REAR DOOR LOCK LH	Not Necessary	222.98 FL	*- FL
14	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	198.00 FL	*- FL
15	1		*REAR LOWER ARM RH	Not Necessary	371.56 FL	*- FL
16	1		*REAR KNUCKLE ARM RH	Not Necessary	496.37 FL	*- FL
17	1		*REAR KNUCKLE ARM BEARING RH	Not Necessary	321.64 FL	*- FL
18	1		*REAR SHOCK ABSORBER RH	Not Necessary	457.42 FL	*- FL
19	1		*REAR STAY ARM RH	Not Necessary	267.34 FL	*- FL
20	1		*REAR ADJUSTABLE ARM RH	Not Necessary	291.35 FL	*- FL
21	1		*REAR UPPER ARM RH	Not Necessary	347.56 FL	*- FL
22	1		*REAR WHEEL RIM RH	Not Necessary	480.00 FL	*- FL
23	2		*SPORT RIMS	Not Necessary	3,600.00 FS	*- FS
24	2		*TYRE	Not Necessary	800.00 FS	*- FS
25	1		*DOOR STICKER (2PCS)	Necessary (1Pc Only)	160.00 FS	*80.00 FS
26	2		*BRAKE FLUID	Not Necessary	100.00 FS	*- FS
27	1		*FRONT BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
28	1		*FRONT FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,299.59	2,347.59
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,087.92	453.52
Total Parts (\$\$)	13,211.67	1,894.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	700.00
2	TUFF COAT	New	250.00	30.00
3	WIRING CHECK	New	180.00	30.00
4	TO RNR FRONT & REAR DOOR MECHANISM TO ASSIST WORK LOAD	New	450.00	30.00
5	TO RNR UNDERCARRIAGE SYSTEM	New	350.00	0.00
6	TO CHECK WHEEL ALIGNMENT	New	150.00	0.00
7	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	New	80.00	0.00
8	TO RNR TYRE AND WHEEL BALANCING	New	100.00	0.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	250.00	0.00
10	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,800.00	500.00
Gross Labour Cost (S\$)			5,210.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >