

ASS. REC. BY:

REF: CS/INC19020501/ KSD36 Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Herzdyga Bt Abraham of INC Date/Time: 19/11/19 @ 9.52am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKW 543D Insured: SJT 6279A

at Workshop m/s Car times Auto Solution Tel: 6471 5111

of 160 Sin Ming Drive #02-04

Policy No: _____ Claim No: MT/1071808-001

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 04/11/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 1005am @ 19/11/19 Person Contacted: yuli Vehicle IN OUT

Date/Time	Action/Instruction
	<u>Johnnie ✓</u>
	<u>SKW 543D-X</u>
	<u>SJT 6279A-X</u>
<u>28/11</u>	<u>111pm @ 2100 email & confirm</u>
	<u>(\$ 4,044.00 Red - 66%)</u>

ASS. REC. BY:

REF: INC/Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

02

days

Res.: _____

Yes or No

Lum Sum: _____

20

%

3 Val.: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

Date/Time, File Pass to?

11/12/19

1)

Typist

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair: 2Resurvey No. of Trlp: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

290290

Report Format :

Lump Sum / I.B.I. (\$

2,100/- 45Veh No: SKW 593DYr Regn: 10, 15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: M. S400L

c.c

2997Colour: M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading: 105006

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2221652A 191655Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD / Rlm orTyre Size: F: 245/45R19R: 275/40R19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 4/11/19D.O.I. 20/11/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Nivitha (LKK Auto)

From: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>
Sent: Tuesday, 19 November 2019 3:26 PM
To: Admin-D (LKKAuto); assignments
Cc: Hazalysa Binte Ibrahim
Subject: RE: TP CASES FARMED OUT TO LKK ON 19/11/2019

Dear LKK,

Re-send with details.

Thank you.

Warmest Regards

Hazalysa Bte Ibrahim
Admin Assistant
Operations, Motor & Personal Lines (PL)
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Hazalysa Binte Ibrahim
Sent: Tuesday, 19 November 2019 9:52 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Alice Low <alice.lowkc@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 19/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1071694-002	SLR1040R	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SJP7344J	16/11/19	
2	Eng Huey Huey	MT/1071605-001	SLD8452M	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SJN6985B	15/11/19	
3	Serene Lim	MT/1071721-001	SLF9471R	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		PC601K	15/11/19	
4	Azhari	MT/1071695-002	SLL3057L	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SLZ3659B	15/11/19	
5	Eng Huey Huey	MT/1071993-001	SLA1405J	OPTIMA WERKZ PTE LTD	9A SERANGOON NORTH AVE 5	Sharon Ten / 6481 1522		SIU5625K	17/11/19	avoid 1PM - 2PM
6	Wo Jessie	MT/1071949-001	SHC3281A	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SLN9343K	16/11/19	65425119 or 6542 7162
7	Quek Swee Keng	MT/1071863-002	SHD3009R	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SMK5648L	16/11/19	65425119 or 6542 7162
8	Quek Swee Keng	MT/1071765-002	SHA7757D	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SJN4823Z	16/11/19	65425119 or 6542 7162
9	Serene Lim	MT/1070016-002	EW3366U	TROPICAL SUCCESS AUTO CARE	BLK 5032 #01-299/303 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569535	Calvin / 64817773		SLG4655E	05/11/19	
10	Muhammad Airwan	MT/1071969-001	YP9666P	WENG KEE MOTOR	BLK 1019 #01-366 YISHUN INDUSTRIAL PARK A	Victor Wong Qi Zhi / 6854 1273 / 8182 1895		SJL9527G	07/11/19	
11	Jeff Lin	MT/1071637-002	SGK775G	AT AUTO CONSULTANT	BLK 01 SIN MING INDUSTRIAL ESTATE	Alan Tan / 83868989		SKD8863Y	15/11/19	

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	034H
Vehicle Details	
Vehicle No.:	SKW593D
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Nov 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	S400L (R19 LED)
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	27682430227875
Chassis No.:	WDD2221652A191655
Maximum Power Output:	245.0 kW (328 bhp)
Open Market Value:	\$96,961.00
Original Registration Date:	15 Oct 2015
First Registration Date:	15 Oct 2015
Transfer Count:	1
Actual ARF Paid:	\$146,530.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2025
PARF Rebate Amount:	\$109,897.00
Intended COE Rebate Details	
COE Expiry Date:	14 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$62,101.00
COE Rebate Amount:	\$36,666.00
Total Rebate Amount:	\$146,563.00
Message	
Transfer of ownership or deregistration is not allowed for this vehicle.	

The information contained herein is correct as at 18 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/11/2019 08:47
Date Of Accident	04/11/2019 22:10
Exact Location Of Accident	WEST COAST HIGHWAY TRAFFIC LIGHT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW593D
Insured/Policyholder	
Name Of Registered Owner	CHONG EE KHIAT
NRIC No	S6821034H
Email Address	SUNNYCHONG68@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98757503
Alternative Phone No	OFFICE-98757503

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	S400L-3.0 R19 LED (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	CHONG EE KHIAT
NRIC No	S6821034H
Date Of Birth	01/06/1968
Occupation	INDOOR
Date Of Driving Pass	01/01/1989
Driving Experience	30 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98757503
Fax Number	
Contact Number	OFFICE-98757503
EEmail Address	SUNNYCHONG68@GMAIL.COM

Address	15 PONGGOL TWENTY-FOURTH AVENUE
Postcode	829487
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT6279A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 7/11, 1545hrs.

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature


Name: Yuki

NRIC/FIN No.: S812420SD

Sketch Plan #2

SKETCH PLAN

West Coast Highway toward harbourfront



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- 1) Driving along west coast highway, come to a traffic light.
- 2) Stop vehicle waiting for traffic light as it turn red colour.
- 3) Wait while waiting, probably around less than 1 minute. Vehicle SJT 6279A bump onto my vehicle SKW 593D from the back.

*Note: I have lost my driving license and is unable to attach the driving license and provide my driving license passing date.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 7/11, 1545hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: Yuli

NRIC/FIN No.: 5812420SD.

AUTOLUTION

CARTIMES

CarTimes Autolution Pte Ltd

160 Sin Ming Drive AutoCity

#02-04 Singapore 575722

Tel : 6471 5111

Email : claims@cartimes.com.sg

Vehicle No. SKW593D

MODEL: MERCEDES S400

DESCRIPTION		REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>		
REAR BUMPER <i>2261-00</i>		<i>Return</i> \$ 2,480.00 ✓
REAR BUMPER LOWER LID		\$ <i>780.00</i> X
REINFORCEMENT BAR		\$ <i>1,450.00</i> X
SIDE RETAINER LH & RH		\$ <i>350.00</i> X
	10	\$ 5,060.00
	20%	\$ 506.00
		\$ 4,554.00
<u>NETT Item</u>		
rear bumper clip		\$ <i>30.00</i> ✓
	TOTAL PARTS	4584.00

Not Notified
L1 Png @ 2100h
Resurvey After Paint
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before *0* spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOLUTION

CARTIMES

CarTimes Autolution Pte Ltd
 160 Sin Ming Drive AutoCity
 #02-04 Singapore 575722
 Tel : 6471 5111
 Email : claims@cartimes.com.sg

Vehicle No.SKW593D

MODEL:MERCEDES S400

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)
	<u>LABOUR</u>	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 800.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 700.00
3	To remove and refix wiring and check all electrical components at damaged areas for proper functions	\$ 60.00
	Labour Total :	\$ 1,560.00
	TOTAL (PARTS & LABOUR):	6144.00

3001

3001

151



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020501/Ksd3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 16-12-2019



ATTN : CHARLOTTE CHEW

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 6279A	Veh. Inspected	SKW 593D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1071808-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	19/11/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ S400L (A)	c.c	2996
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2221652A191655	Colour	METALLIC BLACK
Odometer	105006 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R19	BRIDGESTONE	6 mm
L/H Front Tyre	245/45 R19	BRIDGESTONE	6 mm
R/H Rear Tyre	275/40 R19	BRIDGESTONE	6 mm
L/H Rear Tyre	275/40 R19	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	04/11/2019	Inspect Date / Time	20/11/2019 (10:42 AM)
Survey held at	160 SIN MING DRIVE#02-04		
Repairer	CAR TIMES AUTOLUTION PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 593D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / CRACKED	2,480.00	2,261.00
1	REAR BUMPER LOWER LID	SERVICEABLE	780.00	-
1	REINFORCEMENT BAR	TO REPAIR SEE LABOUR	1,450.00	-
2	SIDE RETAINER LH & RH	SERVICEABLE	350.00	-
	LESS 10% DISCOUNT		-506.00	-226.10
			4,554.00	2,034.90
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
			30.00	30.00
	LABOUR			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF REINFORCEMENT BAR.		800.00	300.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		700.00	300.00
	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.		60.00	15.00
			1,560.00	615.00
	GRAND TOTAL		6,144.00	2,679.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,100.00

Report Ref No. CS/INC19020501/Ksd3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.