



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020507/Ksd3e2

73 BRAS BASAH ROAD

Date: 19-06-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : ENG HUEY HUEY

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                        |                |            |
|--------------|------------------------|----------------|------------|
| Insured Veh. | SJU 5625K              | Veh. Inspected | SLA 1405L  |
| Policy No.   |                        | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1071993-001         | Excess (\$)    | 0.00       |
| Assign From  | HAZALYSA BINTI IBRAHIM | Assign Date    | 19/11/2019 |

#### 2. Vehicle Particulars & Condition

|              |                          |              |                      |
|--------------|--------------------------|--------------|----------------------|
| Make & Model | VOLKSWAGEN SPORTSVAN (A) | c.c          | 1395                 |
| Engine No.   | HIDDEN                   | Year of Reg. | 2016                 |
| Chassis No.  | WVWZZZAUZGW552395        | Colour       | METALLIC PEARL WHITE |
| Odometer     | 66489 KM                 | Steering     | IN ORDER             |
| Brakes       | IN ORDER                 | Modification | STANDARD ALLOY RIM   |
| General      | GOOD                     |              |                      |

#### 3. Conditions of Tyres

|                | Size       | Make        | Balance |
|----------------|------------|-------------|---------|
| R/H Front Tyre | 225/60 R18 | BRIDGESTONE | 7 mm    |
| L/H Front Tyre | 225/60 R18 | BRIDGESTONE | 7 mm    |
| R/H Rear Tyre  | 225/60 R18 | BRIDGESTONE | 7 mm    |
| L/H Rear Tyre  | 225/60 R18 | BRIDGESTONE | 7 mm    |

#### 4. Description of Damages

|  |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.<br>DAMAGES SEE DETAILS. |
|--|

#### 5. General Information

|                |  |                     |                         |
|----------------|--|---------------------|-------------------------|
| Accident Date  | 17/11/2019   | Inspect Date / Time | 19/11/2019 ( 12:21 PM ) |
| Survey held at | OPTIMA WERKZ PTE LTD<br>9A SERANGOON NORTH AVE 5<br>SINGAPORE 554500 |                     |                         |

#### 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

#### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 7 Working Days |
|-------------------------------------|----------------|