

Date: 18.11.2019
 Vehicle No: SLA1405L
 Model: VOLKSWAGEN SPORTSVAN 1.4
 Chassis: WVVZZZAUZGW552395 - 2015
 Reg.Year: 2016

Third Party Insurer: NTUC
 Third Party Veh No: SJU5625K
 Date of Accident: 17.11.2019

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER LOWER GRILLE	1	CRA 310.00	\$420.00
SUB TOTAL				\$420.00
LESS 10%				-\$42.00
PARTS TOTAL				\$378.00

→ Photo taken by Kenneth when he survey this vehicle.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____