

ASS. REC. BY:

REF:

eslinc19020514/ Eqd3

Special Instruction:

Survey: Steve

ASSIGNMENT (Office)

From (Person): Hazelysa St Ibrahim of INC

Date/Time: 9:52am 19/11/09

Estimated Cost: Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YP9666P

Insured: SJL9527G

at Workshop in/s: Wang Kee Motor

Tel: 68541273

of Blk 1019 #01-366 Yishun Ind. Park A

Policy No:

Claim No: MT/1071969-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7/11/2009

21/11/2009

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:01am 19/11/09

Person Contacted: Victor

Vehicle-IN (OUT)

Date/Time	Action/Instruction	Followups	Request Steve
	YP9666P x		
	SJL9527G-NA/III/3006227/01		D.O.A. 21/11/2009

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Tuesday, 19 November 2019 3:26 PM
To: Admin-D (LKKAuto); assignments
CC: Hazalya Binte Ibrahim
Subject: RE: TP CASES FARMED OUT TO LKK ON 19/11/2019

Dear LKK,

Re-send with details.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Operations, Motor & Personal Lines (PL)
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

IN with you

From: Hazalya Binte Ibrahim
Sent: Tuesday, 19 November 2019 9:52 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Alice Low <alice.lowkc@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 19/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1071694-002	SLR1040R	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SJP7344J	16/11/19	
2	Eng Huey Huey	MT/1071605-001	SLD8452M	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SJN6985B	15/11/19	
3	Serene Lim	MT/1071721-001	SLF9471R	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		PC601K	15/11/19	
4	Azhari	MT/1071695-002	5LL3057L	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SLZ3659B	15/11/19	
5	Eng Huey Huey	MT/1071993-001	5LA1405I	OPTIMA WERKZ PTE LTD	9A SERANGOON NORTH AVE 5	Sharon Ten / 6481 1522		SIU5625K	17/11/19	avoid 1PM - 2PM
6	Wo Jessie	MT/1071949-001	SHC3281A	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SLN9343K	16/11/19	65425119 or 6542 7162
7	Quek Swee Keng	MT/1071863-002	SHD3009R	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SMK5648L	16/11/19	65425119 or 6542 7162
8	Quek Swee Keng	MT/1071765-002	SHA7757D	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SIH4823Z	16/11/19	65425119 or 6542 7162
9	Serene Lim	MT/1070016-002	EW3366U	TROPICAL SUCCESS AUTO CARE	BLK 5032 #01-299/303 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569535	Calvin / 64817773		SLG4655E	05/11/19	
10	Muhammad Airwan	MT/1071969-001	YP9666P	WENG KEE MOTOR	BLK 1019 #01-366 YISHUN INDUSTRIAL PARK A	Victor Wong Qi Zhi / 6854 1273 / 8182 1895		SIJ9527G	07/11/19	
11	Jeff Lim	MT/1071637-002	SGK775G	AT AUTO CONSULTANT	BLK 01 SIN MING INDUSTRIAL ESTATE	Alan Tan / 83868989		SKD8863Y	15/11/19	

12	Charlotte Chew	MT/1071808-001	SKW593D	CAR TIMES AUTOLUTION PTE LTD	SECTOR C #01-123 SINGAPORE 575642	Yuki Peck / 64715111		SJT6279A	04/11/19	
13	Charlotte Chew	MT/1071882-001	SMH9185U	CAR TIMES AUTOLUTION PTE LTD	160 SIN MING DRIVE #02-04 AUTO CITY	Yuki Peck / 64715111		FBK9594L	15/11/19	
14	Azhari	MT/1071931-002	SLN4265K	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	Carmen / 8799 0066 / 6566 2112		5GC3973Z	18/11/19	
15	Helena Tan	MT/1071763-001	SLK7414T	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	JENNY // 8799 0066 / 6566 2112		5HD2002R	15/11/19	
16	Eric Tang	MT/1071712-002	SFU6000D	LAI HJAT MENG KEE MOTOR PTE LTD	160 SIN MING DRIVE #04-01 SIN MING AUTO CITY SINGAPORE 575722	Jenny Lim / 6453811D		SIP4536S	16/11/19	
17	Muhammad Airwan	MT/1071932-001	SMG4160D	THIAM HENG HIJAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTO CARE	Steven / 82636295		SFS3089G	15/11/19	
18	Serene Lim	MT/1071619-002	SME782X	THIAM HENG HIJAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTO CARE	Steven / 82636295		SLZ7783Z	15/11/19	
19	Jared Liu	MT/1070409-002	SKV8059H	TONG LUCK AUTO PTE LTD	160 SIN MING DRIVE #07-01/06 SIN MING AUTO CITY	Yu Ching / 6250 0088		SIM5479H	07/11/19	
20	Eng Huey Huey	MT/1072031-001	SJT961C	WORKSHOP 99 AUTO SERVICES	BLK 9 SIN MING ROAD #01-34 SIN MING INDUSTRIAL EST SECTOR C SINGAPORE 575644	William Saw / 65525192 / 97311186		5LU7891X	15/11/19	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg

income
made different



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	412A
Vehicle Details	
Vehicle No.:	YP9666P
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Nov 2019
Vehicle Make:	HINO
Vehicle Model:	HINO XZU710R-HKFMS3
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	N04CUS34231
Chassis No.:	JHHUCS3HX0K022434
Maximum Power Output:	-
Open Market Value:	\$30,987.00
Original Registration Date:	22 Aug 2017
First Registration Date:	22 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$1,550.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Aug 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$18,495.00
COE Rebate Amount:	\$14,308.00
Total Rebate Amount:	\$14,308.00

The information contained herein is correct as at 26 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/11/2019 13:18
Date Of Accident	07/11/2019 16:50
Exact Location Of Accident	GEYLANG LOR 25
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP9866P
Insured/Policyholder	
Name Of Registered Owner	FATT CHAN IRON CANVAS TENT CONSTRUCTION
Co Reg No	52818412A
Email Address	ADMIN@SINZHAN.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-92726370
Vehicle Particulars	
Manufacturer	HINO
Model	HINO XZU710R-HKFMS3
Exact Purpose for which vehicle was being used at time of accident	PARKED - UNLOADING MATERIALS BEHIND
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Flat Policy	NO
Policy Number	5111451592
Cover Note Number	22/08/19 - 21/08/20
Driver	
Name of Driver	HOSSAIN UZZAL
NRIC No	G8147607T
Date Of Birth	15/05/1987
Occupation	OUTDOOR
Date Of Driving Pass	03/08/2016
Driving Experience	3 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85086862
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Code

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH. *THIRD PARTY CLAIM BY WENG KEE MOTOR*

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJL9527G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name


Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

A- YP9666P
B- SJL9527G

Aljuried
MRT



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle A is parked. Vehicle B wants to drive out and knocked into my vehicle A.

Accident happened on 7th Nov 2019, approximately 1650 hrs.

* Third Party Claim by Wang Kae Hsiao

DECLARATION

I/We declare the foregoing particulars are true in every respect

Police Officer's Signature
Date & Time

Driver's Signature
If not the police officer
Date & Time

Reporting Centre Personnel's Signature
Name (Yes)
M/C/IN No.

WENG KEE MOTOR

DATE: 20-11-2019

REPAIR ESTIMATE

VEHICLE: YP 9666 P

MODEL: Hino 300

S/n	Description of part	Qty	Estimate
1	Front bumper ✓ <i>CUT</i>	1	722.00 ✓
2	Front headlight LH ✓ <i>CUT</i>	1	1,050.00 ✓
3	Front door signal lamp LH ✗ <i>NAI</i>	1	80.00 ✗
4	Front door side step LH ✗ <i>NAI</i>	1	288.00 ✗
Sub-total 1			2,140.00 <i>1772</i>
Less 10%			1,926.00 <i>-10%</i>
			1,594.80

Labour

5	To straighten and panel beating front frame members and front bumper reinforcement. To remove and refit above parts	300.00	<i>200</i>
6	To putty, re-spray painting and polish affected areas.	200.00	✓
7	To rectify wiring	40.00	<i>30</i>
8	To rust proof affected areas.	50.00	<i>30</i>
Labour total			600.00
Parts & Labour total			2,526.00 <i>460</i>

[Signature]
27/11/19

Steve (LKK) with Mil 21/11/19, 3.00pm

2 days

L/S

By AL spj

P-1594.80

L-460

2054.80

L/S-1643.84

= 1650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020514/Eqd3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 08-01-2020



ATTN: MUHAMMAD AIRWAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 9527G	Veh. Inspected	YP 9666P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1071969-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	19/11/2019

2. Vehicle Particulars & Condition

Make & Model	HINO XZU710R	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHHUCS3HX0K022434	Colour	BLUE
Odometer	57276 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	7.00 R16	WEST LAKE	4 mm
L/H Front Tyre	7.00 R16	WEST LAKE	4 mm
R/H Rear Tyre	7.00 R16	WEST LAKE	4 mm
L/H Rear Tyre	7.00 R16	WEST LAKE	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/11/2019	Inspect Date / Time	21/11/2019 (02:53 PM)
Survey held at	WENG KEE MOTOR BLK 1019 #01-366 YISHUN INDUSTRIAL PARK A . SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 9666P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CUT	722.00	722.00
1	FRONT HEADLIGHT LH	CUT	1,050.00	1,050.00
1	FRONT DOOR SIGNAL LAMP LH	NOT NECESSARY	80.00	-
1	FRONT DOOR SIDE STEP LH	NOT NECESSARY	288.00	-
	LESS 10% DISCOUNT		-214.00	-177.20
			1,926.00	1,594.80
LABOUR				
	TO STRAIGHTEN AND PANEL BEATING FRONT FRAME MEMBERS AND FRONT BUMPER REINFORCEMENT. TO REMOVE AND REFIT ABOVE PARTS.		300.00	200.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		200.00	200.00
	TO RECTIFY WIRING.		40.00	30.00
	TO RUST PROOF AFFECTED AREAS.		60.00	30.00
			600.00	460.00
GRAND TOTAL			2,526.00	2,054.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,650.00

Report Ref No. CS/INC19020514/Eqd3n2

CHEN TSUE YEE

Automotive Assessor

K.K. LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.