

ASS. REC. BY: Sun Pm

REF:

MSIG

dc

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SLM 54822
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMB58935 Yr Regn: 11/NOV/2015
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MAN A95 c.c 10518
 Colour: Multicolour A/C: Insured / Std / NI / NA
 Sp. Reading: 258987 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WMAA95228G7003046
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modl: Nil / S/Rim / STD A/Rim or steel Rim
 Tyre Size: F: 275 / 70 R 22-5
 R: 275 / 70 R 22-5
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 13/11/2019 D.O.I. 19/11/2019
 Survey held at SMRT
 Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	SMB 58935 - NS/INCIF8013444 / Nsb22 DDA: 13/7/2018
	SLM 54822 - CS3/MSU/7007420 / Jh3s2 DDA: 00/4/2017
	Confirm with catherine.
	Confirm Finalize Amount \$1938 @ 3 days. (P/P) Labour Only
	(\$ 2,355.00 Red, 55%) 26/11/2019

Date/Time, File Pass to? 26/11/19
 1) Type
 Date/Time, File Return to?
 2) _____

Days Of Repair: 3
 Resurvey No. of Trip: 2

Rep. Format: _____
 Lump Sum / L.S.: 1,938.00 P/P

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee:	<u>190</u>
Transportation:	_____
\$ + RS. SI	_____
Police	_____
Others	<u>11</u>
TOTAL	<u>161</u>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SMB58935
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2019
Vehicle Make:	MAN
Vehicle Model:	A95
Primary Colour:	Multicolor
Manufacturing Year:	2015
Engine No.:	50342170624215
Chassis No.:	WMAA95ZZ8G7003046
Maximum Power Output:	-
Open Market Value:	\$438,406.00
Original Registration Date:	11 Nov 2015
First Registration Date:	11 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 20 Nov 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 20 November 2019 3:34 pm
To: motorsurvey@sg.msig-asia.com
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD ,DOA: 13/11/2019 ,SMB 5893S (TP VEHICLE), SLM 5482Z (OI VEHICLE)
Attachments: TP GIA REPORT.pdf; ESTIMATE.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SMB 5893S at M/s: SMRT AUTOMOTIVE SERVICES PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 on 19/11/2019.

Enclosed herewith a copy of TP GIA report and estimated cost of repair.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/11/2019 10:40
Date Of Accident	13/11/2019 18:10
Exact Location Of Accident	BRAS BASAH RD JUNCTION WITH VICTORIA ST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB5893S
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	MAN
Model	MAN A95
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093203MFBP
Cover Note Number	

Driver

Name of Driver	PHUA HWEE ENG
NRIC No	S1549513H
Date Of Birth	04/05/1962
Occupation	OUTDOOR
Date Of Driving Pass	17/08/1983
Driving Experience	36 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	NO ADDRESS
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

While my bus SMB5893S was travelling at left most lane along Bras Basah Road traffic junction with Victoria St, suddenly i heard a loud thud sound. I made a quick check at the right view mirror and saw a private car (SLM5482Z) front left bumper had hit the right rear portion of my bus. There were 3 pax onboard my bus and no injury reported. After exchange particulars with third i continue revenue service. That's all.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING DOWNLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM5482Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PANG KYLE LOONG KENDRICK
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

SKETCH PLAN

541B 5843 S
PAGE 3
6/6/11/17/1033

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the Insurers to the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may have permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature _____ Date & Time: _____

 Driver's Signature _____ (If driver is not the policyholder)
 Date & Time: _____

 Reporting Centre/Adjuster's Signature _____
 Name: _____
 NRIC/PIN No.: _____


Sketch Plan Pg. 2

Hotel
SKETCH PLAN

在多利亞街
NO. 5

July 10
2017
06:00pm
68866

76 SWB 5893



Bus Busch Rd junction with Victoria St

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A large rectangular area with horizontal lines for text entry, currently blank.

DECLARATION: I/We declare that the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NIC/PIN No.:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/11/2019

User ID : BoonChewTay

Section A - Accident Details	
Registration Number	SMB5893S
Case Reference Number	BUS/11/19/1033
Registration Date	11/11/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	PHUA HWEE ENG
Type of Accident	Side Swipe
Accident Date and Time	13/11/2019 6:12 PM
Accident Reported Date and Time	13/11/2019 8:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB5893S-RIGHT REAR PORTION SLM548ZZ (TP) INSURED WITH MSIG
Prepared Date and Time	19/11/2019 9:59 AM
Chassis Number	WMAA95ZZ8G7003046
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$1,048.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$1,920.00	\$0.00
TOTAL COST	\$4,293.00	\$0.00
Lump Sum Total	\$4,300.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	19/11/2019 10:06 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/11/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works									
Job Scope	Quotation from ARC					Adjusted by Surveyor, if applicable			
TO REPAIR REAR RHS PORTION	\$1,325.00					1060			
Total Labour	\$1,325.00								
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope	Quotation from ARC					Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,048.00					878.			
Total Spray Painting & Panel Beating	\$1,048.00								
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope	Quotation from ARC					Adjusted by Surveyor, if applicable			
ADVERTISEMENT STICKER	\$1,920.00					XSVC			
Total Other Costs	\$1,920.00								
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair days - 3 days.

P/P Repair.

After spray photo.

Sun Pm (LKK)

19/11/2019.

TP without prejudice.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

42019



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/11/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB5893S
Case Reference Number	BUS/11/19/1033
Registration Date	11/11/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	PHUA HWEE ENG
Type of Accident	Side Swipe
Accident Date and Time	13/11/2019 6:12 PM
Accident Reported Date and Time	13/11/2019 8:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104422
Special Instruction to ARC, if any	SMB5893S-RIGHT REAR PORTION SLM5482Z (TP) INSURED WITH MSIG
Prepared Date and Time	19/11/2019 9:59 AM
Chassis Number	WMAA95ZZ8G7003046
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$1,060.00
Total Spray Cost	\$1,048.00	\$878.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$1,920.00	\$0.00
TOTAL COST	\$4,293.00	\$1,938.00
Lump Sum Total	\$4,300.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	19/11/2019 10:06 AM	19/11/2019 12:56 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/11/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REPAIR REAR RHS PORTION		\$1,325.00				\$1,060.00			
Total Labour		\$1,325.00				\$1,060.00			
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$1,048.00				\$878.00			
Total Spray Painting & Panel Beating		\$1,048.00				\$878.00			
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
ADVERTISEMENT STICKER		\$1,920.00				\$0.00			
Total Other Costs		\$1,920.00				\$0.00			
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

P/P

$$\begin{array}{r}
 1060 \\
 + 878 \\
 \hline
 1938
 \end{array}$$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Nov 2019		20 Nov 2019 17:15 Edit Adj Rpt	S\$1,938.00 Edit Estimates	S\$1,938.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	SMRT BUSES LTD, Co. Reg. No.: 198202292D		
Vehicle Reg. No.:	SMB5893S	Date of Loss:	13/11/2019 18:00 - :59 [48 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 611525	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLM5482Z	Policy No. (Claimant):	
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Imm.Advice due 21/11/2019]		
Driver/Customer (Insured):	PANG KYLE LOONG KENDRICK (), NRIC: S8032289E, Tel: +6592966905 Email:		
Adj Asg. Remarks:	OI:Grab. Liab: unclear. Direct Survey by LKK Auto Consultants on 19/11/2019.		
ASSOCIATED MAIL RECEIVED			
		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS			
		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
Subject	Handler	Assigned By	Completed On
Created On	Done?		
No results.			

Claim Documents

*SMB5893S (611525)
[SLM5482Z]
TP
SMRT BUSES LTD
Nov 13 2019 6:00PM
[GRAB RENTALS PTE LTD]
SMRT Automotive Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser <input type="button" value="v"/>		
Photos/Images							3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print	
1	25/11/19 08:59	Chassis Number				Load JPG	<input checked="" type="checkbox"/>	
2	25/11/19 08:59	Odometer Reading				Load JPG	<input checked="" type="checkbox"/>	
3	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
4	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
5	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
6	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
7	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
8	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
9	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
10	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
11	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
12	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
13	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
14	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
15	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
16	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
17	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
18	25/11/19 08:59	General View				Load JPG	<input checked="" type="checkbox"/>	
19	25/11/19 18:34	Before Repair Photo				Load JPG	<input checked="" type="checkbox"/>	
20	25/11/19 18:34	Before Repair Photo				Load JPG	<input checked="" type="checkbox"/>	
21	25/11/19 18:34	Before Repair Photo				Load JPG	<input checked="" type="checkbox"/>	
22	25/11/19 18:34	Before Repair Photo				Load JPG	<input checked="" type="checkbox"/>	
23	25/11/19 18:34	Before Repair Photo				Load JPG	<input checked="" type="checkbox"/>	
24	25/11/19 18:34	Before Repair Photo				Load JPG	<input checked="" type="checkbox"/>	
25	25/11/19 18:34	Before Repair Photo				Load JPG	<input checked="" type="checkbox"/>	
26	25/11/19 18:34	Before Repair Photo				Load JPG	<input checked="" type="checkbox"/>	
27	25/11/19 18:35	Photo After Spray				Load JPG	<input checked="" type="checkbox"/>	
28	25/11/19 18:35	Photo After Spray				Load JPG	<input checked="" type="checkbox"/>	
29	25/11/19 18:35	Photo After Spray				Load JPG	<input checked="" type="checkbox"/>	
30	25/11/19 18:35	Photo After Spray				Load JPG	<input checked="" type="checkbox"/>	
Documentation							1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print	
1	20/11/19 17:07	ESTIMATE REPAIR				Load PDF		
2	20/11/19 17:07	TP GIA				Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST		<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19020539/QSD3E2

Date: 27/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant	Insured Vehicle No :	SLM5482Z
Vehicle No : SMB5893S	Nature of Claim:	TP
Date of Loss: 13/11/2019	Claim No:	611525

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB5893S	
Make & Model:	MAN A95, 10.5 D (A)	Engine No: 50342170624215
Reg. Date:	11/11/2015 (Man. Year: 2015)	Chassis No: WMAA95ZZ8G7003046
Colour:	Multi-colour	Odometer: 258987 km
Engine Capacity:	10518 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,920.00	0.00	1,920.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,373.00	1,938.00	435.00	18.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,293.00	1,938.00	2,355.00	54.86

INSPECTION

Date of Assignment:	20/11/2019	
Date Inspected:	19/11/2019 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: OI SUN PIN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Nov 2019)	
Parts:	N/A	MAN A95 10.5 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMB5893S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*ADVERTISEMENT STICKER	Serviceable	1,920.00 F	*- F	
					Total Parts (S\$)	1,920.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR REAR RHS PORTION	New	1,325.00	1,060.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	1,048.00	878.00
Gross Labour Cost (\$\$)			2,373.00	1,938.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >