

ASS. REC. BY:

REF: esl 8MO19020586/1Kvd309 Special Instruction:

Survey: Kenneth

ASSIGNMENT (Office)

From (Person): Yang Lang Melvin of SMO Date/Time: 2011/11/19 @ 9:44am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SAR 5098H Insured: GN 16Z

at Workshop m/s RC Auto Tel: 9761 9383

of 160 Sin Ming Drive #06-20

Policy No: Claim No: CMTD1905390/1JH

Sum Insured: Excess:

Make of Veh: D.O.A. 16/11/19
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:50am @ 20/11/19 Person Contacted: Mr. Tan Vehicle: IN/OUT

Date/Time	Action/Instruction	Follow up
	SAR 5098H - NA / LIP 1901/2009/24	20/11/2019
	GN 16Z - NA / INCL 19008566/24	20/11/2019
21/11/19	Informed Melvin pending workshop est by email	
28/11/19	Email preli revised to melvin	

ASS. REC. BY:

REF:

SAG

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 819k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 2/22 Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

1 File pass to
Est not ready

28/11 11:20 @ 565d Confirm (Ref 5648-93, 479)

RECEIVED 28 NOV 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 7

Resurvey No. of Trlp: 2

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

5650/2

340

340

Veh No:

SGR 5098H

Yr Regn:

02, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Wish

cc

1794

Colour:

M. Gray

A/C: Insured / Std / NI / NA

Sp. Reading:

247760

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ENE10 0353807

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / SRM / STD A/Rim or

Tyre Size:

F: Continental

R: B.S 215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 3 mm

L/Bal. 5 mm

L/Bal. 3 mm

D.O.A. 16/11/19

D.O.I. 20/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 28 November 2019 11:43 AM
To: 'Ye, Yong Kang Melvin'
Cc: 'Henry, Irene James'; SUR
Subject: RE: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca Our ref : CMTD1905390/IJH
Attachments: SGR 5098H PRELI ADVISED.pdf

Dear Melvin,

Enclosed preliminary revised of vehicle SGR 5098H
Date of survey: 20/11/2019
Number of days (estimated) : 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 21 November 2019 10:36 AM
To: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>
Cc: 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca Our ref : CMTD1905390/IJH

Dear Melvin,

Please be informed that we have inspected the vehicle SGR 5098H on 20/11/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 20 November 2019 10:55 AM
To: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca Our ref : CMTD1905390/UH

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]

Sent: Wednesday, 20 November 2019 9:44 AM

To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Henry, Irene James <irene.henry@sompo.com.sg>

Subject: FW: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca
Our ref : CMTD1905390/UH

Hi LKK,

Please make arrangement to conduct survey for SGR5098H.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Candice Lee <accident@kscgp.com>
Sent: Tuesday, 19 November, 2019 5:05 PM
To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Cc: jiapai@kscgp.com; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: RE: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca Our ref : CMTD1905390/IJH

Dear Melvin,

We refer to the above matter.

We enclose herein the 2nd Notice to Conduct Pre-repair inspection for your necessary action. Our client is agreeable to appointing LKK Auto Consultants Pte Ltd as the Single Joint Expert.

Thank you!

Regards,
Candice
For and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]
Sent: Tuesday, 19 November, 2019 4:17 PM
To: Candice Lee
Cc: jiapai@kscgp.com; Henry, Irene James
Subject: RE: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca Our ref : CMTD1905390/IJH

Our Reference : CMTD1905390/IJH
Your Reference: SGR 5098H/RCA/jp/ca

Without Prejudice

Date: 19/11/2019

Attention:
KSCGP JURIS LLP

Dear Candice,

ACCIDENT INVOLVING GN16Z & SGR5098H ON 16.11.2019

We refer to your Notice of Accident dated 19/11/2019.

Please be informed that Ms Irene is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

or

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Candice Lee <accident@kscgp.com>

Sent: Tuesday, 19 November, 2019 9:56 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: jiapei@kscgp.com

Subject: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca

Dear Sirs,

We refer to the above matter.

We enclose herein the notice to conduct pre-repair inspection for your necessary action.

Thank you.

Regards,

Candice

For and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This email has been scanned by the MxScan Email Security System.

This email has been scanned by the MxScan Email Security System.

This email has been scanned by the MxScan Email Security System.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: CMTD1905390/IJH

Our ref: CS/SMO19020586/Kvd3

DATE: 28/11/2019

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SGR 5098H


We thank you for your instruction on 20/11/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/11/2019 at the premises of M/s RC AUTO and have the following to report:-

Workshop Estimate Amount	: S\$10,698.93
Revised Estimate Amount	: S\$5,650.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear and front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 21 November 2019 10:36 AM
To: 'Ye, Yong Kang Melvin'
Cc: 'Henry, Irene James'; SUR
Subject: RE: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca Our ref : CMTD1905390/IJH

Dear Melvin,

Please be informed that we have inspected the vehicle SGR 5098H on 20/11/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 20 November 2019 10:55 AM
To: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca Our ref : CMTD1905390/IJH

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]
Sent: Wednesday, 20 November 2019 9:44 AM
To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Henry, Irene James <irene.henry@sompo.com.sg>

- Subject: FW: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca
- Our ref : CMTD1905390/IJH

Hi LKK,

Please make arrangement to conduct survey for SGR5098H.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Candice Lee <accident@kscgp.com>

Sent: Tuesday, 19 November, 2019 5:05 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: jiapei@kscgp.com; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: RE: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca Our ref : CMTD1905390/IJH

Dear Melvin,

We refer to the above matter.

We enclose herein the 2nd Notice to Conduct Pre-repair inspection for your necessary action. Our client is agreeable to appointing LKK Auto Consultants Pte Ltd as the Single Joint Expert.

Thank you!

Regards,

Candice

For and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]

Sent: Tuesday, 19 November, 2019 4:17 PM

To: Candice Lee

Cc: jiapai@kscgp.com; Henry, Irene James

Subject: RE: Notice to Conduct Pre-repair inspection - Your Insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca
Our ref : CMTD1905390/IJH

Our Reference : CMTD1905390/IJH

Your Reference: SGR 5098H/RCA/jp/ca

Without Prejudice

Date: 19/11/2019

Attention:
KSCGP JURIS LLP

Dear Candice,

ACCIDENT INVOLVING GN16Z & SGR5098H ON 16.11.2019

We refer to your Notice of Accident dated 19/11/2019.

Please be informed that Ms Irene is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	

		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

or

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Candice Lee <accident@kscgp.com>

Sent: Tuesday, 19 November, 2019 9:56 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: jiapei@kscgp.com

Subject: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca

Dear Sirs,

We refer to the above matter.

We enclose herein the notice to conduct pre-repair inspection for your necessary action.

Thank you.

Regards,
Candice

For and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This email has been scanned by the MxScan Email Security System.

This email has been scanned by the MxScan Email Security System.

This email has been scanned by the MxScan Email Security System.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Wednesday, 20 November 2019 9:44 AM
To: SUR; assignments
Cc: Henry, Irene James
Subject: FW: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca Our ref : CMTD1905390/IJH
Attachments: 2nd PRS.pdf

Hi LKK,

Please make arrangement to conduct survey for SGR5098H.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Candice Lee <accident@kscgp.com>
Sent: Tuesday, 19 November, 2019 5:05 PM
To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Cc: jiapei@kscgp.com; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: RE: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca Our ref : CMTD1905390/IJH

Dear Melvin,

We refer to the above matter.

We enclose herein the 2nd Notice to Conduct Pre-repair inspection for your necessary action. Our client is agreeable to appointing LKK Auto Consultants Pte Ltd as the Single Joint Expert.

Thank you!

Regards,

Candice

For and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]

Sent: Tuesday, 19 November, 2019 4:17 PM

To: Candice Lee

Cc: jiapai@kscgp.com; Henry, Irene James

Subject: RE: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca

Our ref : CMTD1905390/IJH

Our Reference : CMTD1905390/IJH

Your Reference: SGR 5098H/RCA/jp/ca

Without Prejudice

Date: 19/11/2019

Attention:

KSCGP JURIS LLP

Dear Candice,

ACCIDENT INVOLVING GN16Z & SGR5098H ON 16.11.2019

We refer to your Notice of Accident dated 19/11/2019.

Please be informed that Ms Irene is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

or

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Candice Lee <accident@kscgp.com>

Sent: Tuesday, 19 November, 2019 9:56 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: jjapei@kscgp.com

Subject: Notice to Conduct Pre-repair inspection - Your insured veh: GN 16Z - Our ref: SGR 5098H/RCA/jp/ca

Dear Sirs,

We refer to the above matter.

We enclose herein the notice to conduct pre-repair inspection for your necessary action.

Thank you.

Regards,

Candice

For and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This email has been scanned by the MxScan Email Security System.

This email has been scanned by the MxScan Email Security System.

This email has been scanned by the MxScan Email Security System.

Your Ref : CMTD1905390/IJH
Our Ref : **SGR 5098H/RCA/jp/ca**
Date : 19 November 2019

Fax : **6538 3708**
Tel : **3152 0979**
Email : **accident@kscgp.com**

Sompo Insurance Singapore Pte Ltd

BY EMAIL ONLY

DATE OF ACCIDENT: 16 NOVEMBER 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that our client is agreeable to appointing LKK Auto Consultants Pte Ltd as a Single Joint Expert.

The said vehicle can be surveyed / inspected at:

Address : RC Auto
160 Sin Ming Drive
#06-20 Sin Ming Autocare
Singapore 575722

Contact Person/Tel : Mr Tan Chuan Kim / 9761 9383

Yours faithfully,

f CA

Your Ref : CMTD1905390/IJH
Our Ref : SGR 5098H/RCA/jp/ca
Date : 19 November 2019

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	357F
Vehicle Details	
Vehicle No.:	SGR5098H
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	1ZZ2836499
Chassis No.:	ZNE100353807
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$16,978.00
Original Registration Date:	09 Feb 2007
First Registration Date:	09 Feb 2007
Transfer Count:	2
Actual ARF Paid:	\$14,788.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Feb 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$26,039.00
COE Rebate Amount:	\$11,547.00
Total Rebate Amount:	\$11,547.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/11/2019 15:20
Date Of Accident	16/11/2019 18:45
Exact Location Of Accident	MAIN ROAD ALONG JALAN EUNOS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGR5098H
Insured/Policyholder	
Name Of Registered Owner	LIM HEE SANG VIVIAN
NRIC No	S0186357F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91459146
Alternative Phone No	OFFICE-91459146
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108356177
Cover Note Number	
Driver	
Name of Driver	URBAN WO TZUU KEI
NRIC No	S7334676B
Date Of Birth	26/09/1973
Occupation	OUTDOOR
Date Of Driving Pass	09/02/2001
Driving Experience	18 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91459146
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 643 HOUGANG AVENUE 8 #10-283 SINGAPORE
Postcode	530643
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT AND ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GN16Z
Vehicle Make/Model/Colour	
Details Of Properties	REFER POLICE REPORT AND ATTACHED
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TEE JIN HUI
NRIC/Passport Number	S9504258i

Contact Number 83225717
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKH9523B
Vehicle Make/Model/Colour
Details Of Properties REFER POLICE REPORT AND ATTACHED
Vehicle Category PRIVATE CAR
Name of Driver LIM LING CHON
NRIC/Passport Number S7237738I
Contact Number 96602828
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name URBAN WO TZUU KEI
Approximate Age
Injuries Sustain REFER POLICE REPORT AND ATTACHED
Injured person in which vehicle? SGR5098H
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 2nd day of the accident, the car in front of SKH 9523B suddenly jam brake ~~to~~ SKH 9523B also jam brake. I also jam my brakes but GN162 could not brake in time and jam into my back forcing my car to surge forward and graze the BMW in front of me. The following day on Sunday, my whole body was aching esp my chest area so I consulted a doctor and seek treatment.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ESTIMATE RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel: 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168X

SGR 5098H

Not Authorized

Date:

22/11/2019

61 Lm @ 5650p

Turning After Paint

7 days

Quantity	Description/Particular	Unit Price	Amount
1 PC	FRONT BUMPER 481.90		Bur 1111 35 ✓
1 PC	BUMPER BUMPER GRILLE		CM 110 22 ✓
2 PCS	FRONT BUMPER LOWER BRACKET@135		R 270 00 X
1 PC	FRONT BONNET		Bur 528 94 ✓
2 PCS	FRONT BUMPER SIDE RETAINER@45.28	dis 1	92 56 ✓
2 PCS	HEADLAMP ASSY@693	mg cm	1386 00 ✓
	TAILGATE	Bur	1062 70 ✓
	TAILGATE CHROME MOULDING	SL	313 85 X
	TAILGATE EMBLEM	mc	52 70 X
	TAILGATE LOCK	net	509 10 ✓
	TAILGATE WEATHERSTRIP 135.275m	mi 1/1	270 54 50%
	TAILGATE INNER TRIM BOARD	Sm	302 00 X
	REAR WINDSCREEN MOULDING	mc	72 90 ✓
	REAR WINDSCREEN SIDE MOULDING	mc	214 50 ✓
	REAR END PANEL	Bur	405 87 ✓
	REAR END PANEL GANISH	net	201 60 ✓
	REAR LAMP (L/H)	CM	430 00 ✓
	Front Bonnet Chrome	net	296 50 ✓
	Rec Bumper	Bur	497 60 ✓
			258

Received the above goods in good order and condition

for RC AUTO
RC AUTO

160, Sin Ming Drive
#06-20 Sin Ming AutoCity
Singapore 575722

HP: 9761 9383

Email: rcauto5555@gmail.com

Received by

E.&O.E.

Authorised Signature

ESTIMATE RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168X

SGR 5098 H

Date: 22/11/2019

[illegible]

Received the above goods in good order and condition

for RC AUTO

HE AUTO

160, Sin Ming Drive
#06-20 Sin Ming AutoCity
Singapore 575722

Received by

E.O.E.

Authorized Signature _____
 Email: TC.Gallos@3M.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19020586/Kvd3e2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 29-11-2019		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GN 16Z	Veh. Inspected	SGR 5098H	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1905390/IJH	Excess (\$)	0.00	
Assign From	YONG KANG MELVIN	Assign Date	20/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	ZNE100353807	Colour	METALLIC GREY	
Odometer	247760	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	CONTINENTAL	5 mm	
L/H Front Tyre	215/45 R17	CONTINENTAL	5 mm	
R/H Rear Tyre	215/45 R17	BRIDGESTONE	5 mm	
L/H Rear Tyre	215/45 R17	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2019	Inspection Date	20/11/2019	
Survey held at	160 SIN MING DRIVE #06-20			
Repairer	R C AUTO			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 5098H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BUCKLED	1,111.35	481.90
1	FRONT BUMPER GRILLE	CRACKED	110.22	110.22
2	FRONT BUMPER LOWER BRACKET @\$135.00	TO REPAIR SEE LABOUR	270.00	-
1	FRONT BONNET	BUCKLED	528.94	528.94
2	FRONT BUMPER SIDE RETAINER @\$46.28	O/S DISTORTED	92.56	46.28
2	HEADLAMP ASSY @\$693.00	MTG CRACKED	1,386.00	1,386.00
1	TAILGATE	BENT	1,062.70	1,062.70
1	TAILGATE CHROME MOULDING	SERVICEABLE	313.85	-
1	TAILGATE EMBLEM	NECESSARY	52.70	52.70
1	TAILGATE LOCK	DENTED	509.10	509.10
1	TAILGATE INNER TRIM BOARD	SERVICEABLE	302.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	72.90	72.90
1	REAR WINDSCREEN SIDE MOULDING	NECESSARY	214.50	214.50
1	REAR END PANEL	BENT	405.87	405.87
1	REAR END PANEL GARNISH	DENTED	201.60	201.60
1	REAR LAMP (L/H)	CRACKED	430.00	430.00
1	FRONT BONNET CHROME	DENTED	296.50	296.50
1	REAR BUMPER	BENT	497.60	497.60
	LESS 25% DISCOUNT		-	-1,574.20
			7,858.39	4,722.61
SPECIAL NETT ITEMS				
1	TAILGATE WEATHERSTRIP (50%)(SN)	DISTORTED / DENTED	270.54	135.27
1	NUMBER PLATES AND HOLDER (SN)	DENTED	50.00	45.00
			320.54	180.27
LABOUR				
	TOWING FEES.		60.00	50.00
	LABOUR CHARGES FOR ABOVE JOB.INCLUSIVE OF THE REPAIR OF FRONT BUMPER LOWER BRACKET.		1,200.00	1,000.00
	TO RESPRAY FRONT AND REAR.		1,000.00	900.00

Report Ref No. CS/SMO19020586/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REINSTATE WINDSCREEN.		120.00	120.00
	TO PERFORM ANTI RUST.		100.00	90.00
	TO CHECK WIRING WORKS.		40.00	40.00
			2,520.00	2,200.00
GRAND TOTAL			10,698.93	7,102.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,650.00

Report Ref No. CS/SMO19020586/Kvd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.