

ASS. REC. BY:

REF:

093/III 19020589/Hcd306

Special Instruction:

Summary: Hock Ann

## ASSIGNMENT (Office)

From (Person):

NUMBER

Cubriel wee

of

TH

Date/Time:

19/11/19 @ 4:04pm

Estimated Cost:

Bill to:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

FBN 69265

Insured:

SHA 2933U

at Workshop m/s

ONG MOTOR

Tel:

9388 1791

of

NO. 464 Macpherson Road

Policy No.:

Claim No.:

Sum Insured:

Excess:

Make of Vehi:

(Client's Record)

D.O.A.

13/05/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:15am @ 20/11/19

Person Contacted:

Mr Ong

Vehicle IN/OUT

Date/Time	Action/Instruction	
	FBN 69265 - NA / INC 19008529/r3	D.O.A: 13/5/2019
	SHA 2933U - NA / INC 19008529/r3	D.O.A: 13/5/2019
	Disassemble: 9/12/2019 01:44pm	

REF: H-ANW

REF: III

### ASSIGNMENT

From: **PRS** Date: **20/11/19**

Estimated Cost: \_\_\_\_\_

OD: **TP/WS** / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **FBN 69265**

at Workshop m/s: **Org Motor**

of: **464 Macpherson Road**

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: **Mr. Org @ 9388 1791**

Veh No: **FBN 69265** Yr Regn: **23/11/2018**

Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: **VESPA GTS** c.c. **155**

Colour: **Black** A/C: **Insured / Std / NI / NA**

Sp. Reading: **Non check sheet** T/Radio: **Insured / Std / NI / NA**

Eng/No: \_\_\_\_\_

C/No: **ZAPMA320000001549**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: **Inorder** / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: **Nil** / S/Rim / STD A/Rim or \_\_\_\_\_


Tyre Size: F: **120/70/R12**

R: **130/70/R12**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum. Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **hup**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Front **5** mic R/Bal. **5** mic

Rear **5** mic R/Bal. **5** mic

L/Bal. mm L/Bal. mm

D.O.A. **13/5/19** D.O.I. **20/11/19**

Survey held at **0221PM**

Des. of Damages: **Frnt** / **Rear** / **O/S** / **N/S** / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>Range → parking survey cost</i>
	<i>repr hrs → 4</i>
	<i>* FBN 69265</i>
	<i>PRS case</i>
	<i>MV - 8800</i>
	<i>PV - 2692</i>
	<i>NV - 6100</i>

Date/Time, File Pass to?  : Prel. Report

1)  : Final Report

Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: **1**

Report Format: **PRC**

Lump Sum / U/C: \_\_\_\_\_

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Inv (\$)

: Weekend (\$)

Survey Fee:	<b>120</b>
Transportation:	_____
Photos:	_____
Other:	<b>11</b>
TOTAL:	<b>131</b>

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	(Not Notified) <a href="#">Edit Reg</a>		20 Nov 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]
Insured:				
Main Claimant:	<b>RASHINAH BINTE ABDUL RASHID, ID: S7629947A</b>			
Vehicle Reg. No.:	<b>FBN6926S</b>	Date of Loss:	13/05/2019 00:00 - :59	
Claim Type:	<b>TP</b>	Policy/Cover Note No.:		
Vehicle Reg. No. (Insured):	<b>SHA2933U</b>	Policy No. (Claimant):		
		Excess:		
Repairer:	<b>Ong Motor Trading (MACPHERSON RD) No. 464 Macpherson Road, 368182 Macpherson - Tel:</b>			
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]</b>			
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 29/11/2019]</b>			

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS	<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 19 November 2019 4:04 PM  
**To:** alfred\_ng@juseq.com.sg; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Sundari Nagarajan - III  
**Subject:** RE: ACCIDENT INVOLVING FBN6926S AND SHA2933U ON 13 MAY 2019.  
**Attachments:** PRI-FBN6926S.PDF

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : FBN6926S  
III INSURED VEHICLE NO. : SHA2933U  
DATE OF LOSS : 13.05.19

We acknowledge receipt of your email.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sundari**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

**\*\*Surveyor kindly upload this assignment to Merimen.**

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

---

**From:** alfred\_ng@juseq.com.sg [mailto:alfred\_ng@juseq.com.sg]  
**Sent:** 19 November, 2019 3:03 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** ACCIDENT INVOLVING FBN6926S AND SHA2933U ON 13 MAY 2019.

Your ref: SHA2933U  
Our ref: JEQ/191196/1119/OMT

Dear Gabriel,

We refer to your email dated today.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1. Absolute Appraisal Services Pte Ltd;
2. Sincere Appraisal Services;
3. Mc Coy Appraiser Pte Ltd;
4. Delta V Consultant;
5. Prominent Appraiser Pte Ltd;
6. Advance Automotive Consultancy Pte Ltd;
7. Pal's Appraiser Pte Ltd;
8. S K Auto Consultants;
9. Oh Appraisal Services;
10. KAAS.

Please be informed that if the above mentioned surveyors is not agreeable by you, our clients' motor vehicle is available for pre-repair inspection at the under-stated workshop:-

Ong Motor Trading  
464 Macpherson Road  
Singapore 368182  
Tel: 6743-0629 Mobile: 9388-1791  
Fax: 6743-2053

With Regards

Alfred Ng  
Executive  
Legal Division  
On behalf of Mr. Michael Yap  
M/s JusEquity Law Corporation  
No. 133 New Bridge Road  
Chinatown Point  
#10-03 Singapore 059413  
Tel : 6536 9339  
Fax: 6536 5368

**IMPORTANT NOTICE:**

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



# JusEquity Law Corporation

**ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS**

133 New Bridge Road #10-03 Chinatown Point Singapore 059413  
Telephone (65) 6536 9339, Fax : (65) 6536 5368 (Litigation)  
Email : [claims@juseq.com.sg](mailto:claims@juseq.com.sg) Website: [www.juseq.com.sg](http://www.juseq.com.sg)

Our Ref: JEQ/191196/1119/OMT  
Your Ref: SHA2933U

19 November 2019.

INDIA INTERNATIONAL INSURANCE PTE LTD  
(Claims Department)  
64 Cecil Street  
#04/05, IOB Building  
Singapore 049711

VIA FAX  
(Fax No. 6224-4174)

Dear Sir

**ACCIDENT INVOLVING FBN6926S AND SHA2933U ON 13.05.2019**

We act for the owner of vehicle no. FBN6926S.

We hereby notify you of a road traffic accident on 13/05/2019 at about 1330hours at 441A Pasir Ris Dr 6 MSCP involving our client's vehicle and vehicle registration no. SHA2933U driven by your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Cc COMFORT TRANSPORTATION PTE LTD  
383 Sin Ming Drive  
GAS Building  
Singapore 575717  
(Your Ref: SHA2933U)

**CONFIDENTIALITY CAUTION**

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	947A
Vehicle Details	
Vehicle No.:	FBN6926S
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Nov 2019
Vehicle Make:	PIAGGIO
Vehicle Model:	VESPA GTS 150 ABS
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	MA32M5001539
Chassis No.:	ZAPMA320000001549
Maximum Power Output:	-
Open Market Value:	\$4,307.00
Original Registration Date:	23 Nov 2018
First Registration Date:	23 Nov 2018
Transfer Count:	1
Actual ARF Paid:	\$647.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Nov 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,989.00
COE Rebate Amount:	\$2,692.00
<b>Total Rebate Amount:</b>	<b>\$2,692.00</b>

The information contained herein is correct as at 21 Nov 2019

OK

Advertisement

Home > Motorbikes > Motorbikes for Sale > Class 2B



BIKE RODUCTIVE bikeprod No reviews

Chat

Make Offer

Advertis

\$8,800

Share 14

VESPA GTS 150

610 Serangoon Road

Mailing · Meetup

Used

DOWNPAYMENT \$800 B4 INSURANCE

REG: SEPT 2017

COE EXP: SEPT 2027

2 weeks ago In Class 2B

Vespa

Scooter

mv-8800  
pv-2672  
NV-6100

Advertisement

Insurance

Meet-up

610 Serangoon Road

Shipping

Listed by bikeprod

Very Responsive



Check seller profile

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/05/2019 15:46
Date Of Accident	13/05/2019 13:30
Exact Location Of Accident	BLK 441A PASIR RIS DRIVE 6 MSCP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN6926S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	RASHINAH BINTE ABDUL RASHID
NRIC No	S7629947A
Email Address	MRSNORMAN2721@YAHOO.COM
Mobile Phone No	(LOCAL) +65-81618553
Alternative Phone No	OTHERS-81618553

### Vehicle Particulars

Manufacturer	VESPA
Model	GTS150
Exact Purpose for which vehicle was being used at time of accident	PARKED VEH
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5105800481
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD NORMAN BIN KAMARUDIN
NRIC No	S7540458A
Date Of Birth	27/03/1975
Occupation	INDOOR
Date Of Driving Pass	15/03/2012
Driving Experience	7 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87001909
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 480 SEMBAWANG DRIVE #02-461
Postcode	750480
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA2933U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	MR PEH
NRIC/Passport Number	
Contact Number	97860206
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	UNKNOWN
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Accident Sketch Plan

### SKETCH PLAN

#### **IMPORTANT NOTICE**


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time: 10/05/19

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Individual Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My bike was parked at the MCCP of BLK 414A PASIR RIS DRIVE 6 AND THE ACCIDENT HAPPENED @ 12:30PM, THE MOB CYCLER WAS TRYING TO CALLED ME AT THE POINT OF TIME AND I WAS BUSY, I HAVE ANSWERED THE CALL @ 12:40PM AND WAS TOLD ABOUT THE ACCIDENT. MANAGED TO SPEAK WITH THE DRIVER INVOLVED ON THE PHONE AND HE HAD TOLD ME THAT AS HE DROVE UP THE SLOPE HE HAD LOST CONTROL AND HAD HIT 2 MOTORBIKE THAT WAS STATIONARY AT THE PARKING LOT AND MY BIKE WAS BADLY DAMAGED.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*Amal*  
 Policyholder's Signature  
 Date & Time: 14/05/19

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

*[Signature]* 14/05/19  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Other

CONFIDENTIAL

ANNEX E

NOTICE OF REPORTING

This is to confirm that Muhammad Norman Bin Kamarudin NRIC / FIN S7540458A has reported to the Police a non injury traffic accident which occurred along Blk 441A Pasir Ris Drive 6 MSCP, on 13/05/2019 at 0130hrs involving the following vehicles:

- A) FBN6926S – Black (Vespa GTS150)
- B) SHA2933U – Taxi (Comfort Delgro)

2 If this accident was reported to the Police within 24 hours of its occurrence then he/she has complied with Sec 84 (2) of the Road Traffic Act, Cap 276

Rank / Name of Issuing Officer: Sgt T160276 Jovson Ng  
Date: 13/05/2019 Time: 2133hrs  
S/D Ref No: 136  
Police Post / Unit: Pasir Ris NPC



Original to be issued to complainant  
Duplicate to be submitted to Traffic Police

CONFIDENTIAL

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Dec 2019 09:05 <a href="#">Edit Reg</a>		19 Nov 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by adjuster]</a></span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>RASHINAH BINTE ABDUL RASHID</b> , ID: S7629947A								
Vehicle Reg. No.:	<b>FBN6926S</b>	Date of Loss:	13/05/2019 00:00 - :59 <b>[5 Months and 20 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>SHA2933U</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Ong Motor Trading (MACPHERSON RD)</b> No. 464 Macpherson Road, 368182 Macpherson - Tel:								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Sundari Nagarajan</b> - 6347 6071]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>LEE HOCK ANN</b> ] ... <b>[Final Rpt due 29/11/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>	<a href="#">Compose Case Mail</a>				
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*FBN6926S  
[SHA2933U]  
TP  
RASHINAH BINTE ABDUL RASHID  
May 13 2019 12:00AM  
[-]  
Ong Motor Trading

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View <input type="button" value="View in Browser"/>
<b>Photos/Images</b>			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	21/11/19 10:49	<b>Odometer Reading</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
2	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
3	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
4	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
5	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
6	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
7	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
8	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
9	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
10	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
11	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
12	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
13	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
14	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
15	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
16	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
17	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
18	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
19	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
20	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
21	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
22	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
23	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
24	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
25	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
26	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
27	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
28	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
29	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
30	21/11/19 10:49	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
31	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
32	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
33	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
34	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
35	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
36	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
37	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
38	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
39	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
40	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
41	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
42	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
43	21/11/19 10:50	<b>General View</b>	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
48	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
49	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
50	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
51	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
52	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
53	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
54	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
55	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
56	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
57	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
58	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
59	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
60	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
61	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
62	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
63	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
64	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
65	21/11/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
66	10/12/19 10:30	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
67	10/12/19 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	10/12/19 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	10/12/19 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	10/12/19 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	10/12/19 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	10/12/19 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	10/12/19 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	10/12/19 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	10/12/19 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	10/12/19 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	10/12/19 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	10/12/19 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	10/12/19 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	10/12/19 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
94	10/12/19 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
95	10/12/19 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
96	10/12/19 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
97	10/12/19 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
98	10/12/19 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
99	10/12/19 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
101	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
102	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
103	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
104	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
105	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
106	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
107	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
108	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
109	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
110	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
111	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
112	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
113	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
114	10/12/19 10:31	Reinspection Photo		<input checked="" type="checkbox"/>
115	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
116	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
117	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
118	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
119	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
120	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
121	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
122	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
123	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
124	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
125	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
126	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
127	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
128	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
129	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
130	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
131	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
132	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
133	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
134	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
135	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
136	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
137	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
138	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
139	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
140	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
141	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
142	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
143	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
144	10/12/19 10:32	Reinspection Photo		<input checked="" type="checkbox"/>
145	10/12/19 10:33	Reinspection Photo		<input checked="" type="checkbox"/>
146	10/12/19 10:33	Reinspection Photo		<input checked="" type="checkbox"/>
147	10/12/19 10:33	Reinspection Photo		<input checked="" type="checkbox"/>
148	10/12/19 10:33	Reinspection Photo		<input checked="" type="checkbox"/>
149	10/12/19 10:33	Reinspection Photo		<input checked="" type="checkbox"/>
150	10/12/19 10:33	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/11/19 17:20	EMAIL FROM III ON 19/11/2019 TO ARRANGE SURVEY		<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/11/19 08:52	Singapore Accident Statement		<input checked="" type="checkbox"/>

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Our File No: CS3/III19020589/HCD3E2

Date: 30/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant FBN6926S

Insured Vehicle No : SHA2933U

Vehicle No : FBN6926S

Date of Loss: 13/05/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBN6926S

Make &amp; Model: VESPA GS150, 150cc

Engine No: MA32M5001539

Reg. Date: 23/11/2018 (Man. Year: 2018)

Chassis No: ZAPMA320000001549

Colour: Black

Odometer: 0 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R12

Rear Tyre Size: 130/70 R12

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 19/11/2019

Date Inspected: 20/11/2019 Inspected At:

Ong Motor Trading (MACPHERSON RD)

No. 464 Macpherson Road  
Singapore 368182

Estimated Period of Repair: 0.0 days

**Adjuster:** LEE HOCK ANN**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 30 Dec 2019)	
<b>Parts:</b>	N/A	VESPA GS150 150cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBN6926S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >