

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/11/2019 15:25
Date Of Accident	18/11/2019 15:10
Exact Location Of Accident	OCEAN DRIVE ROUNDABOUT (SENTOSA)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY5948T
-----------------------------	---------

#### Insured/Policyholder

Name Of Registered Owner	CIVILLAND CONSTRUCTION & ENGRG PTE LTD
Co Reg No	1999000253C
Email Address	CIVILLAND@MSN.COM
Mobile Phone No	(LOCAL) +65-90270437
Alternative Phone No	OFFICE-90270437

#### Vehicle Particulars

Manufacturer	ISUZU
Model	NHR69E-3.1 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

#### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	
Cover Note Number	8VCT1838230

#### Driver

Name of Driver	KANDASAMY KARTHEEBAN
Passport No/FIN	G7285408Q
Date Of Birth	01/06/1970
Occupation	OUTDOOR
Date Of Driving Pass	04/10/2013
Driving Experience	6 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90270437
Fax Number	
Contact Number	OTHERS-90270437
Email Address	CIVILLAND@MSN.COM

Address	-
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : HOSSAIN SHAIKH JAKIR GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT MERAH WEST NPC
Police Station Address	<b>ROAD:</b> 500 BUKIT MERAH VIEW #01-01 , <b>POSTCODE:</b> 159682 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> - <b>FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH AND ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA6527H
Vehicle Make/Model/Colour	HYUNDAI I40
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	ABDUL GAFFOOR MALICK BATCHA
NRIC/Passport Number	S7073804Z
Contact Number	92382680
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



A) GY5948T  
B) SH465274

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER AMBULANCE

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

20/11/19

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

20/11/2019

Sketch Plan #3

Place: Sentosa Cove

Date & Time: 18/11/19 15:12

gy 52  
I parked my vehicle (lorry, YG5948T) at the road side of Sentosa North Cove roundabout near the guard house for unloading of cables and materials. When my lorry was parked at the road side, the hazard signal light was turned-on before I stop and alight from the lorry.

After unloading the materials, before moving off, I turned-off the hazard signal light and signaled left before moving off. When I was moving off, the taxi (SHA6527H) accelerated and overtook my lorry hence the taxi crashed into the front right of my lorry and I came to an immediate halt. As the result of the crash, front right door, front right headlight and front right bumper was damaged.

The taxi did not come to an immediate halt but continues to move forward before stopping in front of my lorry, thus the damage is on the whole left body and left side mirror of the taxi. The security of Sentosa Cove came right after the crash and requested both vehicles to move off.

Neither myself nor the taxi driver were injured in the accident. We have exchanged personal particulars and moved off. Later, I went to police station to file an accident report on 18/11/19, 1910 hrs at Bukit Merah West NPC.



*[Handwritten signature]*

*[Handwritten signature]*  
20/11/2019  
Resin Lian



NOTICE OF REPORTING

Annex D

This is to confirm that Kandasamy Kartheeban NRIC/FIN  
G7285408Q, has reported to the Police a non-injury traffic accident  
which

occurred at Sentosa Cove

on 18/11/2019 at 1512hrs involving the following vehicles:

YG5948T  
SHA6527H

2 If this accident was reported to the Police within 24 hours of its  
occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act,  
Cap 276.

Rank/Name of Issuing Officer: SGT(3) Razeenah

Date: 18/11/2019 Time: 1910hrs

S/D Ref: 34

Police Post/Unit : BUKIT MERAH WEST NPC

Original - to be issued to informant  
Duplicate - to be submitted to Traffic Police

Accident Photo





Accident Photo



Accident Photo



Accident Photo



A close-up photograph of the front left corner of a blue car. The car's body is a vibrant blue. The headlight assembly is heavily damaged, with the clear lens shattered and the internal components exposed. The orange turn signal lens is also cracked and partially broken. The blue bumper is cracked and deformed at the corner. To the left of the headlight, there is a black rectangular sticker with white text that reads: "COLLING CONSTRUCTION &amp; ENGINEERING PTE LTD", "TRADE NO. 21", "SINGAPORE", and "TEL: 6741 1111". A portion of a black tire is visible on the far left. The car is parked on a dark, wet surface.



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo





Accident Photo



Accident Photo





Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo

