

20190001

ASS. REC. BY:

REP: CS/SMT/9020604/KDS/02

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Yong Leng Melvin of SMO

Date/Time: 20/11/19 @ 9.48am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: EP 168G Insured: FBJ 5545K

at Workshop n/s: MBM wheelpower Tel: 9328 8668

of 160 Sn Ming Drive #06-02

Policy No: Claim No: CMTD1905394/THE

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 16/11/2019

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.30am 20/11/19 Person Contacted: Danny Vehicle: IN/OUT

Date/Time	Action/Instruction
	Estimated ✓ EP 168G - CC6/A14/11003236 / Unlg 292 FBJ 5545K ✓
11/12/19	Email preli revised to Sampo
16/12/19	@ 1230pm Danny said vehicle waiting for spare parts

ASS. REC. BY:

REF: JMO/

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s MBM

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Soon: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2-3 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: EP 1886 Yr Regn: 07.19

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A

Make: Mer E300 c.c. 1991

Colour: M-Black A/C: Insured / Std / NI / NA

Sp. Reading: 41.06 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDD 23834821-866618

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD VRim or

Tyre Size: F: 245/40R19

R: 275/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 9 mm Rear 9 mm

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 16/11/19 D.O.I. 10/12/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	File pass to
24/12	LL Rep @ 4250£ Carlow (Red 6655-60, 6190)

Date/Time, File Pass to?  : Prel. Report

: Final Report

Date/Time, File Return to?

24/12 - typist

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation: \_\_\_\_\_ \$ - RS. \$

Fuel:

Other:

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$

TP  
4250£

TOTAL

350



Your ref: CMTD1905394/THE

Our ref: CS/SMO19020604/Kvd3

DATE: 11/12/2019

The Motor Claims Department  
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. EP 168G**


We thank you for your instruction on 20/11/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10/12/2019 at the premises of M/s MBM WHEELPOWER PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$10,905.60
Revised Estimate Amount	: S\$3,817.65
"Check" Items Amount	: S\$2,076.16
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

**KENNETH KONG**  
**Licensed Appraiser**

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 11 December 2019 2:22 PM  
**To:** SUR; melvin.ye  
**Cc:** 'Choo, Thelma'; 'Henry, Irene James'; 'MotorSurvey@sompo.com.sg'  
**Subject:** RE: Liability Status - Accident involving EP168G & FBJ5545K (SOMPO) on 168/11/2019 Our ref : CMTD1905394/THE  
**Attachments:** EP 168G PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle EP 168G  
Date of survey: 10/12/2019  
Number of days (estimated) : 3 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Sent:** Wednesday, 20 November 2019 10:57 AM  
**To:** 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** 'Choo, Thelma' <thelma.choo@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: Liability Status - Accident involving EP168G & FBJ5545K (SOMPO) on 168/11/2019 Our ref : CMTD1905394/THE

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]  
**Sent:** Wednesday, 20 November 2019 9:48 AM  
**To:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** [eric.woo@mbmwheelpower.com.sg](mailto:eric.woo@mbmwheelpower.com.sg); [eryx.tan@mbmwheelpower.com.sg](mailto:eryx.tan@mbmwheelpower.com.sg); Choo, Thelma <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; Danny Ong <[danny.ong@mbmwheelpower.com.sg](mailto:danny.ong@mbmwheelpower.com.sg)>  
**Subject:** RE: Liability Status - Accident involving EP168G & FBJ5545K (SOMPO) on 168/11/2019 Our ref : CMTD1905394/THE

Without Prejudice

Dear LKK Auto,

Please make arrangement to conduct survey for EP168G on a without prejudice basis.

Best Regards

**Melvin Ye**

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



**SOMPO**  
INSURANCE

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG**



Download now @

or

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Danny Ong <[danny.ong@mbmwheelpower.com.sg](mailto:danny.ong@mbmwheelpower.com.sg)>

**Sent:** Tuesday, 19 November, 2019 5:21 PM

**To:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>

**Cc:** [eric.woo@mbmwheelpower.com.sg](mailto:eric.woo@mbmwheelpower.com.sg); [eryx.tan@mbmwheelpower.com.sg](mailto:eryx.tan@mbmwheelpower.com.sg); Choo, Thelma <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>

**Subject:** RE: Liability Status - Accident involving EP168G & FBJ5545K (SOMPO) on 168/11/2019 Our ref : CMTD1905394/THE


Dear Melvin

We would like to select "LKK – Kenneth" to conduct the survey

Kindly arrange them to contact us for the arrangement of the survey as vehicle **is not** in our premises.

*Best regards,*

*Danny Ong | Claims Advisor*



T 6262 8888 | F 6452 5333 | M 9328 8668

Email: [danny.ong@mbmwheelpower.com.sg](mailto:danny.ong@mbmwheelpower.com.sg)

MBM Wheelpower Pte Ltd

160 Sin Ming Drive • #06-02

Sin Ming AutoCity • Singapore 575722

[www.mbmwheelpower.com.sg](http://www.mbmwheelpower.com.sg)

---

**From:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>

**Sent:** Tuesday, 19 November 2019 4:37 PM

**To:** Danny Ong <[danny.ong@mbmwheelpower.com.sg](mailto:danny.ong@mbmwheelpower.com.sg)>

**Cc:** [eric.woo@mbmwheelpower.com.sg](mailto:eric.woo@mbmwheelpower.com.sg); [eryx.tan@mbmwheelpower.com.sg](mailto:eryx.tan@mbmwheelpower.com.sg); Choo, Thelma <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>

**Subject:** RE: Liability Status - Accident involving EP168G & FBJ5545K (SOMPO) on 168/11/2019 Our ref : CMTD1905394/THE

Our Reference : CMTD1905394/THE

Your Reference: EP168G

**Without Prejudice**

Date: 19/11/2019

**Attention:**

**MBM WHEELPOWER PTE LTD**

Dear Danny,

**ACCIDENT INVOLVING SLG9158R & SKR2805G ON 16.11.2019**

We refer to your Notice of Accident dated 19/11/2019.

The handler for this case is Ms Thelma Choo.

We regret to inform that we are unable to revert on liability for direct settlement as we have yet to receive our insured's accident report.

Kindly advise should you still require us to conduct survey on a "Without Prejudice" basis.

If you are agreeable to conduct survey on a "Without Prejudice" basis, we propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

### Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Melvin Ye**

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



**SOMPO**  
INSURANCE

**A Century of Trust**

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG



Download now @

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Danny Ong <[danny.ong@mbmwheelpower.com.sg](mailto:danny.ong@mbmwheelpower.com.sg)>

**Sent:** Tuesday, 19 November, 2019 10:39 AM

**To:** Claims - Motor Survey <[MotorSurvey@sompo.com.sg](mailto:MotorSurvey@sompo.com.sg)>

Cc: [eric.woo@mbmwheelpower.com.sg](mailto:eric.woo@mbmwheelpower.com.sg); [eryx.tan@mbmwheelpower.com.sg](mailto:eryx.tan@mbmwheelpower.com.sg)

Subject: Liability Status - Accident involving EP168G & FBJ5545K (SOMPO) on 16/11/2019

Dear All

**Appreciate if you can advise us on the liability status first** for the below loss and arrange a pre-survey.

Kindly refer to the attached GIA report & estimate.


**\*Kindly provide us with the list of surveyor film\***

Our Client's Vehicle Number:	EP168G
SOMPO Vehicle Number:	FBJ5545K
Date/Time of Loss:	16/11/2019 1640 hrs

**Please contact Danny 93288668 for the survey arrangement**

*Best regards,*

*Danny Ong | Claims Advisor*



T 6262 8888 | F 6452 5333 | M 9328 8668

Email: [danny.ong@mbmwheelpower.com.sg](mailto:danny.ong@mbmwheelpower.com.sg)

MBM Wheelpower Pte Ltd

160 Sin Ming Drive • #06-02

Sin Ming AutoCity • Singapore 575722

[www.mbmwheelpower.com.sg](http://www.mbmwheelpower.com.sg)

--

This message has been scanned for viruses and dangerous content by  
QUAPE SPAM Protection, and is believed to be clean.



This email has been checked for viruses by AVG antivirus software.

[www.avg.com](http://www.avg.com)

## Nivitha (LKK Auto)

---

**From:** Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>  
**Sent:** Wednesday, 20 November 2019 9:48 AM  
**To:** assignments; SUR  
**Cc:** eric.woo@mbmwheelpower.com.sg; eryx.tan@mbmwheelpower.com.sg; Choo, Thelma; Henry, Irene James; Danny Ong  
**Subject:** RE: Liability Status - Accident involving EP168G & FBJ5545K (SOMPO) on 168/11/2019 Our ref : CMTD1905394/THE

Without Prejudice

Dear LKK Auto,

Please make arrangement to conduct survey for EP168G on a without prejudice basis.

Best Regards

**Melvin Ye**

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



**SOMPO**  
INSURANCE

**A Century of Trust**

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG



Download now @

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Danny Ong <danny.ong@mbmwheelpower.com.sg>

**Sent:** Tuesday, 19 November, 2019 5:21 PM

**To:** Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

**Cc:** eric.woo@mbmwheelpower.com.sg; eryx.tan@mbmwheelpower.com.sg; Choo, Thelma <thelma.choo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

**Subject:** RE: Liability Status - Accident involving EP168G & FBJ5545K (SOMPO) on 168/11/2019 Our ref : CMTD1905394/THE


Dear Melvin

We would like to select "LKK – Kenneth" to conduct the survey

Kindly arrange them to contact us for the arrangement of the survey as vehicle **is not** in our premises.

*Best regards,*

*Danny Ong | Claims Advisor*



T 6262 8888 | F 6452 5333 | M 9328 8668

Email: [danny.ong@mbmwheelpower.com.sg](mailto:danny.ong@mbmwheelpower.com.sg)

MBM Wheelpower Pte Ltd

160 Sin Ming Drive • #06-02

Sin Ming AutoCity • Singapore 575722

[www.mbmwheelpower.com.sg](http://www.mbmwheelpower.com.sg)

---

**From:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>

**Sent:** Tuesday, 19 November 2019 4:37 PM

**To:** Danny Ong <[danny.ong@mbmwheelpower.com.sg](mailto:danny.ong@mbmwheelpower.com.sg)>

**Cc:** [eric.woo@mbmwheelpower.com.sg](mailto:eric.woo@mbmwheelpower.com.sg); [eryx.tan@mbmwheelpower.com.sg](mailto:eryx.tan@mbmwheelpower.com.sg); Choo, Thelma <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>

**Subject:** RE: Liability Status - Accident involving EP168G & FBJ5545K (SOMPO) on 168/11/2019 Our ref : CMTD1905394/THE

Our Reference : CMTD1905394/THE

Your Reference: EP168G

**Without Prejudice**

Date: 19/11/2019

**Attention:**

**MBM WHEELPOWER PTE LTD**

Dear Danny,

**ACCIDENT INVOLVING SLG9158R & SKR2805G ON 16.11.2019**

We refer to your Notice of Accident dated 19/11/2019.

The handler for this case is Ms Thelma Choo.

We regret to inform that we are unable to revert on liability for direct settlement as we have yet to receive our insured's accident report.

Kindly advise should you still require us to conduct survey on a "Without Prejudice" basis.

If you are agreeable to conduct survey on a "Without Prejudice" basis, we propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Melvin Ye**

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG



Download now @

or

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Danny Ong <danny.ong@mbmwheelpower.com.sg>  
**Sent:** Tuesday, 19 November, 2019 10:39 AM  
**To:** Claims - Motor Survey <MotorSurvey@sompo.com.sg>  
**Cc:** eric.woo@mbmwheelpower.com.sg; eryx.tan@mbmwheelpower.com.sg  
**Subject:** Liability Status - Accident involving EP168G & FBJ5545K (SOMPO) on 168/11/2019

Dear All

**Appreciate if you can advise us on the liability status first** for the below loss and arrange a pre-survey.

Kindly refer to the attached GIA report & estimate.

**\*Kindly provide us with the list of surveyor film\***

Our Client's Vehicle Number:	EP168G
SOMPO Vehicle Number:	FBJ5545K
Date/Time of Loss:	16/11/2019 1640 hrs

**Please contact Danny 93288668 for the survey arrangement**

*Best regards,*

*Danny Ong | Claims Advisor*



T 6262 8888 | F 6452 5333 | M 9328 8668

Email: [danny.ong@mbmwheelpower.com.sg](mailto:danny.ong@mbmwheelpower.com.sg)

MBM Wheelpower Pte Ltd

160 Sin Ming Drive • #06-02

Sin Ming AutoCity • Singapore 575722

[www.mbmwheelpower.com.sg](http://www.mbmwheelpower.com.sg)

--  
This message has been scanned for viruses and dangerous content by  
QUAPE SPAM Protection, and is believed to be clean.

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	495C
<b>Vehicle Details</b>	
Vehicle No.:	EP168G
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Nov 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E300 AMG COUPE
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	27492031525868
Chassis No.:	WDD2383482F066618
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$62,188.00
Original Registration Date:	11 Jul 2019
First Registration Date:	11 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$83,939.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jul 2029
PARF Rebate Amount:	\$62,954.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	10 Jul 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,000.00
COE Rebate Amount:	\$32,788.00
<b>Total Rebate Amount:</b>	<b>\$95,742.00</b>

The information contained herein is correct as at 18 Nov 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/11/2019 14:31
Date Of Accident	16/11/2019 16:40
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	EP168G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOW HOCK GUAN
NRIC No	S2580495C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97588168
Alternative Phone No	OFFICE-97588168

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E300 AMG COUPE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA482630/1
Cover Note Number	

### Driver

Name of Driver	LOW HOCK GUAN
NRIC No	S2580495C
Date Of Birth	27/02/1961
Occupation	INDOOR
Date Of Driving Pass	31/07/1980
Driving Experience	39 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97588168
Fax Number	
Contact Number	OFFICE-97588168
Email Address	NOEMAIL

Address	BLK 12 STIRLING RAD #28-08 S(148955)
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI N.P.C
Police Station Address	ROAD: 20 CLEMENTI AVE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

refer attached police report.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBJ5545K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBJ5545K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
 Policyholder's Signature  
 Date & Time:

\_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

\_\_\_\_\_  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report no.: T/20191117/2031

DECLARATION

I/We declare the foregoing particulars are true in every respect.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20191117/2031

1 of 3

Report No. T/20191117/2031

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 - SINGAPORE 129858  
Tel No: 1800-8729999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 17/11/2019 11:12		Vide Report No.: E/20191116/0129		Station Diary No. 41
<b>Informant's Particulars</b>				
Name of Informant: LOW HOCK GUAN			Address: APT BLK 12 STIRLING ROAD #28-08 SINGAPORE 148955	
ID Type / ID No.: NRIC NO / S2580495C			Contact No.: Home/Office:	Mobile: 97588168
Nationality: MALAYSIAN			Email:	
Sex: Male	Age: 58	Date of Birth: 27/02/1961	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: SELF EMPLOYED			Driving Licence Information: Class: 2B,2A,3	
			Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 16/11/2019 16:40	Type of Location: Straight Road
Location: Along Road 1 PAN-ISLAND EXPRESSWAY (PAYA LEBAR WAY)				
Along PIE towards Changi Airport at the 20.2KM near lamp post 98P				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Damage	No. of Passengers
EP168G	Car	MERCEDES BENZ	E300 AMG COUPE	Black	Slightly Damaged	0
FBJ5545K	Motorcycle	YAMAHA		Black	Seriously Damaged	0

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Policy No.	Effective Date	Expiry Date
EP168G	AXA INSURANCE SINGAPORE PTE LTD	GA482630	11/07/2019	10/07/2024



**SINGAPORE  
POLICE FORCE**



T/20191117/2031

2 of 3

Report No. T/20191117/2031

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

**CONTINUATION OF REPORT**

Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
<b>Driver:</b>			
Name	LOW HOCK GUAN	ID No	S2580495C
Related Vehicle	NIL	Contact No	97588168
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 16/11/2019 at about 1640hrs, I was driving my Black E300 Mercedes Coupe with registration number EP168G along Pie towards Changi at the 20.2km Mark. It was a four lane road and I was on the second lane.

While I was driving the traffic slowed down ahead of me. I decided to slow down too. Few seconds later, I heard and saw from the rear view mirror that there is a Black Yamaha motorcycle with registration number FBJ5545K travelling at a fast speed and hit the rear portion of my car and he fall to the roadside. I stopped my car and went over to assist him. The passer-by then called for 995 for assistance. I am unsure what is the injuries that the motorcyclist sustain as he was conveyed by ambulance to the hospital. There is not passenger in my car. I have already inform my insurance company on it. My workshop will be open on Monday and I will bring my car there for repair.

The rear bumper of my car is dented and came off. My rear car plate number drop off too. I do not sustain any injuries. Traffic Police and ambulance were at scene. I have an in-vehicle camera in the car and have already issued the SD card to the Traffic Police. They have issued me an acknowledgement slip to me. I was issued a case card and the officer advised me to lodge a report.



**SINGAPORE  
POLICE FORCE**



T/20191117/2031

3 of 3

Report No. T/20181117/2031

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
D /  
Sgt 3 NURAISHAH BINTE OSMAN

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIT /  
SI ONG CHEE HIEN  
Contact No.: 65476437


Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
17/11/2019 11:12

Classification Of Case:

SI 37



SIGNATURE



mbm wheelpower

# MBM WHEELPOWER PTE LTD

Your Ref: FBJ5545K

Our Ref: EP168G

*Not authorized  
Pursuing B4 paint  
2-3 days*

To: SOMPO

Date: 10/12/2019

CC

From: Danny

Fax: 64525333

Contact: 93288668

Make / Model: MERCEDES E300 AMG

Chassis No.: WDD2383482F066618

Engine No.: 27492031525868

Year of Make: 2018

Accident Date: 16 November 2019

Fax

ESTIMATE FOR VEHICLE NO. : EP168G

## DESCRIPTION

DESCRIPTION	QTY		List Price
REAR BUMPER	1	\$	<i>BULL DOG</i> 2,581.00 ✓
REAR BUMPER LOWER COVER	1	\$	<i>ADLUM</i> 529.20 ✓
REAR BUMPER LOWER TRIM - CHROME	1	\$	<i>CM</i> 243.30 ✓
REAR BUMPER TOW COVER	1	\$	<i>SM</i> 75.60 ✓
RIVET @ \$7 EACH	15	\$	<i>SM</i> 105.00 ✓
DISTANCE SENSOR @ \$250 EACH	2	\$	<i>SM</i> 500.00 ✓
DECOUPLING RING @ \$15 EACH	4	\$	<i>SM</i> 60.00 ✓
REAR BUMPER RH BRACKET	1	\$	<i>CM</i> 108.00 ✓
REAR BUMPER LH BRACKET	1	\$	<i>SM</i> 108.00 ✓
REAR BUMPER CENTER BRACKET	1	\$	<i>CM</i> 194.40 ✓
REAR BUMPER CENTER CARRIER	1	\$	<i>SM</i> 120.00 ✓
REAR BUMPER RH SIDE RETAINER	1	\$	<i>SM</i> 85.00 ✓
REAR BUMPER LH SIDE RETAINER	1	\$	<i>SM</i> 85.00 ✓
TAIL PIPE TRIM LH	1	\$	<i>RD</i> 482.00 ✓
TAIL PIPE TRIM RH	1	\$	<i>SM</i> 482.00 ✓
END PANEL	1	\$	<i>R</i> 1,425.50 ✓
END PANEL TOP GARNISH	1	\$	<i>SM</i> 180.00 ✓
END PANEL TOP GARNISH CLIPS @ 7 EACH	10	\$	<i>SM</i> 70.00 ✓
TAIL LAMP RH	1	\$	<i>MY CM</i> 850.00 ✓

Total: \$ 8,284.00

LESS 10% \$ (828.40)

Parts Total: \$ 7,455.60

**LKIC Auto Care Parts Centre notify the Repairer of the following:**

- To receive estimates during working hours
- To check, approve and sign off estimates
- Parts must be replaced with correct ones
- Trust only approved repairers (Digital Seal)
- No alterations to original equipment
- Supplemental estimates for additional work
- Receipts for parts and labour

Authorised by Repairer:  
Signature:  
Date:

**SPECIAL NETT**

BODY SEALANT	1	\$	<i>nn</i> 80.00 <i>λ</i>
REAR NUMBER PLATE & HOLDER	1	\$	<i>nn</i> <i>45nn</i> 50.00
COATING - 3 LAYER	1	\$	<i>nn</i> 400.00 <i>λ</i>

**LABOUR**

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.		\$	<i>300</i> 1,200.00
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR		\$	<i>nn</i> 100.00 <i>λ</i>
TO APPLY ANTI RUST COATING		\$	<i>nn</i> 150.00 <i>λ</i>
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS		\$	<i>nn</i> 150.00 <i>λ</i>
TO REMOVE & REPLACE BUMPER SENSORS		\$	40.00 <i>λ</i>
TO CHECK & RECONNECT ALL NECESSARY WIRING		\$	<i>200</i> 80.00
TO SPRAY PAINT ON THE AFFECTED AREAS		\$	<i>300</i> 1,200.00
Total:	\$		10,905.60
7% GST:	\$		763.39
<b>Grand Total:</b>	<b>\$</b>		<b>11,668.99</b>



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19020604/Kvd3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 24-12-2019	
		Code : SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	FBJ 5545K	Veh. Inspected	EP 168G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1905394/THE	Excess (\$)	0.00
Assign From	YONG KANG MELVIN	Assign Date	20/11/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MERCEDES BENZ E300 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WDD2383482F066618	Colour	METALLIC BLACK
Odometer	4106	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	245/40 R19	MICHELIN	9 mm
L/H Front Tyre	245/40 R19	MICHELIN	9 mm
R/H Rear Tyre	275/35 R19	MICHELIN	9 mm
L/H Rear Tyre	275/35 R19	MICHELIN	9 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	16/11/2019	Inspection Date	10/12/2019
Survey held at	160 SIN MING DRIVE #06-02		
Repairer	MBM WHEELPOWER PTE LTD		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EP 168G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	BUCKLED / DENTED	2,581.00	2,581.00
1	REAR BUMPER LOWER COVER	DENTED / CRACKED	529.20	529.20
1	REAR BUMPER LOWER TRIM - CHROME	CRACKED	243.30	243.30
1	REAR BUMPER TOW COVER	SERVICEABLE	75.60	-
15	RIVET @\$7.00	NECESSARY	105.00	105.00
2	DISTANCE SENSOR @\$250.00	SERVICEABLE	500.00	-
4	DECOUPLING RING @\$15.00	NOT NECESSARY	60.00	-
1	REAR BUMPER RH BRACKET	CRACKED	108.00	108.00
1	REAR BUMPER LH BRACKET	SERVICEABLE	108.00	-
1	REAR BUMPER CENTER BRACKET	CRACKED	194.40	194.40
1	REAR BUMPER CENTER CARRIER	SERVICEABLE	120.00	-
1	REAR BUMPER RH SIDE RETAINER	SERVICEABLE	85.00	-
1	REAR BUMPER LH SIDE RETAINER	SERVICEABLE	85.00	-
1	TAIL PIPE TRIM LH	DENTED	482.00	482.00
1	TAIL PIPE TRIM RH	SERVICEABLE	482.00	-
1	END PANEL	TO REPAIR SEE LABOUR	1,425.50	-
1	END PANEL TOP GARNISH	SERVICEABLE	180.00	-
10	END PANEL TOP GARNISH CLIPS @\$7.00	NOT NECESSARY	70.00	-
1	TAIL LAMP RH	MTG CRACKED	850.00	850.00
	LESS 10% DISCOUNT		-828.40	-509.29
			<b>7,455.60</b>	<b>4,583.61</b>
<b>SPECIAL NETT ITEMS</b>				
1	BODY SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR NUMBER PLATE & HOLDER (SN)	DENTED	50.00	45.00
1	COATING - 3 LAYER (SN)	NOT NECESSARY	400.00	-
			<b>530.00</b>	<b>45.00</b>

Report Ref No. CS/SMO19020604/Kvd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF END PANEL.		1,200.00	300.00
	TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR.	NOT NECESSARY	100.00	-
	TO APPLY ANTI RUST COATING.	NOT NECESSARY	150.00	-
	TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS.	NOT NECESSARY	150.00	-
	TO REMOVE & REPLACE BUMPER SENSORS.		40.00	40.00
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		80.00	20.00
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,200.00	300.00
			2,920.00	660.00
	<b>GRAND TOTAL</b>		<b>10,905.60</b>	<b>5,288.61</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,250.00</b>

Report Ref No. CS/SMO19020604/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.