

ASS. REC. BY:

REF: CS1119020637/Ayds<sup>n2</sup>

Special Instruction:

Surveyor: Adnan Meimien

ASSIGNMENT (Office)

From (Person): ten leah leong

of CTI

Date/Time: 20/11/19 @ 5:46pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP  WS  TP RES  OD RES  EVA  INV  MV  CS

To Inspect Vehicle No: QBJ 7524H

Insured: GBC 2377K

at Workshop m/s Sk Automobile

Tel: 6789 5155

of 8 kaki Bukit Ave 4 # 08-46 premier

Policy No: DMCVSN 30035419000

Claim No: SNM190205516C02

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_  
(Client's Record)

D.O.A. 18/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 9:45am @ 21/11/19

Person Contacted: Heey Lee

Vehicle:  IN  OUT

Date/Time	Action/Instruction	Signature
	QBJ 7524H - NBA / CTI 19020519 / Y	DOA: 18/11/2019
	GBC 2377K - NBA / CTI 19020519 / Y	DOA: 18/11/2019

REF: CFI

REQ. REC. BY:

ASSIGNMENT

From: \_\_\_\_\_ Date: 21/11/19

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBJ7524H

at Workshop n/s SK Automobile

of 8 kaki Bukit Ave 4 # 08-46 premier

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: GBJ7524H Yr Regn: 2019, August

Type: M.Car / M.Cycle / Bus / Van / Car / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Kia K2500 c.c. 2497

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 22439 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNCSJX76LK7383007

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 195R15C

R: 5-00R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS sup

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 21/11/19

Survey held at S.K

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>17/2</u>	<u>TP Claim</u> <u>45 \$10600/- (Red \$20263-00, 65%)</u>
<u>RECEIVED 18 FEB 2020</u>	

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? 17/2/20 Typist

2) \_\_\_\_\_

Report Format: ump 200 / I.B.I. / \$10600/-

Days Of Repair: 7

Resurvey No. of Trip: 2

Arld Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Invs (\$)  : Wheel end (\$)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + FS \$ \_\_\_\_\_

Photo: \_\_\_\_\_

Other: \_\_\_\_\_

TOTAL 220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Nov 2019		20 Nov 2019 17:46 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:			
Main Claimant:	<b>SK RESOURCES DEVELOPMENT PTE LTD, Co. Reg. No.: 201005242G</b>		
Vehicle Reg. No.:	<b>GBJ7524H</b>	Date of Loss:	18/11/2019 19:00 - :59
Claim Type:	<b>TP / SNM19D205516C02</b>	Policy/Cover Note No.:	DMCVSN30035419000
Vehicle Reg. No. (Insured):	<b>GBC2377K</b>	Policy No. (Claimant):	DMCVSN1931601900
		Excess:	S\$0.00
Repairer:	<b>Sk Automobile Pte Ltd ( ) 8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 8121 0478</b>		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]</b>		
Claimant's Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111</b>		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/11/2019]</b>		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS	<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results..									

## Nivitha (LKK Auto)

---

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Sent:** Wednesday, 20 November 2019 5:43 PM  
**To:** SK Admin; assignments  
**Cc:** JING XIONG KHOO  
**Subject:** RE: OUR REF: SNM19D205516-GBC2377K-TKL- Arrange surveyor for GBJ7524H & Your Ref:GBC2377K

### WITHOUT PREJUDICE

Dear Huey Lee,

We refer to your email dated 20.11.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** SK Admin [mailto:admin@skauto.com.sg]  
**Sent:** Wednesday, November 20, 2019 5:36 PM  
**To:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Cc:** JING XIONG KHOO <xionskauto@gmail.com>  
**Subject:** Re: OUR REF: SNM19D205516-GBC2377K-TKL- Arrange surveyor for GBJ7524H & Your Ref:GBC2377K

Dear Kah Leong,

Thank you for your reply

We choose surveyor: Adrian Ling

Regards,  
Huey Lee  
SK Automobile Pte Ltd

On Wed, Nov 20, 2019 at 5:16 PM Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)> wrote:

**Without Prejudice**

Dear Huey Lee,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

**Tan Kah Leong**

Assistant Executive

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI

**Sent:** Wednesday, November 20, 2019 5:07 PM

**To:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; SK Admin <[admin@skauto.com.sg](mailto:admin@skauto.com.sg)>

**Subject:** OUR REF: SNM19D205516-GBC2377K-TKL- Arrange surveyor for GBJ7524H & Your Ref:GBC2377K

Dear Kah Leong,

Please conduct PRS for GBJ7524H.

Note : officer in charge – Kah Leong 63896193.

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** SK Admin [<mailto:admin@skauto.com.sg>]

**Sent:** Wednesday, 20 November, 2019 3:02 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Cc:** JING XIONG KHOO <[xiongskauto@gmail.com](mailto:xiongskauto@gmail.com)>; md daud nadzim <[mddaudn731@gmail.com](mailto:mddaudn731@gmail.com)>

**Subject:** Arrange surveyor for GBJ7524H & Your Ref:GBC2377K

Dear Sir / Mdm,

We the repairers of motor vehicle no. GBJ7524H

Please provide a list of surveyor for further inspection

Location : 8 Kaki Bukit Ave 4#08-46

Premier @ Kaki Bukit

Singapore 415875

Contact No : 8121 0478 Xiong

We appreciate your early reply.

Thanks.

--

*Regards,  
Huey Lee*

*SK Automobile Pte Ltd*

*Tel: 6789 5155 Fax: 6783 5155*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

11/20/2019

Used Kia K2500 Car & Used Cars & Vehicles Singapore - sgCarMart

- 

**Kia K2500 Single-Cab** \$50,988 \$5,150 /yr 11-Oct-2019 2,497 cc - Truck Available

**Fuel Type:** Diesel  
 Cheapest 10t Lorry, 6-speed Manual, Suitable To All Common Usage, Full Loan Available, Free Servicing And CAC Warranty, Trade-in Get \$2000 Discount, T&C Apply, Call Now.

ARWIN Bus Pte Ltd  
Phone: 6744-2212 Fax: 6744-4108 3124-4108, 3124-4109, 3124-4110, 3124-4111, 3124-4112, 3124-4113, 3124-4114
  
- 

**Kia K2500 Single-Cab** \$49,888 \$5,280 /yr 02-May-2019 2,497 cc - Truck Available

**Fuel Type:** Diesel  
 Monthly \$555 Only, Flexible In House Loan Available, Any Trade In Welcome, Call Now For More Details.

ARWIN Bus Pte Ltd  
Phone: 6744-2212 Fax: 6744-4108 3124-4108, 3124-4109, 3124-4110, 3124-4111, 3124-4112, 3124-4113, 3124-4114
  
- 

**Kia K2500 Single-Cab** \$51,300 \$5,250 /yr 31-Jul-2019 2,497 cc - 10 km Truck Available

**Fuel Type:** Diesel  
 New List From CAC, Guaranteed COE, Immediate Registration, In House Loan Available, Just Pay \$1000 Booking Fee & we Will Do The Finance And Insurance For You, Worry Free Purchase When You Buy From Us.

Bull Auto Pte Ltd  
Phone: 6744-2212 Fax: 6744-4108 3124-4108, 3124-4109, 3124-4110, 3124-4111, 3124-4112, 3124-4113, 3124-4114
  
- 

**Kia K2500 Single-Cab** \$51,500 \$5,220 /yr 27-Sep-2019 2,497 cc - Truck Available

**Fuel Type:** Diesel  
 \$0 Drive Away! No Gimicks! Cheapest 10 Feet Lorry In Town, New Vehicle With Ready Stock! Most Affordable Commercial Vehicle, Euro 6 Engine, Low Fuel Consumption, Drive Off With Only \$2500 Including Insurance And First Month Instalment! Call Our Friendly Sales Tea...

KSL Automotive-Pte Ltd  
Phone: 6744-2212 Fax: 6744-4108 3124-4108, 3124-4109, 3124-4110, 3124-4111, 3124-4112, 3124-4113, 3124-4114
  
- 

**Sell your Car for \$3,000 More**  
 Owners who sell with Qeoz typically get up to \$3,000 above market value. Sell your Car for the Highest Price Today.  
 Find out more!
  
- 

**Kia K2500 Single-Cab** \$50,988 \$5,210 /yr 29-Aug-2019 2,497 cc - Truck Available

**Fuel Type:** Diesel  
 Monthly \$588, No Jokes, No Gimicks, Blue Or White, 5 Years Warranty Under Cycle And Carriage, 100% Approval In House Loan Available, Call Now For More Details.

ARWIN Bus Pte Ltd  
Phone: 6744-2212 Fax: 6744-4108 3124-4108, 3124-4109, 3124-4110, 3124-4111, 3124-4112, 3124-4113, 3124-4114
  
- 

**Kia K2500 Single-Cab** \$52,800 \$5,500 /yr 24-Jun-2019 2,497 cc - 18 km Truck Available

**Fuel Type:** Diesel  
 New Kia K2500 Without Canopy, Ready Stock With Immediate Delivery, Powerful 6 Speed Manual Gearbox, 100% Loan Available, High Trade In Welcome, Fast Call Our Friendly Sales For More Details Or Viewing.

ARWIN Bus Pte Ltd  
Phone: 6744-2212 Fax: 6744-4108 3124-4108, 3124-4109, 3124-4110, 3124-4111, 3124-4112, 3124-4113, 3124-4114
  
- 

**Kia K2500 Single-Cab** \$50,988 \$5,380 /yr 09-May-2019 2,497 cc - Truck Available

**Fuel Type:** Diesel  
 Cheapest In Town, New 10 Feet Kia Lorry, Ready Stock, \$550 Monthly Only, 5 Years Or 100,000 KM Warranty, 100% Loan With Lowest Interest Rate Available, Super High Trade In, Call Now!

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	242G
Vehicle Details	
Vehicle No.:	GBJ7524H
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	KIA
Vehicle Model:	K2500 6MT
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	D4CBK856297
Chassis No.:	KNCSJX76LK7383007
Maximum Power Output:	-
Open Market Value:	\$17,337.00
Original Registration Date:	02 Aug 2019
First Registration Date:	02 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$867.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Aug 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$24,599.00
COE Rebate Amount:	\$23,514.00
<b>Total Rebate Amount:</b>	<b>\$23,514.00</b>

The information contained herein is correct as at 10 Jan 2020

OK

11/20/2019

### PARF/COE Rebate Enquiry

A Singapore Government Agency Website

> Back to OneMotoring

#### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Company
Owner ID	7430
<b>Vehicle Details</b>	
Vehicle No.	GEJ7524H
Vehicle to be Exported	No
Intended Deregistration Date	20 Nov 2019
Vehicle Make	MA
Vehicle Model	K2300 SHI
Primary Colour	White
Manufacturing Year	2018
Engine No.	04C86483497
Chassis No.	WNCLE7MLK7383007
Maximum Power Output	-
Open Market Value	\$17,377.00
Original Registration Date	02 Aug 2019
First Registration Date	07 Aug 2019
Transfer Count	0
Actual PARF Paid	\$667.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	No
PARF Eligible For Expiry Date	-
PARF Rebate Amount	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	01 Aug 2029
COE Category	C - Goods Vehicle & Bus
COE Period (Years)	20
QP Paid	\$24,599.00
COE Rebate Amount	\$23,858.00
<b>Total Rebate Amount</b>	<b>\$23,858.00</b>

OK

51000  
- 23858  
-----  
27k

MNA418153056 / National Assessment Centre Services - Bukit Merah  
 ENTRY DATE & TIME: 19/11/2019 17:51  
 SUBMITTED BY: ROSLI BIN ABDUL WAMAB

Cheng

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/11/2019 17:51
Date Of Accident	18/11/2019 19:30
Exact Location Of Accident	AYE TOWARDS TUAS BEFORE CLEMENTI ROAD EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ7524H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SK RESOURCES DEVELOPMENT PTE LTD
Co Reg No	201005242G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83473112
Alternative Phone No	OFFICE-83473112

### Vehicle Particulars

Manufacturer	KIA
Model	K2500 6M/T
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1931601900
Cover Note Number	

### Driver

Name of Driver	ADAIKKAN BOOMI NATHAN
NRIC No	G8349961W
Date Of Birth	20/05/1988
Occupation	OUTDOOR
Date Of Driving Pass	25/03/2019
Driving Experience	0 YEAR AND 7 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83473112
Fax Number	
Contact Number	OTHERS-83473112
EMail Address	NOEMAIL

Address 25 KAKI BUKIT ROAD 4  
 Postcode 417800  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (Including own vehicle) involved in the accident 3  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 5  
 Passenger 1 NAME: : SUBRAMANIAM SATHISHKUMAR  
 GENDER: : MALE  
 Passenger 2 NAME: : MARIMUTHU URUMAI AH  
 GENDER: : MALE  
 Passenger 3 NAME: : MANDKARAN DURAISAMY  
 GENDER: : MALE  
 Passenger 4 NAME: : KOTHANDARAMAN SUBRAMANIYAN  
 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name EUNOS NEIGHBOURHOOD POLICE POST  
 Police Station Address ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-4439999 - FAX NO: 62444376  
 Was notice of Intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20191119/2094

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2377K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLW1647P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	ADAIKKAN BOOMI NATHAN
Approximate Age	
Injuries Sustain	SLIGHT INJURY
Injured person in which vehicle?	GBJ7524H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

#### DETAILS OF INJURED PERSON 2

Name	KOTHANDARAMAN SUBRAMANIYAN
Approximate Age	
Injuries Sustain	SLIGHT INJURY
Injured person in which vehicle?	GBJ7524H
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

#### DETAILS OF INJURED PERSON 3

Name	SUBRAMANIAM SATHISHKUMAR
Approximate Age	
Injuries Sustain	SLIGHT INJURY
Injured person in which vehicle?	GBJ7524H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

**DETAILS OF INJURED PERSON 4**

Name MARIMUTHU URU MAIAH

Approximate Age

Injuries Sustain SLIGHT INJURY

Injured person in which vehicle? GBJ7524H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

**DETAILS OF INJURED PERSON 5**

Name MANDKARAN DURAISAMY

Approximate Age

Injuries Sustain SLIGHT INJURY

Injured person in which vehicle? GBJ7524H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

### Accident Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*A. Poon*  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

*19/11/2019*  
Reporting Centre Personnel's Signature  
Name: *Boon Lee*  
NRIC/FIN No.:



## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T201911192094

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439899

1 of 4

Report No T201911192094

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/11/2019 15:22		Vide Report No.: D/Z0191118/0101		Station Diary No.: 21	
<b>Informant's Particulars</b>					
Name of Informant: ADAIKKAN BOOMI NATHAN			Address: C/O 25 Kaki Bukit Road 4 #07-65 Synergy @KB SINGAPORE 417900		
ID Type / ID No.: FIN NO / G8349961W			Contact No.:		Mobile: 83473112
Nationality: INDIAN			Email:		
Sex: Male	Age: 31	Date of Birth: 20/05/1988	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: 2B.3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/11/2019 19:30	Type of Location: Flyover
Location: Along Road 1 AYER RAJAH EXPRESSWAY AYE (TUAS)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Plate No.	Vehicle Type	Make	Model	Color	Condition	No. of Passengers
GBC2377K	Lorry	TOYOTA	DYNA 150 D	Silver	Seriously Damaged	11
GBJ7524H	Lorry	KIA	K2500 8MT	White	Slightly Damaged	4
SLW1647P	Car	MAZDA	MAZDA3 SEDAN 1.5 AT EU6	Silver	Slightly Damaged	1

## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T.20191119.2024

2 of 4

Police Station Of Origin:  
Eunos NPP  
529 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1900-4439999

Report No T/20191119/2024

## CONTINUATION OF REPORT

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	SUBRAMANYAN SATHISHKUMAR	ID No.	J3934730
Related Vehicle	GBJ7524H (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	19/11/2019	Date Discharge	19/11/2019
No. of Days granted Medical Leave	01	Degree of Injury	NIL
Name	KOTHANDARAMAN SUBRAMANYAN	ID No.	F7920154P
Related Vehicle	GBJ7524H (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	19/11/2019	Date Discharge	19/11/2019
No. of Days granted Medical Leave	02	Degree of Injury	NIL
Name	ADAIKKAN BOOMI NATHAN	ID No.	G8349961W
Related Vehicle	GBJ7524H (Lorry)	Contact No.	83473112
Hospital/Clinic	TEKKA CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	19/11/2019	Date Discharge	19/11/2019
No. of Days granted Medical Leave	01	Degree of Injury	Slight

## POLICE REPORT



SINGAPORE  
POLICE FORCE



T201911192094

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1820  
SINGAPORE 470629  
Tel No: 1800-4439999

3 of 4  
Report No. T201911192094

## CONTINUATION OF REPORT

Passenger			
Name	MARIMUTHU URUMAJAH	ID No.	G7885577R
Related Vehicle	GBJ7524H (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	19/11/2019	Date Discharge	19/11/2019
No. of Days granted Medical Leave	01	Degree of Injury	NIL
Passenger			
Name	MANDKARAN DURAISAMY	ID No.	G6606657L
Related Vehicle	GBJ7524H (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	19/11/2019	Date Discharge	19/11/2019
No. of Days granted Medical Leave	02	Degree of Injury	NIL

Brief Details.

On the 18/11/2019 at 1930hrs I was driving along AYE (Tuas) before Clementi Road exit, I was travelling along lane 2. Suddenly the front car jam brake and so I had to jam brake as well, I managed to stop in time. However the next lorry could not stop in time and collided into the rear of my vehicle, the car behind the lorry also could not stop in time and collided into the second lorry. The car driver then called for the paramedics as a lot of the passengers at the back of the second lorry were hurt. My friend then took photos of the accident and the other drivers did the same. Shortly, the paramedics arrived followed by Aelos and then traffic police. No one from my vehicle was conveyed, however all 12 of the people in the second lorry were all brought to the hospital for further checks. Traffic police then recorded a short statement and advised me to lodge a police report.

POLICE REPORT



SINGAPORE  
POLICE FORCE



T/20191119/2094

4 of 4

Report No. T/20191119/2094


Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470529  
Tel No: 1800-4439999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 LIM SHAO WEI, CLARENCE	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 19/11/2019 15:22
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NOR HIDAYU BINTE ABDUL SAMAD Contact No.: 65476423 Authentication Stamp NP168	Classification Of Case:

SK Automobile Pte Ltd  
 (Co Reg. No. 201500047H)  
 23 Kaki Bukit Ave 4, #03-01  
 Vicom Inspection Centre (S415933)  
 Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 21-Nov-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: GBJ7524H
ADDRESS	: <i>Xhome</i>	MODEL	: KIA K2500
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		<i>KNCSJX76LK7383007</i>
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT	:	DAUD/93911482	

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,845.00	\$ 1,845.00 ✓ 1550
2	SIDE GATE <i>Buckled</i>	2	\$ 1,884.00	\$ 3,768.00 ✓
3	TAILGATE SAFETY LOCK LH <i>Bent</i>	2	\$ 258.00	\$ <del>516.00</del> <sup>235</sup> ✓
4	TAILGATE LOWER END PANEL <i>Dented</i>	1	\$ 845.00	\$ <del>845.00</del> ✓ 525
5	TAILGATE HINGES <i>Bent</i>	3	\$ 65.00	\$ 195.00 ✓
6	TAILGATE 'KIA MOTOR' STICKER <i>New</i>	1	\$ 259.00	\$ 259.00 ✓
7	TAIL LAMP BRACKET <i>Bent</i>	2	\$ 296.00	\$ <del>592.00</del> ✓ 356
8	TAIL LAMP <i>Cracked</i>	2	\$ 412.00	\$ <del>824.00</del> 442 ✓
9	CABIN CAP DOOR FIRM END PANEL RH <i>Repair</i>	1	\$ 2,214.00	\$ 2,214.00 +
10	REAR CROSSMEMBER <del>New</del> <i>Repair</i>	1	\$ 1,245.00	\$ <del>1,245.00</del> +
11	REAR EXHAUST PIPE <i>Repair</i>	1	\$ 722.00	\$ 722.00 +
12	REAR SPARE TYRE BRACKET <i>Repair</i>	1	\$ 321.00	\$ 321.00 +
13	REAR NUMBER PLATE LAMP <i>cut</i>	1	\$ 124.00	\$ 124.00 ✓

TOTAL PRICE \$ 13,470.00  
 LESS 10% \$ 1,347.00  
 SUB TOTAL PRICE \$ 12,123.00

*6729-30*

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00
2	REVERSE SENSOR WITH HODLE <i>2</i>	1	\$ 400.00	\$ 400.00
3	TAILGATE ALUMINIUM PLATE <i>Best</i>	1	\$ 1,200.00	\$ 1,200.00
4	REAR FLOOR PANEL ALUMINIUM PLATE <i>new</i>	1	\$ 1,800.00	\$ 1,800.00
5	SIDE GATE RAILING SET <i>Best</i>	1	\$ 1,800.00	\$ 1,800.00
6	SIDE GATE ALUMINIUM PLATE <i>Not in</i>	2	\$ 1,200.00	\$ 2,400.00
7	REAR TAILGATE COMPANY LOGO SET <i>new</i>	1	\$ 800.00	\$ 800.00
8	SIDE GATE COMPANY LOGO SET <i>new new</i>	1	\$ 1,000.00	\$ <del>1,000.00</del> 600
9	CONOPY (FRONT) <i>Not in</i>	1	\$ 2,500.00	\$ <del>2,500.00</del> 800
10	REAR LOWER SAFETY BAR <i>Best</i>	1	\$ 1,800.00	\$ 1,800.00
11	REAR LOWER SAFETY BAR BRACKET <i>Best</i>	2	\$ 400.00	\$ <del>800.00</del> 400
12	STICKER '70KM' <i>3 per</i>	1	\$ 30.00	\$ 30.00
13	STICKER '13PAX'	1	\$ 30.00	\$ 30.00
14	TAIL LAMP PANEL STOPPER <i>new</i>	2	\$ 50.00	\$ 100.00
<i>4280</i>			TOTAL	\$ 14,710.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	\$ 1,500.00	1200	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	\$ 1,200.00	1000	
3	TUFF COAT	\$ 250.00	80	
4	WIRING CHECK	\$ 150.00	30	
5	TO WELDING REAR SAFETY BAR PANEL	\$ 250.00	*	
6	REAR CHASSIS ALIGNMENT	\$ 680.00	*	
TOTAL		\$ 4,030.00	2310	

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 26,833.00  
TOTAL LABOUR COST : \$ 4,030.00  
TOTAL REPAIR COST : \$ 30,863.00

EXCESS :  
NO. OF WORKING DAYS :  
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :  
SURVEYED BY :  
CONTACT NUMBER :  
FAX NUMBER :

Adrian King

H/S 21/11/19.

07 Days

total: 13319-30

H/S: 10600-00 ✓

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI19020637/AYD3N2  
**Date:** 18/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30035419000  
 Claimant Vehicle No: GBJ7524H Insured Vehicle No: GBC2377K  
 Date of Loss: 18/11/2019 Nature of Claim: TP Claim No: SNM19D205516C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ7524H**  
 Make & Model: KIA K2500 6M/T, 2.5 D (M) Engine No: D4CBK856297  
 Reg. Date: 02/08/2019 (Man. Year: 2019) Chassis No: KNCSJX76LK7383007  
 Colour: White Odometer: 22439 km  
 Engine Capacity: 2497 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 5.00R12  
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>	
Parts	26,833.00	11,009.30	15,823.70	58.97	
Miscellaneous Items	0.00	0.00	0.00		
Labour	4,030.00	2,310.00	1,720.00	42.68	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>30,863.00</b>	<b>13,319.30</b>	<b>17,543.70</b>	<b>56.84</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>10,600.00</b>			
	(S\$)	30,863.00	10,600.00	20,263.00	65.65
	<b>+ GST 7.00/7.00% (S\$)</b>	2,160.41	742.00	1,418.41	65.65
	<b>Nett Amount (S\$)</b>	<b>33,023.41</b>	<b>11,342.00</b>	<b>21,681.41</b>	<b>65.65</b>

INSPECTION

Date of Assignment: 20/11/2019  
 Date Inspected: 21/11/2019 Inspected At: 8 Kaki Bukit Avenue 4 # 08-46  
 Estimated Period of Repair: 7.0 days Repairer: Sk Automobile Pte Ltd

**Adjuster:** ADRIAN LING**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 18 Feb 2020)
<b>Parts:</b>	N/A KIA K2500 6M/T 2.5 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBJ7524H)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,845.00 FL	*1,550.00 FL
2	2		*SIDE GATE	Buckled	3,768.00 FL	*3,768.00 FL
3	2		*TAILGATE SAFETY LOCK LH	Bent	516.00 FL	*258.00 FL
4	1		*TAILGATE LOWER END PANEL	Dented	845.00 FL	*525.00 FL
5	3		*TAILGATE HINGES	Bent	195.00 FL	*195.00 FL
6	1		*TAILGATE KIA MOTOR STICKER	Necessary	259.00 FL	*259.00 FL
7	2		*TAIL LAMP BRACKET	Bent	592.00 FL	*356.00 FL
8	2		*TAIL LAMP	Cracked	824.00 FL	*442.00 FL
9	1		*CABIN CAP DOOR FIRM END PANEL RH	Repair	2,214.00 FL	*- FL
10	1		*REAR CROSSMEMBER	Repair	1,245.00 FL	*- FL
11	1		*REAR EXHAUST PIPE	Repair	722.00 FL	*- FL
12	1		*REAR SPARE TYRE BRACKET	Not Necessary	321.00 FL	*- FL
13	1		*REAR NUMBER PLATE LAMP	Cut	124.00 FL	*124.00 FL
14	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
15	1		*REVERSE SENSOR WITH HODLE	Damaged	400.00 FS	*200.00 FS
16	1		*TAILGATE ALUMINIUM PLATE	Bent	1,200.00 FS	*500.00 FS
17	1		*REAR FLOOR PANEL ALUMINIUM PLATE	Not Necessary	1,800.00 FS	*- FS
18	1		*SET SIDE GATE RAILING	Bent	1,800.00 FS	*800.00 FS
19	2		*SIDE GATE ALUMINIUM PLATE	Not Necessary	2,400.00 FS	*- FS
20	1		*SET REAR TAILGATE COMPANY LOGO	Not Necessary	800.00 FS	*- FS
21	1		*SET SIDE GATE COMPANY LOGO	Necessary	1,000.00 FS	*600.00 FS
22	1		*CONOPY (FRONT)	Dented	2,500.00 FS	*800.00 FS
23	1		*REAR LOWER SAFETY BAR	Bent	1,800.00 FS	*900.00 FS
24	2		*REAR LOWER SAFETY BAR BRACKET	Bent	800.00 FS	*400.00 FS
25	1		*STICKER 70KM	Necessary	30.00 FS	*15.00 FS
26	1		*STICKER 13PAX	Necessary	30.00 FS	*15.00 FS
27	2		*TAIL LAMP PANEL STOPPER	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>28,180.00</b>	<b>11,757.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,347.00</b>	<b>747.70</b>
<b>Total Parts (\$\$)</b>	<b>26,833.00</b>	<b>11,009.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT,WELD,CUT,KNOCK STRAIGHTEN,ADJUST GRAZE,JOIN	New	1,500.00	1,200.00
2	TO PUTTY,SPRAY PAINT,POLISH,WAX AFFECTED PARTS AND PANELS	New	1,200.00	1,000.00
3	TUFF COAT	New	250.00	80.00
4	WIRING CHECK	New	150.00	30.00
5	TO WELDING REAR SAFETY BAR PANEL	New	250.00	0.00
6	REAR CHASSIS ALIGNMENT	New	680.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,030.00</b>	<b>2,310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >