COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our	Ref

305350593

Via Fax

Email

Date

20-11-19

Your Insured:

9GN 899A

Time of Fax:

Date of Acc

AG.

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

C 3557 E

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident __

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle:
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

 Lim Kwok Eng Jumani Bin Masudin 	Tel: 6214 8316 or HP: 9824 0811 Tel: 6214 8315 or HP: 9635 5305	jumanibm@cdge.com.sg
 Lim Tien Siong 	Tel: 6214 8398 or HP: 9635 8546	Fax no. 6546 8156
 Chiang Liat Choon 	Tel: 6214 8314 or HP: 9296 6006	
 Larry Ng Nyuk Phin 	Tel: 6214 8315 or HP: 9230 2824	
Fauzy Bin Mokhtar	Tel: 6214 8319 or HP: 8125 9176)

olf we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

for Vice President Crash Repairs & Claims Recovery

OMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Warkshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286

24 Senoko Loop Singapore 758158 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

Date/Time20 Ub 20 0d 3 Figsp 20 109 16:43

Page: 1

Team: ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO.: 305350593
OMER		REGN NO.: SHC3557E	MILEAGE
7010045	COMFORT TRANSPORTATION PTE LTD 7010045	MAKE: HYUNDAI	FUEL EF
383 SIN MING DRIVE Singapore SINGAPORE 575717		MODEL IONIQ(G2) 2	DATE/TIME IN 20.11.2019 13:50
(A) 65508755 (O) =	10.07.2019	TARGET DATE	
OUNT CARD NO.		CHASSIS CODE KMHC851CVKU164605	COMPLETION DATE/TIME:
	IOD DESCRIPTION		


JOB DESCRIPTION

Accident Date: 20.11.2019

NATURE: 3P 20.11.19

LABOR CODE

DESCRIPTION



6.2				⊕ €	HEAR SIDE
0				ω.	
:KED & PASSE					9
	SERVICE ADVISOR		640		CUSTOMER'S SIGNATURE
ledgement Slip)		Exit Pass		
Vo.:	SHC3557E	JU AIG	Vehicle No.:	SHC3557E	

Service Advisor

Signature/Date

Date

turned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHC 3557E

DATE 20/11/2019 16:43

MAKE: MODEL: HYUNDAI IONIO

Qty	Parts Description/ Labour	Type	Unit	Price		Amount
	Rear Bumper				\$	459.40
	Rear Bumper Centre Moulding Assy				\$	451.25
	Rear Bumper Lower Centre Moulding Assy				\$	155.00
	Rear Bumper Stay				\$	138.10
	Rear Bumper Side Bracket (LH/RH)		\$	33.10	\$	66.20
	Rear Bumper Cover Clips		Ť	55713	\$	22.00
	Rem Bumper cover cups					22.00
	SUB TOTAL				\$	1,291.95
	LESS 20%				\$	258.39
	DISCOUNTED TOTAL				\$	1,033.56
						,
	Rear Bumper Reverse Sensor				\$	135.70
	Rear Bumper Rubber Mat				\$	50.00
						107.70
					\$	185.70
	Labour Charge					
	Panel Beating				\$	350.00
	Spray Painting Charge				\$	250.00
	Wiring Charge				\$	50.00
	Remove/Refix Reverse Sensor				\$	80.00
	TOTAL LABOUR				\$	730.00
	ESTIMATE TOTAL				\$	1,949.26
	1					
	9					
	This is an initial estimate based on a visual inspection of the	above vel	nicle The fir	nal renair qu	antu	m will

MCD619153352 / ComfortDelGro Engineering Pte Ltd - Loyang ENTRY DATE & TIME: 20/11/2019 14:36 SUBMITTED BY: Janet Lim Siang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid	
	ACCIDENT STATEMENT
Date Of Report	20/11/2019 14:36
Date Of Accident	20/11/2019 12:55
Exact Location Of Accident	C'WEALTH AVE (SLIP RD) TWDS ALEXANDRA.
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC3557E
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	IONIQ HYBRID
Exact Purpose for which vehicle was being used at time of accident	t .
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver HO FATT YEW
NRIC No S1155703A
Date Of Birth 12/01/1956
Occupation OUTDOOR
Date Of Driving Pass 31/12/1977

Driving Experience 41 YEARS AND 10 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98167116

Fax Number

Contact Number

EMail Address NOEMAIL

BLK 832 JURONG WEST STREET 81 Address

#09-06

Postcode 640832

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

OTHER - TAXI DRIVER

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

NO

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO NO

YES

NO

2

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

NAME:

GENDER:

MALE

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

NO

NO

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SGV899A

Vehicle Make/Model/Colour

AUDI

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LOKE SENG CHOW

NRIC/Passport Number

S0122317H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Jackson bland CSG


Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

GIARRAC Sketch(4anForm, V3

Fre 4

Lair

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/1/2019 at about 1255 hrs, I vehicle A mag
On adjust a contain 1253 ms, I vericle It was
at the Cheath are (ship Rd) toward alexander
Rd. toliane I was at the ship to all to give way
for on Coming vehicle. Which B Came from behind b
Quito Vehocle H-Ray portion. 120 one was Injured
at that time

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMPORT OF AN EXPRESSION AS LAND

Policyholder's Signature Date & Time: Driver's Signature
(If driver is not the policyholder)
Date & Time:

Claritati Sketchi barforra Va

28/4/19 Jankson Henry

and Acts

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.