



**SINGAPORE  
POLICE FORCE**



T/20191115/2191

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20191115/2191

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 15/11/2019 19:47		Vide Report No.: G/20191115/0138		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: YEOW SIOW QUAN			Address:		
ID Type / ID No.: NEW MALAYSIAN IC / 971020015085			Contact No.: Home/Office:		Mobile: 0109001588
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 22	Date of Birth: 20/10/1997	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: TRANSPORT			Driving Licence Information: Class:		Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 15/11/2019 13:50	Type of Location:
Location:  PAN ISLAND EXPRESSWAY  PIE > CHANGI BEFORE KALLANG WAY LP E642F				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC1868X	Car					0
SKK392E	Car					0
VAD5288	Car					0



**SINGAPORE  
POLICE FORCE**



T/20191115/2191

2 of 3

Report No. T/20191115/2191

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	YEOW SIOW QUAN	ID No.	971020015085
Related Vehicle	VAD5288 (Car)	Contact No.	0109001588
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

ON THE ABOVE MENTIONED DATE, TIME AND LOCATION,

I WAS ON THE THIRD LANE TRAVELLING ALONG PIE TOWARDS CHANGI BEFORE KALLANG WAY. THERE ARE 4 VEHICLES THAT WAS INVOLVED IN THIS ACCIDENT. THE FIRST VEHICLE V1, IS A LORRY BUT THE LORRY HAS LEFT THE SCENE. THE SECOND VEHICLE, V2 IS SKK392E AND I AM THE THRID VEHICLE, V3 VAD5288. AND THE LAST VEHICLE V4 SHC1868X. V2 FIRST COLLIDED INTO THE LORRY V1. THIS CAUSE ME AND V4 TO JAMMED BRAKE BUT WE COULD NOT STOP IN TIME AND I COLLIDED INTO V2 WHILE V4 COLLIDED INTO ME. ALL THE DRIVER GOT DOWN THE VEHICLE AND ECHANGED PARTICULARS. SOON AFTER LTA CAME AND THEN TRAFFIC POLICE CAME. WE WERE INTERVIEW BY THE TRAFFIC POLICE AND TAKEN MY SD CARD. NO ONE WAS INJURED.  
AFTER THE ACCIDENT I FELT PAIN IN MY BACK AND I WANTED TO SEE THE DOCTOR BUT IT WS LATE AND THE IO DAVID ASKED ME TO LOOK FOR HIM IN TRAFFIC POLICE. THAT IS ALL.



**SINGAPORE  
POLICE FORCE**



T/20191115/2191

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20191115/2191

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
TP /  
NG RUI TONG

Signature Of Interpreter:  
Not applicable

Signature Of Informant:

Date/Time:  
15/11/2019 19:47

Officer In Charge Of Case:  
TP / GIT /

Classification Of Case:

Contact No.:

**SINGAPORE  
POLICE FORCE**

Authentication Stamp  
NP168



Signature: \_\_\_\_\_