



Your Ref: AEMD/105/009/2019/074

Date: 11th Dec 2019

Our Ref: CS1/SPF19020697/Etd3e2

M/s Automotive Engineering & MGT Division
Accident Claim Section (Spore Police Force)
1 Mount Pleasant Road Blk 8 Old Police Academy
Singapore 298333

Attn : Hafizul Farhan

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLH 3531E
INSURED VEHICLE: QX 1024Y
ACCIDENT DATE: 19/06/2019

We thank you for your instruction on 19/11/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLH 3531E from M/s Appraisal VP Pte Ltd.
- b) Final Repair Bill of SLH 3531E from M/s Lion City Rentals Pte Ltd.
- c) Singapore Accident Statement and Police Report of Vehicles SLH 3531E.
- d) Colour damaged vehicle photographs of SLH 3531E.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLH 3531E
Make & Model	: Honda Shuttle
Chassis Number	: GP71043563
Year of Registration	: 2016
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.