

22/03/2011

ASS. REC. BY:

REF: CS/MSA/19020704/Ktd307 Special Instructions

Supervisor: Kenneth

## ASSIGNMENT (Office)

merimen

From (Person): Irene Tanof MeigDate/Time: 21/11/2010 4:43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCZ 8261M

Insured:

SJP 1632S

at Workshop in/s

Guan Motor

Tel:

64536111

or

176 Sh Ming Drive # 02-03Policy No: 1000933426

Claim No:

233604

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.B. Endorsement:

Date/Time: 9:43am 22/11/10

Person Contacted:

th loneyVehicle IN / OUT

Date/Time	Action/Instruction	Technician
	SCZ 8261M - CC7 / A1412001952 / Kpu	DOA: 8/3/2012
	SJP 1632S - CS/MSA/1011836 / Kbk3	DOA: 21/6/2014
25/11 -	Revised via merimen	
	11 Lm 8500d email (Red: 1970.39, 28%)	

ASS. REC. BY:

REF:

MS/G

## ASSIGNMENT

From

Date:

22/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SCZ 8261M

at Workshop m/s

Quon Motor

of

176 Sin Ming Drive # 02-03

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SCZ 8261M

Yr Regn:

08/13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Camry Hybrid 2494

Colour

M. Silver

A/C: Insured / Std / NI / NA

Sp Reading

46672

T/Radio: Insured / Std / NI / NA

Eng/No:

NR0530K500 4012185

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

18/11/19

D.O.I.

22/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rn O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/12/2019

RECEIVED 12 DEC 2019

Date/Time, File Pass to?



Preli. Report

1) 21/12 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week end (\$)

Survey Fee:

190

Transportation:

S + RS \$

Photos

Others

TOTAL

11

161

Report Format:

TP

Lump Sum / I.B.I. (\$)

5000/-

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Nov 2019		21 Nov 2019 16:43 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	Yeo Kee Wei, ID: S7174057I, Tel: +6596773870, Email: yeokeewei@gmail.com		
Main Claimant:	YEO CHOK MENG, ID: S0512031D		
Vehicle Reg. No.:	SCZ8261M	Date of Loss:	18/11/2019 12:00 - :59 [130 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 233604	Policy/Cover Note No.:	1000933426 (Comprehensive) Coverage: 13/03/2019 - 12/03/2020
Vehicle Reg. No. (Insured):	SJP1632S	Policy No. (Claimant):	
		Excess:	
Repairer:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/11/2019]		
Driver/Custodian (Insured):	Yeo Kee Wei (48) , NRIC: S7174057I, Tel: +6596773870 Email: yeokeewei@gmail.com		
Adj Asg. Remarks:	on WP, Liab: clear. Agree on SJE. Assign: Kenneth Kong from LKK Auto Consultants Pte Ltd. Contact: Ah Heng @ 6453 6111.		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Denise Tay (LKKAUTO)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Monday, 25 November 2019 1:52 PM  
**To:** Denise Tay (LKKAUTO)  
**Subject:** FW: SHC 5271R / FIRST CAPITAL / DOA: 18/11/2019 -- AAD1911-153  
**Attachments:** SHC 5271R EST.pdf

Hi Denise

Amount confirmed \$ 3,350 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

TRANS-CAB SERVICES PTE LTD  
No. 2 Ang Mo Kio Street 63  
Singapore 569111  
Tel: 6287 6666 Fax: 6287 7764

---

**From:** Denise Tay (LKKAUTO) [mailto:[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)]  
**Sent:** Monday, 25 November, 2019 11:58 AM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** SHC 5271R / FIRST CAPITAL / DOA: 18/11/2019

Dear Wai Yin,

Lump sum \$3350, 2.5days

Please check and get back confirmation

Best Regards,  
**Denise Tay** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 25 Nov 2019

**Preliminary Advice**

Insured Vehicle No	: SJP1632S	Accident Date	: 18/11/2019
TP Vehicle No	: SCZ8261M	Assignment Date	: 21/11/2019
Make	: HYUNDAI AVANTE	Est. Duration of Repair	: 6.00
Date of Inspection	: 22/11/2019		
Inspection At	: GUAN MOTOR WORKS (HQ) 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,632.89
Revised Amount	:S\$	3,490.58
Check Items (Estimated)	:S\$	2,832.31
Total	:S\$	6,322.89
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( x ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/11/2019 10:44
Date Of Accident	18/11/2019 12:50
Exact Location Of Accident	INSIDE TAN TOCK SENG HOSPITAL (CARPARK EXIT)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCZ8261M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YEO CHOK MENG
NRIC No	S0512031D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96716891
Alternative Phone No	OFFICE-96716891

### Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102732655-01
Cover Note Number	

### Driver

Name of Driver	YEO CHOK MENG
NRIC No	S0512031D
Date Of Birth	21/12/1936
Occupation	INDOOR
Date Of Driving Pass	29/01/1957
Driving Experience	62 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96716891
Fax Number	
Contact Number	OFFICE-96716891

Address	APT BLK 350 ANG MO KIO STREET 32 #30-115 SINGAPORE
Postcode	560350
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP1632S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YEO KEE WEI
NRIC/Passport Number	S7174057I
Contact Number	96773870
Address	
Postcode	
Insurance Company Name	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING STRAIGHT WHERE VEHICLE 6  
CAME OUT FROM THE CARPARK AND COLLIDED  
TO FRONT RIGHT PORTION OF MY VEHICLE.  
NO INJURY.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

# 源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

*Not Authorized*  
*25/1/19*  
*Liby \$5000*  
*Resurvey After Paint*

*4-6 days*

## REPAIR ESTIMATE FOR SCZ8261M

No.	Qty	List Items			
1	1	Front bumper	Bu	663.70	✓
2	1	Front bumper RH fog lamp chrome cover	\$ CM	92.70	✓
3	1	Front bumper RH fog lamp	mg CM	236.43	✓
4	1	Front bumper RH parking sensor	\$ Sen	336.95	✓
5	1	Front bumper RH side retainer	\$ Dri	85.70	✓
6	1	Front bumper inner reinforcement	\$ B	386.95	✓
7	1	Front bumper inner foam	\$ CM	122.60	✓
8	1 set	Front bumper clips	\$ M	40.00	✓
9	1	RH headlamp	\$ CM	1,344.90	✓
10	1	Front RH fender	\$ B	787.40	✓
11	1	Front RH fender "HYBRID" emblem	\$ M	45.17	✓
12	1	Front RH fender under shield	\$ Dri	186.95	✓
13	1 set	Front fender under shield clips	\$ M	30.00	✓
14	1	Washer tank	mg B	184.70	✓
15	1	Front support panel	\$ B	1,259.70	✓
			\$	5,803.85	
			Less 25%	\$ 1,450.96	
			Total :	\$ 4,352.89	

## Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	900.00	600
2	To putty and spray Spray Paintings charges.	\$	1,000.00	800
3	To check wirings/lightings & replace front parking sensors.	\$	80.00	500
4	To remove, refit air con condenser, radiator etc., including refill air con gas.	\$	140.00	1000
5	To conduct computerise wheel alignment test.	\$	80.00	X
6	To supply and apply anti rust treatment	\$	80.00	600
		Total :	\$ 2,280.00	

**Total Parts and Labour : \$ 6,632.89**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

25.11.2019

SUPPLEMENTARY REPAIR ESTIMATE FOR  
TOYOTA CAMRY - 2.5 (A) - SCZ 8261 M

1 pc. Items  
Front grille

*cm* \$ 450.00 ✓  
Less 25% 112.50  
\$ 337.50

6970.39

## ...CLAIM SUBFOLDER...(Pending for Survey Report)








































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Nov 2019		21 Nov 2019 16:43 <a href="#">Edit Adj Rpt</a>	<b>S\$5,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured: <b>Yeo Kee Wei</b> , ID: S7174057I, Tel: +6596773870, Email: yeokeewei@gmail.com									
Main Claimant: <b>YEO CHOK MENG</b> , ID: S0512031D									
Vehicle Reg. No.: <b>SCZ8261M</b>		Date of Loss: 18/11/2019 12:00 - :59 [74 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 233604</b>		Policy/Cover Note No.: 1000933426 (Comprehensive) Coverage: 13/03/2019 - 12/03/2020							
Vehicle Reg. No. (Insured): <b>SJP1632S</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Guan Motor Works (HQ)</b> 176 Sin Ming Drive #02-03 Sin Ming Autocare, S75721 Sin Ming - Tel: 64536111									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 21/12/2019]									
Driver/Custodian (Insured): Yeo Kee Wei (48), NRIC: S7174057I, Tel: +6596773870 Email: yeokeewei@gmail.com									
Adj Asg. Remarks: on WP. Liab: clear. Agree on SJE. Assign: Kenneth Kong from LKK Auto Consultants Pte Ltd. Contact: Ah Heng @ 6453 6111.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SCZ8261M (233604)  
[SJP1632S]  
TP  
YEO CHOK MENG  
Nov 18 2019 12:00PM  
[Yeo Kee Wei]  
Guan Motor Works

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/11/19 13:50	Adjuster Immediate Advice	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
2	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
3	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
15	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
16	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
17	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
18	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
19	11/12/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
20	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
21	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	11/12/19 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/11/19 13:26	OI GIA	 Load PDF	
2	20/11/19 13:26	Status of Driving Licence	 Load PDF	
3	20/11/19 13:29	PRI	 Load PDF	
4	21/11/19 10:50	Agree on SJE	 Load PDF	



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	13/12/19 10:59	Supplementary		Load PDF

## Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	1 per page	<input checked="" type="checkbox"/>
1	19/11/19 10:28	Accident Statement		Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail Print
1	19/11/19 10:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	19/11/19 10:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	19/11/19 10:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	19/11/19 10:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	19/11/19 10:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	19/11/19 10:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	19/11/19 10:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	19/11/19 10:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	19/11/19 10:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail Print
1	19/11/19 10:27	Sketch Plan		Load TIF
2	19/11/19 10:27	Sketch Plan #2		Load TIF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19020704/KTD3E2

Date: 13/12/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000933426

Claimant Vehicle No : SCZ8261M

Insured Vehicle No : SJP1632S

Date of Loss: 18/11/2019

Nature of Claim: TP

Claim No: 233604

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCZ8261M**

Make & Model: TOYOTA CAMRY, 2.5 HYBRID CVT (A)

Engine No: 2ARU034989

Reg. Date: 29/08/2013 (Man. Year: 2013)

Chassis No: MR053CK5004012185

Colour: Metallic Silver

Odometer: 46672 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,690.39	4,690.39	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,610.00	670.00	29.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,970.39</b>	<b>6,300.39</b>	<b>670.00</b>	<b>9.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,970.39</b>	<b>5,000.00</b>	<b>1,970.39</b>	<b>28.27</b>

### INSPECTION

Date of Assignment: 21/11/2019

Date Inspected: 22/11/2019 Inspected At:

Guan Motor Works (HQ)  
176 Sin Ming Drive #02-03 Sin Ming  
Autocare  
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2019)
<b>Parts:</b> 143	TOYOTA CAMRY 2.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SCZ8261M)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	663.70 FL	*663.70 FL
2	1		*FRONT BUMPER RH FOG LAMP CHROME COVER	Cracked	92.70 FL	*92.70 FL
3	1		*FRONT BUMPER RH FOG LAMP	Mtg Cracked	236.43 FL	*236.43 FL
4	1		*FRONT BUMPER RH PARKING SENSOR	Scratched	336.95 FL	*336.95 FL
5	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	85.70 FL	*85.70 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	386.95 FL	*386.95 FL
7	1		*FRONT BUMPER INNER FOAM	Cracked	122.60 FL	*122.60 FL
8	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
9	1		*RH HEADLAMP	Cracked	1,344.90 FL	*1,344.90 FL
10	1		*FRONT RH FENDER	Bent	787.40 FL	*787.40 FL
11	1		*FRONT RH FENDER HYBRID EMBLEM	Necessary	45.17 FL	*45.17 FL
12	1		*FRONT RH FENDER UNDER SHIELD	Distorted	186.95 FL	*186.95 FL
13	1		*SET FRONT FENDER UNDER SHIELD CLIPS	Necessary	30.00 FL	*30.00 FL
14	1		*WASHER TANK	Mtg Distorted	184.70 FL	*184.70 FL
15	1		*FRONT SUPPORT PANEL	Bent	1,259.70 FL	*1,259.70 FL
16	1		*FRONT GRILLE	Cracked	450.00 FL	*450.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>6,253.85</b>	<b>6,253.85</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>1,563.46</b>	<b>1,563.46</b>
<b>Total Parts (S\$)</b>	<b>4,690.39</b>	<b>4,690.39</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES FOR REMOVE / REFIT, CUTTING / WELDING AND REPLACEMENT OF DAMAGES	New	900.00	600.00
2	TO PUTTY AND SPRAY PAINTINGS CHARGES	New	1,000.00	800.00
3	TO CHECK WIRINGS / LIGHTINGS & REPLACE FRONT PARKING SENSORS	New	80.00	50.00
4	TO REMOVE, REFIT AIR CON CONDENSER, RADIATOR ETC., INCLUDING REFILL AIR CON GAS	New	140.00	100.00
5	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST	New	80.00	0.00
6	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>2,280.00</b>	<b>1,610.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >