

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jan 2020		23 Jan 2020 18:08 Edit Adj Rpt	S\$5,174.19 Edit Estimates	S\$5,174.19 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured: -, Co. Reg. No.: -				
Main Claimant: PHUA CHEE WHEE RAYMOND				
Vehicle Reg. No.: SKU4932T		Date of Loss: 19/11/2019 07:00 - :59 [51 Months and 20 Days From LTA Reg Date (Man Yr)]		
Claim Type: TP / SNM19D205537		Policy/Cover Note No.: DMPCSN30433819000		
Vehicle Reg. No. (Insured): SJR2896E		Policy No. (Claimant):		
		Excess: S\$0.00		
Repairer: Volkswagen Centre Singapore (HQ) 247 Alexandra Road, 159934 Alexandra - Tel: 63057288				
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]				
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 04/02/2020]				
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS ☐				
View All Search Tasks Create New Task Complete				
Due Date	Priority	Type	Task Group	Subject
Handler	Assigned By	Completed On	Created On	Done?
No results.				

Claim Documents

***SKU4932T (SNM19D205537)**
[SJR2896E]
TP
PHUA CHEE WHEE RAYMOND
Nov 19 2019 7:00AM
[-]
Volkswagen Centre Singapore

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#) ▼

Photos/Images					
			3 per page ▼		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/02/20 13:02	Odometer Reading		Load JPG	
2	05/02/20 13:02	Chassis Number		Load JPG	
3	05/02/20 13:02	General View		Load JPG	
4	05/02/20 13:02	General View		Load JPG	
5	05/02/20 13:02	General View		Load JPG	
6	05/02/20 13:02	General View		Load JPG	
7	05/02/20 13:02	General View		Load JPG	
8	05/02/20 13:02	General View		Load JPG	
9	05/02/20 13:02	General View		Load JPG	
10	05/02/20 13:02	General View		Load JPG	
11	05/02/20 13:02	General View		Load JPG	
12	05/02/20 13:02	General View		Load JPG	
13	05/02/20 13:02	General View		Load JPG	
14	05/02/20 13:02	General View		Load JPG	
15	05/02/20 13:02	General View		Load JPG	
16	05/02/20 13:02	General View		Load JPG	
17	05/02/20 13:02	General View		Load JPG	
18	05/02/20 13:02	General View		Load JPG	
19	05/02/20 13:02	General View		Load JPG	
20	05/02/20 13:02	General View		Load JPG	
21	05/02/20 13:02	General View		Load JPG	
22	05/02/20 13:02	General View		Load JPG	
23	05/02/20 13:02	General View		Load JPG	
24	05/02/20 13:02	General View		Load JPG	
25	05/02/20 13:02	General View		Load JPG	
26	05/02/20 13:02	General View		Load JPG	
27	05/02/20 13:02	General View		Load JPG	
28	05/02/20 13:02	General View		Load JPG	
29	05/02/20 13:02	General View		Load JPG	
30	05/02/20 13:02	General View		Load JPG	
31	05/02/20 13:02	General View		Load JPG	
32	05/02/20 13:02	General View		Load JPG	
33	05/02/20 13:02	General View		Load JPG	
34	05/02/20 13:02	General View		Load JPG	
35	05/02/20 13:02	General View		Load JPG	
36	05/02/20 13:07	BEFORE PAINT PHOTO		Load JPG	
37	05/02/20 13:07	BEFORE PAINT PHOTO		Load JPG	
38	05/02/20 13:07	BEFORE PAINT PHOTO		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Reset

Save

Print

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI19020719/QQD3S2**Date:** 14/04/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30433819000
Claimant Vehicle No :	SKU4932T	Insured Vehicle No :	SJR2896E
Date of Loss:	19/11/2019	Nature of Claim:	TP
		Claim No:	SNM19D205537

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU4932T	Engine No:	CAXF54238
Make & Model:	VOLKSWAGEN JETTA GP, 1.4 TSI 90 (A)	Chassis No:	WVWZZZ16ZFM029853
Reg. Date:	30/07/2015 (Man. Year: 2015)	Odometer:	68820 km
Colour:	Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 ZR18	Rear Tyre Size:	225/40 ZR18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,393.43	1,554.19	3,839.24	71.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,640.00	3,620.00	7,020.00	65.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,033.43	5,174.19	10,859.24	67.73
+ GST 7.00/7.00% (S\$)	1,122.34	362.19	760.15	67.73
Nett Amount (S\$)	17,155.77	5,536.38	11,619.39	67.73

INSPECTION

Date of Assignment:	23/01/2020	
Date Inspected:	03/12/2019 Inspected At:	Volkswagen Centre Singapore 1 KAMPONG AMPAT OFF MACPHERSON ROAD SINGAPORE 368314
Estimated Period of Repair:	4.0 days	

Adjuster: OI SUN PIN**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2020)
Parts:	143	VOLKSWAGEN JETTA GP 1.4 TSI 90 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU4932T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID	Repair	1,885.72 FS	*- FS
2	1		*PACKING ADHESIVE: RR NUMBER PLATE PACKING	Serviceable	27.03 FS	*- FS
3	4		*RIVETTED CAP NUT	Serviceable	7.52 FS	*- FS
4	1		*VW SIGN CHROME COLORED / BI	Necessary	81.94 FS	*81.94 FS
5	1		*INSCRIPTION BRILLIANT CHR: NAME PLATE - JETTA	Necessary	58.14 FS	*58.14 FS
6	1		*INSCRIPTION CHROME / RED: NAME PLATE - TSI	Necessary	61.92 FS	*61.92 FS
7	1		*COVER FOR BUMPER PRIMED	Dented	1,344.03 FS	*1,344.03 FS
8	1		*SPOILER	Serviceable	460.31 FS	*- FS
9	1		*BUMPER: REINFORCEMENT	Serviceable	603.37 FS	*- FS
10	1		*ATTACHMENT STRIP: RR BUMPER CENTRE BRACKET	Serviceable	72.88 FS	*- FS
11	1		*GUIDE PIECE: TAILLIGHT LOWER BRACKET LH	Serviceable	78.37 FS	*- FS
12	1		*GUIDE PIECE: TAILLIGHT LOWER BRACKET RH	Serviceable	78.37 FS	*- FS
13	1		*GUIDE PIECE: BUMPER SIDE BRACKET LH	Serviceable	78.37 FS	*- FS
14	1		*GUIDE PIECE: BUMPER SIDE BRACKET RH	Serviceable	78.37 FS	*- FS
15	6		*EXPANDING NUT	Necessary	8.16 FS	*8.16 FS
16	1		*REFLECTOR: REFLECTOR RH	Serviceable	68.93 FS	*- FS
17	1		*REVERSE SENSOR	Serviceable	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	5,393.43	1,554.19
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK SHORT CIRCUIT / HARNESS REPAIR.	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING.	New	480.00	480.00
3	LABOUR.	New	5,040.00	1,260.00
4	SPRAY PAINTING.	New	4,000.00	1,600.00
5	TRANSFER BOOT LID MECHANISM.	New	840.00	0.00
Gross Labour Cost (\$)			10,640.00	3,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >