

ASS. REC. BY:

REF: 08/CTI/19020729/21d3/

Special Instructions:

Assigner: Rasul

ASSIGNMENT (OIRco)

From (Person): Ben Teng

of

CTI

Date/Time: 22/11/19 @ 11:31am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMG 3779B

Insured:

SKU 875

at Workshop in/s

Cycle & Carriage

Tel:

65684501

of

201 Pandan Garden

Policy No:

Claim No:

8NMI9D205440

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:45am @ 22/11/19

Person Contacted:

Lenny

Vehicle IN / OUT

| Date/Time | Action/Instruction |
|-----------|--|
| | 13/11/2019 ✓ |
| | SMG 3779B-X |
| | SKU 875-X |
| 10/1/2020 | Final fig \$5882 confirmed by email (Ref 3976, 4090) |

ASSIGNMENT

From: _____ Date: 20/12/19

Estimated Cost: _____

OD: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: SMG 3779B

at Workshop with Cycle & Carriage Kia

of 209 Punden Gardens

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After 12pm
Kalvin

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMG 3779B

Regn: 2018 / DBC

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer or

Make: KIA Sorento 2.2 (8AT) C.C. 2199

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 2476 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAP H81BM J5465514

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 235/60R18 R: _____

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☒ YOKO or

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 15/11/19 D.O.I: 20/12/19

Survey held at: CBC (8A)

Des. of Damages: Frt ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 10 JAN 2020

Date/Time, File Path to: _____

☐ : Prel. Report

☐ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Date/Time, File Path to: _____

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Inv. (\$) ☐ Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS: \$ _____

Notes: _____

Other: _____

TOTAL: _____

Date/Time, File Path to: _____

Report Format: menmen

Lump Sum / L.D.: 5880/-

10/1 typist

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Friday, 22 November 2019 11:31 AM
To: assignments@lkkauto.com
Subject: FW: OUR REF: SNM19D205440-SKU87J-BEN- TP CLAIM : SMG3779B AGAINST YOUR INSURED : SKU87J DOA : 15.11.2019

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SMG 3779B.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Kevin Leong Wai Kit <kevin.leong@cyclecarriage.com.sg>
Sent: Thursday, November 21, 2019 10:30 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205440-SKU87J-BEN- TP CLAIM : SMG3779B AGAINST YOUR INSURED : SKU87J DOA : 15.11.2019

Dear Ben,

We choose : 5. XING QUO QIANG

Thank You & Best regards

Kevin Leong
Claim Division Operations
209 Pandan Gardens
Singapore 609339

From: Ben Tang [<mailto:Ben.Tang@sg.entaiping.com>]
Sent: Thursday, 21 November, 2019 9:17 AM
To: Kevin Leong Wai Kit
Cc: Claims Dept of CTI
Subject: RE: OUR REF: SNM19D205440-SKU87J-BEN- TP CLAIM : SMG3779B AGAINST YOUR INSURED : SKU87J DOA : 15.11.2019

This email was sent from outside of your organisation

WITHOUT PREJUDICE

Dear Sirs

We refer to your email of 20.11.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

| | |
|----------------------------|-----------------|
| 1. ADRIAN LING | 6. KENNETH KONG |
| 2. Kelvin Ang | 7. SIMON HO |
| 3. SEE CHEW SENG | 8. CHUA WEIJIE |
| 4. MOHD FADHILAH BIN OSMAN | 9. MARCUS CHUA |
| 5. XING QUO QIANG | 10. HENRY NG |

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

Without admission of liability, please provide our surveyor with repair estimates to facilitate direct settlement.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, November 20, 2019 5:57 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>;
kevin.leong@cyclecarrriage.com.sg
Subject: OUR REF: SNM19D205440-SKU87J-BEN- TP CLAIM : SMG3779B AGAINST YOUR
INSURED : SKU87J DOA : 15.11.2019

Dear Ben,

Please conduct PRS for SMG3779B.

Note : officer in charge- Ben Tang 63896175.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Kevin Leong Wai Kit [<mailto:kevin.leong@cyclecarrriage.com.sg>]
Sent: Wednesday, 20 November, 2019 5:06 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Don Bong Kiong Hua <kionghua.bong@cyclecarrriage.com.sg>; Edwin Abcede Caina
<edwin.caina@cyclecarrriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarrriage.com.sg>; Andre Chow En
De <andre.chow@cyclecarrriage.com.sg>
Subject: TP CLAIM : SMG3779B AGAINST YOUR INSURED : SKU87J DOA : 15.11.2019

Dear All,

Our Client : **SMG3779B** vs your insured : **SKU87J**

Above attach SAS report and repair quotation for your reference.

Please let us have the liability.

Thank You & Best regards

Kevin Leong
Claim Division Operations
209 Pandan Gardens
Singapore 609339



Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4501 • F: +65 6565 1240 • H: +65 81680997 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: PGMFP06@cyclecarriage.com.sg [mailto:PGMFP06@cyclecarriage.com.sg]

Sent: Wednesday, 20 November, 2019 9:32 AM

To: Kevin Leong Wai Kit

Subject:

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---|
| Date Of Report | 15/11/2019 17:41 |
| Date Of Accident | 15/11/2019 08:50 |
| Exact Location Of Accident | SLE TOWARDS BKE(TUAS)AFTER UPPER THOMSON EXIT |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SMG3779B |
| Insured/Policyholder | |
| Name Of Registered Owner | ONG KYE FONG JERRY |
| NRIC No. | S7937306J |
| Email Address | JERRY.OKF@GMAIL.COM |
| Mobile Phone No | (LOCAL) +65-81395198 |
| Alternative Phone No | OFFICE-81395198 |

Vehicle Particulars

| | |
|--------------|-----------------|
| Manufacturer | KIA |
| Model | SORENTO-2.2 (A) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 1800149636 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | ONG KYE FONG JERRY |
| NRIC No | S7937306J |
| Date Of Birth | 26/11/1979 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 21/03/2003 |
| Driving Experience | 16 YEARS AND 7 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-81395198 |
| Fax Number | |
| Contact Number | OFFICE-81395198 |
| Email Address | JERRY.OKF@GMAIL.COM |

| | |
|---|-----------------------------------|
| Address | APT BLK 310C PUNGGOL WALK #02-610 |
| Postcode | 823310 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | NO |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

WHEN I WAS TRAVELING TO WORK SITE ALONG SLE TOWARDS BKE (TUAS), THE VEHICLE MARK 'X' JAMMED BRAKE SUDDENLY, AND I IN VEHICLE MARKED 'A' ALSO HAVE TO JAMMED BRAKE, THEN VEHICLE MARKED 'B' FAILS TO BRAKE IN TIME AND IT COLLIDED WITH MY VEHICLE MARKED 'A'. AFTER THAT I WENT DOWN OF THE VEHICLE & CHECKED THE DAMAGES TAILGATE & BUMPER ARE DAMAGED & REQUIRED FURTHER INSPECTION & EVALUATION FROM THE WORKSHOP TO CONCLUD THE TOTAL DAMAGES INVOLVED/ CAUSE.

Attachment(s)


| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|---------------|
| Vehicle Registration Number | SKU87J |
| Vehicle Make/Model/Colour | PORSCHE BLACK |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | TAY PUAY FONG |
| NRIC/Passport Number | S6910419C |
| Contact Number | 92982388 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WHEN I WAS TRAVELLING TO WORK SITE ALONG A14, I WAS IN THE VEHICLE MARKED 'X' JAMMED BRAKE SLOWLY, AND I IN VEHICLE MARKED 'A' ALSO WERE IN JAMMED BRAKE, THEN VEHICLE MARKED 'E' FAILS TO BRAKE IN TIME AND IT COLLIDED WITH MY VEHICLE MARKED 'A'.

AFTER THAT I WENT DOWN OF THE VEHICLE & CHECKED THE DAMAGES; TAILGATE & BUMPER ARE DAMAGED & ROLLERS. FURTHER INSPECTION & EVALUATION FROM THE WORKING IN SKECHES LOCATED THE TOTAL DAMAGES INVOLVED/CAUSE.

DECLARATION

I hereby declare that foregoing statements are true in every respect.

[Signature] 15/11/19
 Policyholder's Signature 12:55pm
 Date & Time

Driver's Signature
 (If driver is not the policyholder)
 Date & Time

[Signature]
 Reporting Officer's Signature
 Name: L. J. J. (196) 1000 1000
 Date & Time: 15/11/2019 12:55pm

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 15/11/19
12:48 pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: William Chow Vm KHIONG
NRIC/FIN No.: 93414 49802

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7937306J



Name
ONG KYE FONG, JERRY

Race
CHINESE

Date of birth
25-11-1975

Sex
M

Country of birth
SINGAPORE

4675110

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE - DRIVING LICENCE



My Number: **S7937306J**

Name
ONG KYE FONG, JERRY

Date from: **25 Nov 1975**

Valid from: **21 Mar 2003**

4675110

FOR C&C USE ONLY

4675110



NR ID: **S7937306J**



Date of issue
01-02-2011

APT BLK 310C FUNGSI WALK #02-010
SINGAPORE 623310

HNC No: **S7937306J** Date: **04/03/2010 (R)**

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2000 kilograms

Valid from: **17 Mar 2003**

4675110

FOR C&C USE ONLY

NR 422A





COVER NOTE

KIA AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby **HELD COVERED** on the terms and conditions of the policy issued by the Policyholder.

Name of Policyholder : ONG KYE FONG, JERRY
 Period of Insurance : 13 Dec 2018 to 13 Dec 2020
 Engine No. : D4HBJH373815
 Chassis No. : KNAPH01BMJ5465514



Vehicle No. :
 Cover Note No. : 1800149636
 Endorsement No. :
 Issued Date : 12 Dec 2018



ABOUT THE COVER

Make/Model : KIA SORENTO 2.2 A DIESEL
 Engine Capacity/Tonnage : 2,199.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2018
 Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 25 and/or has less than 3 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, speed-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with Motor Trade.

Loss of Use 1500cc - 1800cc

* Limitations rendered irrespective by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 180) and Section 25 of the Road Transport Act, 1987 (Singapore), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$500 Theft - \$2 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

ONG KYE FONG, JERRY - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 60338000

2. Cycle & Carriage Body & Panel Centre Add: 300 Pandan Gardens Singapore 600039 68844001

3. Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 109831 64378800

4. Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408050 67461000

For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour customer emergency hotline at +65 6332 0200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from Google Play Store.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.
 We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 180), Part IV of the Road Transport Act, 1987 (Singapore) and Motor Vehicles (Third-Party Risks) Rules, 1989 (Singapore). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

0804822341

CYCLE & CARRIAGE BRAND

230 ALEXANDRA ROAD

SINGAPORE 109930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. J. J.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

2018/12/14



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65661240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|------------------------|---|
| ONG KYE FONG, JERRY | Cust No/Name LCV07758/ONG KYE FONG, JERRY |
| BLK 310C PUNGGOL WALK | Reg No/Reg Date SMG3779B / 18/12/201 |
| #02-610 | Date In/Mileage / 0 |
| SINGAPORE 823310 | Chassis No KNAPH81BMJ5465514 |
| Contact No | Engine No D4HBJH373815 |
| | Make/Model KIA/SORENTO 2.2 A D SX SR GDS7 |
| | Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|--|----------------|-------------------|------------|-------------------|-------------------------|
| LCV07758 | CRDVCH | 20/11/2019/ 09:29 | QUK | 282 / Kevin Leong | 62214 |
| Description of Goods / Services | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 TO RENEW REAR BUMPER, REAR TAILGATE & AFFECTED AREA TO REPAIR ON END PANEL | | | | | 1100 2200.00 |
| E PNT98000 PAINT WORK ON REAR BUMPER, REAR TAILGATE & END PANEL | | | | | 840 1680.00 |
| E PNT88000 TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR | | | | | ✓ 160.00 |
| E PNT88000 TO TRANSFER REAR TAILGATE ATTACHMENTS TO NEW PANEL | | | | | ✓ 120.00 |
| E PNT88000 TO REMOVE & INSTALL REAR PARKING ASSIST | | | | | 80 120.00 |
| M SUNDRY TO APPLY BODY SEALANT | | | | | ✓ 80.00 |
| M SUNDRY PERFORM RUST PREVENTION | | | | | 60 80.00 |
| A 54900099 CHECK ELECTRICAL SYSTEM | | | | | 60 80.00 |
| A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | | | | | ✓ 180.00 |
| M SUNDRY SUNDRIES | | | | | 20 50.00 |
| M W/STRIP-TAIL GATE OPNG | Rec ✓ | 1.00 | 128.00 | 00.00 | 128.00 |
| M LOGO ASSY-KIA SUB | Rec ✓ | 1.00 | 69.00 | 00.00 | 69.00 |
| M EMBLEM-SORENTO | Rec ✓ | 1.00 | 28.00 | 00.00 | 28.00 |
| M EMBLEM-ECO DYNAMICS | Rec ✓ | 1.00 | 37.00 | 00.00 | 37.00 |
| M GLASS ASSY-TAIL GATE | ? photo? x n ✓ | 1.00 | 690.00 | 00.00 | 690.00 |
| M COVER ASSY-RR BPR UNDER | X SUC ✓ | 1.00 | 30.00 | 00.00 | 30.00 |
| M CAP-RR HOOK | cut ✓ | 1.00 | 5.00 | 00.00 | 5.00 |
| M SKID PLATE-RR BUMPER | ? ✓ SUC ✓ | 1.00 | 90.00 | 00.00 | 90.00 |
| M COVER-RR BUMPER LWR | ? ✓ SUC ✓ | 1.00 | 565.00 | 00.00 | 565.00 |
| M RETAINER-BUMPER MTG | ? X SUC ✓ | 1.00 | 2.00 | 00.00 | 2.00 |
| M COVER-BLANKING RR FOG, LH | X SUC ✓ | 1.00 | 11.00 | 00.00 | 11.00 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



GST Reg No : MR-8500111-X

Co Reg No : 199405410K

| Invoice Name & Address | Owner Name & Vehicle Info | |
|------------------------|---------------------------|-------------------------------------|
| ONG KYE FONG, JERRY | Cust No/Name | LCV07758/ONG KYE FONG, JERRY |
| BLK 310C PUNGGOL WALK | Reg No/Reg Date | SMG3779B / 18/12/201 |
| #02-610 | Date In/Mileage | / 0 |
| SINGAPORE 823310 | Chassis No | KNAPH81BMJ5465514 |
| Contact No | Engine No | D4HBJH373815 |
| | Make/Model | KIA/SORENTO 2.2 A D SX SR GDS7 |
| | Colour/Trim | DN9 RICH ESPRESSO / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|--------|-------------------|-----|-------------------|--------|
| LCV07758 | CRDVCH | 20/11/2019/ 09:29 | OUK | 282 / Kevin Leong | 62214 |

| Description of Goods / Services | | Qty | Unit Price | Disc% | Amount |
|---------------------------------|--------------------------------|------|------------|-------|---------|
| M | COVER-BLANKING RR FOG,RH | 1.00 | 44.00 | 00.00 | 44.00 |
| M | HOLDER-PARKING ASSIST SYSTEM N | 1.00 | 3.00 | 00.00 | 3.00 |
| M | HOLDER-PARKING ASSIST SYSTEM N | 1.00 | 3.00 | 00.00 | 3.00 |
| M | WIRING HARNESS-R.P.A.S | 1.00 | 240.00 | 00.00 | 240.00 |
| M | RAIL ASSY-REAR BUMPER | 1.00 | 341.00 | 00.00 | 341.00 |
| M | ANTENNA ASSY-SMARTKEY | 1.00 | 53.00 | 00.00 | 53.00 |
| M | BRACKET-RR BUMPER SIDE LWR,LH | 1.00 | 13.00 | 00.00 | 13.00 |
| M | BRACKET-RR BUMPER SIDE LWR,RH | 1.00 | 13.00 | 00.00 | 13.00 |
| M | BRACKET ASSY-RR BUMPER SIDE,LH | 1.00 | 25.00 | 00.00 | 25.00 |
| M | BRACKET ASSY-RR BUMPER SIDE,RH | 1.00 | 25.00 | 00.00 | 25.00 |
| M | ULTRASONIC SENSOR-S.P.A.S | 1.00 | 187.00 | 00.00 | 187.00 |
| M | ULTRASONIC SENSOR-S.P.A.S | 1.00 | 187.00 | 00.00 | 187.00 |
| M | PANEL ASSY-TAIL GATE | 1.00 | 1445.00 | 00.00 | 1445.00 |
| M | TRIM ASSY-RR TRANSVERSE | 1.00 | 59.00 | 00.00 | 59.00 |

SURVEYOR NAME :

SURVEYOR SIGNATURE: _____

DATE : _____

REMARKS:

Confirm & accepted by

9858

| | | |
|-----------|---------|----------|
| | Nett | 9,043.00 |
| 7% GST on | 9043.00 | 633.01 |

| | |
|---------------|----------|
| Total Payable | 9.676.01 |
|---------------|----------|

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



TP CLAIM
CHINA TAIPIING
Rasul

VEHICLE NO : SMG 3779B

MODEL : KIA/SORENTO 2.2 A D SX

WIP : 62214

| | | | |
|--------------------|-------------------------|----|-----------------|
| Material | : | \$ | <u>2,982.00</u> |
| Labour | : | \$ | <u>2,900.00</u> |
| Sub-Total | : | \$ | <u>5,882.00</u> |
| Less 2% Disc | : | \$ | <u>-</u> |
| Less Excess | : | \$ | <u>-</u> |
| Total | : | \$ | <u>5,882.00</u> |
| GST 7% | : | \$ | <u>411.74</u> |
| Grand Total | : | \$ | <u>6,293.74</u> |
| Finalise By/Date : | <u>Ammy ON 10/01/20</u> | | |

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 07 WORKING DAYS + 2 days (wk. end)
+ 2 days P.H.

* TP VEHICLE NO: SKUB7J

* claim GIA search fee \$2.00

* claim loss of use.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------|---|
| ONG KYE FONG, JERRY | Cust No/Name LCV07758/ONG KYE FONG, JERRY |
| BLK 310C PUNGGOL WALK | Reg No/Reg Date SMG3779B / 18/12/2018 |
| #02-610 | Date In/Mileage 20/12/2019/ 24786 |
| SINGAPORE 823310 | Chassis/Package KNAPH81BMJ5465514 /KC17P |
| Contact No Mobile: 81395198 | Engine No 04HB3H373815 |
| 20/12/2019 | Make/Model KIA/SORENTO 2.2 A D SX SR GDS7 |
| | Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---|-------|-------------------|-----|----------------------|--------|------------|-------|-----------|
| CTP00080 | Cash | 10/01/2020/ 11:13 | TLK | 884 / Laura Songcuan | 62214 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | | | | | | | | 1100.00 ✓ |
| RENEW REAR BUMPER, REAR TAILGATE & AFFECTED AREAS | | | | | | | | 840.00 ✓ |
| E PNT98000 | | | | | | | | 160.00 ✓ |
| SPRAY PAINT ON REAR BUMPER & REAR TAILGATE | | | | | | | | 120.00 ✓ |
| E PNT88000 | | | | | | | | 80.00 ✓ |
| REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR | | | | | | | | 80.00 ✓ |
| E PNT88000 | | | | | | | | 60.00 ✓ |
| TRANSFER REAR TAILGATE ATTACHMENT TO NEW PANEL | | | | | | | | 60.00 ✓ |
| E PNT88000 | | | | | | | | 180.00 ✓ |
| REMOVE & INSTALL REAR PARKING ASSIST | | | | | | | | 20.00 ✓ |
| M SUNDRY | | | | | | | | 120.00 X |
| APPLY BODY SEALANT ON AFFECTED AREAS | | | | | | | | 80.00 X |
| M SUNDRY | | | | | | | | 128.00 ✓ |
| PERFORM RUST PREVENTION ON AFFECTED PORTIONS | | | | | | | | 69.00 ✓ |
| A 54900099 | | | | | | | | 28.00 ✓ |
| CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | | | | | | | | 37.00 ✓ |
| A 10028901 | | | | | | | | 5.00 ✓ |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST | | | | | | | | 565.00 ✓ |
| USING HI-SCAN PRO TEST | | | | | | | | 1445.00 ✓ |
| M SUNDRY | | | | | | | | 605.00 X |
| SUNDRIES | | | | | | | | |
| E PNT88000 | | | | | | | | |
| REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR → supp (A) | | | | | | | | |
| M SUNDRY | | | | | | | | |
| APPLY SEALANT FOR REAR WINDSCREEN → supp (A) | | | | | | | | |
| X W/STRIP-TAIL GATE OPNG ✓ | | | | | 1.00 | 128.00 | 00.00 | 128.00 ✓ |
| X LOGO ASSY-KIA SUB ✓ | | | | | 1.00 | 69.00 | 00.00 | 69.00 ✓ |
| X EMBLEM-SORENTO ✓ | | | | | 1.00 | 28.00 | 00.00 | 28.00 ✓ |
| X EMBLEM-ECO DYNAMICS ✓ | | | | | 1.00 | 37.00 | 00.00 | 37.00 ✓ |
| X CAP-RR HOOK ✓ | | | | | 1.00 | 5.00 | 00.00 | 5.00 ✓ |
| X COVER-RR BUMPER LWR ? | | | | | 1.00 | 565.00 | 00.00 | 565.00 ? |
| X PANEL ASSY-TAIL GATE ✓ | | | | | 1.00 | 1445.00 | 00.00 | 1445.00 ✓ |
| X COVER-RR BUMPER,UPR → supp. (A) | | | | | 1.00 | 605.00 | 00.00 | 605.00 X |

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------|---|
| ONG KYE FONG, JERRY | Cust No/Name LCV07758/ONG KYE FONG, JERRY |
| BLK 310C PUNGGOL WALK | Reg No/Reg Date SMG37798 / 18/12/2018 |
| #02-610 | Date In/Mileage 20/12/2019/ 24786 |
| SINGAPORE 823310 | Chassis/Package KNAPH81BMJ5465514 / KC17P |
| Contact No Mobile: 81395198 | Engine No D4HBJH373815 |
| 20/12/2019 | Make/Model KIA/SORENTO 2.2 A D SX SR GDS7 |
| | Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|-------|-------------------|-----|----------------------|--------|
| CTP00080 | Cash | 10/01/2020/ 11:13 | TLK | 884 / Laura Songcuan | 62214 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---|-------|------------|-------|--------|
| X CLIP → (A) | 10.00 | 1.00 | 00.00 | 10.00 |
| X SKID PLATE-RR BUMPER ? | 1.00 | 90.00 | 00.00 | 90.00 |
| Z TEXT | | | | |
| TP CLAIM CHINA TAIPING - SKU87J | | | | |
| DOA: 15/11/2019 | | | | |
| SURVEY: RASUL 20/12/2019 | | | | |
| 07 DAYS | | | | |
| Pro Forma | | | | |
| <i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i> | | | | |

| | | | |
|-----------------|----------|---------------|----------|
| Parts | 2,982.00 | Nett | 5,882.00 |
| Labour | 2,660.00 | 7% GST on | 411.74 |
| Standard Menu | 0.00 | | |
| Specialist Job | 0.00 | | |
| Diagnostics Job | 0.00 | Total Payable | 6,293.74 |
| Sundry/Others | 240.00 | | |
| Total(w/o GST) | 5,882.00 | | |

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO.: CHINA TAIPING

Supplementary For Registration No.: SMG 3779 B

| <u>Materials</u> | | <u>Cost (\$)</u> |
|--------------------|---|------------------|
| 1 | Cover- RR Bumper, UPR <i>SL</i> ✓ | 605.00 |
| 2 | Clip (10 pcs) <i>ne</i> ✓ | 10.00 |
| | | <u>615.00</u> |
| <u>Labour</u> | | |
| 1 | Remove & Install Rear Windscreen Glass to Facilitate Repair | 120.00 ✓ |
| 2 | Apply Sealant for Rear Windscreen | 80.00 ✓ |
| | | <u>200.00</u> |
| Materials & Labour | | 815.00 |
| 7% Gst | | 57.05 |
| Total | | <u>872.05</u> |

Thank You.

Yours faithfully

CYCLE & CARRIAGE KIA PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE
TEL: 6568 4658
FAX: 6567 5258

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 10 January 2020 12:26 PM
To: Songcuan JR Lauro Araos; Rasul (LKKAUTO); SUR
Cc: Admin A; Andre Chow En De; Loi Ai Ting; Jojo Cheng; Kevin Leong Wai Kit
Subject: RE: SMG3779B (KIA) - FINALIZE TP CLAIM (CHINA TAIPING)

Dear Larry,

WITHOUT PREJUDICE

Confirm finalized amount of \$ 5,882.00 before Gst @ 7 working days.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>

Sent: Friday, 10 January 2020 11:45 AM

To: Rasul (LKKAUTO) <Rasul@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Jojo Cheng <jojo.cheng@cyclecarriage.com.sg>; Kevin Leong Wai Kit <kevin.leong@cyclecarriage.com.sg>

Subject: SMG3779B (KIA) - FINALIZE TP CLAIM (CHINA TAIPING)

Dear Rasul,

Pls. refer to attached files.

Kindly confirm finalized amount of \$ 5,882.00 before Gst.

Thank you so much.

Best regards,

Larry Songcuan
Customer Service



CYCLE & CARRIAGE

Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---|---|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 10 Jan 2020 | | 10 Jan 2020 15:24 Edit Adj Rpt | \$5,882.00 Edit Estimates | \$5,882.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|--|------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by Insurer] | | | | | | | | | |
| Insured: -, ID: - | | | | | | | | | |
| Main Claimant: ONG KYE FONG JERRY , ID: S7937306 | | | | | | | | | |
| Vehicle Reg. No.: SMG3779B | | Date of Loss: 15/11/2019 08:00 - :59 [10 Months and 28 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: TP / SNM19D205440C02 | | Policy/Cover Note No.: DMPCSN30952018011 | | | | | | | |
| Vehicle Reg. No. (Insured): SKU87J | | Policy No. (Claimant): 1800149636 | | | | | | | |
| | | Excess: S\$0.00 | | | | | | | |
| Repairer: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens, 609339 West Coast - Tel: | | | | | | | | | |
| Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen] | | | | | | | | | |
| Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/01/2020] | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SMG3779B (SNM19D205440C02)
[SKU87J]

TP

ONG KYE FONG JERRY

Nov 15 2019 8:00AM

[-]

Cycle & Carriage KIA Pte Ltd

| | | | | | | | |
|--------------------|-----------------|--|--|--------------------|--|------------------------------------|-------------|
| Upload Documents | | Upload Photos | | Compose New Letter | | View <div>View in Browser</div> | |
| Video | | | | | | 1 per page <div></div> <div></div> | |
| No | Finalized On | Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) | | | | Thumbnail | Print |
| 1 | 15/11/19 18:41 | Video - Accident [Linked Accident Report Documents] | | | | <div></div> Load MP4 | |
| 2 | 15/11/19 18:41 | Video - Accident [Linked Accident Report Documents] | | | | <div></div> Load MP4 | |
| | | | | | | | |
| Assessment Reports | | | | | | 1 per page <div></div> <div></div> | |
| No | Finalized On | Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) | | | | Thumbnail | Print |
| 1 | 19/11/19 16:23 | Addendum Sheet | | | | <div></div> Load JPG | <div></div> |
| 2 | 06/12/19 19:29 | Accident Statement | | | | <div></div> Load HTM | |
| 3 | 06/12/19 19:34 | Accident Statement | | | | <div></div> Load HTM | |
| 4 | 06/12/19 19:37 | Accident Statement | | | | <div></div> Load HTM | |
| | | | | | | | |
| Photos/Images | | | | | | 3 per page <div></div> <div></div> | |
| No | Finalized On | Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) | | | | Thumbnail | Print |
| 1 | 15/11/19 18:04 | Accident Photo [Linked Accident Report Documents] | | | | <div></div> Load JPG | <div></div> |
| 2 | 15/11/19 18:04 | Accident Photo [Linked Accident Report Documents] | | | | <div></div> Load JPG | <div></div> |
| 3 | 15/11/19 18:04 | Accident Photo [Linked Accident Report Documents] | | | | <div></div> Load JPG | <div></div> |
| 4 | 15/11/19 18:04 | Accident Photo [Linked Accident Report Documents] | | | | <div></div> Load JPG | <div></div> |
| 5 | 15/11/19 18:04 | Accident Photo [Linked Accident Report Documents] | | | | <div></div> Load JPG | <div></div> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | Thumbnail | Print |
| 1 | 10/01/20 15:37 | General View | | | | <div></div> Load PDF | |
| 2 | 10/01/20 15:37 | Reinspection Photo | | | | <div></div> Load PDF | |
| | | | | | | | |
| Documentation | | | | | | 1 per page <div></div> <div></div> | |
| No | Finalized On | Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) | | | | Thumbnail | Print |
| 1 | 15/11/19 18:04 | Sketch Plan [Linked Accident Report Documents] | | | | <div></div> Load JPG | <div></div> |
| 2 | 15/11/19 18:25 | Common Statement [Linked Accident Report Documents] | | | | <div></div> Load JPG | <div></div> |
| 3 | 15/11/19 18:25 | Common Statement [Linked Accident Report Documents] | | | | <div></div> Load JPG | <div></div> |
| 4 | 15/11/19 18:25 | Common Statement [Linked Accident Report Documents] | | | | <div></div> Load TIF | |
| 5 | 15/11/19 18:25 | Driving License [Linked Accident Report Documents] | | | | <div></div> Load TIF | |
| 6 | 15/11/19 18:25 | Common Statement [Linked Accident Report Documents] | | | | <div></div> Load TIF | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | Thumbnail | Print |
| 1 | 14/01/20 09:19 | SUPPLEMENTARY PART | | | | <div></div> Load PDF | |

Linked Accident Report Documents

| | | | | | |
|--------------------|----------------|--|--|--|-------------------------------------|
| | | | | View View in Browser | |
| Video | | | | | |
| | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) | | Thumbnail | Print |
| 1 | 15/11/19 18:41 | Video - Accident FRONT DASH CAM | |  Load MP4 | |
| 2 | 15/11/19 18:41 | Video - Accident REAR DASH CAM | |  Load MP4 | |
| Assessment Reports | | | | | |
| | | | | 1 per page | <input checked="" type="checkbox"/> |

| Video | | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|--|---|------------|-------------------------------------|
| No | Finalized On | Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) | | Thumbnail | Print |
| No | Finalized On | Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) | | Thumbnail | Print |
| 1 | 19/11/19 16:23 | Addendum Sheet | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 06/12/19 19:25 | Accident Statement | 1 | Load HTM | |
| 3 | 06/12/19 19:28 | Accident Statement | 1 | Load HTM | |
| 4 | 06/12/19 19:29 | Accident Statement | 1 | Load HTM | |
| 5 | 06/12/19 19:29 | Accident Statement | 1 | Load HTM | |
| 6 | 06/12/19 19:30 | Accident Statement | 1 | Load HTM | |
| 7 | 06/12/19 19:30 | Accident Statement | 1 | Load HTM | |
| 8 | 06/12/19 19:31 | Accident Statement | 1 | Load HTM | |
| 9 | 06/12/19 19:31 | Accident Statement | 1 | Load HTM | |
| 10 | 06/12/19 19:34 | Accident Statement | 1 | Load HTM | |
| 11 | 06/12/19 19:34 | Accident Statement | 1 | Load HTM | |
| 12 | 06/12/19 19:35 | Accident Statement | 1 | Load HTM | |
| 13 | 06/12/19 19:37 | Accident Statement | 1 | Load HTM | |
| Photos/Images | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) | | Thumbnail | Print |
| 1 | 15/11/19 18:04 | Accident Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 15/11/19 18:04 | Accident Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 15/11/19 18:04 | Accident Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 15/11/19 18:04 | Accident Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 15/11/19 18:04 | Accident Photo THIRD PARTY VEHICLE | 1 | Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) | | Thumbnail | Print |
| 1 | 15/11/19 18:04 | Sketch Plan | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 15/11/19 18:25 | Common Statement | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 15/11/19 18:25 | Common Statement | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 15/11/19 18:25 | Common Statement | 1 | Load TIF | |
| 5 | 15/11/19 18:25 | Driving License | 1 | Load TIF | |
| 6 | 15/11/19 18:25 | Common Statement | 1 | Load TIF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119020729/R1VD3Q2

Date: 14/01/2020

REFERENCE

| | | | |
|-----------------------|---|----------------------|-------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMPCSN30952018011 |
| Claimant Vehicle No : | SMG3779B | Insured Vehicle No : | SKU87J |
| Date of Loss: | 15/11/2019 | Nature of Claim: | TP |
| | | Claim No: | SNM19D205440C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SMG3779B | Engine No: | D4HBH373815 |
| Make & Model: | KIA SORENTO, 2.2 (A) | Chassis No: | KNAPH81BMJ5465514 |
| Reg. Date: | 18/12/2018 (Man. Year: 2018) | Odometer: | 24786 km |
| Colour: | Black | | |
| Engine Capacity: | 2199 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 235/60 R18 | Rear Tyre Size: | 235/60 R18 |
| Front Left Side: | Yokohama 6 mm | Rear Left Side: | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|-----------------|-----------------|--------------|
| Parts | 4,958.00 | 3,002.00 | 1,956.00 | 39.45 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,900.00 | 2,880.00 | 2,020.00 | 41.22 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 9,858.00 | 5,882.00 | 3,976.00 | 40.33 |
| + GST 7.00/7.00% (S\$) | 690.06 | 411.74 | 278.32 | 40.33 |
| Nett Amount (S\$) | 10,548.06 | 6,293.74 | 4,254.32 | 40.33 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 10/01/2020 | |
| Date Inspected: | 20/12/2019 Inspected At: | Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339 |
| Estimated Period of Repair: | 7.0 days | |

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|----------------------|--|---|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 13 Jan 2020) |
| Parts: | M1-SUV | KIA SORENTO 2.2 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMG3779B) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *SUNDRIES | Necessary | 50.00 FS | *20.00 FS |
| 2 | 1 | | *W/STRIP -TAIL GATE OPNG | Necessary | 128.00 FS | *128.00 FS |
| 3 | 1 | | *LOGO ASSY -KIA SUB | Necessary | 69.00 FS | *69.00 FS |
| 4 | 1 | | *EMBLEM -SORENTO | Necessary | 28.00 FS | *28.00 FS |
| 5 | 1 | | *EMBLEM -ECO DYNAMICS | Necessary | 37.00 FS | *37.00 FS |
| 6 | 1 | | *GLASS ASSY -TAIL GATE | Not Necessary | 690.00 FS | *- FS |
| 7 | 1 | | *COVER ASSY -RR BPR UNDER | Serviceable | 30.00 FS | *- FS |
| 8 | 1 | | *CAP -RR HOOK | Cut | 5.00 FS | *5.00 FS |
| 9 | 1 | | *SKID PLATE -RR BUMPER | Scratched | 90.00 FS | *90.00 FS |
| 10 | 1 | | *COVER-RR BUMPER LWR | Scratched | 565.00 FS | *565.00 FS |
| 11 | 1 | | *RETAINER -BUMPER MTG | Serviceable | 2.00 FS | *- FS |
| 12 | 1 | | *COVER -BLANKING RR FOG, LH | Serviceable | 11.00 FS | *- FS |
| 13 | 1 | | *COVER -BLANKING RR FOG, RH | Not Necessary | 44.00 FS | *- FS |
| 14 | 1 | | *HOLDER -PARKING ASSIST SYSTEM N | Not Necessary | 3.00 FS | *- FS |
| 15 | 1 | | *HOLDER -PARKING ASSIST SYSTEM N | Not Necessary | 3.00 FS | *- FS |
| 16 | 1 | | *WIRING HARNESS -R.P.A.S | Not Necessary | 240.00 FS | *- FS |
| 17 | 1 | | *RAIL ASSY -REAR BUMPER | Not Necessary | 341.00 FS | *- FS |
| 18 | 1 | | *ANTENNA ASSY -SMARTKEY | Not Necessary | 53.00 FS | *- FS |
| 19 | 1 | | *BRACKET-RR BUMPER SIDE LWR ,LH | Not Necessary | 13.00 FS | *- FS |
| 20 | 1 | | *BRACKET-RR BUMPER SIDE LWR ,RH | Not Necessary | 13.00 FS | *- FS |
| 21 | 1 | | *BRACKET ASSY -RR BUMPER SIDE ,LH | Not Necessary | 25.00 FS | *- FS |
| 22 | 1 | | *BRACKET ASSY -RR BUMPER SIDE ,RH | Not Necessary | 25.00 FS | *- FS |
| 23 | 1 | | *ULTRASONIC SENSOR -S.P.A.S | Not Necessary | 187.00 FS | *- FS |
| 24 | 1 | | *ULTRASONIC SENSOR -S.P.A.S | Not Necessary | 187.00 FS | *- FS |
| 25 | 1 | | *PANEL ASSY -TAIL GATE | Bent | 1,445.00 FS | *1,445.00 FS |
| 26 | 1 | | *TRIM ASSY -RR TRANSVERSE | Not Necessary | 59.00 FS | *- FS |
| 27 | 1 | | *COVER -RR BUMPER ,UPR | Scratched | 605.00 FS | *605.00 FS |
| 28 | 10 | | *CLIP | Necessary | 10.00 FS | *10.00 FS |

F=Franchise part, S=SpcNett.

| | | |
|---------------------------|-----------------|-----------------|
| Total Parts (\$\$) | 4,958.00 | 3,002.00 |
|---------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR | New | 120.00 | 120.00 |
| 2 | APPLY SEALANT FOR REAR WINDSCREEN | New | 80.00 | 80.00 |
| 3 | TO RENEW REAR BUMPER ,REAR TAILGATE & AFFECTED AREA TO REPAIR ON END PANEL | New | 2,200.00 | 1,100.00 |
| 4 | PAINT WORK ON REAR BUMPER ,REAR TAILGATE & END PANEL | New | 1,680.00 | 840.00 |
| 5 | TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR | New | 160.00 | 160.00 |
| 6 | TO TRANSFER REAR TAILGATE ATTACHMENTS TO NEW PANEL | New | 120.00 | 120.00 |
| 7 | TO REMOVE & INSTALL REAR PARKING ASSIST | New | 120.00 | 80.00 |
| 8 | TO APPLY BODY SEALANT | New | 80.00 | 80.00 |
| 9 | PERFORM RUST PREVENTION | New | 80.00 | 60.00 |
| 10 | CHECK ELECTRICAL SYSTEM | New | 80.00 | 60.00 |
| 11 | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI -SCAN PRO TEST | New | 180.00 | 180.00 |
| Gross Labour Cost (S\$) | | | 4,900.00 | 2,880.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >