

ASS. REC. BY:

REF:

C1/TPD19020751/Pa

Special Instructions:

SURVEYOR

ASSIGNMENT (Office)

FROM (Person): Kamaliah Kamis

of

SPF

Date/Time: 21/11/2019

Estimated Cost:

Bill to:

OD+TP+WS+TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SL 2103T

Insured:

at Workshop m/s

**Tek:**

of

Policy No: MHA SP F060000 2841211

Claim No: TP 1P 70391 2019

**Surv Insured:**

Excess:

D.O.A. 12/11/2019

Make of Veh: \_\_\_\_\_  
(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction ( )	Estimate
-----------	------------------------	----------

84-2103T-X

500/9

E55  
kg m-

New Cases

21/11/2019

**Sherwin Beh (LKK Auto)**

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
**Sent:** Thursday, 21 November, 2019 12:21 AM  
**To:** Sherwin Beh (LKK Auto); Naz (LKKAuto)  
**Cc:** Bryan Ang (LKKAuto); SPF-TP FAIT; David DY YAP (SPF); NOORHIDAYAH ABDULLAH (SPF)  
**Subject:** Mechanical Inspection Report Request

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **19 vehicles** below: [The ones marked in RED are deemed to be URGENT hence please EXPEDITE ON THESE REQUESTS]

a) **Case IAFP-IB-20191115 - Mechanical Inspection of Motor Car, SLL2103T (TP/IP/70391/2019)**

On 12 November 2019 (Tuesday) sometime before 3.29 p.m, the Accused was driving a motor car, SLL 2103T, exiting a car park gantry of Blk 288A Jurong East Street 21. When she exited the car park gantry, the Accused made a right turn heading towards the main road of Jurong East Street 21. While the Accused was in the midst of turning right, the Accused's frontal portion of the motor car collided onto the Deceased who was walking across the service road of Blk 288A Jurong East Street 21 from Accused right to left view. Upon impact, the Accused front right wheel ran over the Deceased. As a result of the accident, the Deceased sustained serious head and chest injuries. She was conveyed to Ng Teng Fong General Hospital (NTFGH) by the ambulance. On the same day, the Deceased succumbed to her injuries and was pronounced dead at NTFGH A & E at 4.36 p.m.

**Vehicles to be inspected:** SLL2103T - Driver (Accused)

IO In-Charge: SIO Dzul Hairie

- b) **Case IAFP-IB-20191115 - Mechanical Inspection of Motor Van, GBD9373U (TP/IP/71057/2019)**  
c) **Case IAFP-IB-20191115 - Mechanical Inspection of Bicycle (TP/IP/71057/2019)**

On 15 November 2019 (Friday) sometime before 10.14 a.m, the Accused was travelling on the left lane of 2-lanes along Bedok North Avenue 2 towards Bedok North Street 1. Approaching the signalised cross-junction of Bedok North Road, the Accused made a left turn into Bedok North Road towards New Upper Changi Road. While the Accused was in the midst of turning left, the Deceased cycled across the signalised pedestrian crossing from Accused left to right view. The frontal centre portion of the motor van collided onto the Deceased. As a result of the accident, the Deceased sustained serious head injuries. She was conveyed to Changi General Hospital (CGH) by the ambulance. On the same day, the Deceased succumbed to her injuries and was pronounced dead at CGH A & E at 12.31 p.m.

**Vehicles to be inspected:** GBD9373U - Driver (Accused)  
Bicycle - (Deceased)

IO In-Charge: IO Dzul Hairie

d) **Case IAFP-IB-20191115 - Mechanical Inspection of Pick-Up, JPT4189 (TP/IP/69661/2019)**

On 10 November 2019, Sunday at about 2130hrs, the first accident was a Minor hit & run involving this pick-up and a car along Orchard Boulevard. The Malaysian pick-up failed to stop and exchange