

ASS. REC. BY:

REF:

CS/SMD 190 20768/ K436

Special Instruction:

Surveyor

Kenny

ASSIGNMENT (Office)

From (Person):

Melvin Ye Yung Kong

of

SMD

Date/Time:

26.11.19 11.05am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

WC 9901C

Insured:

YN 4277Y

at Workshop m/s

AE Auto

Tel:

93825367

of

160 Sn ming drive #06-01

Policy No:

Claim No:

CMTD19054721 AGC

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time:

25.11.2019 11.37am

Person Contacted:

Ryan Soh

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

WC 9901C - X

YN 4277Y - X

27/11-

Sent email preli advise

ASS. REC. BY:

REF: JMO /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 / File pass to

61 Lnp B 3400h

Carbur

Cfled: 26016.25, 88%

RECEIVED 10 DEC 2019

Date/Time, File Pass to?

11/10/12 Typist

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair: 3

Resurvey No. of Trlp:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fixes

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

3400/-

| |
|-----|
| 440 |
| |
| |
| |
| |
| 440 |

Veh No:

WC 9901C

Yr Regn:

03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Cancron Mixe

Make:

Isuzu

C.C.

15681

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

125154

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JALCYH52SK 7000216

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: 110

2P5180 R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MICT / HTS / TPIR / SUMI

TOYO / YOKO or

Front

Rear

R/Bal. 22 99 mm

R/Bal. 22 33 mm

L/Bal. 22 99 mm

L/Bal. 22 33 mm

D.O.A. 22/11/19

D.O.I. 26/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 27 November 2019 4:53 PM
To: 'Ye, Yong Kang Melvin'; assignments; SUR
Cc: Henry, Irene James; Chan, Shu Hui Agnes; Autoexcel Engineering
Subject: RE: PRE REPAIR SURVEY FOR WC 9901C Our ref : CMTD1905472/AGC
Attachments: PRELI ADVISED OF WC 9901C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **WC 9901C**
Number of days (estimated) : 3 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Monday, 25 November 2019 11:05 AM
To: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Henry, Irene James <irene.henry@sompo.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>;
Autoexcel Engineering <aeexcel@singnet.com.sg>
Subject: RE: PRE REPAIR SURVEY FOR WC 9901C Our ref : CMTD1905472/AGC

Dear LKK Auto,

Please make the arrangement to survey for WC9901C on a without prejudice basis and revert with your preliminary report upon completion of survey to my colleague, Agnes.

Thank you.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1905472/AGC

Date: 27/11/2019

Our Ref: CS/SMO19020768/Ktf3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE P

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. WC 9901C.

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 26/11/2019 at the premises of M/s AE Auto and have the following to report: -

| | |
|--------------------------|-----------------|
| Workshop Estimate Amount | : S\$ 29,416.25 |
| Revised Estimate Amount | : S\$ 4,280.00 |
| "Check" Items Amount | : S\$ 0.00 |
| Market Value | : S\$ |
| LTA Reimbursement Value | : S\$ - |
| Nett Value | : S\$ - |

Description of Damage:

The vehicle sustained damages at the rear portion.



Repair days: 3

Comments/ Present Status:

Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

Nivitha (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Monday, 25 November 2019 11:05 AM
To: assignments; sur@lkkauto.com
Cc: Henry, Irene James; Chan, Shu Hui Agnes; Autoexcel Engineering
Subject: RE: PRE REPAIR SURVEY FOR WC 9901C Our ref : CMTD1905472/AGC

Dear LKK Auto,

Please make the arrangement to survey for WC9901C on a without prejudice basis and revert with your preliminary report upon completion of survey to my colleague, Agnes.

Thank you.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



or



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Autoexcel Engineering <aeexcel@singnet.com.sg>
Sent: Monday, 25 November, 2019 10:54 AM
To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Cc: Henry, Irene James <irene.henry@sompo.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>
Subject: RE: PRE REPAIR SURVEY FOR WC 9901C Our ref : CMTD1905472/AGC

Dear Sirs,

We wish to appoint LKK Auto Consultants - Kenneth Kong

Thank you

Best Regards
Ryan Soh
93825367

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Monday, November 25, 2019 10:48 AM
To: Autoexcel Engineering <aeexcel@singnet.com.sg>
Cc: Henry, Irene James <irene.henry@sompo.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>
Subject: RE: PRE REPAIR SURVEY FOR WC 9901C Our ref : CMTD1905472/AGC

Our Reference : CMTD1905472/AGC
Your Reference: WC9901C

Without Prejudice

Date: 25/11/2019

Attention:
AUTOEXCEL ENGINEERING

Dear Ryan,

ACCIDENT INVOLVING WC9901C & YN4277Y ON 22.11.2019

We refer to your Notice of Accident dated 25/11/2019.

Please be informed that Ms Agnes Chan is the handler of this case.

We regret to inform that we are unable to revert on liability for direct settlement as we have yet to receive our insured's accident report.

Kindly advise should you still require us to conduct survey on a "Without Prejudice" basis.

If you are agreeable to conduct survey on a "Without Prejudice" basis, we propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

| | Motor Surveyor | Surveyor | Selection (Indicate as tick) |
|---|------------------|----------------|------------------------------|
| 1 | Raleigh Services | Andrew Ow Yong | |
| | | Vincent Ng | |

| | | | |
|---|----------------------|---------------------------|--|
| 2 | LKK Auto Consultants | Kenneth Kong (North area) | |
| | | Marcus Chua (East area) | |
| | | Mohd Rasul (West area) | |
| | | Mohd Taufikh (West area) | |
| 3 | Priority Services | Jimmy Lee | |
| | | Lawrence Ng | |
| | | Jeffery Ong | |
| 4 | In House surveyor | Teo See Ling | |

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Autoexcel Engineering <aeexcel@singnet.com.sg>

Sent: Monday, 25 November, 2019 9:26 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: PRE REPAIR SURVEY FOR WC 9901C

Importance: High

Dear Officer,

Please help us arrange for pre repair survey.

Our vehicle – WC 9901C

Accident date – 22/11/2019

Your insure – YN 4277Y

Location – AE AUTO PTE LTD
160 SIN MING DRIVE # 06-01
SIN MING AUTOCITY (S) 575722

Please also let us have the list of surveyor to appoint.

Thank you

Regards
Ryan Soh
93825367

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 645 35654, 64591630
Fax: 64591698

Not Authorized
Call @ 3400h
Person After Pain
3 days

Date : 25/11/2019

QUOTATION -THIRD PARTY CLAIM

SOMPO INSURANCE SINGAPORE PTE LTD

Attn: Motor Claim Department . Officer In Charge

Accident on : 22/11/2019

Claim : Third Party Claim
Veh. No : WC 9901 C
Model : ISUZU CYH52S
Insured Ins: CHINA TAIPING

| QTY | PARTICULARS | AMOUNT | SURVEYOR |
|-----|--------------------------------------------|--------------|----------|
| | Your Insurer Vehicle No : YN 4277 Y | | |
| | LIST PARTS | | |
| 1 | TAILLAMP RH | \$ 580.00 | X |
| 2 | TAILLAMP SOCKET RH | \$ 400.00 | X |
| 1 | REAR No.PLATE HOLDER | \$ 180.00 | X |
| 1 | REAR No.PLATE LAMP | \$ 385.00 | X |
| | TOTAL PARTS : | \$ 1,545.00 | |
| | LESS 15% | \$ 1,806.25 | |
| | SPECIAL NETT | | |
| 1 | TAILAMP BRACKET | \$ 400.00 | X |
| 1 | REAR No.PLATE | \$ 50.00 | X |
| 1 | REAR GLUTTER GEAR & LEVER | \$ 2,850.00 | X |
| 1 | RERA GLUTTER | \$ 2,200.00 | X |
| 1 | HYDRAULIC FLUID | \$ 200.00 | X |
| 1 | REAR WHEELTOP ARCH ASSY RH | \$ 4,800.00 | X |
| 1 | REAR WHEELTOP ARCH MUDFLAP RH | \$ 480.00 | X |
| 1 | REAR SAFETY BAR | \$ 5,500.00 | ✓ 1500\$ |
| 2 | REAR SAFETY BAR BRACKETS | \$ 900.00 | X |
| 2 | REAR SAFETY BAR BRACKET SUPPORTS | \$ 2,200.00 | X |
| 1 | REAR LH TRAY | \$ 1,850.00 | ✓ 1100\$ |
| 1 | REAR LH TRAY BRACKET | \$ 480.00 | ✓ |
| | TOTAL S/NETT | \$ 21,910.00 | |
| | TOTAL PARTS : | \$ 23,716.25 | |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

| | | | |
|--|-----------------------------------------------------------------------------------------|--------------|------|
| | Balance b/f | \$ 23,716.25 | |
| | LABOUR CHARGES FOR REAR | | |
| | | | |
| | Labour charges dismantle whole rear damage area to do cutting welding on damage area | \$ 2,000.00 | Foot |
| | | | |
| | To do rear body chassis repair | \$ nn 800.00 | X |
| | | | |
| | To do spray painting on rear accident area | \$ 2,000.00 | 5000 |
| | | | |
| | To do anti rust, tuff coating . nn | \$ 200.00 | X |
| | | | |
| | Checking on wiring system, for rear nn | \$ 200.00 | X |
| | | | |
| | To replace hydraulic parts & refill fluid assy nn | \$ 500.00 | X |
| | | | |
| | LABOUR CHARGES | \$ 5,700.00 | |
| | | | |
| | Grand Total Parts & Labour : | \$ 29,416.25 | |
| | | | |
| | | 28973.25 | |

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

| | |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID: | 062D |

Vehicle Details

| | |
|-------------------------------|-------------------|
| Vehicle No.: | WC9901C |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 22 Nov 2019 |
| Vehicle Make: | ISUZU |
| Vehicle Model: | CYH52S |
| Primary Colour: | White |
| Manufacturing Year: | 2015 |
| Engine No.: | 6WG1426571 |
| Chassis No.: | JALCYH52SF7000216 |
| Maximum Power Output: | - |
| Open Market Value: | \$115,744.00 |
| Original Registration Date: | 01 Mar 2016 |
| First Registration Date: | 01 Mar 2016 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$5,788.00 |

Intended PARF Rebate Details

| | |
|-------------------------------|--------|
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |

Intended COE Rebate Details

| | |
|-----------------------------|-------------------------|
| COE Expiry Date: | 28 Feb 2026 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| QP Paid: | \$45,036.00 |
| COE Rebate Amount: | \$28,227.00 |
| Total Rebate Amount: | \$28,227.00 |

The information contained herein is correct as at 22 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--------------------|
| Date Of Report | 23/11/2019 12:43 |
| Date Of Accident | 22/11/2019 14:30 |
| Exact Location Of Accident | ALONG HOLLAND ROAD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|--------------------------|
| Vehicle Registration Number | WC9901C |
| Insured/Policyholder | |
| Name Of Registered Owner | DYNAMIC CONSTR ENGRG P L |
| CO Reg No | 2013270620 |
| Email Address | ANDY.LEE@POS.SG |
| Mobile Phone No | (LOCAL) +65-86523334 |
| Alternative Phone No | OFFICE-92366363 |

Vehicle Particulars

| | |
|------------------------------------------------------------------------------|--------------------|
| Manufacturer | ISUZU |
| Model | CYH 52S |
| Exact Purpose for which vehicle was being used at time of accident | WORK PURPOSE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | COMMERCIAL VEHICLE |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | MSIG INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | YES |
| Policy Number | B29130771MKF (COMP) |
| Cover Note Number | |

Driver

| | |
|----------------------|----------------------|
| Name of Driver | MAHALINGAM MURUGESAN |
| NRIC No | F7904257U |
| Date Of Birth | 10/02/1974 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 03/03/2014 |
| Driving Experience | 5 YEARS AND 8 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-86523334 |
| Fax Number | |
| Contact Number | OTHERS-86523334 |
| Email Address | NOEMAIL |

Address 1, SUNVIEW ROAD #06-32
 Postcode 627615
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : KUMAR
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN4277Y
 Vehicle Make/Model/Colour ISUZU LORRY
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver TANG ZHIJUN
 NRIC/Passport Number G2682824X
 Contact Number 65701880
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to renew policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

I consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



23 NOV 2019




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Attach Scene photo

A- WC 9901C
B- TN 4277Y

My vehicle stationery waiting for traffic light to turn green.
After around One to two minute
Suddenly a impact from rear
Vehicle TN 4277Y hit my vehicle rear.
Claiming third Party.
Attach accident Scene photo.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

X M. Anderson



Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|-----------------------------|------------|-------------------------------------------------------------------------------------|
| SOMPO INSURANCE SINGAPORE PL | | Ref : CS/SMO19020768/Ktf3e2 | | |
| 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623 | | Date : 18-12-2019 | |  |
| | | Code : SMO | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | YN 4277Y | Veh. Inspected | WC 9901C | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | CMTD1905472/AGC | Excess (\$) | 0.00 | |
| Assign From | MELVIN YE YONG KANG | Assign Date | 25/11/2019 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | ISUZU CYH52S | c.c | 15681 | |
| Engine No. | HIDDEN | Year of Reg. | 2016 | |
| Chassis No. | JALCYH52SF7000216 | Colour | WHITE | |
| Odometer | 125154 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | NIL | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 295/80 R22.5 (D) | HILO | 2/2 mm | |
| L/H Front Tyre | 295/80 R22.5 (D) | HILO | 2/2 mm | |
| R/H Rear Tyre | 295/80 R22.5 (D) | WEST LAKE | 3/3 mm | |
| L/H Rear Tyre | 295/80 R22.5 (D) | WEST LAKE | 3/3 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 22/11/2019 | Inspection Date | 26/11/2019 | |
| Survey held at | AE AUTO PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WC 9901C

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---------------------------------------------|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | TAILLAMP RH | SERVICEABLE | 580.00 | - |
| 2 | TAILLAMP SOCKET RH | SERVICEABLE | 400.00 | - |
| 1 | REAR NO. PLATE HOLDER | TO REPAIR SEE LABOUR | 180.00 | - |
| 1 | REAR NO. PLATE LAMP | SERVICEABLE | 385.00 | - |
| | LESS 15% DISCOUNT | | -231.75 | - |
| | | | 1,313.25 | - |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | TAILLAMP BRACKET (SN) | TO REPAIR SEE LABOUR | 400.00 | - |
| 1 | REAR NO. PLATE (SN) | SERVICEABLE | 50.00 | - |
| 1 | REAR GLUTTER GEAR & LEVER (SN) | TO REPAIR SEE LABOUR | 2,850.00 | - |
| 1 | REAR GLUTTER (SN) | TO REPAIR SEE LABOUR | 2,200.00 | - |
| 1 | HYDRAULIC FLUID (SN) | NOT NECESSARY | 200.00 | - |
| 1 | REAR WHEELTOP ARCH ASSY RH (SN) | TO REPAIR SEE LABOUR | 4,800.00 | - |
| 1 | REAR WHEELTOP ARCH MUDFLAP RH (SN) | SERVICEABLE | 480.00 | - |
| 1 | REAR SAFETY BAR (SN) | BENT | 5,500.00 | 1,500.00 |
| 2 | REAR SAFETY BAR BRACKETS (SN) | TO REPAIR SEE LABOUR | 900.00 | - |
| 2 | REAR SAFETY BAR BRACKET SUPPORTS (SN) | TO REPAIR SEE LABOUR | 2,200.00 | - |
| 1 | REAR LH TRAY (SN) | BENT | 1,850.00 | 1,100.00 |
| 1 | REAR LH TRAY BRACKET (SN) | DISTORTED | 480.00 | 480.00 |
| | | | 21,910.00 | 3,080.00 |
| <u>LABOUR</u> | | | | |
| | TO DO REAR BODY CHASSIS REPAIR. | NOT NECESSARY | 800.00 | - |
| | TO DO SPRAY PAINTING ON REAR ACCIDENT AREA. | | 2,000.00 | 500.00 |
| | TO DO ANTI RUST, TUFF COATING. | NOT NECESSARY | 200.00 | - |
| | CHECKING ON WIRING SYSTEM, FOR REAR. | NOT NECESSARY | 200.00 | - |

Report Ref No. CS/SMO19020768/Ktf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| | TO REPLACE HYDRAULIC PARTS & REFILL FLUID ASSY. | NOT NECESSARY | 500.00 | - |
| | LABOUR CHARGES DISMANTLE WHOLE REAR DAMAGE AREA TO DO CUTTING WELDING ON DAMAGE AREA. INCLUSIVE OF THE REPAIR OF REAR NO. PLATE HOLDER, TAILLAMP BRACKET, REAR GLUTTER GEAR & LEVER, REAR GLUTTER, REAR WHEELTOP ARCH ASSY RH, REAR SAFETY BAR BRACKETS AND REAR SAFETY BAR BRACKET SUPPORTS. | | 2,000.00 | 700.00 |
| | | | 5,700.00 | 1,200.00 |
| GRAND TOTAL | | | 28,923.25 | 4,280.00 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 3,400.00 |

Report Ref No. CS/SMO19020768/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.