

22/03/2012

ASS. REC. BY:

REF: (S) FCI 19020787 / BY f302

Special Instruction:

(CWS)

Supervisor: Lim

ASSIGNMENT (Office)

From (Person): Mevina Chia San San of FCI Date/Time: 25.11.19 12.24pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKH 907L Insured: SHA 865X

at Workshop m/s Ah Lim motor Tel: 64563637

of 176 Sh Ming Drive #05-12

Policy No: _____ Claim No: D19007329 MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS ^(imp) H.O.D. Endorsement: _____

Date/Time: 26.11.19 1.13p.m Person Contacted: Mei Li Vehicle-IN OUT

Date/Time	Action/Instruction (✓) : Estimate
	SKH 907L - X
	SHA 865X - (C3) CAI 150 / 1376 / Hijab 3h2 ROA - 05/07/2019

REF: FCI

ISS. REC. BY

ASSIGNMENT

From: _____ Date: 02/12/2019

Veh No: SKH 907 L Yr Regn: 26/11/2015
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: SKH 907 L
at Workshop m/s Ah Lim Motor
of 176 Sin Ming Drive # 02-12

Make: Volkswagen Sharan 2.0 c.c 1984
Colour Grey A/C: Insured / Std / NI / NA
Sp. Reading 54484 T/Radio: Insured / Std / NI / NA
Eng/No: CCZ482431
C/No: WVVZ8X7NZFV035921

Insured: _____
Policy No. _____
Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____
(Client's Record)

Steering: Inorder / Jammed / Leaked / Burnt or

Make of Veh: 4pm (waiting)

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 225/50/17
R: 225/50/17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value: 90,000/2

Front _____ Rear _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

R/Bal. 7 mm R/Bal. 7 mm

GIA / PR Seen: _____ Consistent? : Yes or No

L/Bal. 7 mm L/Bal. 7 mm

Est. Repairs: 3 days Res.: Yes or No

D.O.A. 17/11/2019 D.O.I. 2/12/2019

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at Ah Lim Motor

CA / REV / REP. / 24 HRS ^{1up}

Des. of Damages: FR / Rear / O/S / N/S / UIC / Rooftop or

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
4/12/19	Sent Preli by email
	L/S 1350/2 TCRim lin 2/12/19 (Red \$939-79, 41%)
	MV 90,000/2
	PV 70,375/2
	NV 19,625/2

RECEIVED 29 JAN 2020

TCRim lin 2/12/19

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 3

1) : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2) 29/1/20 Typist

Add Fee: : Site Insp (\$)

Survey Fee:	110
Transportation:	50
S + RS. SI	
Photos	19
Others	
TOTAL	179

Report Format:

Lump Sum / L&I: (\$) \$1350/2

: Interview (\$)

: Tech. Invs (\$)

: Weel end (\$)

Yvonne Wong (LKK Auto)

From: Kee Mui Hong - Ah Lim Motor @ Sin Ming <muihong@almsm.com.sg>
Sent: Wednesday, January 29, 2020 9:12 AM
To: TG Lim (LKK Auto)
Cc: Yvonne Wong (LKK Auto)
Subject: Re: Draft Finalisation SKH907L

Dear Mr Lim,

Noted and Thanks.

We are agreeable and will submit documents shortly.

Thanks !

Best Regards,

Kee Mui Hong
Ah Lim Motor @ Sin Ming
Tel : 64563637 Fax : 64563686

From: TG Lim (LKK Auto)
Sent: 23 January, 2020 12:28 PM
To: <mailto:muihong@almsm.com.sg>
Cc: Yvonne Wong (LKK Auto)
Subject: RE: Draft Finalisation SKH907L

Dear Mui Hong,

Can we finalise SKH907L at \$1350.00 with 3 repair days?

If you are agreeable with our offer, please contact Ms Yvonne Wong with the necessary documents.

Wishing you a Happy and Prosperous Lunar New Year



Best Regards,
TG Lim | Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: TeowGuan@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kee Mui Hong - Ah Lim Motor @ Sin Ming [mailto:muihong@almsm.com.sg]

Sent: Thursday, 23 January, 2020 11:08 AM

To: TG Lim (LKK Auto) <TeowGuan@lkkauto.com>

Subject: Draft Finalisation SKH907L

Dear Mr Lim,

Pls see attached the Draft Finalisation SKH907L for your approval.

Pls advise

Thanks

Best Regards,

Kee Mui Hong

Ah Lim Motor @ Sin Ming

Tel : 64563637 Fax : 64563686

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Wednesday, December 04, 2019 2:53 PM
To: 'CWS Motor Claims'
Cc: 'Merina Chia'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007325MFSH/1
Attachments: SKH907L DOA 17112019 REVERT.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SKH907L
Date of survey : 02/12/2019
Number of days : 3 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, November 25, 2019 1:14 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007325MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>

Sent: Monday, 25 November, 2019 12:24 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19007325MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007325MFSH

Date: 04 Dec 2019

Our Ref: CS/FCI19020787/Byf3

The Motor Claims Department
MS First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKH907L

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/12/2019 at the premises of M/s AH LIM MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 2,450.08 .
Revised Estimate Amount	: S\$ 1,351.77 .
“Check” Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages at the front o/s portion.



Yours faithfully

LIM TEOW GUAN
Licensed Appraiser

meili@almsm.com.sg

From: "CWS Motor Claims" <cwsmotorclaims@msfirstcapital.com.sg>
Date: Monday, November 25, 2019 11:43 AM
To: <MEILI@ALMSM.COM.SG>
Subject: PRI REQUEST : FC REF: SHA0865X. (D19007325MFSH) & TP REF: SKH907L. (SJX1085D)
ACCIDENT ON 17-11-2019

Dear Sir,

Thank you for informing us of your choice **LKK AUTO CONSULTANTS PTE LTD**, the surveyor will be appointed within 2 working days of your email.

Thanks and Regrds
MS First Capital Insurance Ltd
cwsmotorclaims@msfirstcapital.com.sg

25/11/2019

MOTOR SURVEY ASSIGNMENT

Date 19-11-2019 **Our Ref No.** D19007325MFSH

Accident Date 17-11-2019 **Claim Type.** Third Party

Insured Vehicle SHA0865X **Third Party Vehicle.** SKH907L

Survey Location 176 SIN MING DRIVE #05-12 SIN MING AUTOCARE

Contact Person. MEILI TAN - (SIN MING)

Contact No. 64563637/ 0 **Fax No.** 64563686

Survey Type DIRECT SETTLEMENT:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop AH LIM MOTOR COMPANY **Attention.** NIL

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge MERINA CHIA SAN SAN

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/11/2019 18:38
Date Of Accident	17/11/2019 12:30
Exact Location Of Accident	BACK ALLEY LANE BEHIND STRAND /RENDEZVOUS HOTEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH907L
Insured/Policyholder	
Name Of Registered Owner	DOREEN BARTH-TEO TUN LIN
NRIC No	S7801327C
Email Address	MAILDOT@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96925225
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	SHARAN 2.0 TSI AT 7N14H3 W/O SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00347338/02
Cover Note Number	26/11/2018 TO 25/11/2019

Driver

Name of Driver	DOREEN BARTH-TEO TUN LIN
NRIC No	S7801327C
Date Of Birth	31/01/1978
Occupation	OUTDOOR
Date Of Driving Pass	20/03/2000
Driving Experience	19 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96925225
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	MAILDOT@YAHOO.COM

Address 29 BUKIT TUNGGAL RD
 Postcode 309714
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 5
 Passenger 1 NAME: : IDRIES
 GENDER: : MALE
 Passenger 2 NAME: : KARL
 GENDER: : MALE
 Passenger 3 NAME: : KATE
 GENDER: : FEMALE
 Passenger 4 NAME: : SEAN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA865X
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN


Direct AS19
Vehicle: SKY 907L

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 18/11/19



 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: gerald
 NRIC/FIN No.: 18/11/2019



Sketch Plan Pg. 2

Date of accident: 17/11/2019 Time: 12.33pm Location: Back ALLEY Lane Behind STRAND HOTEL
 My Vehicle A: SKH 907L Vehicle B: SHA 865x Vehicle C: RENDEZVOUS HOTEL
 SKETCH PLAN near Bencoolan street



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17-11-2019, Sunday afternoon at about 12.30pm, I turned into the back alley where we can see Rendezvous Hotel and the back of Strand Hotel. I just fetched my children from NAFA at Bencoolan Street. It was a two-lanes, one-way carriage way. I was travelling straight on the left side of the two-way/one way lanes. A yellow taxi was seen turning out from a car park. Driver of vehicle B did not give way to the travelling straight vehicle A. He turned out, not only ^{did not turn} onto the lane near him, he turned out into two-lanes, the left lane I was travelling on. Vehicles A and B collided. I stopped in time, but vehicle B still moved more onto vehicle A. In addition, he immediately reversed back. This had caused more dents and scratches on vehicle A. Driver of vehicle B had only offered \$50, maximum \$100 for to repair the damages. This amount is not reasonable and unrealistic to get the bumper fixed, sprayed, patched and done to good state. We have

Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only

Remarks: Please forward a copy of my efile accident report to:
 My workshop:
 Email address:
 & myself:
 Email address: maildot@yahoo.com

agreed that we will claim his insurance.

Note: Please take note that your Insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Vehicle: SKH 907L

Disseal
 Policyholder's Signature
 Date & Time: 18/11/2019 4:35pm

Disseal
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 18/11/2019 4:35pm

[Signature]
 Reporting Centre Personnel's Signature
 Name: Gerald
 NRIC/FIN No.:
 18/11/2019
 AH LIM MOTOR COMPANY

Policy ID : **MT/00347228/02**

Policyholder/Car
Owner : DOREEN TUN LIN BARTH-TEO

Declared Main
Driver : DOREEN TUN LIN BARTH-TEO

Vehicle Registration
No. : SKH907L

Plan Type : Comprehensive

Driver Plan : Value Plus Plan

Period of Insurance : 26/11/2018 to 25/11/2019

Vehicle Usage : Private Use

No Claim Discount : 30%

Policy Excess : S\$ 600.00 (before any applicable
GST)

Based on the information provided and coverage selected, you are covered under the following driver plan:

Value Plus Plan: in addition to the Main Driver and any Name Driver(s) under the policy, authorized drivers who are 30 years old and above* and with 2 or more years of valid driving licenc

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	327C
Vehicle Details	
Vehicle No.:	SKH907L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Nov 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SHARAN 2.0 TSI AT 7N14H3 W/O SR
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	CCZ482431
Chassis No.:	WVWZZZ7NZFV035921
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$37,823.00
Original Registration Date:	26 Nov 2015
First Registration Date:	26 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$44,953.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2025
PARF Rebate Amount:	\$33,714.00
Intended COE Rebate Details	
COE Expiry Date:	25 Nov 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,103.00
COE Rebate Amount:	\$36,661.00
Total Rebate Amount:	\$70,375.00

The information contained herein is correct as at 18 Nov 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	327C
Vehicle Details	
Vehicle No.:	SKH907L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Nov 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SHARAN 2.0 TSI AT 7N14H3 W/O SR
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	CCZ482431
Chassis No.:	WVWZZZ7NZFV035921
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$37,823.00
Original Registration Date:	26 Nov 2015
First Registration Date:	26 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$44,953.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2025
PARF Rebate Amount:	\$33,714.00
Intended COE Rebate Details	
COE Expiry Date:	25 Nov 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,103.00
COE Rebate Amount:	\$36,661.00
Total Rebate Amount:	\$70,375.00

The information contained herein is correct as at 18 Nov 2019

OK

MOTOR CAR (Fr)

Front Portion

Vehicle No: SHK-907L

NAC	INC	Item	CON	AC	Qty
1001	991886	Frnt Number Plate			
1002	991887	Frnt Number Plate Base			
1003	991889	Frnt Number Plate Garnish			
1004	991300	Frnt Bumper			
1005	992341	Frnt Bumper Clips			
1006	991325	Frnt Bumper Bracket			
1007	991462	Frnt Bumper Side Retainer			
1008	991433	Frnt Bumper Reinforcement			
1009	991318	Frnt Bumper Beam			
1010	991468	Frnt Bumper Sponge			
1011	991427	Frnt Bumper Protector			
1012	991420	Frnt Bumper Pad			
1013	991363	Frnt Bumper Grille			
1014	991301	Frnt Bumper Moulding			
1015	991407	Frnt Bumper Lower Spoiler			
1016	991438	Frnt Bumper Sensor			
1017	995100	Frnt LH Bumper Fog Lamp Cover			
1018	991355	Frnt RH Bumper Fog Lamp Cover			
1019	995079	Frnt LH Bumper Fog Lamp			
1020	995080	Frnt RH Bumper Fog Lamp			
1021	991793	Frnt Grille			
1022	991328	Frnt Grille Emblem			
1023	991799	Frnt Grille Chrome Moulding			
1024	991222	Frnt Apron Panel			
1025	992013	Frnt Support Panel			
1026	992025	Frnt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frnt Brace Panel			
1029	995153	Frnt LH Headlamp Assy			
1030	991821	Frnt RH Headlamp Assy			
1031	995088	Frnt LH Side Lamp			
1032	995089	Frnt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frnt Exhaust Manifold			
1064	991713	Frnt Exhaust Manifold Cover			
1065	991054	Frnt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frnt LH Chassis Member			
1093	991520	Frnt RH Chassis Member			
1094	990728	Frnt Vertical Cross Member			
1095	991863	Frnt Lower Cross Member			
1096	995070	Frnt LH Fender			
1097	995072	Frnt LH Fender Inner Panel			
1098	995147	Frnt LH Fender Lamp			
1099	995148	Frnt LH Fender Protector			
1100	991740	Frnt LH Fender Inner Shield			
1101	995179	Frnt LH Mudflap			
1102	995170	Frnt LH Wheel Rim			
1103	994025	Frnt LH Rim Cover			
1104	995065	Frnt LH Tyre			
1105	995071	Frnt RH Fender			
1106	991739	Frnt RH Fender Inner Panel			
1107	991744	Frnt RH Fender Lamp			
1108	991752	Frnt RH Fender Protector			
1109	991740	Frnt RH Fender Inner Shield			
1110	991884	Frnt RH Mudflap			
1111	992087	Frnt RH Wheel Rim			
1112	994025	Frnt RH Rim Cover			
1113	995065	Frnt RH Tyre			
1114	992093	Frnt Windscreen Glass			
1115	992117	Frnt Windscreen Rubber			
1116	992108	Frnt Windscreen Moulding			
1117	992098	Frnt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frnt Wiper Arm			
1121	992142	Frnt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frnt Driver Seat			
1133	991922	Frnt RH Seat Belt Assy			
1134	991899	Frnt Passenger Seat			
1135	995182	Frnt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: 1

ADDRESS: TORUM

2/12/19

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	327C
Vehicle Details	
Vehicle No.:	SKH907L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Nov 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SHARAN 2.0 TSI AT 7N14H3 W/O SR
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	CCZ482431
Chassis No.:	WVWZZZ7NZFV035921
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$37,823.00
Original Registration Date:	26 Nov 2015
First Registration Date:	26 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$44,953.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2025
PARF Rebate Amount:	\$33,714.00
Intended COE Rebate Details	
COE Expiry Date:	25 Nov 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,103.00
COE Rebate Amount:	\$36,661.00
Total Rebate Amount:	\$70,375.00

The information contained herein is correct as at 18 Nov 2019

OK

Dep 1,540/yr
962/mth

MV 90,000/2
PV 70,375/2
NV 19,625/2

TG Lim
lim
2/12/19

Best Car Repair Workshops in Singapore

Browse more than 3,000 car workshops in Singapore.
You can read customers' reviews & ratings on their services too.

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2009 Toyota VELLFIRE 2.4Z A COE Till Mar 2029, \$76k



Low Mileage 125k, Good Condition, Family Car Driven By Driver, New Battery Tires Direct Owner StarAd

Browse by Category

Sort by Date Posted 20 results/page

6 vehicles

Volkswagen Sharan

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Volkswagen Sharan	Any	Any	2015	Any	Any	Any	All
	Volkswagen Sharan 2.0A TSI Sunroof	\$88,800	\$11,320 /yr	31-Jul-2015	1,984 cc	83,339 km	MPV	Available
Offer 1.98% Interest Rate! Purchase From An Award Winning Dealership! 1 Year Comprehensive Warranty Inclusive! STA Certified Accident Free Quality Pre Owned With Low Mileage And Agent Service History For Peace Of Mind. 100% Loan Approval With Our Flexibl... Cosmo Automobiles Posted: 02-Dec-2019 Tags: 2015 Volkswagen Sharan, 2015 volkswagen sharan, Volkswagen Sharan, volkswagen sharan, Volkswagen, Sharan, sharan, Used Volkswagen								
	Volkswagen Sharan 2.0A TSI	\$91,000	\$11,540 /yr	09-Nov-2015	1,984 cc	68,000 km	MPV	Available
1 Owner, Low Mileage Clocked. Lowest Depreciation! Well Maintained And Timely Serviced With Available Records With VW Now VAG. Comes With 3x Free Servicing With VAG. Wear And Tear Fully Replaced. Comes With In Built Foldable Child Seats. Great Space, Power... Bavarian Marques Pte Ltd Posted: 27-Nov-2019 Tags: 2015 Volkswagen Sharan, 2015 volkswagen sharan, Volkswagen Sharan, volkswagen sharan, Volkswagen, Sharan, sharan, Used Volkswagen								
	Volkswagen Sharan 2.0A TSI Sunroof	-	N.A	30-Jul-2015	1,984 cc	-	MPV	SOLD
1 Owner Only! High Loan And High Trade In Available. Just Serviced. Ideal 7 Seater MPV With Power, Comfort And Convenience. Powerful Engine Yet Very Comfortable Suspension Setup, Convenience Via Electric Sliding Door And Boot, Spacious 2nd And 3rd Row, Pr... Mayfair Motoring Posted: 31-Oct-2019 Tags: 2015 Volkswagen Sharan, 2015 volkswagen sharan, Volkswagen Sharan, volkswagen sharan, Volkswagen, Sharan, sharan, Used Volkswagen								
	Volkswagen Sharan 2.0A TSI	-	N.A	09-Nov-2015	1,984 cc	-	MPV	SOLD
Posted: 21-Oct-2019 Tags: 2015 Volkswagen Sharan, 2015 volkswagen sharan, Volkswagen Sharan, volkswagen sharan, Volkswagen, Sharan, sharan, Used Volkswagen								
	Volkswagen delivers 100,000th e-Golf	Launched in 2004, the e-Golf has been one of the most successful electric vehicles in Europe, having reached 100,000 delivered units. Read this article						
	Volkswagen Sharan 2.0A TSI	-	N.A	18-Dec-2015	1,984 cc	-	MPV	SOLD
Flexible Bank, In House Loan And Full Loan Available! 1 Owner. Low Mileage Done. Rare MPV With Good Value, Performance And Comfort For The Family! Trade In Welcome. Viewing Available In Showroom Daily, Hurry Call Now! SKL Automobile Pte Ltd Posted: 27-Sep-2019 Tags: 2015 Volkswagen Sharan, 2015 volkswagen sharan, Volkswagen Sharan, volkswagen sharan, Volkswagen, Sharan, sharan, Used Volkswagen								
	Volkswagen Sharan 2.0A TSI	-	N.A	17-Nov-2015	1,984 cc	-	MPV	SOLD
1 Owner, Full Sized German MPV Equipped With A 2L Turbo Engine And Mated To A Direct Shift Gearbox Ensuring You A Smooth And Powerful Drive! Spacious Cabin For 7 Adults To Travel In Comfort! Flat Folding Individual Rear Seats, Providing You With Endless Lugga... Posted: 10-Sep-2019 Tags: 2015 Volkswagen Sharan, 2015 volkswagen sharan, Volkswagen Sharan, volkswagen sharan, Volkswagen, Sharan, sharan, Used Volkswagen								

Save this search criteria, to get email alerts whenever a match is found.

Compare Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
 TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
 GST:M9-0009639-E RCB NO:06470300B

TP

Direct Area / MS
 1st
 Corp.

M/S : DOREEN BARTH-TEO TUN LIN
 29 BUKIT TUNGGAL ROAD
 SINGAPORE 309714

Estimate No: MCS1900200
 Date: 19 Nov 2019
 Policy No: MT/00347338/02
 Veh Reg No: SKH907L
 Make/Model: VOLKSWAGEN SHARAN 2.0

Choice: LKK
 Auto
 Tel: 6256-3861

ATTN:

Your Ref No: SKH907L
 Claim Type: Third Party
 Accident Date: 17/11/2019

Estimate Repair Cost to Vehicle No :SKH907L

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 FRONT BUMPER - TO INDENT	1 PC	1,399.69	1,399.69
2 FRONT FOG LAMP - RH	1 PC	388.96	388.96
		1,399.69	1,788.65
	Less 10%	139.97	178.87
		1259.72	1,609.79
LABOUR			
3 TO CHECK WIRING AND TO REINSTALL FRONT PARKING SENSOR	1 PC	30.00	30.00
4 TO DISMANTLE THE FORNT BUMPER & INSTALL LISTED PARTS BACK SAME	1 PC	350.00	200.00
5 TO SPRAY FRONT BUMPER	1 PC	300.00	200.00
		430.00	680.00
	Total		SS 2,289.79
	Add GST @ 7%		160.29
	Total Amount Payable		SS 2,450.08

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FOUR HUNDRED FIFTY AND CENTS EIGHT ONLY

For AH LIM MOTOR COMPANY

Lump sum repair
 Repair days 3

[Handwritten signature]
 5/12/19



AUTHORISED SIGNATURE

Terim Lin
 2/12/19
 160 hours

Parts 1259.72
 SN 0.00
 Labour 430.00
 1689.72
 @ 20% 337.94
 1351.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

L/S 1350/2 Terim Lin, 2/12/19

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : DOREEN BARTH-TEO TUN LIN
29 BUKIT TUNGGAL ROAD
SINGAPORE 309714

Estimate No: MCS1900200
Date: 19 Nov 2019
Policy No: MT/00347338/02
Veh Reg No: SKH907L
Make/Model: VOLKSWAGEN
SHARAN 2.0

ATTN:

Your Ref No: SKH907L
Claim Type: Third Party
Accident Date: 17/11/2019

Estimate Repair Cost to Vehicle No :SKH907L

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 FRONT BUMPER - TO INDENT	1 PC	1,399.69	CUT ✓
2 FRONT FOG LAMP - RH	1 PC	388.96	NDX
		1,788.65	
	Less 10%	178.87	1,609.79
LABOUR			
3 TO CHECK WIRING AND TO REINSTALL FRONT PARKING SENSOR	1 PC	30.00	✓
4 TO DISMANTLE THE FORNT BUMPER & INSTALL LISTED PARTS BACK SAME	1 PC	350.00	200.00
5 TO SPRAY FRONT BUMPER	1 PC	300.00	200.00
		680.00	680.00
		Total	SS 2,289.79
		Add GST @ 7%	160.29
		Total Amount Payable	SS 2,450.08

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FOUR HUNDRED FIFTY AND CENTS EIGHT ONLY

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
 TEL: 6456 3637 FAX: 6456 3686 Email: admin@alm.com.sg
 GST:M9-0009639-E RCB NO:06470300B

TH

Direct Aka/MS
 1st
 Corp.

M/S : DOREEN BARTH-TEO TUN LIN
 29 BUKIT TUNGGAL ROAD
 SINGAPORE 309714

Estimate No: MCS1900200
 Date: 19 Nov 2019
 Policy No: MT/00347338/02
 Veh Reg No: SKH907L
 Make/Model: VOLKSWAGEN SHARAN 2.0

ATTN:

Choice: LKK
 Auto
 Tel: 6256-3561

Your Ref No: SKH907L
 Claim Type: Third Party
 Accident Date: 17/11/2019

Yvonne

Estimate Repair Cost to Vehicle No :SKH907L

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 FRONT BUMPER - TO INDENT	1 PC	1,399.69	Cut ✓
2 FRONT FOGLAMP - RH	1 PC	388.96	N/A
		1,788.65	
	Less 10%	178.87	1,609.79
		1399.69	
	@ 10%	139.96	
		1259.73	
LABOUR			
3 TO CHECK WIRING AND TO REINSTALL FRONT PARKING SENSOR	1 PC	30.00	✓ 1259.73
4 TO DISMANTLE THE FORNT BUMPER & INSTALL LISTED PARTS BACK SAME	1 PC	350.00	200.00
5 TO SPRAY FRONT BUMPER	1 PC	300.00	200.00
		680.00	680.00 430.00
Total			SS 2,289.79
Add GST @ 7%			160.29
Total Amount Payable			SS 2,450.08 1689.73

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FOUR HUNDRED FIFTY AND CENTS EIGHT ONLY

@ 20% 337.95
 1351.78

For AH LIM MOTOR COMPANY

Lump sum repair
 Repair days 3



AUTHORISED SIGNATURE

Tim Lin
 2/12/19
 1600 hrs

HS 1,350/2

Tim
 23/11/2020

Tim Lin
 23/11/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19020787/Byf3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-02-2020	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 865X	Veh. Inspected	SKH 907L
Policy No.		Coverage (\$)	0.00
Claim No.	D19007325MFSH	Excess (\$)	0.00
Assign From	MERINE CHIA SAN SAN	Assign Date	25/11/2019
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN SHARAN 2.0	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WWWZZZ7NZFV035921	Colour	GREY
Odometer	54484	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R17	PIRELLI	7 mm
L/H Front Tyre	225/50 R17	PIRELLI	7 mm
R/H Rear Tyre	225/50 R17	PIRELLI	7 mm
L/H Rear Tyre	225/50 R17	PIRELLI	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/11/2019	Inspection Date	02/12/2019
Survey held at	AH LIM MOTOR COMPANY 176 SIN MING DRIVE #05-12 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 907L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER - TO INDENT	CUT	1,399.69	1,399.69
1	FRONT FOG LAMP - RH	NOT NECESSARY	388.96	-
	LESS 10% DISCOUNT		-178.87	-139.97
			1,609.78	1,259.72
	LABOUR			
	TO CHECK WIRING AND TO REINSTALL FRONT PARKING SENSOR.		30.00	30.00
	TO DISMANTLE THE FRONT BUMPER & INSTALL LISTED PARTS BACK SAME.		350.00	200.00
	TO SPRAY FRONT BUMPER.		300.00	200.00
			680.00	430.00
	GRAND TOTAL		2,289.78	1,689.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,350.00

Report Ref No. CS/FC119020787/Byf3e2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.