

22/11/2019

ASS. REC. BY:

Surveyor: Ram

REF: C83/CR19020810/Fcd302

Special Instruction:

ASSIGNMENT (Office)

From (Person): Bentong

of CTI

Date/Time: 26/11/19 @ 2:22pm

Estimated Cost:

Bill to:

GD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMJ 31094

Insured:

SLP 18079

at Workshop m/s

AKA Auto

Tel:

8188 0754

of

25 Kelci Bulkit Road 4 #05-36 Synergy

Policy No:

DMPCEN3079951800

Claim No:

SNM19D205564

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/11/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:07pm 26/11/19

Person Contacted:

Rachel

Vehicle

IN OUT

Date/Time	Action/Instruction	Estimated
	<u>SMJ 31094 - X</u>	<u>X</u>
	<u>SLP 18079 - X</u>	
	<u>Dismantle: 26/11/2019.</u>	

ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMTJ 3109U

at Workshop m/s AKA

of 25 KAKI BUKIT RD A # 05-36

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMTJ 3109U

Yr Regn: 03/06 / 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda civic

c.c 1799

Colour:

green

A/C: Insured / Std / NI / NA

Sp. Reading

21726.7

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMFD0163095202161

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225 / 45 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/11/19

D.O.I.

25/11/19

Survey held at

AKA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

rear & DIS rear & N/S rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No GIA

Range: \$9000 - \$11000

Repair days: 8 days

MV: \$36974.82

RV: \$14343.00

RV: \$22631.82

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Misc. Insp (\$

Survey Fee:

Transportation:

3 + RS. \$

Photos

Other:

190

190

190

Report Form 4

PRG.

Comp. Sign / Mark

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Nov 2019		29 Nov 2019 11:04 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	SATHEESHWARAN S/O VIJEYAN JAMES		
Vehicle Reg. No.:	SMJ3109U	Date of Loss:	22/11/2019 00:00 - :59
Claim Type:	TP / SNM19D205564	Policy/Cover Note No.:	DMPCSN30799518000
Vehicle Reg. No. (Insured):	SLP1807G	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Aka Auto (HQ) 25 Kaki Bukit Road 4, #05-58, Synergy@KB, 417800 Kaki Bukit - Tel: 81880754		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 10/12/2019]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Monday, 25 November 2019 2:22 PM
To: AKA AUTO
Cc: Chee So Chow; Claims Dept of CTI; assignments@lkkauto.com
Subject: RE: OUR REF: SNM19D205564-SLP1807G-BEN - notice of accident for SMJ3109U and your insured SLP1807G

WITHOUT PREJUDICE

Dear Sirs

We refer to your email below.

We noted that you are not agreeable to our proposed list of surveyors. We will assign our panel surveyor M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the pre repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please arrange for the survey.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: AKA AUTO <akaautopte@gmail.com>
Sent: Monday, November 25, 2019 1:16 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Chee So Chow <sochow.chee@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D205564-SLP1807G-BEN - notice of accident for SMJ3109U and your insured SLP1807G

Hi,

Any update sir?

Regards
Rachel

On Sun, 24 Nov 2019 at 9:50 AM, AKA AUTO <akaautopte@gmail.com> wrote:

Hi,

We refer to the above matter.

We regret to inform you that our client will not appoint any of the surveyors from your list provided in your letter dated today.

However, we are pleased to provide below a list of ten surveyors for your consideration.

Gilbert Leow Impact Analysis Consultant

Andy Ho Impact Analysis Consultant

Shandy Loh Impact Analysis Consultant

Michael Yap Mccoy Pte Ltd

Joshua Ong Delta-V Consultant

James Ong Delta-V Consultant

Nick Ng Delta-V Consultant

Loo Yee Khang Cozon Engineers

Alex Teo Cozon Engineers

Denise Yap Pal's Appraiser Pte Ltd

Kindly let us know if you agree or disagree to appointing any of the above surveyors within the timeline stipulated under the NIMA protocol.

Thank you.

Regards

Rachel

On Fri, 22 Nov 2019 at 2:48 PM, Ben Tang <Ben.Tang@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sirs

We refer to your email of 22.11.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

Without admission of liability, please provide our surveyor with repair estimates to facilitate direct settlement.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please coordinate with our surveyor immediately after the repair is completed.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Friday, November 22, 2019 3:31 PM

To: Ben Tang <Ben.Tang@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; akaaautopte@gmail.com

Subject: OUR REF: SNM19D205564-SLP1807G-BEN - notice of accident for SMJ3109U and your insured SLP1807G

Dear Ben,

Please conduct PRS for SMJ3109U.

Note : officer in charge – Ben Tang 63896175.

**** kindly quote our reference number when replying.*

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: AKA AUTO [<mailto:akaautopte@gmail.com>]

Sent: Friday, 22 November, 2019 2:28 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: notice of accident for SMJ3109U and your insured SLP1807G

hi,

attachment is the notice of accident for the above mentioned accident.

hope to hear from you soon.

Regards

Rachel

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

AKA AUTO PTE LTD
25 KAKI BUKIT ROAD 4
SYNERGY@KB #05-36, #05-37
SINGAPORE 417800

Date: 22/11/2019

To china taiping claims department
3 Anson Rd, #16-00 Springleaf Tower,
Singapore 079909

Dear Sir/Mdm,

NOTIFICATION OF ACCIDENT

Please be informed that an accident involving my/our vehicle no, SMJ3109U and vehicle(s) no. SLP1807G had taken place at / along Woodlands Drive 16 on date 22/11/2019 at time 12.15am.

Kindly let us know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

If we do not hear from you within 2 working days, we shall proceed to repair the vehicle without further notice and our client shall claim for the additional loss of use arising from the giving of this notification to you.

Please call Rachel 81880754 to arrange.

Yours sincerely,
Rachel

PRI

Date / Time	
Company Name	
Surveyor	
Contact No.	
Signature	

DISMANTLED PARTS

Date / Time	
Surveyor	

AFTER REPAIR

Date / Time	
Surveyor	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 621J

Vehicle Details

Vehicle No.: SMJ3109U
Vehicle to be Exported: No
Intended Deregistration Date: 27 Nov 2019
Vehicle Make: HONDA
Vehicle Model: HONDA CIVIC 1.8L 5AT
Primary Colour: Blue
Manufacturing Year: 2008
Engine No.: R18A14013161
Chassis No.: JHMFD16309S202161
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$26,221.00
Original Registration Date: 03 Jun 2009
First Registration Date: 03 Jun 2009
Transfer Count: 2
Actual ARF Paid: \$26,221.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Mar 2024
COE Category: B - Car (1601cc & above)
COE Period(Years): 5
PQP Paid: \$16,509.00
COE Rebate Amount: \$14,343.00
Total Rebate Amount: \$14,343.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Nov 2019

POA: 22/11/19

OK

Remaining: ⁴ 4 years 4 months 9 days (52.2)

Depri: \$8500/= \$708.33/=

52.2 x \$708.33 = \$36974.82

STEP INTO THE DRIVER'S SEAT WITH EXCLUSIVE DEALS

Tampines One | 22nd - 27th Nov 2019 | 10am - 10pm

FIND OUT MORE



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Renewal Coe Toyota Altis 1.6A



2.68% P.A. \$0 Down, \$0 Admin,
Mtuw from \$168, 2 Years
Warranty engine, gearbox
GV Credit [StarAd](#)



Browse by Category

« Back (1 2 3) Next »

Sort by Date Posted

20 results/page

41 vehicles

honda civic 1.8

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	honda civic 1.8		Any	Any	2009	Any	Any	Any	Available
	Honda Civic 1.8A VTI-S (New 5-yr COE)		\$66,800	\$13,350 /yr	08-Oct-2009	1,799 cc	-	Sedan	Available
Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Before The Car Is Gone.									
Posted: 26-Nov-2019 Tags: 2009 Honda Civic, 2009 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda									
	Honda Civic 1.8A VTI-S (COE till 06/2024)		\$41,800	\$9,100 /yr	01-Jul-2009	1,799 cc	91,500 km	Sedan	Available
Kah Motor Unit. Low Mileage Done. White Colour With Black Interior. Low-Risk Purchase, An Ideal Choice For Daily Commute. Call Our Sales Consultants For A Viewing Today.									
Inchcape Pre-Owned									
Posted: 24-Nov-2019 Tags: 2009 Honda Civic, 2009 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda									
	Honda Civic 1.8A VTI-S (COE till 04/2024)		\$38,800	\$8,810 /yr	22-Apr-2009	1,799 cc	118,000 km	Sedan	Available
Consignment Code: A506. Flexible And Attractive Loan Available. Trade In Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us, Ksport Collover (AUG 2019), Manual Lookalike Mugen...									
Posted: 15-Nov-2019 Tags: 2009 Honda Civic, 2009 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda									
	Honda Civic 1.8A (COE till 06/2024)		\$39,800	\$8,780 /yr	08-Jun-2009	1,799 cc	93,000 km	Sedan	Available
Excellent Condition Assured! Looks, Drive And Feels Like New, Pre Purchase Mechanical Inspection/STA Evaluation Welcomed. In House Loan/Bank Loan Available. Only! Kindly Call Us For A Viewing And Test Drive Today. Cheapest In The Market. Trade In, Scrap And Insur...									
Posted: 23-Nov-2019 Tags: 2009 Honda Civic, 2009 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda									
	Honda Civic 1.8A VTI-S (COE till 10/2024)		\$41,800	\$8,480 /yr	03-Nov-2009	1,799 cc	130,526 km	Sedan	Available
Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Before The Car Is Gone.									
Posted: 26-Nov-2019 Tags: 2009 Honda Civic, 2009 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda									
	Honda Civic 1.8A VTI-S (COE till 08/2024)		\$39,800	\$8,460 /yr	11-Aug-2009	1,799 cc	91,000 km	Sedan	Available
Low Ownership!Low Mileage!New Leather, Roof Lining, New Paintwork, No Repairs Needed, No Gimmicks!Loan And Insurance Flexibility!Hassle And Worry Free Purchase! In House 6 Months Comprehensive Warranty With 24/7 Breakdown Recovery Service. We W...									
Posted: 22-Nov-2019 Tags: 2009 Honda Civic, 2009 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda									
	Honda Civic 1.8A VTI-S (COE till 10/2024)		\$40,800	\$8,390 /yr	08-Oct-2009	1,799 cc	121,159 km	Sedan	Available
Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan									

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/11/2019 12:57
Date Of Accident	22/11/2019 00:15
Exact Location Of Accident	WOODLANDS DRIVE 16
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ3109U
Insured/Policyholder	
Name Of Registered Owner	SATHEESHWARAN S/O VIJEYAN JAMES
NRIC No	S9218621J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87874504
Alternative Phone No	OFFICE-87874504

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108369138
Cover Note Number	

Driver

Name of Driver	SATHEESHWARAN S/O VIJEYAN JAMES
NRIC No	S9218621J
Date Of Birth	29/05/1992
Occupation	INDOOR
Date Of Driving Pass	07/03/2017
Driving Experience	2 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87874504
Fax Number	
Contact Number	OFFICE-87874504
EMail Address	NOEMAIL

Address	BLK 617 WOODLANDS AVE 4 #06-543
Postcode	730617
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP1807G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature:
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

A - SMJ 3109U
B - SLP1807G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Front car slowing down hence I slowing down as well.
Suddenly CAR B hit onto my rear, the impact was
Strong.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

...CLAIM SUBFOLDER...(Pending for Survey Report)












































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2019		29 Nov 2019 11:04 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case
























































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: SATHEESHWARAN S/O VIJEYAN JAMES									
Vehicle Reg. No.: SMJ3109U		Date of Loss: 22/11/2019 00:00 - :59 [125 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D205564		Policy/Cover Note No.: DMPCSN30799518000							
Vehicle Reg. No. (Insured): SLP1807G		Policy No. (Claimant):							
		Excess: \$0.00							
Repairer: Aka Auto (HQ) 25 Kaki Bukit Road 4, #05-58, Synergy@KB, 417800 Kaki Bukit - Tel: 81880754									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 10/12/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






























Claim Documents

*SMJ3109U (SNM19D205564)
[SLP1807G]
TP
SATHEESHWARAN S/O VIJEYAN JAMES
Nov 22 2019 12:00AM
[-]
Aka Auto

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser](#)

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
2	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
3	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
4	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
5	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
6	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
7	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
8	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
9	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
10	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
11	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
12	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
13	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
14	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
15	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
16	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
17	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
18	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
19	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
20	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
21	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
22	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
23	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
24	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
25	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
26	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
27	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
28	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
29	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
30	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
31	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
32	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
33	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
34	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
35	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
36	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
37	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
38	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
39	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
40	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
41	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
42	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
43	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
45	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
46	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
47	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
48	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
49	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
50	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
51	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
52	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
53	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
54	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
55	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
56	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
57	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
58	29/11/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
59	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	29/11/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19020810/FCD3E2

Date: 29/11/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30799518000

Claimant
Vehicle No : SMJ3109UInsured Vehicle
No : SLP1807G

Date of Loss: 22/11/2019

Nature of Claim: TP

Claim
No: SNM19D205564

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMJ3109U

Make & Model: HONDA CIVIC, 1.8 L 5AT (A)

Engine No: R18A14013161

Reg. Date: 03/06/2009 (Man. Year: 2008)

Chassis No: JHMFD16309S202161

Colour: Green

Odometer: 217267 km

Engine Capacity: 1799 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/11/2019

Date Inspected: 25/11/2019 Inspected At:

25 KAKI BUKIT ROAD 4 # 05-36
Repairer : Aka Auto (HQ)

Estimated Period of Repair: 8.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 -\$11,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Nov 2019)
Parts:	143	HONDA CIVIC 1.8 L 5AT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ3109U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >