

PAR Automotive Consultancy

Regn. No. 1298/9742.

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0412-19-TCA

30 September 2019

ACCIDENT VEHICLE SURVEY REPORT

Lim Sok Mei
Blk 277C Compassvale Link #06-294
Singapore 543277

VEHICLE INFORMATION:

Vehicle Reg No.:	SKR1927U	Odometer:	085376km
Make & Model:	Honda Vezel 1.5G	Colour:	Blue
Chassis number:	RU11016050	Date of accident:	02/10/2018
Year of Regn.:	22/01/2015	Date inspected:	03/10/2018
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	15/10/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.















































































































