

ASS. REC. BY:

REF: es/c1119020817/As d3¹²

Special Instruction:

Surveyor: ArjunASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

28/11/19 @ 2:33pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Impact Vehicle No:

SMC 9653L

Insured:

SLB 5740L

at Workshop in/s

Soo Huk Kee

Tel:

6743 1913

of

Blk 3007 Ubi Road 1 # 01-406

Policy No:

Claim No:

SNM19D205597

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:15pm 28/11/19

Person Contacted:

Bridge

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimated
	<u>SMC 9653L - X</u>	<input checked="" type="checkbox"/>
	<u>SLB 5740L - X</u>	<input checked="" type="checkbox"/>

115 3400/1

ASSIGNMENT

From:

Date:

28/11/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SMC 9653L

at Workshop m/s

Joo Huk Kee

of Blk 3007 Ubi Road 1 # 01-406

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 10am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Imp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMC9653L

Yr Regn:

2018 / July

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra cc 1591

Colour:

Gray.

A/C:

Insured / Std / NI / NA

Sp. Reading

32114.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMH D841CMJU 727646

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

195/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

28/11/19.

Survey held at

JHK.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP China.

Adrian confirmed US \$3,400/- @ 6 days with Bass
(\$ 2,535.20 Red - 43%)

Date/Time, File Page to?

1) 19/02/20
Type: 4

Date/Time, File Return to?

2)

Report Format:

Lump Sum / J.E.B.G \$3,400/- US

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Wheel and (\$

Survey Fee:

Transportation:

5 x RS. 31

Phone:

Other:

TOTAL

220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 25 November 2019 2:33 PM
To: shimin poh
Cc: 'assignments'
Subject: RE: OUR REF: SNM19D205597/SLB5740L/CBS & YOUR REF: SMC9653L -NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SMC9653L/SLB5740L DOA 22/11/2019

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: shimin poh [mailto:shimin@jhk.com.sg]

Sent: Monday, November 25, 2019 2:10 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D205597/SLB5740L/CBS & YOUR REF: SMC9653L -NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SMC9653L/SLB5740L DOA 22/11/2019

Dear sir :

We choose lkk

Thank You !

Bridget Poh (Shimin)
Joo Hak Kee Auto Pte Ltd
Blk 3007 Ubi Road 1
#01-406 Singapore 408701
Office: 67431913

On Mon, Nov 25, 2019 at 1:41 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without prejudice
Dear Sir,
LKK
STA
LBS

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, November 25, 2019 11:31 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; shimin@jkh.com.sg

Subject: OUR REF: SNM19D205597/SLB5740L/CBS & YOUR REF: SMC9653L -NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SMC9653L/SLB5740L DOA 22/11/2019

Dear Boon Sen,

Please conduct PRS-SMC9653L soonest possible.

File with officer-in-charge- Chong Boon Sen- DID 6389 6171.

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: (65) 63896116 - F: (65) 6224 7478

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: shimin poh [<mailto:shimin@jhk.com.sg>]

Sent: Saturday, November 23, 2019 12:43 PM

To: Claims Dept of CTI

Subject: NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SMC9653L/SLB5740L DOA 22/11/2019

Dear Sir/Mdm,

Kindly arrange pre-repair survey for the above and if possible would like to do direct settlement.

Please provide us your list of surveyors for our selection. **VEH NOT IN, IN ON 25/11/2019 AFTER 10AM**

Attached is the accident report for your reference and we're currently in the midst of preparing the estimate.

Thank you and hope to hear from you soon.

Thank You !

Bridget Poh (Shimin)

Joo Hak Kee Auto Pte Ltd

Blk 3007 Ubi Road 1

#01-406 Singapore 408701

Office: 67431913

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

MJHK19154747 / Joo Hak Kee Auto Pte Ltd - HQ
 ENTRY DATE & TIME: 23/11/2019 11:58
 SUBMITTED BY: Poh Shi Min

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/11/2019 11:58
 Date Of Accident 22/11/2019 23:10
 Exact Location Of Accident AIRPORT BOULEVARD TOWARDS PIE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMC9653L
Insured/Policyholder
 Name Of Registered Owner NG GEK WOO
 NRIC No S1509331E
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-81125537
 Alternative Phone No Office-NOPHONE

Vehicle Particulars

Manufacturer HYUNDAI
 Model ELANTRA-1.6 AD GLS (A)
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5111419763
 Cover Note Number

Driver

Name of Driver NG JIN HAO, JACOB (HUANG JINHAO)
 NRIC No S9012792F
 Date Of Birth 12/04/1990
 Occupation INDOOR
 Date Of Driving Pass 26/03/2013
 Driving Experience 6 YEARS AND 7 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-92251912

Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 456 TAMPINES STREET 42 #10-282
Postcode	520456
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : KELLIE WOON Gender: : Female

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB5740L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SGT7446M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/11/19 at around 11:04pm @ Airport Boulevard. the traffic was jammed and I was stationary and vehicle behind of me bearing SLB5740L was stationary as well, suddenly I felt an impact then found out vehicle SKT7446M has knocked onto SLB5740L and in-turn bumped onto my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

2019/11/22 11:04 PM

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: Ng Gek Woo
 INSURER: China Taiping Insurance (Singapore) Pte. Ltd
 POLICY NO: 5111419763
 DOA: 22/11/2019

Shirley

REPAIR ESTIMATE

Est No. : EST19110008
 Date : 23-Nov-19
 Vehicle Num : SMC9653L
 Make/Model : Hyundai Elantra 1.6
 Chassis # : KMHD841CMJU727646
 Engine # : G4FGJU235518
 Yr. Of Manu : 2018

No.	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	Rear Bumper <i>Deformed</i>	1.00	459.40	459.40 ✓
2	Rear Bumper Reinforcement <i>Bent</i>	1.00	294.80	294.80 ✓
3	Rear Bumper Retainer RH/LH <i>Nee</i>	2.00	44.30	88.60 ✓
4	Rear Bumper Reflector RH/LH <i>Nee</i>	2.00	40.80	81.60 ✓
5	Rear Bumper Clips <i>Nee</i>	10.00	3.00	30.00 ✓
6	Reverse Sensor <i>Damaged</i>	2.00	132.00	264.00 ✓
7	Bootlid <i>Dented</i>	1.00	1782.40	1782.40 17615 ✓
8	Bootlid Inner Lock <i>Damaged</i>	1.00	116.20	116.20 ✓
9	Bootlid Inner Lock Hook <i>Nee</i>	1.00	18.00	18.00 ✓
10	Bootlid Logo	1.00	28.00	28.00 ✓
11	Bootlid "ELANTRA" Emblem	1.00	48.80	48.80 ✓
12	Bootlid "S" Emblem	1.00	21.00	21.00 ✓
13	Bootlid Inner Taillamp RH/LH	2.00	284.90	569.80 +
14	Bootlid Outer Taillamp RH/LH	2.00	362.60	725.20 +
15	Rear End Panel <i>Bent</i>	1.00	454.60	454.60 ✓
16	Rear End Panel Top Garnish <i>Deformed</i>	1.00	59.80	59.80 ✓
17	Bootlid Weaterstrip <i>Lot</i>	1.00	92.50	92.50 ✓
18	Bootlid Inner Trim <i>Nee</i>	1.00	146.80	146.80 +
Amt S\$				5281.50
Discount (20.00%) S\$				1056.30
Subtotal S\$				4225.20

Section: SPECIAL NETT ITEMS

19	Rear Number Plate With Cover <i>Not Nee</i>	1.00	50.00	50.00 +
Amt S\$				50.00
Discount (0.00%) S\$				0.00
Subtotal S\$				50.00

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: Ng Gek Woo
 INSURER: China Taiping Insurance (Singapore) Pte. Ltd
 POLICY NO: 5111419763
 DOA: 22/11/2019

REPAIR ESTIMATE

Est No. : EST19110008
 Date : 23-Nov-19
 Vehicle Num : SMC9653L
 Make/Model : Hyundai Elantra 1.6
 Chassis # : KMHD841CMJU727646
 Engine # : G4FGJU235518
 Yr. Of Manu : 2018

No.	Description	Qty	U/P	Amt
Section: LABOUR				
20	To Panel Beat on Necessary Damaged Parts	1.00	980.00	980.00 820
21	To Sand Down, Putty and Spray Paint on Necessary Damaged Parts	1.00	680.00	680.00 600
				Amt S\$ 1660.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1660.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Ling
 4/5 28/11/19

06 Days

total 425816

4/5 34K ✓

LIST ITEMS Subtotal S\$ 4225.20
 SPECIAL NETT ITEMS Subtotal S\$ 50.00
 LABOUR Subtotal S\$ 1660.00
Total S\$ 5935.20

Joo Hak Kee Auto Pte. Ltd.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119020817/ASD3N2
Date: 19/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30345819033
Claimant Vehicle No :	SMC9653L	Insured Vehicle No :	SLB5740L
Date of Loss:	22/11/2019	Nature of Claim:	TP
		Claim No:	SNM19D205597C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC9653L	Engine No:	G4FGJU235518
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU727646
Reg. Date:	30/07/2018 (Man. Year: 2018)	Odometer:	32114 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,275.20	2,858.16	1,417.04	33.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,400.00	260.00	15.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,935.20	4,258.16	1,677.04	28.26
Approved Total (Overridden) (S\$)		3,400.00		
	5,935.20	3,400.00	2,535.20	42.71
+ GST 7.00/7.00% (S\$)	415.46	238.00	177.46	42.71
Nett Amount (S\$)	6,350.66	3,638.00	2,712.66	42.71

INSPECTION

Date of Assignment:	19/02/2020		
Date Inspected:	28/11/2019	Inspected At:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406 Singapore 408701
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2020)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC9653L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	294.80 FL	*294.80 FL
3	2		*REAR BUMPER RETAINER RH/LH	Necessary	88.60 FL	*88.60 FL
4	2		*REAR BUMPER REFLECTOR RH/LH	Not Necessary	81.60 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
6	2		*REVERSE SENSOR	Damaged	264.00 FL	*264.00 FL
7	1		*BOOTLID	Dented	1,782.40 FL	*1,615.00 FL
8	1		*BOOTLID INNER LOCK	Damaged	116.20 FL	*116.20 FL
9	1		*BOOTLID INNER LOCK HOOK	Not Necessary	18.00 FL	*- FL
10	1		*BOOTLID LOGO	Necessary	28.00 FL	*28.00 FL
11	1		*BOOTLID ELANTRA EMBLEM	Necessary	48.80 FL	*48.80 FL
12	1		*BOOTLID S EMBLEM	Necessary	21.00 FL	*21.00 FL
13	2		*BOOTLID INNER TAILLAMP RH/LH	Not Necessary	569.80 FL	*- FL
14	2		*BOOTLID OUTER TAILLAMP RH/LH	Not Necessary	725.20 FL	*- FL
15	1		*REAR END PANEL	Dented	454.60 FL	*454.60 FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	59.80 FL	*59.80 FL
17	1		*BOOTLID WEATHERSTRIP	Cut	92.50 FL	*92.50 FL
18	1		*BOOTLID INNER TRIM	Not Necessary	146.80 FL	*- FL
19	1		*REAR NUMBER PLATE WITH COVER	Not Necessary	50.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	5,331.50	3,572.70
- List Item Discount on L Items 20.00/20.00% (S\$)	1,056.30	714.54
Total Parts (S\$)	4,275.20	2,858.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ON NECESSARY DAMAGED PARTS	New	980.00	800.00
2	TO SAND DOWN,PUTTY AND SPRAY PAINT ON NECESSARY DAMAGED PARTS	New	680.00	600.00
Gross Labour Cost (S\$)			1,660.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >