

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	15:05HRS
ACCIDENT DATE	19-Nov-19
BUS CAPTAIN NAME	GOH HAN SOON
THIRD PARTY CLAIM AGAINST	AIG INSURANCE

BUS REGISTRATION NUMBER	SMB3024Y
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

LKK Curvey - Rasu!

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	N/S/R CORNER BUMPER <i>de -</i>	1	\$678.00
2	STOP LAMP <i>con /</i>	2	\$226.60
3	FLASHER ASSY <i>con /</i>	1	\$319.30
4	N/S SIDE PANEL L7 <i>repar</i>	1	\$230.00
5	N/S SIDE PANEL L8 <i>repar</i>	1	\$230.00
6	N/S SIDE PANEL L10 <i>cut /</i>	1	\$682.00
7	N/S SIDE PANEL L11 <i>cut /</i>	1	\$760.00
8	ADVERTISEMENT STICKER <i>na /</i>	* SPECIAL NETT *	3500 \$500.00
		7% GST	\$253.81
		PARTS TOTAL COST	\$3,879.71

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE DAMAGED BODY PARTS <i>1950</i>	2560 \$3,250.00
SPRAY PAINTING	<i>2560</i> \$3,200.00
TO REMOVE REPLACE ADVERTISEMENT STICKER * SPECIAL NETT BY CONTRACTOR *	<i>1500</i> \$1,800.00
	7% GST
	\$577.50
	LABOUR TOTAL COST
	\$8,827.50

SPRAY PAINTING \$640 PER PANEL

LABOUR CHARGES \$650 PER DAY

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN	25/11/2019
		DATE OUT	
BUS TYPE (SD / DD)	SD	TOTAL NUMBER OF DAYS	
LOSS OF USE COST			

SUMMARY	
SECTION NO.	COST
1	\$3,879.71
2	\$8,827.50
3	-
4	\$0.00
GRAND TOTAL	\$12,707.21

Resue
Hf 90010068
5 days
25/11/19 @ 1445
Resue before paint

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: