

Ram

cc3/TMI19020856/Psd307

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: **XD 853A**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

/	
N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SHD3093X** Yr Regn: **22/12/2016**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / **Taxi** / Prime Mover /
 Truck / Trailer or _____
 Make: **Hyundai i40** C.C. **1685**
 Colour: **Blue** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **293986** T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **KMHLB41UMHV097257**
 Gen. Cond: **Good** / Fair / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Modi: **Nil** / S/Rim / **STD A/Rim** or
 Tyre Size: F: **205/60 R16**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Hankook**
 Front Rear
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. **22/11/19** D.O.I. **25/11/19**
 Survey held at **comfortdelgro (coyang)**
 Des. of Damages: **Frnt** / Rear / O/S / **N/S** / U/C / Rooftop or
Frnt / **N/S Frnt**
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHD3093X - NS/INC12010669 / Hlyllk3 DOA: 26/5/2012 XD853A - NA/INC18011776/h1 TOKIO
26/11/19 @ 17:16 pm	revised PA to Dillen Sathler via message
	P/P: \$1056.68 / = (\$ 1,893.12 Red - 64%) 3 repair days COMfirm LIM KWOK ENG.

RECEIVED 05 DEC 2019

Date/Time, File Pass by: **05/12/19**
 : Preli. Report
 : Final Report
 Typist
 Date/Time, File Return to?
 Report Format
 Temp. Sum: **\$ 1,056.68 P/P**

Days Of Repair: **3**
 Resurvey No. of Trip: **1**
 Survey Fee: **290**
 Transportation: _____
 S+RS: _____
 Fines: _____
 Other: **11**
261

Our Job Ref No 305351241

Date : 28.11.19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr RAM

Vehicle Reg No. SHD3093X CTPL

22.11.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- XD853A
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$85.68
(b) Labour Charges	\$971.00
Total for Part-By-Part Repair Cost	\$1,056.68
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM KWOK ENG

Name : Ram

Tel : 62148316

Date : 29/11/2019

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Nov 2019)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD3093X/25/11/2019 10:34

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER - LH X (R)	20.00	0.00	*566.30 FL
2	1		*FRONT FENDER SHIELD - LH X NN	20.00	0.00	*175.90 FL
3	1		*FRONT WHEEL COVER - LH DEF	20.00	0.00	*107.10 FL
4	1		*FRONT BUMPER X (R)	20.00	0.00	*1,052.20 FL
5	10		*FRONT BUMPER CLIPS X NN	20.00	0.00	*22.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

1,923.50

- List Item Discount on L Items (S\$)

384.70

Total Parts (S\$)

1,538.80

ComfortDelGro Engineering Pte Ltd/SHD3093X/25/11/2019 10:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	\$560 600.00
2	SPRAY PAINTING	New	\$400 500.00
3	TUFF KOTE	New	X 100.00
4	WIRING CHARGE	New	X 100.00
5	FRONT WHEEL ALIGNMENT	New	X 100.00
Gross Labour Cost (S\$)			1,400.00

ComfortDelGro Engineering Pte Ltd/SHD3093X/25/11/2019 10:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Ram (LKR)
 25/11/19 1130
 qtt repair photo
 P9193093X@Lickauton
 88622778
 P...
 3...
 P...
 P...

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305351241
 REGN NO : SHD3093X
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 22.12.2016
 DATE/TIME IN : 25.11.2019 08:00
 ACCIDENT DATE : 22.11.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0658-G I40VC CAP ASSY-WHEEL HUB 1 L 107.10 20.00 85.68

SUB-TOTAL : 85.68

JOB NATURE

0000 L MERIMEN CHARGE 11.00

0001 L PANEL BEATING 560.00

0002 23-502 SPRAYPAINT ON AFFECTED AREA 400.00

SUB-TOTAL : 971.00

TOTAL : 1,056.68

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Workshops

59 Loyang Drive Singapore 508869
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609285
320 Upper Road Singapore 609599

24 Senoko Loop Singapore 758156
7 Sungei Kadit Way Singapore 728791
501 Yehun Industrial Park A Singapore 768732

Date/Time: 25.11.2019 09:17

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305351241

CUSTOMER MS COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO.: SHD3093X	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 25.11.2019 08:00
	YR OF MANU 22.12.2016	TARGET DATE
	CHASSIS CODE KMHLB41UMHU097257	COMPLETION DATE/TIME:


COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 22.11.2019
NATURE: 3P 22.11.2019

S/NO LABOR CODE DESCRIPTION

TOKIO - Frt - Left



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHD3093X LKE

Vehicle No.: SHD3093X

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dillen Senthilan so Selvarajoo

Date: 26 Nov 2019

Preliminary Advice

Insured Vehicle No : XD853A
TP Vehicle No : SHD3093X
Make : HYUNDAI I40
Date of Inspection : 25/11/2019
Inspection At : ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Accident Date : 22/11/2019
Assignment Date : 26/11/2019
Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s & n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,949.80
Revised Amount	:S\$	1,056.68
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,056.68

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/11/2019 09:25
Date Of Accident	22/11/2019 16:30
Exact Location Of Accident	HOUANG AVE 2 OPEN AIR CARPARK.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3093X
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFTY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	PWA MUI KIAM
NRIC No	S1303358G
Date Of Birth	24/02/1958
Occupation	OUTDOOR
Date Of Driving Pass	01/01/1990
Driving Experience	29 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97103139
Fax Number	
Contact Number	
EEmail Address	SHER@BANQUET.COM.SG

Address	710 02-137 HOUGANG AVENUE 2
Postcode	530710
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD853A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	NO DAMAGE
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/11/2019 at about 1630 hrs, I vehicle A was stationary at the Hougang ave 2 block 710 HDB open air Carpark. At that time it was heavy rain and I was in the taxi. Suddenly vehicle B reverse his lorry and collided onto vehicle A left front portion. No one was injured at that time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO REG NO: 199901821R

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

22/11/19

Reporting Centre Personnel's Signature

[Handwritten Signature]

Name:
NRIC/FIN No.:

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

OMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R


23/11/19
Reporting Centre Personnel's Signature

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





22/11 1630

XD853A



ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
COMFORT TRANSPORTATION PTE LTD

Singapore

Claimant **India International Insurance Pte Ltd**
Insurer:

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	22/11/2019
Vehicle Reg. No.:	SHD3093X	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	PWA MUI KIAM		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	22/12/2016
Vehicle Colour:	BLUE	Gen Condition:	FAIR
Engine No:	D4FDGU695584	Chassis No:	KMHLB41UMHU097257
Odometer:	293640 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	SEE ATTACH.		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,538.80
Miscellaneous Items	11.00
Labour	1,400.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,949.80

+ GST 7.00% (S\$) 206.49

Nett Amount (S\$) 3,156.29

This claim is handled by: NG NYUK PHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Nov 2019)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD3093X/25/11/2019 10:34

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER - LH x (R)	20.00	0.00	*566.30 FL
2	1		*FRONT FENDER SHIELD - LH x nn	20.00	0.00	*175.90 FL
3	1		*FRONT WHEEL COVER - LH DEF	20.00	0.00	*107.10 FL
4	1		*FRONT BUMPER x (R)	20.00	0.00	*1,052.20 FL
5	10		*FRONT BUMPER CLIPS x nn	20.00	0.00	*22.00 FL


F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 1,923.50

- List Item Discount on L Items (\$\$) 384.70

Total Parts (\$\$) 1,538.80

ComfortDelGro Engineering Pte Ltd/SHD3093X/25/11/2019 10:34. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**



Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	\$560 600.00
2	SPRAY PAINTING	New	\$400 500.00
3	TUFF KOTE	New	\$ X 100.00
4	WIRING CHARGE	New	X 100.00
5	FRONT WHEEL ALIGNMENT	New	X 100.00
Gross Labour Cost (S\$)			1,400.00

ComfortDelGro Engineering Pte Ltd/SHD3093X/25/11/2019 10:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Handwritten notes:
 Ram (LKK)
 25/11/19 1130
 aft repair photo
 Ram@SG.com @LKKAuto.com
 88622778
 3 repair days
 (PP)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Nov 2019 10:28 Sendback Est	25 Nov 2019 10:34 S\$2,949.80	26 Nov 2019 09:30 Edit Adj Rpt	S\$1,056.68 Edit Estimates	S\$1,056.68 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHD3093X	Date of Loss:	22/11/2019 16:00 - :59 [35 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1909118	Policy/Cover Note No.:	MB016279 (TP, Fire & Theft) Coverage: 26/09/2019 - 25/09/2020						
Vehicle Reg. No. (Insured):	XD853A	Policy No. (Claimant):	MCOM0015						
		Excess:	S\$0.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 05/12/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHD3093X (M1909118)
[XD853A]
TP
COMFORT TRANSPORTATION PTE LTD
Nov 22 2019 4:00PM
[COMFORT TRANSPORTATION PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Assessment Reports										
									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)						Thumbnail	Print	
1	25/11/19 10:34	Repairer Estimates							Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)						Thumbnail	Print	
1	26/11/19 09:31	Accident Statement From: SC - Reg. No: XD853A, Claimant: SIN AIK HARDWARE (PTE) LTD							Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	26/11/19 17:16	Adjuster Immediate Advice							Load HTM	
Photos/Images										
									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)						Thumbnail	Print	
1	23/11/19 09:34	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>
2	23/11/19 09:34	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>
3	23/11/19 09:34	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>
4	23/11/19 09:34	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>
5	23/11/19 09:34	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>
6	23/11/19 09:34	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>
7	23/11/19 09:34	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>
8	23/11/19 09:34	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
2	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
3	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
4	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
5	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
6	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
7	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
8	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
9	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
10	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
11	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
12	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
13	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
14	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
15	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
16	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
17	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
18	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
19	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
20	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
21	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
22	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
23	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>
24	28/11/19 09:29	General View							Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
25	28/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
26	28/11/19 09:29	General View	Load JPG	<input checked="" type="checkbox"/>
27	02/12/19 09:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	02/12/19 09:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	02/12/19 09:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	02/12/19 09:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	02/12/19 09:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	03/12/19 15:20	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	Load PDF	

No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	23/11/19 09:32	Sketch Plan <small>[Linked Accident Report Documents]</small>	Load TIF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	23/11/19 09:34	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	23/11/19 09:34	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	23/11/19 09:34	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	23/11/19 09:34	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	23/11/19 09:34	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	23/11/19 09:34	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	23/11/19 09:34	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	23/11/19 09:34	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	23/11/19 09:34	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	23/11/19 09:32	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>	
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19020856/FSD3E2

Date: 05/12/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No: MB016279	
Claimant		
Vehicle No : SHD3093X	Insured Vehicle No : XD853A	
Date of Loss: 22/11/2019	Nature of Claim: TP	Claim No: M1909118

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD3093X	
Make & Model: HYUNDAI I40, 1.7 D CRDi (A)	Engine No: D4FDGU695584
Reg. Date: 22/12/2016 (Man. Year: 2016)	Chassis No: KMHLB41UMHU097257
Colour: Blue	Odometer: 293986 km
Engine Capacity: 1685 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 205/60 R16	Rear Tyre Size: 205/60 R16
Front Left Side: Hankook 6 mm	Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm	Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,538.80	85.68	1,453.12	94.43
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,400.00	960.00	440.00	31.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,949.80	1,056.68	1,893.12	64.18
+ GST 7.00/7.00% (S\$)	206.49	73.97	132.52	64.18
Nett Amount (S\$)	3,156.29	1,130.65	2,025.64	64.18

INSPECTION

Date of Assignment: 26/11/2019	Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)	
Date Inspected: 25/11/2019	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969	
Estimated Period of Repair: 3.0 days		

Adjuster: PARASURAM SHANMUGAM

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2019)
Parts: 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD3093X)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT FENDER - LH	Repair	566.30 FL	*- FL	
2	1		*FRONT FENDER SHIELD - LH	Not Necessary	175.90 FL	*- FL	
3	1		*FRONT WHEEL COVER - LH	Deformed	107.10 FL	*107.10 FL	
4	1		*FRONT BUMPER	Repair	1,052.20 FL	*- FL	
5	10		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL	
					Sub Total (S\$)	1,923.50	107.10
					- List Item Discount on L Items 20.00/20.00% (S\$)	384.70	21.42
					Total Parts (S\$)	1,538.80	85.68

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	560.00
2	SPRAY PAINTING	New	500.00	400.00
3	TUFF KOTE	New	100.00	0.00
4	WIRING CHARGE	New	100.00	0.00
5	FRONT WHEEL ALIGNMENT	New	100.00	0.00
Gross Labour Cost (S\$)			1,400.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >