

REG: CS/CTI 19020896/Hqf3ST

Special Instruction:

ASS. REC. BY:

Surveyor:

Huck Ann

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

20.11.19 13.58p.m

Estimate / Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

YP 8196K

Insured:

GBL 2352T

at Workshop n/s:

Vertex Euro Motors

Tel:

98531969

of

3 ubi Rd 4

Policy No:

DMCVSN 14303019055

Claim No:

SNM19D 205524102

Sum Insured:

Excess:

D.O.A.

18.11.19

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time:

2.11.19 2.07p.m

Person Contacted:

Chris

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

YP 8196K - X

GBL 2352T - NA / ASG / 16/11/19

P41 - 21/11/2019

* YP 8196K finalised amt 4/sup cor \$4000. Don indy close.

(Ref B 1965, 33.1.7)

RECEIVED 25 MAR 2020

ASSIGNMENT

From: _____ Date: 27.11.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 4P 8196K

at Workshop m/s Vertex X Automobile

of 3 Vbi Road 4

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 3.000m Omni Wally

Veh No: 4P 8196K Yr Regn: 28/12/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: FOTON BJ1079V0J26-PP CC 3759

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 56533 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LUBU3JBB2HP002271

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or


Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/75/R17.5

R: 215/75/R17.5

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front chiso Yank Rear CHAO YANK

R/Bal. 47 mm R/Bal. 4x2 mm

L/Bal. 4 mm L/Bal. 4x2 mm

D.O.A. 18/11/19 D.O.I. 27/11/19

Survey held at Vertex Automobile

Des. of Damages: Frt Rear O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>* 4P 8196K</u>
	<u>NO limit</u>
	<u>lv 28/11</u>
	<u>Pls check parts prices</u>
	<u>mv - 40000 (cost)</u>
	<u>UTR - 36442</u>
	<u>NV - 35000SSB</u>
	<u>CHRIS</u>
	<u>28/11</u>
	<u>lv 28/11</u>

Date/Time, File Pass In? ☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Wash up (\$)

Survey Fee: _____

Transportation: _____

S. + P. \$ _____

Photos: _____

Notes: _____

TOTAL: _____

Reply all Delete Junk Block

Re: YP 8196K FINALIZED

Hock Ann (LKK Auto)

Tue 3/24/2020 2:43 PM

sa1@vertex.sg; Shiau Chan (LKKAuto); SUR



YP 8196K FINALIZED.pdf

2 MB

Dear christopher ,

Good day, after management checking total finalized amount L/SUMP repair is

COR - \$ 4000

DOR - 2 DAYS

we be base on this amount finalized yours, please to take noted.

Noted : All finalized document > LOA ,LOD,DV,LTA need direct to insurance claim dept (china taiping insurance)

thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(4089

From: Chistopher Dass Anthonidas <sa1@vertex.sg>

Sent: Tuesday, March 24, 2020 9:32 AM

To: Hock Ann (LKK Auto) <HockAnn@lkkauto.com>

Cc: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: Re: YP 8196K AFTER PAINT PHOTO

Dear Hock,

Good morning to you.

Noted

Please refer to attachment

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2019		26 Nov 2019 13:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS		[Created by insurer]																						
Insured:																								
Main Claimant:	VERTEX AUTOMOBILE PTE LTD, Co. Reg. No.: 200605693R																							
Vehicle Reg. No.:	YP8196K	Date of Loss:	18/11/2019 14:00 - :59																					
Claim Type:	TP / SNM19D205524C02	Policy/Cover Note No.:	DMCVSN14303019055																					
Vehicle Reg. No. (Insured):	GBC2357T	Policy No. (Claimant):	5113886342																					
		Excess:	S\$0.00																					
Repairer:	Vertex Euro Motors Pte Ltd (HQ) 3 UBI ROAD 4, 408608 Ubi - Tel: 98531969																							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]																							
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/12/2019]																							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail																						
There are no mail for this case.																								
<div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 26 November 2019 1:54 PM
To: sa1@vertex.sg
Cc: 'assignments'; Tan Kah Leong
Subject: RE: Re: SPAM LOW RE: OUR REF: SNM19D205524/GBC2357T/TKL & YOUR REF: YP8196K-THIRD PARTY CLAIM -TO CONDUCT PRS

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Tuesday, November 26, 2019 1:47 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; sa1@vertex.sg

Cc: Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>

Subject: FW: Re: SPAM LOW RE: OUR REF: SNM19D205524/GBC2357T/TKL & YOUR REF: YP8196K-THIRD PARTY CLAIM -TO CONDUCT PRS

Dear Boon Sen

Please assist Kah Leong on PRS soonest possible.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
TEL: (65) 63896116 - F: (65) 6224 7478

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Chistopher Dass Anthonidas [<mailto:sa1@vertex.sg>]
Sent: Tuesday, November 26, 2019 9:30 AM
To: Claims Dept of CTI
Subject: Fwd: Re: SPAM LOW RE: OUR REF: SNM19D205524/GBC2357T/TKL & YOUR REF: YP8196K-THIRD PARTY CLAIM -TO CONDUCT PRS

Dear Motor claims department,

FYI -since Mr Tan Kah Leong on leave,i forward this email to you

Please Reply

Thank You

Best Regards

Christopher Dass | Tel: +65 98531969
Service Advisor
Vertex Euro Motors Pte Ltd | SEAT Authorised Distributor

SEAT CENTRE SINGAPORE
3 Ubi Road 4 Singapore 408608 | Tel: +65 67429368
www.seat.sg | www.facebook.com/seat.sg



From: "Chistopher Dass Anthonidas" <sa1@vertex.sg>
Sent: 11/26/19 8:55 AM
To: "Tan Kah Leong" <KahLeong.Tan@sg.cntaiping.com>
Subject: Re: SPAM LOW RE: OUR REF: SNM19D205524/GBC2357T/TKL & YOUR REF: YP8196K-THIRD PARTY CLAIM -TO CONDUCT PRS
Dear Tan,

Good morning to you.

Thank you for your reply.


Please be informed you that we are agree to the appointment of any of those motor surveyors as a single joint expert.

Thank You

Best Regards

Christopher Dass | Tel: +65 98531969
Service Advisor
Vertex Euro Motors Pte Ltd | SEAT Authorised Distributor

SEAT CENTRE SINGAPORE
3 Ubi Road 4 Singapore 408608 | Tel: +65 67429368
www.seat.sg | www.facebook.com/seat.sg



From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: 11/25/19 6:59 PM
To: "sa1@vertex.sg" <sa1@vertex.sg>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: SPAM LOW RE: OUR REF: SNM19D205524/GBC2357T/TKL & YOUR REF: YP8196K-THIRD PARTY CLAIM -TO CONDUCT PRS

Without Prejudice

Dear Christopher,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, November 25, 2019 6:12 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; sa1@vertex.sg

Subject: OUR REF: SNM19D205524/GBC2357T/TKL & YOUR REF: YP8196K-THIRD PARTY CLAIM -TO CONDUCT PRS

Dear Kah Leong,

Please conduct PRS-YP8196K- soonest possible

File with officer-in-charge –Tan Kah Leong –DID 6389 6193.

Dear Christopher,

***** kindly quote our reference number when replying *****

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

TEL: (65) 63896116 - F: (65) 6224 7478

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Chistopher Dass Anthonidas [<mailto:sa1@vertex.sg>]
Sent: Monday, November 25, 2019 3:23 PM
To: Claims Dept of CTI
Subject: YP8196K-THIRD PARTY CLAIM

Dear China Taiping,

(Motor claim department)

Good afternoon to you.

We would like to inform that a claim has been made against your insured motor policy.

We wish to submit a third party claim against on your insured GBC2357T

Please find the attached file for your perusal

Thank You

Best Regards

Christopher Dass | Tel: +65 98531969

Service Advisor
Vertex Euro Motors Pte Ltd | SEAT Authorised Distributor

SEAT CENTRE SINGAPORE

3 Ubi Road 4 Singapore 408608 | Tel: +65 67429368

www.seat.sg | www.facebook.com/seat.sg

MVA119152648 / VAC - Bukit Batok
 ENTRY DATE & TIME: 19/11/2019 09:55
 SUBMITTED BY: LYNDANG AH HIANG

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 19/11/2019 09:55
 Date Of Accident 18/11/2019 14:30
 Exact Location Of Accident TPE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number YP8196K
Insured/Policyholder
 Name Of Registered Owner VERTEX AUTOMOBILE PTE LTD
 Co Reg No 200605693R
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-97159731
 Alternative Phone No Office-97159731

Vehicle Particulars

Manufacturer FOTON
 Model TRUCK
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage THIRD PARTY
 Fleet Policy NO
 Policy Number 5113886342
 Cover Note Number

Driver

Name of Driver YIN ZHONG
 NRIC No G2556139U
 Date Of Birth 11/10/1987
 Occupation OUTDOOR
 Date Of Driving Pass 09/03/2015
 Driving Experience 4 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97159731

Fax Number
Contact Number
EMail Address NOEMAIL
Address ---
Postcode
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC2357T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


Sketch Plan


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: _____


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: _____


 Reporting Centre Personnel's Signature
 Name: _____
 NRIC/FIN No.: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Driver A was travelling at about 60km/h at the most left lane of TPE towards Changi, between Pongol field exit and Lorong Halus Exit. While he was travelling normally, driver B, G8C23577, hit his vehicle (vehicle A) at the back of his vehicle. Both stop and exchange driver particulars. The time of accident was about 2:30pm on 18 November 2019.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC RIUKIT BATOK (VAC)

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	693R

Vehicle Details

Vehicle No.:	YP8196K
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Nov 2019
Vehicle Make:	FOTON
Vehicle Model:	BJ1079VDJE6-FP 3.8L MANUAL
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	ISF38S515489892552
Chassis No.:	LVBV3JBB2HE002271
Maximum Power Output:	-
Open Market Value:	\$34,455.00
Original Registration Date:	28 Dec 2017
First Registration Date:	28 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$1,723.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	27 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$45,112.00
COE Rebate Amount:	\$36,442.00
Total Rebate Amount:	\$36,442.00

The information contained herein is correct as at 28 Nov 2019

OK

Download Chrome Browser

Install Chrome Device-based Group Policies & More. Deploy Chrome MSI

Foton BJ1041

Price Range

Depreciation

Year Reg

Truck

Submit

Advanced Search

Home > Used Cars > Vertex Automobile Pte Ltd > Foton BJ1041

Foton BJ1041

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$40,000	Lifespan	25-Dec-2037
Depreciation	\$5,150 /yr View models with similar depre	Reg Date	26-Dec-2017 (7yrs 9mths 3days COE left)
Mileage	48,773 km (21.8k /yr)	Manufactured	2017
Road Tax	N.A.	Transmission	Manual
Derog Value	\$32,610 as of today (change)	OMV	\$24,773
COE	\$42,000	ARF	\$1,239
Engine Cap	2,775 cc	No. of Owners	2
Curb Weight	2,340 kg		
Type of Vehicle	Truck		



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Description
Nice Condition, For Sales.

Category

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Posted on: 03-Mar-2020 | Last Updated on: 03-Mar-2020

Upfront Payment

= more Financial info

Transfer Fee

\$25

Down Payment

\$4,000 (change)

Maximum 90% Loan

1st Instalment

\$531

Based on 3.9% interest rate

Insurance

You'll also need a valid car insurance to drive this vehicle. **18% off with code CAR18**
Get a quote now!

Powered by

AVIVA

Total Upfront Payment

\$4,536 (Without insurance)

Check with broker for exact figure

Tags: Foton BJ1041, 2017 Foton BJ1041, Foton, BJ1041

Recommended for you

1-6 of 18



Foton Motor Auv (S) Pte Ltd

3 Ubi Road 4 Singapore 408608 RCB NO: 200903164N GST NO: 200903164N

RCB NO:200903164N

QUOTATION

M/S: ~~DEL~~ CHINA TRADING INSURANCE

NO: WQT0700170
DATE: 27 Nov 2019
A/C CODE: D0002
YOUR REF: YP8196K
VEH REG NO: YP8196K
MAKE/MODEL: FOTON TRUCK
BJ1079VDJE6-FP

ATTN: CHRIS

SALESMAN: HUANG YANJIN

PAGE:1

Description	Quantity	Unit Price	%	Amount
		SS		SS
LAMP-24VCOMBINATION LAMP ASSY-RR ✓ <i>c.R.H.</i>	1 PC	150.00		150.00
REAR BUMPER WITH REFLECTOR ✓ <i>6+</i>	1 UNIT	1,125.00		1,125.00
ADHESIVE (Sealant) ✓ <i>all</i>	1 UNIT	300.00		300.00
LABOUR TO DISMANTLE AND REPLACE ABOVE DAMAGE PARTS TO NEW & TO PENAL BEATING, RE-ALIGN & KNOCK OUT DENTS, STARIGHTEN & RE-ALIGN ALL AFFECTED PARTS <i>colour</i>	1 UNIT	1,440.00		1,440.00
REAR DOOR STICKER ✓ <i>all</i>	1 UNIT	350.00		350.00
REAR RHS DOOR ✓ <i>TN</i>	1 UNIT	2,300.00		2,300.00
DAMPER RUBBER ✓ <i>CR4</i>	2 UNIT	150.00		300.00
	Total			SS 5,965.00
	Add GST @ 7%			417.55
	Grand Total			SS 6,382.55

TOTAL: SINGAPORE DOLLAR SIX THOUSAND THREE HUNDRED EIGHTY TWO AND CENTS FIFTY FIVE ONLY

DEL

For Foton Motor Auv (S) Pte Ltd

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

L/S repair without prejudice 2 day 27/11/19 3:25 pm After paint Resurvey Hock ANN@LKK Auto.com 4p 85311883 / 67418434 - offer Hock ANN

Foton Motor Auy (S) Pte Ltd

RCB No: 209603164N
3109 Road 4 Singapore 408508 RCB No: 209603164N GST No: 209603164N

TAX INVOICE NO:

INV0703949

Owner's Information

A/C: C0009
CHINA TAIPING INSURANCE
(SINGAPORE) PTE LTD

Registration No.
YP8196K

3 ANSON ROAD, #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Mileage (km):
65074

Chassis No.
LVBV3JBB2HF002271

Service Advisor:

CHRISTOPHER DASS
ANTHONIDAS

Make Model:
FOTON TRUCK BJ1079VDJE6-TP

Job Card No

JB073936

Date of Invoice:

19/03/2020

Date In:

18/03/2020

Time In:

3:52 PM

Promised Date/Time:

18/03/2020 3:52:00 PM

Service Description	Quantity	Unit Price SS	Amount SS
MANHOOR RATE ✓ <i>1 hour</i>	1 UNIT	960.00	960.00
LAMP L LAMP RH ✓	1 PC	150.00	150.00
REAR BUMPER WITH REFLECTOR ✓	1 UNIT	1,125.00	1,125.00
ADHESIVE (sealant) ✓	1 UNIT	300.00	300.00
REAR DOOR STICKER ✓	1 UNIT	350.00	350.00
REAR RHS DOOR ✓	1 UNIT	2,300.00	2,300.00
DAMPER RUBBER ✓	2 UNIT	150.00	300.00
		TOTAL	SS 5,485.00
		ADD GST @ 7%	383.95
		GRAND TOTAL	SS 5,868.95

SINGAPORE DOLLAR FIVE THOUSAND EIGHT HUNDRED SIXTY EIGHT AND CENTS NINETY FIVE ONLY

Remark: 1.) ACCIDENT REPAIR - (THIRD PARTY CLAIM) Re: FW: Re: SPAM LOW RE: OUR REF: SNM19D205524 GBC23571 TK1 & YOUR REF: YP8196K-THIRD PARTY CLAIM

parts 4525

parts less 10%

4072.5

labor 960

5032.50

4/5 less 20%

4026

total \$4000.00

Customer's Signature Co. Stamp

E & O E

Service Advisor's Signature



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2019		26 Nov 2019 13:58 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	-, Co. Reg. No.: -								
Main Claimant:	VERTEX AUTOMOBILE PTE LTD , Co. Reg. No.: 200605693R								
Vehicle Reg. No.:	YP8196K	Date of Loss:	18/11/2019 14:00 - :59 [22 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205524C02	Policy/Cover Note No.:	DMCVSN14303019055						
Vehicle Reg. No. (Insured):	GBC2357T	Policy No. (Claimant):	5113886342						
		Excess:	S\$0.00						
Repairer:	Vertex Euro Motors Pte Ltd (HQ) 3 UBI ROAD 4, 408608 Ubi - Tel: 98531969								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 05/12/2019]								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YP8196K (SNM19D205524C02)**
[GBC2357T]

TP

VERTEX AUTOMOBILE PTE LTD

Nov 18 2019 2:00PM









































[-]

Vertex Euro Motors Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Photos/Images			3 per page	
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	19/11/19 10:06	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	19/11/19 10:06	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	19/11/19 10:06	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	19/11/19 10:06	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	19/11/19 10:06	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	19/11/19 10:06	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/11/19 10:11	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	28/11/19 10:11	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
11	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
12	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
17	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
18	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
19	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
20	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
21	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
22	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
23	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
24	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
25	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
26	28/11/19 10:12	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
27	28/11/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
28	28/11/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
29	28/11/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
30	28/11/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
31	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
32	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
33	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
38	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
43	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
44	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
45	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
46	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
47	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
48	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
49	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
50	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
51	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
52	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
53	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
54	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
55	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
56	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
57	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
58	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
59	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
60	28/11/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
61	24/03/20 12:18	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
62	24/03/20 12:18	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
63	24/03/20 12:18	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
64	24/03/20 12:18	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	19/11/19 10:02	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	19/11/19 10:02	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	06/12/19 19:33	Accident Statement	Load HTM	
2	06/12/19 19:33	Accident Statement	Load HTM	
3	06/12/19 19:34	Accident Statement	Load HTM	
4	06/12/19 19:35	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	19/11/19 10:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	19/11/19 10:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	19/11/19 10:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	19/11/19 10:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	19/11/19 10:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	19/11/19 10:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	19/11/19 10:02	Sketch Plan	Load TIF	
2	19/11/19 10:02	Sketch Plan #2	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19020896/HQF3S2

Date: 31/03/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN14303019055
Claimant Vehicle No :	YP8196K	Insured Vehicle No :	GBC2357T
Date of Loss:	18/11/2019	Nature of Claim:	TP
		Claim No:	SNM19D205524C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP8196K	Engine No:	ISF38S515489892552
Make & Model:	FOTON BJ1041V9JD6-FP, 2.8 D (M)	Chassis No:	LVBV3JBB2HE002271
Reg. Date:	28/12/2017 (Man. Year: 2000)	Odometer:	56533 km
Colour:	White		
Engine Capacity:	3759 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/75 R17.5	Rear Tyre Size:	215/75 R17.5(D)
Front Left Side:	Chao Yong 4 mm	Rear Left Side:	Chao Yong 4/4 mm
Front Right Side:	Chao Yong 4 mm	Rear Right Side:	Chao Yong 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,525.00	4,072.50	452.50	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,440.00	960.00	480.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,965.00	5,032.50	932.50	15.63
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	5,965.00	4,000.00	1,965.00	32.94
+ GST 7.00/7.00% (S\$)	417.55	280.00	137.55	32.94
Nett Amount (S\$)	6,382.55	4,280.00	2,102.55	32.94

INSPECTION

Date of Assignment:	26/11/2019		
Date Inspected:	27/11/2019	Inspected At:	Vertex Euro Motors Pte Ltd (HQ) 3 UBI ROAD 4 Singapore 408608
Estimated Period of Repair:	2.0 days		

Adjuster: LEE HOCK ANN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$41,000.00 (EST) - LTA REIMBURSEMENT VALUE: \$36,442.00 = NETT VALUE: \$4,558.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Mar 2020)	
Parts:	N/A	FOTON BJ1041V9JD6-FP 2.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP8196K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP-24V COMBINATION LAMP ASSY - RR	Cracked	150.00 F	*150.00 FL
2	1		*UNIT REAR BUMPER WITH REFLECTOR	Bent	1,125.00 F	*1,125.00 FL
3	1		*UNIT ADHESIVE (SEALANT)	Necessary	300.00 F	*300.00 FL
4	1		*UNIT REAR DOOR STICKER	Necessary	350.00 F	*350.00 FL
5	1		*UNIT REAR RHS DOOR	Torn	2,300.00 F	*2,300.00 FL
6	2		*UNIT DAMPER RUBBER	Crushed	300.00 F	*300.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,525.00	4,525.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	452.50
Total Parts (\$\$)	4,525.00	4,072.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO DISMANTLE AND REPLACE ABOVE DAMAGE PARTS TO NEW & TO PANEL BEATING, RE-ALIGN & KNOCK OUT DENTS, STRAIGHTEN & RE-ALIGN ALL AFFECTED PARTS.	New	1,440.00	960.00
Gross Labour Cost (\$\$)			1,440.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >