ASS. REC. BY: Steve | REF: FCI

ASSIGNMENT

From: | Date: 5.12.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKU 4079G

at Workshop m/s Eurokars Habstart

of 27 A Tanjong Penjuru

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: 10.30a.m Omar waiting

(Policy Condition)

N/S	O/S
XX	

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (mp)

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SKU 4079G | Yr Regn: 24/7/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mini One | c.c 1198?

Colour Red | A/C: Insured / Std / NI / NA

Sp.Reading 48593 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WMW X S120 702 C73453

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	21/11/19	D.O.I.	5/12/19

Survey held at Trans

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

RECEIVED 11 FEB 2020

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 11/2 - typist

☑ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weel and ($)

Report Former : CWS

Lump Sum / LPJ: (%)

Survey Fee:	145
Transportation:	50
S + RS. SI	
Photos	20
Others	
TOTAL	215