



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD	Ref : CS/FCI19020910/Evd3s2
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877	Date : 11-02-2020
	Code : FCI2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9810U	Veh. Inspected	SKU 4079G
Policy No.		Coverage (\$)	0.00
Claim No.	D19007450MFSH	Excess (\$)	0.00
Assign From	RACHEL WU LIMEI	Assign Date	26/11/2019

2. Vehicle Particulars & Condition

Make & Model	MINI ONE	c.c	1198
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WMWXS120702C73453	Colour	RED
Odometer	48593	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R16	MICHELIN	5 mm
L/H Front Tyre	195/55 R16	MICHELIN	5 mm
R/H Rear Tyre	195/55 R16	MICHELIN	5 mm
L/H Rear Tyre	195/55 R16	MICHELIN	5 mm

4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--	--

5. General Information

Accident Date	21/11/2019	Inspection Date	05/12/2019
Survey held at	27A TANJONG PENJURU		
Repairer	EUROKARS HABITAT PTE LTD		

5a. Remarks

	A)THE VEHICLE HAS NOT SEND IN FOR REPAIR. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	---

5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
--	-------------------------------------	-----------------------