

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	14:30HRS
ACCIDENT DATE	25-Nov-19
BUS CAPTAIN NAME	JEGAN JAYAMANAY
THIRD PARTY CLAIM AGAINST	AIG ASIA PACIFIC INSURANCE PTE. LTD.

BUS REGISTRATION NUMBER	SBS3345L
BUS TYPE (SD/DD)	DD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	N/S/F MILLENN 1/4 GLASS <i>bro</i> ✓	1	\$265.40
2	N/S/F CORNER BUMPER <i>con</i> ✓	1	\$390.00
3	N/S/F DEFLECTOR <i>mis</i> ✓	1	\$160.00
4	N/S/F LIGHT BAZEL <i>con</i> ✓	1	\$190.00
5	SIKAFLEX BLACK <i>net</i> ✓	2	\$32.00
6	1/4 GLASS SEALANT <i>net</i> ✓	1	\$200.00
7			
8			
		7% GST	\$86.62
		PARTS TOTAL COST	\$1,324.02

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE DAMAGED PARTS	<i>780</i> \$1,950.00
TO CLEAR / CLEAN BROKEN N/S/F 1/4 GLASS & REPLACE N/S/F 1/4 GLASS INCL. SEALANT	\$650.00 ✓
TO CHECK AND REPAIR INTERNAL WIRING	<i>80?</i> \$650.00
SPRAY PAINTING	<i>768</i> \$1,920.00
	7% GST
	\$361.90
	LABOUR TOTAL COST
	\$5,531.90

SPRAY PAINTING \$640 PER PANEL

LABOUR CHARGES \$650 PER DAY

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN	25/11/2019
		DATE OUT	
BUS TYPE (SD / DD)	DD	TOTAL NUMBER OF DAYS	-43794
LOSS OF USE COST			

SUMMARY	
SECTION NO.	COST
1	\$1,324.02
2	\$5,531.90
3	-
4	\$0.00
GRAND TOTAL	\$6,855.92

Resue
 Hp 9m10068
 4 days
 26/11/19 @ 1610
 Resue before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: