ASS. REFER

Yvonne Wong (LKK Auto)

From:

Yvonne Wong (LKK Auto)

Sent:

Thursday, November 28, 2019 10:35 AM

To:

claims@premiumauto.com.sg; 'Mohd Rizal, Nur Mariah Huibrechts'; 'Tan, Bennie-WZ'

Cc:

SUR; 'Koh, Victor-CK'; 'Khoo, Kay-Eng'

Subject:

OD CLAIM FOR SKD 6777 B VEH IN URGENT

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SKD6777B (excess \$0/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

NOTE: REPLACEMENT RIGHT "B PILLAR PANEL" BEFORE PAINTING PHOTO IS REQUIRE.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yvonne Wong (LKK Auto)

Sent: Thursday, November 28, 2019 9:46 AM

To: claims@premiumauto.com.sg; 'Mohd Rizal, Nur Mariah Huibrechts' < Nur Mariah Huibrechts. Mohd Rizal@aig.com >;

'Tan, Bennie-WZ' <Bennie-WZ.Tan@aig.com>

Cc: SUR <sur@lkkauto.com>; 'Koh, Victor-CK' <Victor-CK.Koh@aig.com>; 'Khoo, Kay-Eng' <Kay-Eng.Khoo@aig.com>

Subject: RE: RE: OD CLAIM FOR SKD 6777 B VEH IN URGENT

Morning All

Pending on AIG approval.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

View Received Message

This mail is associated with:

*SKD6777B (1829251077SG)

OD
Nov 23 2019 1:05AM
[TEE MER LING PATRICIA]
Premium Automobiles Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 28/11/2019 10:07 AM.
To LKK HO

Subject Alert - Adj Mandate Approved (S\$27296.00) - SKD6777B - Claim Handler: Mohd Rizal, Nur Mariah Huibrechts

Approved:27296.00:NOTE: Re-inspection require on hidden item, check item and supplementary item with CLEAR photo. NOTE: Replacement right "B Pillar Panel" before painting photo is REQUIRED.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #08-16 Singapore 079120

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Date:

26 Nov 2019

Preliminary Advice

Vehicle No

: SKD6777B

Accident Date

: 23/11/2019

Make

: AUDI A3

Policy No.

: 2100485764-03

Assignment Date

: 26/11/2019

Excess

:S\$

:S\$

33,786.00

: S\$0.00

Date of Inspection

: 26/11/2019

Inspection At

Est. Duration of Repair

: 14.00

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s & n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,841.00
Revised Amount	:S\$	19,320.00
Check Items (Estimated)	:S\$	7,976.00
Total	:S\$	27,296.00

Lump Sum Repair

Total Loss Consideration

Margin for Repair

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	48,214.00
Salvage Value	:S\$	

Remarks

()	X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

	20	DEL	VT S	TAT		7
VΔ	S	UEI	412	IAI		ı

Date Of Report 23/11/2019 12:37 Date Of Accident 23/11/2019 01:05

Exact Location Of Accident OUTSIDE 30 AND 32 BEGONIA WALK

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKD6777B

Insured/Policyholder

Name Of Registered Owner TEE MER LING PATRICIA

NRIC No S1659488A Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-97316769 Alternative Phone No OTHERS-97316769

Vehicle Particulars

AUDI Manufacturer

A3 SEDAN 1.4 TFSI Model

Exact Purpose for which vehicle was being used at PRIVATE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 2100485764-03

Cover Note Number

Driver

Name of Driver TEE MER LING PATRICIA

NRIC No S1659488A Date Of Birth 06/01/1964 Occupation **INDOOR Date Of Driving Pass** 21/02/1986

33 YEARS AND 9 MONTHS Driving Experience

Gender **FEMALE**

Mobile Number (LOCAL) +65-97316769 Fax Number (LOCAL) +65-97316769 Contact Number OTHERS-97316769

EMail Address NOEMAIL Address

32 BEGONIA WALK VILLA BEGONIA

Postcode

805814

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

3

involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

10 UBI AVENUE 3

Police Station Address

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given? If Yes, against whom?

NO

Circumstances of Accident

REFER TO POLICE REPORT T/20191123/2037 AFTER THE TAXI HIT MY VEHICLE & PUSH MY VEHICLE TO LEFT, MY FRONT RIM HIT THE KERB.

Attachment(s)

Are accident photos available for attachment?

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera?

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHA5719C

Vehicle Make/Model/Colour

COMFORT

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SGJ69S

Vehicle Make/Model/Colour

NISSAN

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5 Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Try Foog

NRIC/FIN No.: -4-2040 147

SKETCH PLAN

A = 5kg 6777 B

8 = 5G J 695

Danged by Tax: SHA 57 19 C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

	Please	Refer	to	the	Police	Repor
	7/201	91123/2	037			
After left	the taxi My From	hit my Ria hit	vehicle, & the Kei	Push.	my vehicle	to
_						

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name: Tory Flowy NRIC/FIN No. 4204JLR 74



POLICE REPORT





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 1 of 3 Report No. T/20191123/2037

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/11/2019 11:01			Vide Report No.:	Station Diary No.:	
Informan	t's Partic	ulars			
Name of Informant: TEE MER LING PATRICIA			Address: APT BLK 32 BEGONIA WALK SINGAPORE 805814		
ID Type / ID No.: NRIC NO / S1659488A			Contact No.: Home/Office:	Mobile: 97316769	
Nationality: SINGAPORE CITIZEN		ŒN.	Email:		
Sex: Age: Date of Birth: Female 55 06/01/1964		Date of Birth: 06/01/1964	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: EXECUTIVE			Driving Licence Information Class: 3	on: Date of Expiry:	

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 23/11/2019 01:15	Type of Location	
Location: Along Road 1 BEGONIA W.	ALK				
OPP OF BEGONIA WALK Weather:		Road Surface:	Ro	ad Speed Limit:	
Traffic Flow:		Traffic Control:		Traffic Volume:	
Traffic Flow:		Tranic Control.		affic Volume:	

Details of V	ehicle Invo	lved	和美洲人 超高度级等 战事			
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SHA5719C	Car					0
SKD6777B	Car	AUDI	A3 SEDAN 1.4 TFSI (ATTRACTL ON)	Grey	-	0

Details of Vehicle	Insurance	AND THE STATE OF T		
Vehicle No. Insur	ance Company	Insurance No	Effective	Expiry Date

POLICE REPORT





2 of 3 Report No. T/20191123/2037

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Details of V	ehicle Insurance	is sais and bed on i	The second second second	
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKD6777B	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100485764-03	11/10/2019	10/10/2020

ON THE ABOVE MENTIONED DATE, TIME AND LOCATION.

MY CAR WAS PARKED ALONG 32 BEGONIA WALK OUTSIDE OF MY HOUSE. I SAW A NOTE STUCKED ONTO MY CAR FROM A WITNESS REGARDING THE HIT AND RUN ACCIDENT I WAS GIVEN THE CAR PLATE NUMBER OF THE SUSPECTED HIT AND RUN DRIVER (SHA5719C) BY THE WITNESS.

POLICE REPORT





3 of 3

Report No. T/20191123/2037

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: Signature Of Informant: BERNARD KOH REN JUN PA Signature Of Interpreter: Date/Time: Not applicable 23/11/2019 11:0 Officer In Charge Of Case: Classification Of Case: TP / HRT / Staff Sgt MUHAMMAD KHAIRIL BIN KAMAL Contact No.: 65476131 Authentication Stamp POLICE FORCE NP168 Signature:

UNDERTAKING

	Ling Patricia(NRIC No. 5 1659488A), hereby Accident Statement lodged by me on 23/11/19
at 100 hours pe	ertaining to the accident involving motor car Reg. No:
	th I was the driver are true and accurate to the best of my
knowledge, information and	
	rers are not liable under the contract of insurance if there is
a breach of policy terms an	d conditions.
In the event that an unrela	ted/unreported third party property or injury claim arises or
there is evidence emerges	s that there is a breach of policy terms and conditions, I
	bsolve my insurer from all liability under the contract of
	to re-pay any sums paid by my insurers pursuant to the
contract of insurance upon	receipt of written demand by my insurers.
Signature	: Patin
Name of Insured / Driver	Tee Mer Ling Patricia S 1659488A
Nric No.	S (659488A
Date	: 23/11/19
Signature	: Same as above
Name of Policyholder	:
Nric No.	•
Date	



AIG Asia Pacific Insurance Pte. Ltd AIG Building 78 Shenton Way #07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME	: _ Tee Mer Ling Patricia
VEHICLE NUMBER	S/LD 6777 B
DATE/ TIME OF ACCIDENT	: 23/11/19 0115 -0130 Cas
PLACE OF ACCIDENT	: Dut Rood outside 30 and 32 W
THIRD PARTY VEHICLE (IF ANY)	Begonia Walle SHA 571

The car is	parload (stationary)
	9
DID YOU DRINK ANY ALCOHOLIC DRINKS BE POLICE CONDUCT ANY BREATHE-ANALYSER T	FORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC TEST ON YOU? IF YES, WHAT WAS THE RESULTS?
	TENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED? It and file damage
WERE YOU OR YOUR PASSENGER/S INJURED? FOR INVESTIGATION?	P IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE
Patricio de	

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: TEE MER LING PATRICIA

Period of Insurance Engine No.

: 11 Oct 2019 To 10 Oct 2020

Chassis No.

: CZC572490 : WAUZZZ8V9G1109818 Vehicle No. Policy No.

: SKD6777B : 2100485764-03

Endorsement No.

Issued Date

: 10 Sep 2019

ABOUT THE COVER

Make/Model

: AUDI A3 Sedan 1.4 TFSI (Attraction)

Engine Capacity/Tonnage: 1,395.00 CC

: NA

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2016

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

Driver Restriction

b) Any other person who is driving on the Policyholder's order or with his/her permission. This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition

: All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

TEE MER LING PATRICIA - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from ITunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of githe Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125207

PREMIUM LEASING - SLEE

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

SSPOSO



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

21 Feb 1986

NID 400

Licence No: \$1659488A

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 20411

Telefax

Estimate

: Accident Repairs

Workshop Contact No : Ubi Road 1 : 6366 2323

Fax No

: 6841 1183

Reference

: PA/OD/20411/2019/NS

Date

25-Nov-19

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

: Ms Tee Mer Ling Patricia

Address

32 Begonia Walk

Singapore 805814

Telephone

HP +65 97316769

Type of Claim

: Own Damage Claim

Policy No.

2100485764-03

Vehicle No

SKD 6777 B

Model Code

: Audi A3 Sedan 1.4 TFSI

Model / Year

Oct-16

Engine No

CZC 572490

Chassis No

: WAUZZZ8V9G1109818

Mileage

46510

Date In

23-Nov-19

Estimated By

Johnny Boo / Allan Wu

Accident Date

: 23-Nov-19

Place of Accident

: Outside 30 And 32 Begonia walk

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 6777 B

S/N	Nature of Jobs		Estimated Charges		Surveyor's mmendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	/	\$360-00
2	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00	X	
3	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Check function and renew if necessary.	S/N	\$ 560.00	/	\$560-00
4	To dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy.	S/N	\$ 300.00	X	
5	To dislodge rhs front wheel suspension. To inspect for further damages and renew accordingly.	S/N	\$ 1,800.00	?	\$1800-00
	SUB TOTAL LABOUR CHARGES	:	\$ 3,300.00	=	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 6777 B

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
6	To remove and reinstall front seat assy, back rest, ABCD pillar trims, sill trims, carpets, electronic components and fuse trays.	S/N	\$ 1,800.00	\$1800-00
7	To dismantle front bumper, rhs front fender, rhs front door, rhs rear door and rear bumper. To renew rhs front fender, rhs front door and rhs rear door. To repair rhs rear fender. To cut out and reweld rhs sill panel. Re-organise crash management components. Reinstall all parts removed.		\$ 7,350.00	. 4000 \$400000
8	To respray front bumper, rhs front fender, rhs front door, door handle, rhs wing mirror cover, rhs rear door, rhs sill panel, rhs rear fender and rear bumper.		\$ 2450. 6,400.00	550 x 4 = 2200 Mirror: 150 Hadle: 100. \$2450-00
9	To renew rhs front rim, lhs front rim and rhs rear rim. To carry out wheel alignment.	S/N	\$ 360.00	\$360-00
10	To carry out diagnostic checks.	S/N	\$ 192.00	\$192-00
	TOTAL LABOUR CHARGES	:	\$ 19,402.00	

Telefax

Material List for Accident Vehicle Regn No. SKD 6777 B

S/N	Parts Description		Damage Parts & /NETT	Prices REMARKS
3/11	raits description		 / NETT	REMARKS
1	FRONT BUMPER GUIDE SECTION - RH HEN		\$ 35.00 ⁾	(*
2	FRONT FENDER - RH Rented		\$ 778.00 -	\$622-00
3	FRONT FENDER ATTACHMENT PARTS THE NEW		\$ 65.00 🛪	ř .
4	FRONT FENDER BRACKET - RH HEL		\$ 25.00 🛪	
5	FRONT FENDER BRACKET		\$ 35.00 🔾	-
6	FRONT FENDER BRACE - LH / BH WE ME		\$ 88.00	
7	FRONT WHEEL HOUSING LINER - RH Deld		\$ 158.00	\$126-00
8	WHEEL HOUSING LINER ATTACHMENT PARTS HOME		\$ 81.00	
9	FRONT DOOR - RH Distal		\$ 2,279.00	- \$1823-20
10	FRONT DOOR OUTER SEAL - RH Jan	NEC	\$ ا 146.00	\$116-80
11	BONDING AGENT REC	NEC	\$ 45.00	\$35.92
12	CLEANING SOLUTION WELL	NEC	\$ 65.00 P	\$51-68
13	FRONT DOOR ATTACHMENT PARTS THE NEW		\$ 218.00	
14	FRONT DOOR CATCH		\$ 96.00	
15	TYRE PRESSURE DATA PLATE		\$ 26.00	\$ 20-56
16	EXTERIOR MIRROR MOUNTING - RH		\$ 938.00	۲.
17	MIRROR CAP - RH Res		\$ 136.00 +	
18	MIRROR GLASS - RH Me ~		\$ 1,553.00 +	
19	REAR DOOR - RH Distole		\$ 2,279.00	± 1823-20
20	REAR DOOR OUTER SEAL - RH ALL	NEC	\$ 146.00	\$ 116-80
	SUB TOTAL SPARE PARTS	:	\$ 9,192.00	

Telefax

Material List for Accident Vehicle Regn No. SKD 6777 B

S/N	Parts Description			S/NETT REMARKS	
21	BONDING AGENT THE NEW	NEC	\$	45.00	
22	CLEANING SOLUTION THE	NEC	\$	65.00	
23	REAR DOOR ATTACHMENT PARTS THE		\$	117.00	
24	REAR DOOR CATCH → ~		\$	85.00+	
25	CENTRE PILLAR - RH Perse Deuted		\$	2,142.00 M. Check Price	7
26	DATA TAG THE NEW		\$	423.00	J
27	ALUMINIUM RIM CUT Front LH FRONT	PH ₃	\$	1,953.00 1302 \$1041-60	10
28	ALUMINIUM RIM RUBBER VALVE *** ~	4	\$	13.00 🖈	
29	TRACK CONTROL ARM BEST		\$	336.00 0 \$768-80	
30	STABILIZER BAR XM M		\$	372.00 🛠	
31	WHEEL BEARING HOUSING - RH		\$	532.00? \$443.60	
32	WHEEL BEARING - FRONT		\$	442.00 ? \$ 353-60	
33	LOWER BALL JOINT - RH Fest		\$	117.00 - \$ 93-20	
34	COUPLING ROD HEM		\$	88.00	
35	DRIVE SHAFT - RH		\$	2,005.00	
36	GAS SHOCK ABSORBER Best.		\$	251.00 7 \$200.40 114.00 7 \$91-20 43.00 7 \$74-00	
37	STRUT MOUNT Dend.		\$	114.00 ? \$91-20	
38	DEEP GROOVE BALL THRUST BEARING		\$	43.00 ? \$34-00	
39	TRACK ROD Hem		\$	86.00 3	
40	TIE ROD END - RH MEM		\$	118.00 ?	
41	ACRYLIC SEALANT)	S/N	\$	180.00 - \$180-00	
42	CAVITY WAX WEL	S/N	\$	140.00 / \$140-60	
43	STONE CHIP	S/N	\$	180.00 / \$180-00	
44	SUNDRIES NOC.		\$	180.00 / \$180-00 400.00 ? \$152-88	
	TOTAL SPARE PARTS		\$	19,439.00	
	TOTAL LABOUR CHARGES	•		19,402.00	
	GRAND TOTAL	: .	\$ \$	38,841.00	

Damage Parts & Prices

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

are Authorised,

12 Days. Are inclusive of undercarrege.

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

: Accident Repairs

Workshop

Ubi Road 1

Contact No Fax No 6366 2323 6841 1183

Reference

PA/OD/20411/2019/NS

Date

: 25-Nov-19

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Hi Adrian We took 18 days exclude 3 Sundays jb 16 Mar 20

WIP: 20411

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

: Ms Tee Mer Ling Patricia

Address

32 Begonia Walk

Singapore 805814

Telephone

HP +65 97316769

Type of Claim

Own Damage Claim

Policy No.

2100485764-03

Vehicle No

SKD 6777 B

Model Code

Audi A3 Sedan 1.4 TFSI

Model Code

Oct-16

Model / Year

CZC 572490

Engine No

020 072430

Chassis No

WAUZZZ8V9G1109818 46510

Mileage Date In

46510

Date III

23-Nov-19

Estimated By

Johnny Boo / Allan Wu

Accident Date

: 23-Nov-19

Place of Accident

Outside 30 And 32 Begonia walk

Telefax

Estimated Labour Charges for Accident Vehicle SKD 6777 B

S/N	Nature of Jobs		Estimated Charges		urveyor's mmendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$	360.00 /
2	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00		
3	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Check function and renew if necessary.	S/N	\$ 560.00	\$	560.00 /
4	To dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy.	S/N	\$ 300.00	*	
5	To dislodge rhs front wheel suspension. To inspect for further damages and renew accordingly.	S/N	\$ 1,800.00	\$	1,800.00 /
	SUB TOTAL LABOUR CHARGES	•	\$ 3,300.00	\$	2,720.00

Telefax

Estimated Labour Charges for Accident Vehicle SKD 6777 B

S/N	Nature of Jobs		Estimated Charges	Surveyor's ommendation
	c/f			\$ 2,720.00
6	To remove and reinstall front seat assy, back rest, ABCD pillar trims, sill trims, carpets, electronic components and fuse trays.	S/N	\$ 1,800.00	\$ 1,800.00 /
7	To dismantle front bumper, rhs front fender, rhs front door, rhs rear door and rear bumper. To renew rhs front fender, rhs front door and rhs rear door. To repair rhs rear fender. To cut out and reweld rhs sill panel. Re-organise crash management components. Reinstall all parts removed.		\$ 7,350.00	\$ 4,000.00 /
8	To respray front bumper, rhs front fender, rhs front door, door handle, rhs wing mirror cover, rhs rear door, rhs sill panel, rhs rear fender and rear bumper.		\$ 6,400.00	\$ 2,450.00
9	To renew rhs front rim, lhs front rim and rhs rear rim. To carry out wheel alignment.	S/N	\$ 360.00	\$ 360.00
10	Added labour - see attached		\$ 280.00	\$ 280.00 /
11	To carry out diagnostic checks.	S/N	\$ 192,00	\$ 192.00 /
	TOTAL LABOUR CHARGES		\$ 19,682.00	\$ 11,802.00

Telefax

Material List for Accident Vehicle Regn No. SKD 6777 B

			Damage Parts	& Pr	ices
S/N	Parts Description		S/NETT	ŀ	REMARKS
1	FRONT BUMPER GUIDE SECTION - RH		\$ 35.00		
2	FRONT FENDER - RH		\$ 778.00	\$	622.00
3	FRONT FENDER ATTACHMENT PARTS		\$ 65.00		
4	FRONT FENDER BRACKET - RH		\$ 25.00		
5	FRONT FENDER BRACKET		\$ 35.00		
6	FRONT FENDER BRACE - LH / RH		\$ 88.00		
7	FRONT WHEEL HOUSING LINER - RH		\$ 158.00	\$	126.00 /
8	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 81.00		
9	FRONT DOOR - RH		\$ 2,279.00	\$	1,823.20 /
10	FRONT DOOR OUTER SEAL - RH	NEC	\$ 146.00	\$	116.80
11	BONDING AGENT	NEC	\$ 45.00	\$	35.92
12	CLEANING SOLUTION	NEC	\$ 65.00	\$	51.68
13	FRONT DOOR ATTACHMENT PARTS		\$ 218.00		
14	FRONT DOOR CATCH		\$ 96.00		
15	TYRE PRESSURE DATA PLATE		\$ 26.00	\$	20.56 /
16	EXTERIOR MIRROR MOUNTING - RH		\$ 938.00		
17	MIRROR CAP - RH		\$ 136.00		
18	MIRROR GLASS - RH		\$ 1,553.00		
19	REAR DOOR - RH		\$ 2,279.00	\$	1,823.20
20	REAR DOOR OUTER SEAL - RH	NEC	\$ 146.00	\$	116.80 /
	SUB TOTAL SPARE PARTS		\$ 9,192.00	\$	4,736.16

Telefax

Material List for Accident Vehicle Regn No. SKD 6777 B

S/N	Parts Description		Damage Parts S/NETT	rices REMARKS	
		c/f	OHIE!	\$	4,736.16
21	BONDING AGENT	NEC	\$ 45.00		
22	CLEANING SOLUTION	NEC	\$ 65.00		
23	REAR DOOR ATTACHMENT PARTS		\$ 117.00		
24	REAR DOOR CATCH		\$ 85.00		
25	CENTRE PILLAR - RH		\$ 2,142.00	\$	1,713.60
26	DATA TAG		\$ 423.00		
27	ALUMINIUM RIM	3	\$ 1,953.00	\$	1,041.60
28	ALUMINIUM RIM RUBBER VALVE	4	\$ 13.00		
29	TRACK CONTROL ARM		\$ 336.00	\$	268.80/
30	STABILIZER BAR		\$ 372.00		is .
31	WHEEL BEARING HOUSING - RH		\$ 532.00	\$	443.60/
32	WHEEL BEARING - FRONT		\$ 442.00	\$	353.60/
33	LOWER BALL JOINT - RH		\$ 117.00	\$	93.20/
34	COUPLING ROD		\$ 88.00		
35	DRIVE SHAFT - RH		\$ 2,005.00		
36	GAS SHOCK ABSORBER		\$ 251.00	\$	200.40 /
37	STRUT MOUNT		\$ 114.00	\$	91.20/
38	DEEP GROOVE BALL THRUST BEARING		\$ 43.00	\$	34.00
39	TRACK ROD		\$ 86.00		
40	TIE ROD END - RH		\$ 118.00		
41	ACRYLIC SEALANT	S/N	\$ 180.00	\$	180.00 /
42	CAVITY WAX	S/N	\$ 140.00	\$	140.00/
43	STONE CHIP	S/N	\$ 180.00	\$	180.00
14	Added parts - see attached		\$ 442.00	\$	353.60
45	SUNDRIES		\$ 400.00	\$	152.88
	TOTAL SPARE PARTS		\$ 19,881.00	\$	9,982.64
	TOTAL LABOUR CHARGES		\$ 19,682.00		11,802.00
	GRAND TOTAL All charges are not inclusive of GST	•	\$ 39,563.00	\$	21,784.64

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu

Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Shenton 07-16 AIG ngapore 0 ttn: Mr. Ac	Building	Estimate No. Date Service Advisor Pages Regn No Model No	12-De Glory 1 of 1 SKD	Tan			
Quantity	Description		Uı	nit Price		Amount	
Parts 1	Wheel bearing assy parts LHS	sond.	\$	442.00	\$	353.60	
			\$	442.00	\$	353. 6 0	H
<u>Labour</u> 1	To remove and renew wheel bearing assy LHS	s/N	\$	280.00	\$	280.00	Mh.
		Labor total	\$	280.00	\$	280.00	
		Part total GRAND TOTAL	\$ \$	442.00 722.00	\$ \$	353. 6 0	

For Premium Automobiles Pte Ltd

Adoin 5

Authorised Signature