

Our Job Ref No : 305351166

Date : 28/11/19

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

To: Saughulan

FINALIZATION FORM

To : LKK

Fax :

Attn : PARAM

: SHD6741P

22/11/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: QBE XD9730L

2. The finalized amount shall be:

(a) Spare Parts after List discount \$171.00

(b) Labour Charges \$480.00

Total for Part-By-Part Repair Cost \$651.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : Ram

Date : 5/11/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305351166
REGN NO : SHD6741P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 23.06.2016
DATE/TIME IN : 22.11.2019 17:15
ACCIDENT DATE : 22.11.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0738-G I40VC COVER-RR BUMPER LWR 1 228.00 25.00 171.00

SUB-TOTAL : 171.00

JOB NATURE

0000 PB PANEL BEATING 280.00

0001 SP SPRAYPAINT CHARGE 200.00

SUB-TOTAL : 480.00

TOTAL : 651.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :