

ASS. REC. BY:

REF: CS3 / msg 19020972 / Gcf 307 Special Instruction:

Surveyor: GA ASSIGNMENT (Office)From (Person): Ferve / Foo Wen yao of MSG Date/Time: 27.11.19 10.319.19

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLN 2790Z Insured: SFR 199Uat Workshop m/s Tk Car Repairs Tel: 64532598of 176 Sin ming drive #01-12Policy No: 29058184 Claim No: 612451

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24.11.2019
(Client's Record)CA / REV / REP. / REV 24 HRS ^{"imp"} H.O.D. Endorsement: _____Date/Time: 27-11-19 10.40.19 Person Contacted: Miss Foo Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLN 2790Z - X
	SFR 199U - X
<u>28/11 9.15pm</u>	<u>Spoken to Miss Foo, she said this case quite complicated so submit PRS they will pass lawyer to handle.</u>
	<u>Demantle: 28/11/2019</u>
	<u>After repair: 3/12/2019</u>

ASS. REC. BY:

REF: MS19

PRS

ASSIGNMENT

From: _____ Date: 27.11.2019
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLN 2790Z
 at Workshop m/s TK car Repairs
 of 176 sin ming drive #01-12
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLN2790Z Yr Regn: 27 Apr 2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Aqua 1.5 c.c. 1496
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 57107 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: NHP 1025677-98
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In Order / Jammed / Leaked / Burnt or _____
 Brake: In Order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/65R15
 R: 11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS "mp"
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 27-11-19
 Survey held at w/s 12pm
 Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$3000 - \$4000</u>

RECEIVED 18 DEC 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Rep. Form: PR2.
 Lump Sum / MP: _____

Days Of Repair: 5
 Resurvey No. of Trip: 2
 Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Survey Fee:	<u>120</u>
Transportation:	_____
S + RS. SI	_____
Photos	_____
Others	<u>11</u>
TOTAL	<u>131</u>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Nov 2019		27 Nov 2019 10:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS				[Created by insurer]																				
Insured:	SEE HSIEN HUEI MELVIN , ID: S7623738G, Tel: +6582018892																							
Main Claimant:	SOO SENG GUAN , ID: S0920971I																							
Vehicle Reg. No.:	SLN2790Z	Date of Loss:	24/11/2019 17:00 - :59 [30 Months and 28 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / 612451	Policy/Cover Note No.:	29058184 (Comprehensive) Coverage: 30/11/2018 - 29/11/2019																					
Vehicle Reg. No. (Insured):	SFR199U	Policy No. (Claimant):																						
		Excess:																						
Repairer:	Tk Car Repairs Pte Ltd (HQ) 176 SIN MING DRIVE, #01-12 SIN MING AUTOCARE, 575721 Sin Ming - Tel: 6453 2598 / 6453 9730																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/11/2019]																							
Driver/Custodian (Insured):	LAM WING CHUEN WINNIE (), NRIC: S7778741J, Tel: +6581230904 Email:																							
Adj Asg. Remarks:	on WP. Liab: unclear. choose LKK. Please outsource.																							
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail																				
There are no mail for this case.																								
<div style="border: 1px solid black; padding: 5px;"> <p>ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	971I
Vehicle Details	
Vehicle No.:	SLN2790Z
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	AQUA HYBRID 1.5S A
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1NZ8020191
Chassis No.:	NHP102567798
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$23,235.00
Original Registration Date:	27 Apr 2017
First Registration Date:	27 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Apr 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	26 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$38,564.00
Total Rebate Amount:	\$42,314.00

The information contained herein is correct as at 27 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/11/2019 16:18
Date Of Accident	24/11/2019 17:30
Exact Location Of Accident	HAIG COURT SERVICE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN2790Z
Insured/Policyholder	
Name Of Registered Owner	SOO SENG GUAN
NRIC No	S0920971I
Email Address	SHANGHAI1005@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96256829
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	AQUA HYBRID 1.5S A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090234320-02
Cover Note Number	

Driver

Name of Driver	SOO SENG GUAN
NRIC No	S0920971I
Date Of Birth	10/05/1945
Occupation	INDOOR
Date Of Driving Pass	30/08/1965
Driving Experience	54 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96256829
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	SHANGHAI1005@GMAIL.COM

Address	5 WARINGIN WALK
Postcode	416276
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHING MEE KHENG (SPOUSE)
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFR199U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name SOO SENG GUAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLN2790Z
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name CHING MEE KHENG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLN2790Z
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:




 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/11/19 about 5.30pm, I was driving my vehicle along the service road of Harg Court, before I enter the car park, vehicle B (SFR 1994) coming from the car park did not stop his vehicle at the stop line, and give way to on coming vehicle, suddenly his vehicle hit onto the right side of my vehicle.

The damaged of my vehicle is right side from front to rear, vehicle B front right side

Vehicle B front right side in

After the accident, I & my wife (Passenger) not feeling well.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Nov 2019		27 Nov 2019 10:31 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	SEE HSIEN HUEI MELVIN, ID: S7623738G, Tel: +6582018892								
Main Claimant:	SOO SENG GUAN, ID: S09209711								
Vehicle Reg. No.:	SLN2790Z	Date of Loss: 24/11/2019 17:00 - :59 [30 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 612451	Policy/Cover Note No.: 29058184AVW (Comprehensive) Coverage: 30/11/2018 - 29/11/2019							
Vehicle Reg. No. (Insured):	SFR199U	Policy No. (Claimant):							
		Excess:							
Repairer:	Tk Car Repairs Pte Ltd (HQ) 176 SIN MING DRIVE, #01-12 SIN MING AUTOCARE, 575721 Sin Ming - Tel: 6453 2598 / 6453 9730								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 28/11/2019]								
Driver/Custodian (Insured):	LAM WING CHUEN WINNIE (), NRIC: S7778741J, Tel: +6581230904 Email:								
Adj Asg. Remarks:	on WP. Liab: unclear. choose LKK. Please outsource.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN2790Z (612451)
[SFR199U]
TP
SOO SENG GUAN
Nov 24 2019 5:00PM
[SEE HSIEN HUEI MELVIN]
Tk Car Repairs Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
2	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
3	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
4	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
5	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
6	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
7	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
8	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
9	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
10	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
11	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
12	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
13	28/11/19 09:01	General View			 Load JPG	<input checked="" type="checkbox"/>	
14	28/11/19 09:02	General View			 Load JPG	<input checked="" type="checkbox"/>	
15	28/11/19 09:02	General View			 Load JPG	<input checked="" type="checkbox"/>	
16	28/11/19 09:02	General View			 Load JPG	<input checked="" type="checkbox"/>	
17	28/11/19 09:02	General View			 Load JPG	<input checked="" type="checkbox"/>	
18	28/11/19 09:02	General View			 Load JPG	<input checked="" type="checkbox"/>	
19	28/11/19 09:02	General View			 Load JPG	<input checked="" type="checkbox"/>	
20	28/11/19 09:02	General View			 Load JPG	<input checked="" type="checkbox"/>	
21	28/11/19 09:02	General View			 Load JPG	<input checked="" type="checkbox"/>	
22	28/11/19 09:02	General View			 Load JPG	<input checked="" type="checkbox"/>	
23	28/11/19 09:02	Odometer Reading			 Load JPG	<input checked="" type="checkbox"/>	
24	28/11/19 09:02	Chassis Number			 Load JPG	<input checked="" type="checkbox"/>	
25	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
26	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
27	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
28	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
29	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
30	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
31	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
32	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
33	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
34	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
35	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
36	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
37	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
38	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
39	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
40	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
41	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
42	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	
43	29/11/19 09:10	Dismantled Parts			 Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	29/11/19 09:10	Dismantled Parts		<input checked="" type="checkbox"/>
45	29/11/19 09:10	Dismantled Parts		<input checked="" type="checkbox"/>
46	29/11/19 09:10	Dismantled Parts		<input checked="" type="checkbox"/>
47	29/11/19 09:10	Dismantled Parts		<input checked="" type="checkbox"/>
48	29/11/19 09:10	Dismantled Parts		<input checked="" type="checkbox"/>
49	29/11/19 09:10	Dismantled Parts		<input checked="" type="checkbox"/>
50	29/11/19 09:10	Dismantled Parts		<input checked="" type="checkbox"/>
51	29/11/19 09:10	Dismantled Parts		<input checked="" type="checkbox"/>
52	29/11/19 09:10	Dismantled Parts		<input checked="" type="checkbox"/>
53	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
54	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
55	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
56	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
57	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
58	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
59	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
60	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
61	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
62	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
63	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
64	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
65	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
66	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>
67	17/12/19 18:42	After Repair Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/11/19 15:08	TP SLN2790Z E-REPORT		<input type="checkbox"/>
2	26/11/19 15:08	PRI		<input checked="" type="checkbox"/>
3	26/11/19 17:48	email to workshop		<input type="checkbox"/>
4	26/11/19 17:48	email from opts		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19020972/GCF3E2

Date: 24/12/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29058184AVW
Claimant	Insured Vehicle No :	SFR199U
Vehicle No : SLN2790Z		
Date of Loss: 24/11/2019	Nature of Claim:	TP Claim No: 612451

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN2790Z		
Make & Model:	TOYOTA AQUA HYBRID, 1.5 E S CVT (A)	Engine No:	1NZ8020191
Reg. Date:	27/04/2017 (Man. Year: 2016)	Chassis No:	NHP102567798
Colour:	White	Odometer:	57107 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	27/11/2019	
Date Inspected:	27/11/2019 Inspected At:	Tk Car Repairs Pte Ltd (HQ) 176 SIN MING DRIVE, #01-12 SIN MING AUTOCARE Singapore 575721
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Dec 2019)
Parts: 144	TOYOTA AQUA HYBRID 1.5 E S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN2790Z)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >