

ASS. REC. BY:

REF: CS3

III/1902/015/Hqd304

Special Instruction:

Supervisor:
Munnen

Hock Ann

ASSIGNMENT (Office)

From (Person)

Gabriel Wee

of

III

Date/Time:

27/11/19 @ 4:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 7956R

Insured:

84A 1871X

at Workshop m/s

M.S. panel Beating

Tel:

9739 1788

of

2 Keeki Bukit Ave 2 # 02-17 Autohub

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26/11/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:47pm @ 27/11/19

Person Contacted:

Mr. Koh

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (X)

SLL 7956R-NA/INC19020938/h4

DOA: 26/11/2019

84A 1871X-NA/INC19020938/h4

DOA: 26/11/2019

Disassemble resurvey - 29/11/19 0133PM

After paint - 04/12/19 0143PM

20/12/19

Submit PPS.

ASS. REC. BY: H-ANIVREF: III

PRS

ASSIGNMENT

From: _____

Date: 28/11/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLL 7956 Rat Workshop m/s M.S. panel Beatingof 2 Kaki Bukit Ave 2 #02-17Insured: Autohub

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: After 10amMr. Koh

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS sup

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLL 7956 RYr Regn: 10/03/2014Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Kia Fortec.c. 1591Colour: whiteA/C: Insured / Std / NI / NASp. Reading: 77728kmT/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 1KNAFJ411M#5708213Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 175/65/R15R: 175/65/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 47 mmR/Bal. 47 mmL/Bal. 47 mmL/Bal. 47 mmD.O.A. 26/11/19D.O.I. 28/11/191215PMSurvey held at M.S. panel BeatingDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range -
Range Days - pending survey cost* SLL 7956 R
PRS caseMV - 55000PV - 45732IVL - 9600

RECEIVED 20 DEC 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 20/12/19 Maser☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee: 120

Transportation: _____

S + RS: _____

Photos _____

Others 11

TOTAL

131Report Format: PRS

Lump Sum / L&E (\$)

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 27 November 2019 4:31 PM
To: Oracle Law Corp; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Zuhaidah Samsuri
Subject: RE: Our Ref: SB/PO/Acc/2019-9203 Your Ref: SHA 1871X
Attachments: 9203 - List of MS_20191127141805.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SLL7956R
III INSURED VEHICLE NO. : SHA1871X
DATE OF LOSS : 26.11.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANT to conduct the pre-repair survey.

This claim is handled by Aida.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Oracle Law Corp [mailto:mail@oraclelaw.sg]
Sent: 27 November, 2019 2:22 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: Our Ref: SB/PO/Acc/2019-9203 Your Ref: SHA 1871X

Dear Gabriel,

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SLL 7956R & SHA 1871X ALONG JUNCTION OF FRENCH ROAD & HORNE ROAD ON 26-11-2019 @ 9.30 A.M.

Please refer to attachment the contents of which are self-explanatory for your kind attention and immediate action.

Regards

Alvin Ong



• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]

Sent: Wednesday, 27 November 2019 2:05 PM

To: Oracle Law Corp <mail@oraclelaw.sg>

Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLL7956R (Accident involving SLL7956R and SHA1871X on 26.11.2019)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860
Email: mail@oracelaw.sg

FACSIMILE TRANSMISSION

To	: India International Insurance Pte Ltd	Date	: 27 th November 2019
Attention	: Motor Claims (Attn: Gabriel Wee)	From	: Mr Stanley Bay / Miss Pauline Ong
Your Ref.	: Insurer of SHA 1871X	Our Ref.	: SB/PO/Acc/2019-9203
Facsimile	: 6225-7743 / 6224-4174	No. of Pages	: 1 (including this page)

IMMEDIATE ATTENTION

Dear Gabriel,

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SLL 7956R & SHA 1871X ALONG JUNCTION OF FRENCH ROAD & HORNE ROAD ON 26-11-2019 @ 9.30 A.M.

1. We refer to your email of even date and your list of motor surveyors.
2. We are instructed by our clients that they are not agreeable to the appointment of any one of the surveyors named in your said list. We append herewith our list of our clients' proposed motor surveyors for your kind consideration to conduct a joint pre-repair survey:-
 - a. Auto Performance Appraisal or
 - b. Absolute Appraisal Services Pte Ltd
3. Kindly let us know **within the two (2) working days** whether you agree to any of the said proposed motor surveyors failing which you are deemed to have agreed to the appointment of any of the motor surveyors named in our said list.

Yours faithfully



Mr Stanley Bay / Miss Pauline Ong

Enc

cc. M.S. Panel Beating Workshop

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	773H
Vehicle Details	
Vehicle No.:	SLL7956R
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Nov 2019
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	G4FGGH651195
Chassis No.:	KNAFJ411MH5708213
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$12,191.00
Original Registration Date:	10 Mar 2017
First Registration Date:	10 Mar 2017
Transfer Count:	1
Actual ARF Paid:	\$12,191.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Mar 2027
PARF Rebate Amount:	\$9,143.00
Intended COE Rebate Details	
COE Expiry Date:	09 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,751.00
COE Rebate Amount:	\$36,189.00
Total Rebate Amount:	\$45,332.00

The information contained herein is correct as at 29 Nov 2019

OK

BLACK FRIDAY WEEKEND DEALS AWAIT.

[REGISTER FOR DEALS](#)


kia forte

Price Range ▼

Depreciation ▼

2017 ▼

Vehicle Type ▼



Home » Used Cars » Euro Performance Asia Pte Ltd » Kia Cerato Forte K3 1.6A

Kia Cerato Forte K3 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREM



EURO PERFORMANCE ASIA PTE LTD

Your Consignment Partner™

Price \$63,500

Depreciation ⓘ \$7,120 /yr
View models with similar depreReg Date 28-Dec-2017
(8yrs 28days COE left)

Mileage 40,000 km (20.8k /yr)

Manufactured ⓘ 2017

Road Tax ⓘ \$738 /yr

Transmission Auto

Dereg Value ⓘ \$43,110 as of today (change)

OMV ⓘ \$11,854

COE ⓘ \$42,339

ARF ⓘ \$11,854

Engine Cap 1,591 cc

Power 95.3 kW (127 bhp)

Curb Weight ⓘ 1,295 kg

No. of Owners ⓘ 1

Type of Vehicle Mid-Sized Sedan

Features

1.6L 4 Cylinders Dual CVT Engine, 127Bhp, 6 Speeds Auto Transmission, ABS, Airbags, Cruise Control, Disc Brakes, Auto Headlights And Rain Sensors. View specs of the Kia Cerato K3 (2013-2018)

Accessories

Full Leather Seats, Factory Audio System, AUX/USB Port, Cruise Control, Multi Control Steering Wheel, Remote Key, Parking Sensors, Solar Films.

Description

1 Owner, Full Agent Maintained. 5 Years C&C Warranty. Accident-Free Condition. Luxury Grey With Black Leather Interiors! Most Popular Kia Model In The Market. Superb Fuel Efficient And Handling! Call Us Now To View This Beauty!

Category

PARF Car, Premium Ad Car

Status

Available

Resources

Compare

- Free

Get value of your existing car for free. Get started



Shortlist

Compare

Add nc

Report Error

More Actions

Seller Information

Euro Performance Asia Pte Ltd

42 vehicles for sale. 47 sold in past 3 mths

1 Magazine Road #01-08

Central Mall

Tel: 65330588 / 85009000

Search cars nearby

Braden

81501500

Sindy

90602839

Felix

90906655

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/11/2019 17:23
Date Of Accident	26/11/2019 09:30
Exact Location Of Accident	FRENCH RD JUNC WITH HORNE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL7956R
Insured/Policyholder	
Name Of Registered Owner	QUEK TING CHYE FRANKIE
NRIC No	S1432773H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87230233
Alternative Phone No	OFFICE-87230233

Vehicle Particulars

Manufacturer	KIA
Model	FORTE K3
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107294329
Cover Note Number	

Driver

Name of Driver	QUEK TING CHYE FRANKIE
NRIC No	S1432773H
Date Of Birth	25/09/1960
Occupation	OUTDOOR
Date Of Driving Pass	28/06/1979
Driving Experience	40 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87230233
Fax Number	
Contact Number	OFFICE-87230233
Email Address	NOEMAIL

Address	BLK 653 SENJA LINK #07-28
Postcode	670653
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I STOP AT THE FRENCH RD TO CHECK ON THE TRAFFIC COMING FROM THE MAIN ROAD, WHEN THE TRAFFIC WAS CLEAR, I CROSS THE JUNC TOWARDS PENHAS RD, SUDDENLY THE TAXI COME FROM MY LEFT SIDE AND HIT ONTO MY VEH FRONT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA1871X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	YEO CHENG KIEW
NRIC/Passport Number	S1113058E
Contact Number	91995038
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Smith

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Ld

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2019 09:50 Edit Reg		27 Nov 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS		[Created by adjuster]		
Insured: -, Co. Reg. No.: -				
Main Claimant: QUEK TING CHYE FRANKIE , Co. Reg. No.: S1432773H				
Vehicle Reg. No.: SLL7956R		Date of Loss: 26/11/2019 09:00 - :59 [32 Months and 16 Days From LTA Reg Date (Man Yr)]		
Claim Type: TP		Policy/Cover Note No.:		
Vehicle Reg. No. (Insured): SHA1871X		Policy No. (Claimant):		
		Excess:		
Repairer: M.s Panel Beating Workshop (HQ) 2 KAKI BUKIT AVE 6, # 02 . 17 AUTOHUB @ KAKI BUKIT, 417921 Kaki Bukit - Tel:				
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]				
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 06/12/2019]				
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Claim Documents

*SLL7956R
[SHA1871X]
TP
QUEK TING CHYE FRANKIE
Nov 26 2019 9:00AM
[-]
M.s Panel Beating Workshop

Upload Documents

Upload Photos

Compose New Letter























































View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/11/19 18:16	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
2	29/11/19 18:16	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
3	29/11/19 18:16	General View		Load JPG	<input checked="" type="checkbox"/>
4	29/11/19 18:16	General View		Load JPG	<input checked="" type="checkbox"/>
5	29/11/19 18:16	General View		Load JPG	<input checked="" type="checkbox"/>
6	29/11/19 18:16	General View		Load JPG	<input checked="" type="checkbox"/>
7	29/11/19 18:16	General View		Load JPG	<input checked="" type="checkbox"/>
8	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
9	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
10	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
11	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
12	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
13	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
14	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
15	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
16	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
17	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
18	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
19	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
20	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
21	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
22	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
23	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
24	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
25	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
26	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
27	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
28	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
29	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
30	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
31	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
32	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
33	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
34	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
35	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
36	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
37	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
38	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
39	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
40	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
41	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
42	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
43	29/11/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	29/11/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
45	29/11/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	29/11/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	29/11/19 18:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	04/12/19 18:29	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
97	04/12/19 18:29	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
98	04/12/19 18:29	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
99	04/12/19 18:29	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	04/12/19 18:29	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	04/12/19 18:29	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
102	04/12/19 18:29	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	04/12/19 18:29	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
104	04/12/19 18:29	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/19 16:59	EMAIL FROM III ON 27/11/2019 TO ARRANGE FOR SURVEY	 Load PDF	
2	27/11/19 17:00	WORKSHOP DETAILS	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	28/11/19 08:34	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19021015/HQD3E2

Date: 26/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SLL7956R

Insured Vehicle No : SHA1871X

Date of Loss: 26/11/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL7956R

Make & Model: KIA FORTE K3, 1.6 (A)

Engine No: G4FGGH651195

Reg. Date: 10/03/2017 (Man. Year: 2017)

Chassis No: KNAFJ411MH5708213

Colour: White

Odometer: 79728 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Continental 4 mm

Rear Left Side: Continental 4 mm

Front Right Side: Continental 4 mm

Rear Right Side: Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/11/2019

Date Inspected: 28/11/2019 Inspected At:

M.s Panel Beating Workshop (HQ)
2 KAKI BUKIT AVE 6, # 02-17
AUTOHUB @ KAKI BUKIT
Singapore 417921

Estimated Period of Repair: 0.0 days

Adjuster: LEE HOCK ANN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Dec 2019)

Parts: 143 KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLL7956R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >