

REF: CS3/CTI18009215/RISd3-1⁰²

Special Instruction:

L/S: \$5800.00

ASSIGNMENT (Office)

From (Person): Edwing Fan of U1911C Date/Time: 26/11/2019

Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: OH Appraisal Service

Workshop: Lim Siang chow

OD/TP Re-inspection ☒ Evaluation

To Inspect Vehicle No: FBH 9443E Insured: Gx7403R

at Workshop m/s Lim Motor Tel: 9766 7543

of 160 Sin Ming Drive # 05-20

Policy No: _____ Claim No: EFA/China 0943A/vi

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28/04/2018

(Client's Record)

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 6 days)

Date/Time: 11/12/19 Submit Final Fig \$3,900/-, 4 days (Red \$ 1,900/- 133 %; Original 6 days)

Date/Time	Action/Instruction
	FBH 9443E-CS3/CTI18009215/R124622 DOA: 28/4/18 1) the reasonable of cost price
	Gx7403R-CS3/CTI18009215/R124622 DOA: 28/4/18 2) The reasonable period of repairs
	3) whether it is economical to repair the plaintiff's Motorcycle - if not what is the value of total loss.
①	Cost price is \$3,900
②	4 day of repair
③	its uneconomical to repair and advisable to total loss
	Noted: MV: 9,000.00 LTA: 1,008.00 NV: 7,992.00
	<i>[Signature]</i> 9/12/2019

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 11 DEC 2019

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

100
100

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____