

TURBOCHARGER

ASS. REC. BY:

REF: CS/TM2 190210331 P2/F3/12

Special Instruction:

Surveyor Ram

ASSIGNMENT (Office)

From (Person): Francis Ng Kwai Kung of TMI

Date/Time: 28.11.19 6:59 AM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SH 61255

Insured: SGX FB5K

at Workshop m/s Combridge

Tel: 214888

of 59 Loyang Drive

Policy No: MJ001137

Claim No: M1909275

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

D.O.A. 27.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 28.11.19 9:10 AM

Person Contacted: Jumani

R.O.D. Endorsement: \_\_\_\_\_

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SH 61255 - CC4 / M18015217 / T119 202 D.O.A. 13/02/2019
	SGX FB5K - A3A / M18015217 / T119 202 D.O.A. 21/11/2019
02/12/19	@ 10:57 am revised PA to Ng Kwai Kung Francis via messenger

view

ASSIGNMENT

SH 61253

11/12/2018

From: \_\_\_\_\_ Date: 28.11.2019

Veh No: SH 72266 Yr Regn: 24/09/2016

Estimated Cost: \_\_\_\_\_

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or \_\_\_\_\_

To inspect Vehicle No: SH 61253

Make: Hyundai iONIQ(G2) cc 1580

at Workshop m/s Comfordelgro

Colour: blue A/C: Insured / Std / NI / NA

of 59 Loyang Drive

Sp. Reading: 18809 T/Radio: Insured / Std / NI / NA

Insured: \_\_\_\_\_

Eng/No: - 18809

Policy No: \_\_\_\_\_

C/No: KMHC851CVKUI21995

Claims No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Steering: Inorder / Jammed / Leaked / Burnt or


(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)



Tyre Size: F: 195/65 R15

R: -

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or DAVANT

Bal. or Market Value: \_\_\_\_\_

Front Rear

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

R/Bal. 7 mm

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

L/Bal. 7 mm

Est. Repair: \_\_\_\_\_ days Res.: Yes or No

D.O.A. 27/11/19 D.O.I. 28/11/19

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

Survey held at Comfordelgro (Loyang)

CA / REV / REP. / 24 HRS myo

Des. of Damages: Frt Rear / O/S / N/S / UIC / Rooftop or rear

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PIP: \$2421.96/=
	3 repair days
	in confirm with Larry NG on 6/12/19
	( \$ 1,353.70 Red - 36% )
	12/12/2019
	RECEIVED 1 DEC 2019

Date/Time File Pass to? 13/12/19

Days Of Repair: 3

1) Type  : Prell. Report

Resurvey No. of Trip: 1

2)  : Final Report

Survey Fee:	
Transportation:	250
3 + RS:	11
PR/RS:	
TR/RS:	
TOTAL:	261

Add Fee:  : Site Insp \$

: Interview \$

: Tech. Invs \$

: Mech/Bus \$

Exp. Total: \$ 2,421.96 PP

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd  
20 McCallum Street  
#09-01 Tokio Marine Centre  
Singapore 069046

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ng Kwai Kay Francis

Date: 02 Dec 2019

**Preliminary Advice**

Insured Vehicle No	: SGX7815K	Accident Date	: 27/11/2019
TP Vehicle No	: SH6125S	Assignment Date	: 28/11/2019
Make	: HYUNDAI IONIQ HYBRID	Est. Duration of Repair	: 3 days
Date of Inspection	: 28/11/2019		
Inspection At	: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,673.62
Revised Amount	:S\$	2,096.96
Check Items (Estimated)	:S\$	437.04
Total	:S\$	2,534.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TP : WP

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2019 16:21 Sendback Est	27 Nov 2019 16:38 S\$3,673.62	28 Nov 2019 08:59 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	OON SAY LEE, ID: S1828324G								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SH6125S	Date of Loss:	27/11/2019 12:00 - :59 [11 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1909275	Policy/Cover Note No.:	M001137 (Comprehensive) Coverage: 06/09/2019 - 05/09/2020						
Vehicle Reg. No. (Insured):	SGX7815K	Policy No. (Claimant):	MCOM0015						
		Excess:	S\$0.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/12/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>									
			View All	Compose Case Mail					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/11/2019 14:17
Date Of Accident	27/11/2019 12:25
Exact Location Of Accident	PIE(TUAS) B4 PAYA LEBAR EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH6125S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ HYBRID
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	CHUA KIAN TIONG
NRIC No	S1615587Z
Date Of Birth	30/06/1963
Occupation	OUTDOOR
Date Of Driving Pass	30/04/1983
Driving Experience	36 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97814578
Fax Number	
Contact Number	
Email Address	KTCHUAKENT@GMAIL.COM

Address	BLK 33 AMBER ROAD #06-10
Postcode	439944
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: - GENDER: FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGX7815K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mali packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


POLICYHOLDER'S SIGNATURE: \_\_\_\_\_  
 Date & Time: \_\_\_\_\_

DRIVER'S SIGNATURE: \_\_\_\_\_  
 (If driver is not the policyholder)  
 Date & Time: \_\_\_\_\_

REPORTING CENTRE PERSONNEL SIGNATURE: \_\_\_\_\_  
 Name: *J. H. H. H.*  
 NRIC/FIN No.: \_\_\_\_\_

1. 1  
 1. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/11/19 at about 1225hrs when I (Veh A) slowed down gradually because vehicles in front stopped, Veh B collided into the rear of my stationary.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*[Signature]*  
S R Moorthy  
CSO 27/11/19

A member of COMFORTDELGRO

Date/Time: 27.11.2019 15:36 Page : 1

Team: ARC Repair TP(CLS0)1      **JOB CARD**      Sales Order:      JC NO.: 305357554


CUSTOMER MS: COMFORT TRANSPORTATION PTE LTD CUSTOMER NO.: 7010045 ADDRESS: 383 SIN MING DRIVE SINGAPORE SINGAPORE 575717 (R) 65508755      (O) (P)	REGN NO.: SH 6125S MAKE: HYUNDAI MODEL: IONIQ(G2) YR OF MANU: 11.12.2018 CHASSIS CODE: RMHC851CVKU121995	MILEAGE FUEL: E _____ 1/2 _____ F DATE/TIME IN: 27.11.2019 13:15 TARGET DATE COMPLETION DATE/TIME:
--	--	--

JOB DESCRIPTION

Accident Date: 27.11.2019  
 NATURE: 3P 27.11.2019

S/NO      LABOR CODE      DESCRIPTION

TOKIO - Rear



CHECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SH 6125S      LARRY

Vehicle No.: SH 6125S

Larry Ng

Signature/Date

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

# ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)**  
**COMFORT TRANSPORTATION PTE LTD**

Singapore

**Claimant Insurer: India International Insurance Pte Ltd**

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	27/11/2019
Vehicle Reg. No.:	SH6125S	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	CHUA KIAN TIONG		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	11/12/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4EAA891659	Chassis No:	KMHC851CVKU121995
Odometer:	1 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER ATTACHED		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,752.62
Miscellaneous Items	11.00
Labour	1,910.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>3,673.62</b>

*Larry Ng* 3777.66

# ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

## (SUPPLEMENTARY)

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**OOON SAY LEE**

Singapore

**Claimant Insurer:** India International Insurance Pte Ltd

### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MJ001137	Date of Loss:	27/11/2019
Vehicle Reg. No.:	<b>SH6125S</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	CHUA KIAN TIONG		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	11/12/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4EAA891659	Chassis No:	KMHC851CVKU121995
Odometer:	1 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER ATTACHED		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

### COST OF CLAIMS

	Amount
Parts	104.04
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 Nov 2019)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SH6125S/27/11/2019 16:38**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>crv</i>	20.00	0.00	*459.40 FL
2	10		*REAR BUMPER CLIPS <i>rec</i>	20.00	0.00	*22.00 FL
3	1		*REAR BUMPER REINFORCEMENT <i>BT</i>	20.00	0.00	*294.80 FL
4	2		*REAR BUMPER REINFORCEMENT BRACKETS - RH/LH <i>DD</i>	20.00	0.00	*276.20 FL
5	1		*REAR BUMPER CENTRE MOLDING ASSY <i>crv</i>	20.00	0.00	*451.25 FL
6	1		*REAR BUMPER LOWER CENTRE MOLDING <i>scr</i>	20.00	0.00	*155.00 FL
7	2		*REAR BUMPER SIDE BRACKETS - RH/LH <i>XUN</i>	20.00	0.00	*66.20 FL
8	1		*REAR PANEL <i>QXUN</i>	20.00	0.00	*155.00 FL
9	1		*REAR PANEL LOWER PANEL <i>QXUN</i>	20.00	0.00	*78.80 FL
10	1		*REVERSE SENSOR <i>XUN</i>	0	0.00	*135.70 FS
11	1		*REAR BUMPER RUBBER MAT <i>rec</i>	0	0.00	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,144.35
- List Item Discount on L Items (S\$)	391.73
<b>Total Parts (S\$)</b>	<b>1,752.62</b>

ComfortDelGro Engineering Pte Ltd/SH6125S/27/11/2019 16:38. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

Larry Ng

# Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New 6.40	900.00
2	SPRAY PANTING	New \$200	500.00
3	WIRING CHARGE	New \$30	80.00
4	TUFF KOTE	New \$30	80.00
5	REMOVE / REFIX REVERSE SENSOR	New \$30	100.00
6	COMPUTER PROGRAMMING FOR BSD RADAR	New x min?	250.00
<b>Gross Labour Cost (S\$)</b>			<b>1,910.00</b>

ComfortDelGro Engineering Pte Ltd/SH6125S/27/11/2019 16:38. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Larry Ng

RAM (LKC)  
 28/11/19 1130hrs  
 Parasuram@LKCauto.com  
 88622778 hr  
 (P/P) Ref paint photo  
 (3 days) ref paint days

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2019)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SH6125S/05/12/2019 15:53**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR LICENSE PLATE <i>CAA</i>	0	0.00	*25.00 FS A
2	1		*REAR BUMPER TOW HOOK COVER <i>CAA</i>	20.00	0.00	*98.80 FL A
<b>Sub Total (S\$)</b>						<b>123.80</b>
<b>- List Item Discount on L Items (S\$)</b>						<b>19.76</b>
<b>Total Parts (S\$)</b>						<b>104.04</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SH6125S/05/12/2019 15:53. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305357554  
 REGN NO : SH 6125S  
 MILEAGE : 000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 11.12.2018  
 DATE/TIME IN : 27.11.2019 13:15  
 ACCIDENT DATE : 27.11.2019

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52	era
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	new
0003	04-01-0104-2533-G	IONIQV2 MOULDING ASSY-RR	1	451.25	20.00	361.00	era
0004	04-01-0104-2545-G	IONIQVC MOULDING-REAR BUM	1	155.00	20.00	124.00	era era
0005	04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1	50.00		50.00	new
0006	FNPS	NO PLATE(S) 1 N	25.00	25.00		?	era Suff
0007	04-01-0104-3819-G	IONIQ STAY-RR BUMPER LH	1	138.10	20.00	110.48	DD - Suff
0008	04-01-0104-3919-G	IONIQ STAY-RR BUMPER RH	1	138.10	20.00	110.48	DD - Suff
0009	04-01-0104-2288-G	IONIQ BEAM-RR BUMPER	1	294.80	20.00	235.84	BT
0010	04-01-0104-2544-G	IONIQVC CAP-RR HOOK	1	98.80	20.00	79.04	era Suff

SUB-TOTAL : 1,480.96

## JOB NATURE

0000 L MERIMEN FEE

11.00

9.9A 20% \$1480.96/=

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305357554  
 REGN NO : SH 6125S  
 MILEAGE : 000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 11.12.2018  
 DATE/TIME IN : 27.11.2019 13:1  
 ACCIDENT DATE : 27.11.2019

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	PB PANEL BEATING	640.00				
0002	23-502 SPRAYPAINT ON AFFECTED AREA	200.00				
0003	17-01 WIRING CHARGE	30.00				
0004	20-00 TUFF COAT ON AFFECTED PARTS.	30.00				
0005	L REMOVE/REFIX REVERSE SENSOR	30.00				
SUB-TOTAL :						941.00
TOTAL :						2,421.96

MVA NAME & SIGNATURE  
 DATE :

AUTHORISED : YES / NO  
 SURVEYOR NAME & SIGNATURE  
 DATE :

Our Job Ref No : 305357554

Date : 4. Dec. 2019

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SH 6125S

Date of Accident: 27. Nov. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO SGX7815K

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,480.96

(b) Labour Charges \$941.00

**Total for Part-By-Part Repair Cost** \$2,421.96


(c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
Final Lumpsum Repair cost \_\_\_\_\_

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Ram

Date : 6/12/19

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI19021033/FSF3N2  
**Date:** 23/12/2019

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MJ001137  
**Claimant Vehicle No :** SH6125S **Insured Vehicle No :** SGX7815K  
 Date of Loss: 27/11/2019 Nature of Claim: TP Claim No: M1909275

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH6125S**  
 Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEJU132618  
 Reg. Date: 11/12/2018 (Man. Year: 2018) Chassis No: KMHC851CVKU121995  
 Colour: Blue Odometer: 188019 km  
 Engine Capacity: 1580 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

### CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15  
 Front Left Side: Davanti 7 mm Rear Left Side: Davanti 7 mm  
 Front Right Side: Davanti 7 mm Rear Right Side: Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,858.66	1,480.96	375.70	20.24
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,910.00	930.00	980.00	51.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,777.66</b>	<b>2,421.96</b>	<b>1,355.70</b>	<b>35.89</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>264.43</b>	<b>169.54</b>	<b>94.89</b>	<b>35.88</b>
<b>Nett Amount (S\$)</b>	<b>4,042.09</b>	<b>2,591.50</b>	<b>1,450.59</b>	<b>35.89</b>

### INSPECTION

Date of Assignment: 28/11/2019 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)  
 Date Inspected: 28/11/2019 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
 59 Loyang Drive  
 Singapore 508969  
 Estimated Period of Repair: 3.0 days

**Adjuster:** PARASURAM SHANMUGAM

**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2019)

**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SH6125S)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Cracked	459.40 FL	-	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	294.80 FL	-	*294.80 FL
4	2		*REAR BUMPER REINFORCEMENT BRACKETS - RH/LH	Dented	276.20 FL	-	*276.20 FL
5	1		*REAR BUMPER CENTRE MOLDING ASSY	Cracked	451.25 FL	-	*451.25 FL
6	1		*REAR BUMPER LOWER CENTRE MOLDING	Scratched	155.00 FL	-	*155.00 FL
7	2		*REAR BUMPER SIDE BRACKETS - RH/LH	Not Necessary	66.20 FL	-	*- FL
8	1		*REAR PANEL	Not Necessary	155.00 FL	-	*- FL
9	1		*REAR PANEL LOWER PANEL	Not Necessary	78.80 FL	-	*- FL
10	1		*REVERSE SENSOR	Not Necessary	135.70 FS	-	*- FS
11	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	-	*50.00 FS
<b>Supplementary #1</b>							
12	1		*REAR LICENSE PLATE	Cracked	25.00 FS	-	*25.00 FS
13	1		*REAR BUMPER TOW HOOK COVER	Cracked	98.80 FL	-	*98.80 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,268.15</b>	<b>1,832.45</b>
- List Item Discount on L Items 20.00/20.00% (S\$)	411.49	351.49
<b>Total Parts (S\$)</b>	<b>1,856.66</b>	<b>1,480.96</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	900.00	640.00
2	SPRAY PANTING	New	500.00	200.00
3	WIRING CHARGE	New	80.00	30.00
4	TUFF KOTE	New	80.00	30.00
5	REMOVE / REFIX REVERSE SENSOR	New	100.00	30.00
6	COMPUTER PROGRAMMING FOR BSD RADAR	New	250.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,910.00</b>	<b>930.00</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;