

2200000

ASS. REC. BY:

REF: CSB/AG/002/051/Gg d 2019

Special Instructions:

Signature: GOV

ASSIGNMENT (Office)

From (Person): McMinn Winnie Fan

of AG

Date/Time: 27/11/19 @ 5:11pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDD1212E

Insured:

SLC9244X

at Workshop m/s

Green Star Spray

Tel:

65463092

of

Blk 3011 Bedok North Avenue 4 # 01-2004

Policy No:

2100467724

Claim No:

789569534154

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:32am @ 27/11/19

Person Contacted:

Jane

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>SDD1212E - CSB/MSA/0010491/Kfg1</u>
	<u>SLC9244X</u>
	<u>Disassemble rearview - 07/12/19</u>
	<u>After paint - 13/12/19</u>
<u>10/1/20</u>	<u>Submit MR.</u>

2019/12/07/2019

ASS. REC. BY:

REF:

MIG

PRS

ASSIGNMENT

(C-2020)

From:

Date:

29/11/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SDD 1212 E

at Workshop m/s

Green Star Spray

of Blk 3011 Bedok North Ave 4 #

Insured:

01-200 4 Ind. polyc G

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

\$32k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SDD 1212 E

Yr Regn:

19 Aug 2010

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 523i 2.5 c.c. 2497

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

84521

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAFP32010C 545317

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

245/45 R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

29-11-19

Survey held at

W/S

3230/pm

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 10 MAR 2020

Date/Time, File Pass to?

☐

: Preli. Report

1) 18/3/2020

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Inve (\$)

☐

: Weekend (\$)

Survey Fee:

180

Transportation:

S + PS \$

Photos

Others

TOTAL

11

191

Report Format:

MEMOAR

Lump Sum / L.B.E (\$)

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE ...

From: Fan, Winnie-LW
To: Admin A, assignments
Cc: Fong, Andy-SY
Sent: 11/27/2019 5:11:47 PM

Hi LKK,

Kindly assist to survey.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: jiamin.mak@alt.sg <jiamin.mak@alt.sg>
Sent: Wednesday, November 27, 2019 4:00 PM
To: AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>
Cc: 'Jerdine' <jerline.wang@alt.sg>; vincent@alt.sg; allister@alt.sg; sales@greenstarsp.com
Subject: [EXTERNAL] PRI - SDD 1212 E

This message is from an external sender; be cautious with links and attachments.

Your Ref: SLC 9244 X

Our Ref: AL.INS.2019.SDD1212E

27 November 2019

AIG ASIA PACIFIC INSURANCE PTE. LTD. **BY EMAIL ONLY**
78 Shenton Way
Tower 2 #07-16
Singapore 079120

Dear Sirs,

ACCIDENT INVOLVING SDD 1212 E & SLC 9244 X ALONG BEDOK SOUTH AVENUE 3 ON 25 NOVEMBER 2019 AT ABOUT 1430 HOURS

We act for the owner of vehicle no. SDD 1212 E.

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop:-

GREEN STAR SPRAY PAINTING

Blk 3011 Bedok North Avenue 4
#01-2004 Bedok Industrial Park E
Singapore 489977
Person In-Charge: Jane
Mobile Number: 6546 3092

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jerdine / Jiamin at 6422 2187 or email us at jiamin.mak@alt.sg / jerline.wang@alt.sg for future correspondences.

** Kindly be reminded of the change of our address as stated below.*

Best Regards,

Jiamin

For and on behalf of
Allister Lim

**ALLISTER LIM & THRUMURGAN
ADVOCATES & SOLICITORS**

1 Coleman Street
#05-01, The Adelphi
Singapore 179803
Telephone : 6422 2187
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	542A
Vehicle Details	
Vehicle No.:	SDD1212E
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Dec 2019
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	07467497N52B25AF
Chassis No.:	WBAFP32010C545317
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$44,354.00
Original Registration Date:	19 Aug 2010
First Registration Date:	19 Aug 2010
Transfer Count:	1
Actual ARF Paid:	\$44,354.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Aug 2020
PARF Rebate Amount:	\$22,177.00
Intended COE Rebate Details	
COE Expiry Date:	18 Aug 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$41,000.00
COE Rebate Amount:	\$2,838.00
Total Rebate Amount:	\$25,015.00

The information contained herein is correct as at 02 Dec 2019

OK

▶ bmw 523i Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
BMW 5 Series 523i	\$29,700	\$19,380 /yr	28-Jun-2010	2,497 cc	107,000 km		Availabl
Perfect Daily Driver. Sleek Piano Black Interior, No Uncle Feels. Serviced By R2D. Usual Wear And Tear Suspects All Done Up. Planned For COE Extension But Job Dictates Otherwise. No Finance On The Car... Office No. - - Jo - 97774892							
BMW 5 Series 523i	\$34,500	\$24,800 /yr	21-Jun-2010	2,497 cc	101,000 km	Creation Auto	Availabl
10yr COE At Only 2.98%Very Low Mileage Car In Excellent Condition And Leather Washed Plus Armrest Changed. Engine Fully Stock And In Good Condition! View To Test Drive And Check The Car. Serviced Ever... Office No. - 96428388 Jimmy Tang - 96428388							
BMW 5 Series 523i	\$39,800	\$22,880 /yr	27-Oct-2010	2,497 cc	-	Classic Credit Pte Ltd	Availabl
Best Unit.Elegant White.Luxury Interior.Free Extended Warranty.Optional 10 Years COE Renewal For \$79,800. Elegant White With Beautiful Interior.Very Clean Looking.Must View.Up To 100% Flexible Loan, W... Office No. - 68412076 / 68481203 / 68414849 Mike - 96365270 Roland - 97479331 Mr Chen - 90044461							
BMW 5 Series 523i (New 10-yr COE)	\$69,800	\$6,970 /yr	02-Jun-2010	2,497 cc	168,000 km	D&L Auto Trading	Availabl
100% Guaranteed Accident-Free, Cheapest In Market, New \$10K Wear & Tear Parts Replaced Receipts Proof, 90% Loan At 3.18%, Guaranteed Loan For Bad Credit/Ex-Bankruptcy, View After Lunch Till 11PM Daily... Office No. - 62960188 Charles Low - 98213200							
BMW 5 Series 523i (New 10-yr COE)	\$73,800	\$7,370 /yr	21-May-2010	2,497 cc	-	Performa'r Auto Trading Pte Ltd	Availabl
Very Well Taken Care By Owner! All Wear And Tear Replaced! Smooth Engine, Gearbox And Interior Very Clean Condition!, Low Depreciation Own A BMW 5 Series! Ready For The Next 10 Years.Hurry Call Us ... Office No. - - Sam - 92479123							
BMW 5 Series 523i Highline (New 10-yr COE)	\$75,500	\$7,540 /yr	30-Jul-2010	2,497 cc	94,000 km		Availabl
100% Worth To View. Genuine Low Mileage. Look Photos! Superb Perfect Clean. Beautiful Car Showroom Looks. Expensive Sport Rims. All Servicing Done. All Engine Oil Changed, Automatic Transmission Fluid... Office No. - - AI - 96986115 NK - 93876534							
BMW 5 Series 523i (New 10-yr COE)	\$76,888	\$7,680 /yr	31-May-2010	2,497 cc	122,000 km	Euro-Asia Motor	Availabl
2 Owner, PML Unit, Fully Serviced And Maintained By Juzz For Cars (BMW Specialist), All Wear And Tear Replaced, No Repaired Needed, All Inspection Welcome, View Now. Office No. - 65150595 Desmond - 91070316							
BMW 5 Series 523i (New 10-yr COE)	\$76,999	\$7,690 /yr	28-Jun-2010	2,497 cc	-	99 Motors Trading	Availabl
No Gimmicks! Price Negotiable, Low Mileage Done, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worthy Buy, Call N For Viewing. Office No. - 62844922 Mr Nah - 81896183 Raymond Tang - 81850016 Mr Wong - 98533943 Bobby Geh - 96365598							
BMW 5 Series 523i Sunroof (New 10-yr COE)	\$77,068	\$7,700 /yr	29-Sep-2010	2,497 cc	176,000 km	Autoline Credit Pte Ltd	Availabl

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/11/2019 11:36
Date Of Accident	25/11/2019 14:30
Exact Location Of Accident	BEDOK SOUTH AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDD1212E
Insured/Policyholder	
Name Of Registered Owner	LIM CHIN HUAT
NRIC No	S1192542A
Email Address	LIMCHINHUAT8@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90916878
Alternative Phone No	OTHERS-90916878

Vehicle Particulars

Manufacturer	BMW
Model	523i-2.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA497848/1
Cover Note Number	

Driver

Name of Driver	LIM CHIN HUAT
NRIC No	S1192542A
Date Of Birth	05/07/1956
Occupation	INDOOR
Date Of Driving Pass	08/08/1987
Driving Experience	32 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90916878
Fax Number	
Contact Number	OTHERS-90916878
EMail Address	LIMCHINHUAT8@GMAIL.COM

Address	488 UPPER EAST COAST ROAD #05-09 SINGAPORE
Postcode	466520
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WIFE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC9244X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

11:47am

26/11/15

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:

pemen

Sketch Plan #2

SKETCH PLAN

		Vehicle A - 6D51212E B - 5LC9244X
Legend Vehicle Motorcycle		

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At abt 2.30pm, I was driving along New Upper Changi Rd East turning right into Bedok South Ave 3. The other car was turning left from the slip road into Bedok South Ave 3. I was in the right lane whereas the other car was in the left lane. She somehow kept her car moving towards the right lane unaware till it scrapped against the left side of my car. We stopped both car cars along the roadside. She told me she is willing to pay for the damages of my car and asked me to go to my own workshop to estimate the cost. I did just that and she called me to find out. Apparently the cost was too high and she decided that I should from her insurance.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

26/11/2019
 11:47am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

penen

Common Statement

ACCIDENT STATEMENT (Part I)

This is NOT an admission of blame / liability, but a summary of identities and facts which will speed up the settlement of claims.

1) Date of accident: 25/11/19 Time: 1430 2) Exact location of accident: Badok South Ave 3

3) Material damage to vehicles other than vehicles A and B: No ☒ Yes ☐ To objects other than vehicles: No ☒ Yes ☐ 4) Witness' name, address and tel no. (to be undertaken if vehicle is passenger in vehicle A or vehicle B):

To be signed by BOTH drivers: 5) Injuries even if slight: No ☒ Yes ☐ Vehicle Video Camera Available: Yes ☒ No ☐

Registration No. (VEHICLE A): SDD122E

6) Insured / policyholder (see insurance card):

Name: Lim Chin Huat (capital letters)

Address: 488 Upper East Coast Road #05-09 546620

NRIC / Passport No: S1192542A

Tel no. (Home/Cell/ISD/Other): 9091 6878

7) Vehicle: BMW 523i 2.5

Make, type:

8) Insurance company: AXA - C ☒ TPFT ☐ TPO

Does the policy cover damage to vehicle A? No ☐ Yes ☒

Policy No: GA497848/1

9) Driver: ☒ Driver as Owner

Name: (capital letters)

NRIC / Passport No: 3

Class of licence: 3

HP: Gender: Male ☒ Female ☐

12) CIRCUMSTANCES

Put a cross (X) in each of the relevant boxes applicable to your vehicle

- A
- Q1 ☐ Other's offence
- Q2 ☐ Collided with Roadside
- Q3 ☐ Collided with Motorcyclist
- Q4 ☐ Collided with Pedestrian
- Q5 ☐ Collided with Passenger
- Q6 ☐ Collided with Property
- Q7 ☐ Collision - changed lanes / lane
- Q8 ☐ Collision - front / rear
- Q9 ☐ Collision - head on / oblique
- Q10 ☐ Collision - head to head
- Q11 ☐ Collision - vehicle / vehicle
- Q12 ☐ Collision - opening door of vehicle
- Q13 ☐ Collision - Roadblock
- Q14 ☐ Collision - U Turn
- Q15 ☐ Driver Drunk / Drug Influence
- Q16 ☐ Fire Explosion or lightning
- Q17 ☐ Road
- Q18 ☐ Wind Rain / Haze / Fog / Damaged when parked
- Q19 ☐ Hit by falling tree / other objects
- Q20 ☐ See Collision
- Q21 ☐ See Collision
- Q22 ☐ Road

State TOTAL number of boxes marked with a cross

13) Sketch of accident when impact occurred

Please indicate: 1. layout of the road; 2. the direction of vehicles A and B with arrows; 3. their positions at the time of impact; 4. the road signs; 5. names of the streets or roads

REFER TO ATTACHED

10) Indicate the point of initial impact with an arrow (→)



11) Visible damage to vehicle A



14) My remarks

10) Indicate the point of initial impact with an arrow (→)



11) Visible damage to vehicle B



14) My remarks

15) Signatures of drivers

event of disputes over the extent of damage to property, please refer to 11 and 12. This information is essential.

Do not alter anything in this statement after signing. Subsequently, both drivers should take the same steps.

For insured's individual statement (Part II) see overleaf →

Individual Statement

Sales @ green stars sp. com

INDIVIDUAL STATEMENT (Part II)
To be completed and submitted within 24 hours to your insurer or local or appointed workshop (use a separate sheet of paper where necessary)

Overseas driver's license / Tax (if any): _____ Email: tim.chinhua@gmail.com

Insured

1. Occupation (if more than one, state all): _____

2. Vehicle registration no.: CC If commercial vehicle, state permissible carrying capacity: _____

3. Is driver the owner? ☒ Yes ☐ No If no, state relationship of driver with owner: _____ State the vehicle number and name of owner of driver's own vehicle (where applicable): _____

4. Exact purpose for which vehicle was being used at time of accident: ☐ Private use ☐ Commercial use ☐ Hire & reward ☐ Private hire ☐ Others - please specify: _____

5. Is the vehicle still in use? ☐ Yes ☐ No If no, state where it is at present: _____ for no: _____

6. Are you claiming under your own insurance policy for repair to your vehicle? ☐ Yes ☒ No If no, state action to be taken: ☐ Third Party ☐ Reporting Only ☒ Third Party (Own Workshop)

Driver or person in charge of vehicle at the time of accident (including insured)

7. Date of birth: 5/7/5 Occupation: Indoor Date of license pass: 8/8/07 Was vehicle driven with the insured's permission? ☒ Yes ☐ No Was driver an employee of the insured's company? ☐ Yes ☒ No

8. Give details of any pre-existing impairment of sight or hearing and of any other disability: _____

9. Full details of all driving convictions including pending prosecutions in the last 36 months:

Date	Offence	Penalty

Injured persons

10. Name(s), address(es) and approximate age(s)	Injuries sustained	If vehicle occupants, state in which vehicle	Were seat belts being worn?	Was injured conveyed to hospital by ambulance?
			Yes ☐ No ☐	Yes ☐ No ☐
			Yes ☐ No ☐	Yes ☐ No ☐
			Yes ☐ No ☐	Yes ☐ No ☐
			Yes ☐ No ☐	Yes ☐ No ☐

Damage to property & vehicles (other than vehicles A and B)

11. Name(s) and address(es) of owner(s)	Vehicle registration no. or details of property	Nature of damage	Insurer's name and address (if known)

Police action

12. Was the accident reported to the Police? ☐ Yes ☒ No If yes, please state which Police station: _____

13. Was notice of intended prosecution given? ☐ Yes ☒ No If yes, against whom? _____

Accident details

14. Weather conditions: ☒ Clear ☐ Raining ☐ Others: _____

15. Road surface: ☐ Wet ☒ Dry ☐ Others: _____

16. Speed of vehicles: A ☐ km/hr B ☐ km/hr

17. What warnings were given by driver or other party? _____

18. Were street lights illuminated? ☐ Yes ☐ No

19. What lights were displayed on your vehicle/the other vehicle(s)? _____

20. If your vehicle is commercial, state weight of load carried at time of accident: _____

21. State how accident happened, width of road, speed limits, etc. (Refer to attached): _____

22. State number of Passengers (including Driver): 2 Wife

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's signature: _____ Date: _____

Driver's signature (if driver is not the policyholder): _____ Date: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2019 Edit Reg		27 Nov 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	CHER TSE HONG ANNE, ID: S1256769C		
Main Claimant:	-		
Vehicle Reg. No.:	SDD1212E	Date of Loss:	25/11/2019 00:00 - :59 [111 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7895695341SG	Policy/Cover Note No.:	2100467924 (Comprehensive) Coverage: 30/05/2019 - 29/05/2020
Vehicle Reg. No. (Insured):	SLC9244X	Policy No. (Claimant):	
		Excess:	
Repairer:	Green Star Spray Painting Garage (Bedok) Blk3011 Bedok North Ave4, #01-2004/2006 Bedok Ind. Park E, 489977 Bedok - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/12/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (02/12/2019): Request to upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDD1212E (7895695341SG)

[SLC9244X]

TP

-

Nov 25 2019 12:00AM

[CHER TSE HONG ANNE]

Green Star Spray Painting Garage

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		v	☒		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	02/12/19 10:52	Video - Accident													Load MP4					
2	02/12/19 10:52	Video - Accident													Load MP4					
															3 per page		v	☒		
Photos/Images																				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	16/12/19 09:44	Odometer Reading													Load JPG	☒				
2	16/12/19 09:44	Chassis Number													Load JPG	☒				
3	16/12/19 09:45	General View													Load JPG	☒				
4	16/12/19 09:45	General View													Load JPG	☒				
5	16/12/19 09:45	General View													Load JPG	☒				
6	16/12/19 09:45	General View													Load JPG	☒				
7	16/12/19 09:45	General View													Load JPG	☒				
8	16/12/19 09:45	General View													Load JPG	☒				
9	16/12/19 09:45	General View													Load JPG	☒				
10	16/12/19 09:45	General View													Load JPG	☒				
11	16/12/19 09:45	General View													Load JPG	☒				
12	16/12/19 09:45	General View													Load JPG	☒				
13	16/12/19 09:45	General View													Load JPG	☒				
14	16/12/19 09:45	General View													Load JPG	☒				
15	16/12/19 09:45	General View													Load JPG	☒				
16	16/12/19 09:45	General View													Load JPG	☒				
17	16/12/19 09:45	General View													Load JPG	☒				
18	16/12/19 09:45	General View													Load JPG	☒				
19	16/12/19 09:45	General View													Load JPG	☒				
20	16/12/19 09:45	General View													Load JPG	☒				
21	16/12/19 09:45	General View													Load JPG	☒				
22	16/12/19 09:45	General View													Load JPG	☒				
23	16/12/19 09:45	General View													Load JPG	☒				
24	16/12/19 09:45	General View													Load JPG	☒				
25	16/12/19 09:45	General View													Load JPG	☒				
26	16/12/19 09:45	General View													Load JPG	☒				
27	16/12/19 09:45	General View													Load JPG	☒				
28	16/12/19 09:45	General View													Load JPG	☒				
29	16/12/19 09:45	General View													Load JPG	☒				
30	16/12/19 09:45	General View													Load JPG	☒				
31	16/12/19 09:45	General View													Load JPG	☒				
32	16/12/19 09:45	General View													Load JPG	☒				
33	16/12/19 09:45	General View													Load JPG	☒				

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	16/12/19 09:45	General View		☒
35	16/12/19 09:45	General View		☒
36	16/12/19 09:45	General View		☒
37	16/12/19 09:45	General View		☒
38	16/12/19 09:45	General View		☒
39	16/12/19 09:45	General View		☒
40	16/12/19 09:45	General View		☒
41	16/12/19 09:45	General View		☒
42	16/12/19 09:45	General View		☒
43	16/12/19 09:45	General View		☒
44	16/12/19 09:45	General View		☒
45	16/12/19 09:45	General View		☒
46	16/12/19 09:45	General View		☒
47	16/12/19 09:45	General View		☒
48	16/12/19 09:45	General View		☒
49	16/12/19 09:45	General View		☒
50	16/12/19 09:45	Dismantled Parts		☒
51	16/12/19 09:45	Dismantled Parts		☒
52	16/12/19 09:45	Dismantled Parts		☒
53	16/12/19 09:45	Dismantled Parts		☒
54	16/12/19 09:45	Dismantled Parts		☒
55	16/12/19 09:45	Dismantled Parts		☒
56	16/12/19 09:45	Dismantled Parts		☒
57	16/12/19 09:45	Dismantled Parts		☒
58	16/12/19 09:45	Dismantled Parts		☒
59	16/12/19 09:45	Dismantled Parts		☒
60	16/12/19 09:45	Dismantled Parts		☒
61	16/12/19 09:45	Dismantled Parts		☒
62	16/12/19 09:45	Dismantled Parts		☒
63	16/12/19 09:45	Dismantled Parts		☒
64	16/12/19 09:45	Dismantled Parts		☒
65	16/12/19 09:45	Dismantled Parts		☒
66	16/12/19 09:45	Dismantled Parts		☒
67	16/12/19 09:45	Dismantled Parts		☒
68	16/12/19 09:45	Dismantled Parts		☒
69	16/12/19 09:45	Dismantled Parts		☒
70	16/12/19 09:45	Dismantled Parts		☒
71	16/12/19 09:45	Dismantled Parts		☒
72	16/12/19 09:45	Dismantled Parts		☒
73	16/12/19 09:45	Dismantled Parts		☒
74	16/12/19 09:45	Dismantled Parts		☒
75	16/12/19 09:45	Dismantled Parts		☒
76	16/12/19 09:45	Dismantled Parts		☒
77	16/12/19 09:46	After Repair Photo		☒
78	16/12/19 09:46	After Repair Photo		☒
79	16/12/19 09:46	After Repair Photo		☒
80	16/12/19 09:46	After Repair Photo		☒
81	16/12/19 09:46	After Repair Photo		☒
82	16/12/19 09:46	After Repair Photo		☒
83	16/12/19 09:46	After Repair Photo		☒

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
84	16/12/19 09:46	After Repair Photo	 Load JPG	☒
85	16/12/19 09:46	After Repair Photo	 Load JPG	☒
86	16/12/19 09:46	After Repair Photo	 Load JPG	☒
87	16/12/19 09:46	After Repair Photo	 Load JPG	☒
88	16/12/19 09:46	After Repair Photo	 Load JPG	☒
89	16/12/19 09:46	After Repair Photo	 Load JPG	☒
90	16/12/19 09:46	After Repair Photo	 Load JPG	☒
91	16/12/19 09:46	After Repair Photo	 Load JPG	☒
92	16/12/19 09:46	After Repair Photo	 Load JPG	☒
93	16/12/19 09:46	After Repair Photo	 Load JPG	☒
94	16/12/19 09:46	After Repair Photo	 Load JPG	☒
95	16/12/19 09:46	After Repair Photo	 Load JPG	☒
96	16/12/19 09:46	After Repair Photo	 Load JPG	☒
97	16/12/19 09:46	After Repair Photo	 Load JPG	☒
98	16/12/19 09:46	After Repair Photo	 Load JPG	☒
99	16/12/19 09:46	After Repair Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/03/20 16:55	TP GIA REPORT	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	02/12/19 10:52	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19021051/GQD3E2

Date: 19/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100467924
Claimant Vehicle No : SDD1212E **Insured Vehicle No :** SLC9244X
Date of Loss: 25/11/2019 **Nature of Claim:** TP **Claim No:** 7895695341SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDD1212E
Make & Model: BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) **Engine No:** 07467497N52B25AF
Reg. Date: 19/08/2010 (Man. Year: 2010) **Chassis No:** WBAFP32010C545317
Colour: Grey **Odometer:** 84521 km
Engine Capacity: 2497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 **Rear Tyre Size:** 245/45 R18
Front Left Side: Pirelli 6 mm **Rear Left Side:** Pirelli 6 mm
Front Right Side: Pirelli 6 mm **Rear Right Side:** Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/11/2019
Date Inspected: 29/11/2019 **Inspected At:** Green Star Spray Painting Garage (Bedok)
 Blk3011 Bedok North Ave4, #01-
 2004/2006 Bedok Ind. Park E
 Singapore 489977
Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Repair	0.00 F	*- F
2	1		*FRT LH DOOR WING MIRROR	Repair	0.00 F	*- F
3	1		*ROCKER PANEL LH	Repair	0.00 F	*- F
4	1		*FRT BUMPER	Cut	0.00 F	*- F
5	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
6	1		*FRT LH FENDER	Repair	0.00 F	*- F
7	1		*FRT LH FENDER LAMP	Missing	0.00 F	*- F
8	1		*FRT LH WHEEL RIM	Cut	0.00 F	*- F
9	1		*FRT LH KNUCKLE ARM BEARING	Distorted	0.00 F	*- F
10	1		*REAR LH DOOR	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >