



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 27/11/2019

User ID : BoonChewTay

Section A - Accident Details	
Registration Number	SG6018Z
Case Reference Number	BUS/11/19/1020
Registration Date	3/12/2018
Company Type	SMRT Buses Ltd
Make	A95 MAN E6
Model	MAN A95
Name of Driver	Mohamad Aideal Bin Mohd Noor
Type of Accident	Side Swipe
Accident Date and Time	7/11/2019 9:34 PM
Accident Reported Date and Time	11/11/2019 3:12 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG6018Z-RIGHT REAR PORTION SMJ8975C ( TP ) INSURED WITH AIG
Prepared Date and Time	27/11/2019 11:20 AM
Chassis Number	WMAA95ZZXKF008277
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$0.00
Total Spray Cost	\$324.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$854.00</b>	<b>\$0.00</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	27/11/2019 11:27 AM	
Signature		x
Remarks		

*Steve (LKR) wir Anruf  
27/11/19, 1.39pm  
1 day  
L/S  
By ALSP*

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Date: \_\_\_\_\_  
 Signature: \_\_\_\_\_  
 Acknowledged by Repairer: \_\_\_\_\_  
 is subject to final approval from Insurance Company  
 • Subsequently, items must be reviewed  
 • No legal action will be allowed  
 • Third party survey is on "Without Prejudice" basis  
 • Parts prices are subject to confirmation  
 • To ensure damaged parts during survey  
 the Repairer of the following:



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/11/2019

User ID : BoonChewTay

### Section D - Details of Repair Estimates

<b>Part 1 - Labour Works</b>									
Job Scope				Quotation from AR			Adjusted by Surveyor, if applicable		
TO REPAIR REAR RHS PORTION				\$530.00			265		
<b>Total Labour</b>				<b>\$530.00</b>					
<b>Part 2 - Spray Painting &amp; Panel Beating Related Works</b>									
Job Scope				Quotation from ARC			Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$324.00			262		
<b>Total Spray Painting &amp; Panel Beating</b>				<b>\$324.00</b>					
<b>Part 3 - Other Costs - Accident and Accident Repair Related Expense</b>									
Job Scope				Quotation from ARC			Adjusted by Surveyor, if applicable		
<b>Total Other Costs</b>									
<b>Part 4 - Spare Parts / Material Usage</b>									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
<b>Total</b>									
<b>Added Spare Parts / Material Usage After Surveyor Signed off</b>									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date: