



Jin Le

SMRT Accident Vehicle Repair Estimates


SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/12/2019
 User ID : CatherineLee

Section A - Accident Details

Registration Number	SG6018Z
Case Reference Number	BUS/11/19/1020
Registration Date	3/12/2018
Company Type	SMRT Buses Ltd
Make	A95 MAN E6
Model	MAN A95
Name of Driver	Mohamad Aideel Bin Mohd Noor
Type of Accident	Side Swipe
Accident Date and Time	7/11/2019 9:34 PM
Accident Reported Date and Time	11/11/2019 3:12 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104581
Special Instruction to ARC, if any	SG6018Z-RIGHT REAR PORTION SMJ8975C (TP) INSURED WITH AIG
Prepared Date and Time	27/11/2019 11:20 AM
Chassis Number	WMAA95ZZXKF008277
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$324.00	\$262.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$854.00	\$527.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN
ARC / Surveyor Sign Off Date	27/11/2019 11:27 AM	27/11/2019 3:59 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/12/2019

User ID : CatherineLee

Section D - Details of Repair Estimates										
Part 1 - Labour Works										
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable			
O REPAIR REAR RHS PORTION			\$530.00				\$265.00 /			
Total Labour			\$530.00				\$265.00			
Part 2 - Spray Painting & Panel Beating Related Works										
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$324.00				\$262.00 /			
Total Spray Painting & Panel Beating			\$324.00				\$262.00			
Part 3 - Other Costs - Accident and Accident Repair Related Expense										
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs										
Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
Total										
Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
Total										



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/11/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REPAIR REAR RHS PORTION		\$530.00				265			
Total Labour		\$530.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$324.00				262			
Total Spray Painting & Panel Beating		\$324.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: