



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 13/12/2019

User ID : CatherineLee

### Section A - Accident Details

Registration Number	SG6019X
Case Reference Number	BUS/11/19/1056
Registration Date	11/12/2018
Company Type	SMRT Buses Ltd
Make	A95 MAN E6
Model	A95
Name of Driver	Loh Wan Thim
Type of Accident	Side Swipe
Accident Date and Time	22/11/2019 12:55 PM
Accident Reported Date and Time	25/11/2019 4:09 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104590
Special Instruction to ARC, if any	SG6019X-RIGHT FRONT PORTION YP832K ( TP ) INSURED WITH
Prepared Date and Time	26/11/2019 11:42 AM
Chassis Number	WMAA95Z26KF008311
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$1,060.00
Total Spray Cost	\$616.00	\$524.00
Total Spare Part Cost	\$3,820.41	\$1,997.91
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,761.41	\$3,581.91
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN
ARC / Surveyor Sign Off Date	26/11/2019 11:57 AM	27/11/2019 4:00 PM
Signature		
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/12/2019

User ID : CatherineLee

Section D - Details of Repair Estimates									
<b>Part 1 - Labour Works</b>									
Job Scope				Quotation from ARC			Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$1,325.00			\$1,060.00		
Total Labour				\$1,325.00			\$1,060.00		
<b>Part 2 - Spray Painting &amp; Panel Beating Related Works</b>									
Job Scope				Quotation from ARC			Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$616.00			\$524.00		
Total Spray Painting & Panel Beating				\$616.00			\$524.00		
<b>Part 3 - Other Costs - Accident and Accident Repair Related Expense</b>									
Job Scope				Quotation from ARC			Adjusted by Surveyor, if applicable		
Total Other Costs									
<b>Part 4 - Spare Parts / Material Usage</b>									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010161			FRONT VIEW MIRROR RH	1.00	\$1,244.90	10.00	\$1,120.41	Replace	Replace
6013471	Body	124-2-2-009-002	O/S FRP FRONT HEADLAMP COVER	1.00	\$975.00	10.00	\$877.50	Replace	Replace
		81-25101-6766	HEADLAMP RHS	0.00	\$2,025.00	0.00	\$0.00	Replace	Check
Total					\$4,244.90		\$1,997.91		
<b>Added Spare Parts / Material Usage After Surveyor Signed off</b>									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

**LKK Auto Consultants** hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662523
Accident Reporting Number : 68662672

Date Generated : 27/11/2019

User ID : BoonChewTay

### Section A - Accident Details

Registration Number	SG6019X
Case Reference Number	BUS/11/19/1056
Registration Date	11/12/2018
Company Type	SMRT Buses Ltd
Make	A95 MAN E6
Model	A95
Name of Driver	Loh Wan Thim
Type of Accident	Side Swipe
Accident Date and Time	22/11/2019 12:55 PM
Accident Reported Date and Time	25/11/2019 4:09 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG6019X-RIGHT FRONT PORTION YP832K (TP) INSURED WITH
Prepared Date and Time	26/11/2019 11:42 AM
Chassis Number	WMAA95ZZ6KF008311
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$3,820.41	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$5,761.41</b>	<b>\$0.00</b>
Lump Sum Total	\$0.00	
Number of Repair Days	4.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	26/11/2019 11:57 AM	
Signature		
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

27/11/19, 2:00pm

Steve

w/ L M/L  
3 days

P/P  
Ry B/L SY





# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/11/2019  
User ID : BoonChewTay

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope									
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.					Quotation from AR				
Total Labour					\$1,325.00		Adjusted by Surveyor, if applicable		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope									
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS					Quotation from ARC				
Total Spray Painting & Panel Beating					\$616.00		Adjusted by Surveyor, if applicable		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope									
Total Other Costs					\$616.00		Adjusted by Surveyor, if applicable		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
9010161			FRONT VIEW MIRROR RH	1.00	\$1,244.90	10.00	\$1,120.41	Replace	OR
9013471	Body	124-2-2-009-002	O/S FRP FRONT HEADLAMP COVER	1.00	\$975.00	10.00	\$877.50	Replace	OR
		\$1-25101-6766	HEADLAMP RHS	1.00	\$2,025.00	10.00	\$1,822.50	Replace	OR
Total					\$4,244.90		\$3,820.41	Replace	? X A/N
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey