

22/03/2002

ASS. REC. BY:

REF: CS/MSG19021071/R14f3

Special Instruction:

Surveilor: Rosu

ASSIGNMENT (Office)

From (Person): Trin Ton Get Ing of ms19 Date/Time: 28.11.19 15.52p.m

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKP 984x Insured: FBF 7802 Bat Workshop m/s K's Performance Tel: 96889279of LT Yunnan Drive 3Policy No: MSD/VMT/18-391739-CA Claim No: MSC/V/19-001831

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 6.11.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 28.11.19 3.57p.m Person Contacted: William H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>SKP 984x - x</u>
	<u>FBF 7802 B - CS3/INC/16007186/6h3c2 DUA-18/04/2016</u>

ACT. REC. BY: Ram

REF:

ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKP 984Xat Workshop m/s K's Performanceof 67, YUNAN DRIVE 3

Insured:

MSK

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKP 984X

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen

C.C

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

162916

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVG 222 1TZFW 000 771Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firenza

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

06/11/19

D.O.I.

28/11/19

Survey held at

67, YUNAN DR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/12/19Sent Preli by Merimen (Pending Estimate)16/11/20Sent Preli by Merimen16/11/20Submit US \$4000/- (Red \$2424-00, 37%)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

16/11/20 TypistDays Of Repair: 6Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format:

Total Sum of Fees:

\$4000/-

View Sent Message

This mail is associated with :

***SKP984X (MSC/V/19-001383)**
[FBF7802B]

TP
K'S PERFORMANCE
Nov 6 2019 11:00AM
[MATBI BIN AWI]
K's Performance & Services

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **03/12/2019 19:51 PM.**
To irene_tan@sg.msg-asia.com
CC sur@lkkauto.com
Subject **VEHICLE NO SKP984X**

Dear Irene

Please be informed that we have inspected the vehicle SKP984X on 28/11/2019.

We are still pending estimate from repairer.

Thank you

Best Regards
Yvonne Wong
LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN201330709H

ARULCHELVAN S • A. RAVIDASS • DON TAN

Our ref: SKP 984 X (iz)

Your ref: -

27 November 2019

MSIG Insurance (Singapore) Pte Ltd
Singapore

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2
WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION
PROTOCOL FOR NIMA CASE
ACCIDENT INVOLVING MOTOR VEHICLES SKP 984 X AND FBF 7802 B
ALONG VICTORIA STREET ON 6 NOVEMBER 2019**

We act for K's Performance, the owner of motor vehicle SKP 984 X which has appointed us to act on their behalf to claim against your insured's vehicle no. FBF 7802 B in regards to the road traffic accident on 6 November 2019..

Please be informed that the said motor vehicle can be inspected at:-

**K'S Performance
67 Yunnan Drive 3
Singapore 637954**

Kindly contact Mr Willam at 8306 3535 to make the necessary arrangements.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

MR ARULCHELVAN S

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	690C
Vehicle Details	
Vehicle No.:	SKP984X
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.6 TDI AT 1T332Z
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	CAYAB4662
Chassis No.:	WVGZZZ1TZFW000771
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$25,091.00
Original Registration Date:	13 Aug 2014
First Registration Date:	13 Aug 2014
Transfer Count:	1
Actual ARF Paid:	\$17,128.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Aug 2024
PARF Rebate Amount:	\$11,989.00
Intended COE Rebate Details	
COE Expiry Date:	12 Aug 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$64,600.00
COE Rebate Amount:	\$29,643.00
Total Rebate Amount:	\$41,632.00

The information contained herein is correct as at 10 Jan 2020

OK