

22/03/2002

ASS. REC. BY:

REF: CS/MSG19021071/R19f3

Special Instruction:

Surveyor: RASHI

ASSIGNMENT (Office)

From (Person): Irwin Ton Get Ing of MS19 Date/Time: 28.11.19 15.52p.m

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKP 984x Insured: FBF 7802 Bat Workshop m/s K's Performance Tel: 96889279of LT Yunnan Drive 3Policy No: ~~MSD/WT/19/391739/1A~~ Claim No: MSC/V/19-001831Sum Insured: MSC/V/19-0013183

Excess: _____

Make of Veh: _____

D.O.A. 6.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 28.11.19 3.57p.mPerson Contacted: William

H.O.D. Endorsement: _____

Vehicle IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>SKP 984x - x</u>
	<u>FBF 7802 B - CS3/INC/16007186/6h3c2 DUA-18/04/2016</u>

ACT. REC. BY: Ram

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKP 984Xat Workshop m/s K's Performanceof 67, YUNAN DRIVE 3

Insured:

MSK

Policy No.:

Claims No.:


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKP 984X

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen

C.C

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

162916

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVG 222 1T2FW 000 771Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firenza

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

06/11/19

D.O.I.

28/11/19

Survey held at

67, YUNAN DR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/12/19Sent Preli by Merimen (Pending Estimate)16/11/20Sent Preli by Merimen16/11/20Submit US \$4000/- (Red \$2424-00, 37%)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

16/11/20 TypistDays Of Repair: 6Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format:

Total Sum \$4000/-

\$4000/-

View Sent Message

This mail is associated with :

***SKP984X (MSC/V/19-001383)**
[FBF7802B]

TP
K'S PERFORMANCE
Nov 6 2019 11:00AM
[MATBI BIN AWI]
K's Performance & Services

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **03/12/2019 19:51 PM.**
To irene_tan@sg.msg-asia.com
CC sur@lkkauto.com
Subject **VEHICLE NO SKP984X**

Dear Irene

Please be informed that we have inspected the vehicle SKP984X on 28/11/2019.

We are still pending estimate from repairer.

Thank you

Best Regards
Yvonne Wong
LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2019		28 Nov 2019 15:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS [Created by insurer]				
Insured:		MATBI BIN AWI, ID: S1741183G, Tel: +6596493283, Email: NOEMAIL		
Main Claimant:		K'S PERFORMANCE, Co. Reg. No.: 53265690C		
Vehicle Reg. No.:		SKP984X	Date of Loss:	06/11/2019 11:00 - :59 [62 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:		TP / MSC/V/19-001831	Policy/Cover Note No.:	MSD/VMT/18-391739-CA (TP, Fire & Theft) Coverage: 23/11/2018 - 24/11/2019
Vehicle Reg. No. (Insured):		FBF7802B	Policy No. (Claimant):	
Repairer:		K's Performance & Services (HQ) 67 Yunnan Drive 3, 637954 Jurong West - Tel: 96889279		
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/11/2019]		
Driver/Custodian (Insured):		MATBI BIN AWI (53 / Male) , NRIC: S1741183G, Tel: +6596493283 Email: NOEMAIL		
Adj Asg. Remarks:		on WP. Liab: unclear. Agree on SJE. Assign: Xing Guo Qiang from LKK Auto Consultants Pte Ltd. Contact: Mr William @ 8306 3535.		

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN201330709H

ARULCHELVAN S • A. RAVIDASS • DON TAN

Our ref: SKP 984 X (iz)

Your ref: -

27 November 2019

MSIG Insurance (Singapore) Pte Ltd
Singapore

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2
WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION
PROTOCOL FOR NIMA CASE
ACCIDENT INVOLVING MOTOR VEHICLES SKP 984 X AND FBF 7802 B
ALONG VICTORIA STREET ON 6 NOVEMBER 2019**

We act for K's Performance, the owner of motor vehicle SKP 984 X which has appointed us to act on their behalf to claim against your insured's vehicle no. FBF 7802 B in regards to the road traffic accident on 6 November 2019..

Please be informed that the said motor vehicle can be inspected at:-

**K'S Performance
67 Yunnan Drive 3
Singapore 637954**

Kindly contact Mr Willam at 8306 3535 to make the necessary arrangements.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

MR ARULCHELVAN S

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	690C
Vehicle Details	
Vehicle No.:	SKP984X
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.6 TDI AT 1T332Z
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	CAYAB4662
Chassis No.:	WVGZZZ1TZFW000771
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$25,091.00
Original Registration Date:	13 Aug 2014
First Registration Date:	13 Aug 2014
Transfer Count:	1
Actual ARF Paid:	\$17,128.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Aug 2024
PARF Rebate Amount:	\$11,989.00
Intended COE Rebate Details	
COE Expiry Date:	12 Aug 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$64,600.00
COE Rebate Amount:	\$29,643.00
Total Rebate Amount:	\$41,632.00

The information contained herein is correct as at 10 Jan 2020

OK