MALY MANNO Om (Person)	: winnie Fen	ASSIGN:	MENT (Office) AG	Date/	Time: 28/11/19@ 3-24pm
stimated Cos	t		Bill to:	,	
D (FF) WS o Inspect Ve	HTP RES / OD RES /	EVA/ENV/MV SIG	6113M	Insured:	SKA 7744E
: Workghop 1	n/s	Motorwe	rlez	Tel: _ 8	200 1239 .
No-	280 woodlands li	nd park Es	5 #01-03		- Company of the Comp
olicy No:		,	Claim No:		
ium Insured:			Excess:		
Make of Vehi					PIOGIN/FC A
	/ / REP. / REV 24 FIR	CI.			III 9
	332pm@28Culla	s Person Confact	ed: Pior		
Onte/Time	Action/Instruction	Tohonoly (X)		
	8196113M-	×			
	1 SICA 7444	e-×			
		WOOD SHIP ONE HIS			

Nivitha (LKK Auto)

From:

AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>

Sent:

Thursday, 28 November 2019 3:24 PM

To:

Admin A; assignments

Cc:

Fong, Andy-SY

Subject:

Aigencypt - PRI AIG Insured SKA7744E(4TH) [EAL.2019.6592.MK.ya -

SJG6113M(3RD)]

Attachments:

191128-GIA report of SJG6113M(ins).pdf

HILKK,

Kindly assist to survey.

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Yvonne < yvonne@ealc.com.sg>

Sent: Thursday, November 28, 2019 3:15 PM

To: Hor, Yinrul <Yinrul.Hor@aig.com>; AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>

Subject: [EXTERNAL] PRI AIG Insured SKA7744E(4TH) [EAL.2019.6592.MK.ya - SJG6113M(3RD)]

This message is from an external sender; be cautious with links and attachments.

Our ref

: 2019.6592.MK.ya - SJG6113M(3RD)

Your ref

: SKA7744E(4TH)

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

AIG Asia Pacific Insurance Pte Ltd

No. 78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s AIG Asia Pacific Insurance Pte Ltd
Vehicle SJG6113M(3RD) inspected as follows by Name:
Before repair Parts removed After repair

Signature Date/ Time: Signature Date/ Time: Signature Date/ Time:

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: GO AH TEE

ACCIDENT INVOLVING SJG6113M(3RD) & SKA7744E(4TH) & SJC3142U(1ST) & JLX9206(2ND) ON 27 NOVEMBER 2019 ALONG JOHOR CAUSEWAY BEFORE MALAYSIA CUSTOM AT ABOUT 1330 HOURS

We refer to the above matter wherein we are instructed to act for GO AH TEE, the owner of vehicle no. SJG6113M(3RD).

There is no agreement to the surveyors proposed by parties.

Our client's vehicle SJG6113M(3RD) is available as follows, please call prior appointment for the pre-repair inspection:

M/s D Motorwerkz Pte. Ltd. No. 280 Woodlands Industrial Park E5, #01-03 Harvest @ Woodlands, Singapore 757322 Tel: Fion Ng 82004239

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards, Yvonne Ang

East Asia Law Corporation

No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413

Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACC	Ę	IT OT		CAL
ALL	DEN	11 51/	ATEM	II N I

Date Of Report 27/11/2019 17:10

Date Of Accident 27/11/2019 13:30

Exact Location Of Accident JOHOR CAUSEWAY BEFORE MALAYSIA CUSTOM

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJG6113M

Insured/Policyholder

Name Of Registered Owner GO AH TEE NRIC No S2530441A

Email Address NOEMAIL

 Mobile Phone No
 (LOCAL) +65-91370691

 Alternative Phone No
 OTHERS-91370691

Vehicle Particulars

Manufacturer TOYOTA

Model VIOS E AUTO

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy NO

Policy Number 5093715920-02

Cover Note Number

Driver

 Name of Driver
 GO AH TEE

 NRIC No
 \$2530441A

 Date Of Birth
 24/11/1952

 Occupation
 OUTDOOR

 Date Of Driving Pass
 05/09/1975

Driving Experience 44 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91370691

Fax Number

Contact Number OTHERS-91370691

EMail Address NOEMAIL

Address

BLK 227 YISHUN STREET 21

#10-516

Postcode

760227

OWNER

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? YES

Foreign Vehicle Registration Number

JLX9206 (PRIVATE CAR)

Number of vehicles (including own vehicle)

involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance? Was any other material or property damaged? NO YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

IBU PEJABAT POLIS DAERAH JOHOR BAHRU SELATAN

Police Station Address

ROAD: JALAN TERBAU , POSTCODE: 80250 , COUNTRY: MALAYSIA

Police Station Contact Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

TEL NO: 607-2237977 - FAX NO:

Vehicle Registration Number

SKA7744E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MOHAMAD HAFIZ BIN BIN JUMALI

NRIC/Passport Number

S8213012H

Contact Number

92282944

Address

BLK 189C RIVERVALE DRIVE

#10-998

Postcode

543189

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

JLX9206

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SJC3142U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

97636019

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy flability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims,
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policification Signature.

Date & Time:

Abriver's Signature

(If driver is not the paticyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.

Accident Sketch Plan & Describe Circumstances Of The Accident

KETCH PLAN		
	1 16/1	A: 33G G113M
1	'W'	B : 3KA 7744E
<i>*</i>	r [6]	C : & JLX 9206
	(同)	D: 53C 3142 U.
	1051	
	13	
	/ / /	
DESCRIBE CIRCUMSTANCES	OF THE ACCIDENT	
I was leaken	YOUR FOR MY TURK TO THE MY	MAYSIA CUSTOMS WHIM I HEARD A 2010 BAKE & IMPACT
		THE ENDE, MY CER MAS BEING FOR SHOP FOR MARKED AND HIS THE
VHICK IN FROM		
ECLARATION		
	iculars are true in every respect.	
1		
NY	100	
olicyholder's Signigure	priver's Signature	Reporting Centre Personnel's Signature
ate & Time:	'(If driver is not the golicy)	older) Name:
	Date & Time:	NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	441A	
Vehicle No.:	SJG6113M	
Vehicle to be Exported:	No	
Intended Deregistration Date:	02 Dec 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	VIOSEAUTO	
Primary Colour:	Red	
Manufacturing Year:	2008	
Engine No.:	1NZX778941	
Chassis No.:	MR053HY9305071442	
Maximum Power Output:	80.0 kW (107 bhp)	
Open Market Value:	\$12,344.00	
Original Registration Date:	09 Jul 2008	
First Registration Date:	09 Jul 2008	
Fransfer Count:	1	
Actual ARF Paid: Intended PARF Rebate Details	\$12,344.00	
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:		
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	08 Jul 2028	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
PQP Paid:	\$37,165.00	
COE Rebate Amount;	\$31,959.00	
Total Rebate Amount:	\$31,959.00	

The information contained herein is correct as at 02 Dec 2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	27/11/2019 17:10
Date Of Accident	27/11/2019 13:30
Exact Location Of Accident	JOHOR CAUSEWAY BEFORE MALAYSIA CUSTOM
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SJG6113M
Insured/Policyholder	
Name Of Registered Owner	GO AH TEE
NRIC No	S2530441A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91370691
Alternative Phone No	OTHERS-91370691
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	VIOS E AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5093715920-02
Cover Note Number	
Driver	
Name of Driver	GO AH TEE

 Name of Driver
 GO AH TEE

 NRIC No
 S2530441A

 Date Of Birth
 24/11/1952

 Occupation
 OUTDOOR

 Date Of Driving Pass
 05/09/1975

Driving Experience 44 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91370691

Fax Number

Contact Number OTHERS-91370691

EMail Address NOEMAIL

Address

BLK 227 YISHUN STREET 21

#10-516

Postcode

760227

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OWNER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

JLX9206 (PRIVATE CAR)

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

IBU PEJABAT POLIS DAERAH JOHOR BAHRU SELATAN

Police Station Address

ROAD: JALAN TERBAU , POSTCODE: 80250 , COUNTRY: MALAYSIA

Police Station Contact

TEL NO: 607-2237977 - FAX NO:

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

PLEASE REFER TO THE ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKA7744E

Vehicle Make/Model/Colour Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MOHAMAD HAFIZ BIN BIN JUMALI

NRIC/Passport Number

S8213012H

Contact Number

92282944

Address

BLK 189C RIVERVALE DRIVE

#10-998

Postcode

543189

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

JLX9206

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SJC3142U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

97636019

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of "...
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to coffect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents[including their lawyers/law firms], which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Oriver's Signature

Date & Time

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Accident Sketch Plan & Describe Circumstances Of The Accident

KETCH PLAN			
	1 16/1	1	A: SJG GIIBM
	1607		B : SKA 7744E
	1 61		C : & Jr x 9206
	(12)		D: 53c 3142 U.
			0. 300
	1/3		
	Y		
ESCRIBE CIRCUMSTANCES			
			WHEN I HEARD A 2000 BANK of IMPART
FROM THE ROBER OF MY 1	CAR. DUF TO THE MANT FROM	THE ROAR, MY CAR	was Bendi Risulvo Horward divo 417 THE
VIHILLE IN FROM .			
		7/10	
		and the second	
		-	
ECLARATION			
We declare the foregoing part	ticulars are true in every respect.		
1	1		
/ 1- X	1000		
Ricyholder's Signature yte & Time:	Driver's Signature (If driver is not the policy)	older)	Reporting Centre Personnel's Signature Name:

Date & Time:

NRIC/FIN No.:

POL.316



POLIS DIRAJA MALAYSIA CAWANGAN TRAFIK IBU PEJABAT POLIS DAERAH JOHOR BAHRU SELATAN, JALAN TEBRAU, 80250 JOHOR BAHRU

District OT-223		
Resit Akuan Penerimaan Repot F	Polis :	
Namæ Pengadu	: GO AH TEE	(5)
lo Kæd Pengenalan / Paspot	: 521124015153	
lo Respot Polis	: TRAFIK JOHOR BAHRU(\$)/030772/19	
arikh @ Masa Repot Polis	: 27/11/2019 @ 14:29	
engæsahan Penerimaan Repot	1	
	Tandatangan Ketua Pejabat Pertanyaan	
egavvai Penylasat :		
lama Pegawai Penylasat	: (R112169) SJN CHANDRAN A'L SAMINAT	HAN
empat Tugas	: JOHOR , J/BAHRU SELATAN	
lo Te lefon Pejabat	No Telefon Birhbit	:019-7161690
ASSERTING AND TO STORY OF THE SECOND PROPERTY.	29/11/19	- 1×55812
arikh @ masa Perjumpaan	CHANDRAN AA SAMINATHANI SIN 112169	
engesahan Penerimaan Repot	Pen. Pegawai Penyiasat Balai Polis Trafik	
	IPPD Johor Bakru (s)	
	Tandatangan Pegawai Penyiasat	
uru Gambar :	/	
lama	No Badan	Pangkat :
(delitor	CONT. MORPHONE	,
	040001400100140100	
arikh @ Masa Gambar Diambil	4	
Pengesahan Gambar Diambil		

1	Tandatangan Juru Gambar	
Jnit Pembekalan Dokumen Sias	atan :	
1		
No Tellefon Unit Pembekalan Doi	kumen :	Op blan solutions
Waktu Pejabat :	Jenis Dokumen Dibekal Kepada Per	ngadu ;
snin - Khamis :	1. Salinan Repot Polis	
8:00 Pagi - 01:00 Tengah Hari	2.Gambar Kenderaan	
2:00 Petang - 04:30 Petang		\vdash
Jumaat ;	3.Rajah Kasar Kemalangan	
08:00 Pagi - 12:30 Tengah Hari	4. Keputusan Siasatan	
02:45 Petang - 04:30 Petang	5. Lain-lain Dokumen	
Cuti Umum / Khas : Tutup	Tarikh @ Masa Dokumen Diserah :	

	Pengesahan Kaunter Pembekalan	
	Dokumen :	
	W-9000011944-5	100000000000000000000000000000000000000
		Tandatangan Pegawai Kaunter
		Pembekalan Dokumen

Front Portlon

	t Portion				
NA		- 110111	TCON	TA C	0.
100		6 Frt Number Plate	CON	AL	VU
100	2 99188	7 Frt Number Plate Base	BT	_	1
100	1 99138	9 Frt Number Plate Gorniels	BR	-	1
100	4 35130	O [Frt Bumper	R	-	-
100	5 99234	1 Frt Bumper Clips	10	-	-
100	0 99132	5 IFrt Bumner Bracket	-	-	-
001	7 99146	Z Fri Bumper Side Retainer	1	+	-
100	0 00131	3 Frt Bamper Reinforcement	1	?	
101	0 00146	8 Frt Bumper Beam	1	_	-
101	1 99140	8 Frt Bumper Sponge		-	-
101	2 00142	7 Fri Bumper Protector			
101	1 00126	0 Frt Bumper Pad			-
101	4 00130	3 Frt Bumper Grille		-	-
101	5 00140	1 Frt Bumper Moulding			-
101	6 00143	7 Frt Bumper Lower Spoiler	1	-	-
101		8 Frt Bumper Sensor			-
101	8 99135	0 Fit LH Bumper Fog Lamp Cover			
101	9 99507	5 Frt RH Bumper Fog Lamp Cover 9 Frt LH Bumper Fog Lamp			
102	99508	0 Frt RH Bumper Fog Lamp			
102	99179	3 Prt Grille			
1023	99132	8 Frt Grille Embless			
102	99179	9 Frt Grille Cheonie Moulding	-		
102	1 33177	2 Prt Apron Panel	CRA	_	
102	99201.	Frt Support Panel	-	-	
1020	992023	Frt Support Panel Ton Gamish Co.	-	-	-
1027	45.50.686	1/10/0	-	-	
1028		Fit Brace Panel	-	_	
1029	1925153	Fit LH Headlama Assu	-	-	_
1030	1221021	Fit RH Hendlamy Arms		-	-
1032	333088	Sitts I H Side Lanan	-	+	-
1033	000040	Fri RH Side Lamp		7	-
1034	991128	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator		_	
1037	990273	Bonnet Hinga	-	-	_
1038	990261	Bonnet Damper	-	+	\dashv
1039	990305	Bonnet Rubber	-	+	-
1040	990252	Bonnet Cable	-	+	-
1041	990311	Bonnet Stand	-	-	-
1042	990119	Air Con Condenser		+	-
1043	990122	Air Con Fan Assy	-	+	-
1044	790134	Air Con Suction Pine (Leave Dec.)	-	+	-
1046	5501 PW	IAM Con Suction Flore		\top	
1047	990114	Air Con Discharge Pipe (High Pressure) Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receives Drine	_	1	
1050	1339111	Air Con Compareson Ases		+	-
1051	332734	Air Con Belt	-	+	-
1053	993074	Radiator	-	+	\dashv
1054	992738	Radiator Cowling		+	\dashv
1055	992745	Radiator Fan Assy		1	7
1056	002250	Radiator Fan Clutch			-
1057	002752	Radiator Hose Top		+	7
1058	902741	Radiator Hose Bottom		T	
1059	990151	Radiator Expansion Tank		T	
1060	990070	Air Oliet		T	7
1061	99(1054	Air Cleaner Assy .	-	1	
1062	990036	Air Cleaner Hose	-	T	
Participate Administra		Air Cleaner Resonator		T	7
1064	501712	Frt Exhaust Manifold		T	
1065	991054	Frt Exhaust Manifold Cover		T	
	991714	ret Exhaust Manifold Sensor (Oxygen) Front Exhaust Pipe		T	
1067	990219	Patters		I	
1002	990224	Battery Cover		-	-
1009	990223	lattery Bracket		-	-
1070	990229	Buttery Tray		+	-
	- management de la	Contract to a section of the part of the section of		1	1

ASTRONOMI SUN PM

No of Irenst

NAC	INC	Vehicle No: SJG61	CON	10	10
1071	99220	5 Fuse Box	CON	AC	Qt
1072	99401		-	_	-
1073	92505		-	_	-
1074	99505	2 Wiper Washer Tank Motor		-	-
1075	99015	9 Alternator Assy	-	-	-
1076	99016			-	-
1077	99268	The state of the s			-
1078	99266				-
1079	99443	1. Power Steering Cooler Pipe			-
1080	33203	2 Power Steering Hose	-	-	-
1031	99001	O ABS Pump Control Unit			-
1082	99042	7 Brake Master Pump Assy	-	-	-
1083	99040	3 Brake Booster Pump Assy		-	-
1084	99100	5 Engine Top Cover		-	-
1085	99101	Engine Under Cover		-	-
1037		6 Engine Mounting			
1088	00005	9 Engine Mounting Frt			
1039		D Engine Mounting LH 2 Engine Mounting RH			
1090-	99095	Engine Mounting Rear			
1091		Gear Box Mounting			_
1092	991520	Frt LH Chassis Member	-	-	-
1093.	991520	Frt RH Chassis-Member	-	-	_
1094	990728	Frt Vertical Cross Member	-	-	-
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Funder		-	-
1097	995072	Frt LH Fender Inner Panel	-	-	-
1099	993147	Frt LH Fender Lamp			
1100	991740	Frt LH Fender Protector Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflen	-	-	
1102	995170	Frt LH Wheel Rim	-	+	_
1103	994025	Frt LH Rim Cover	-	+	-
1104	995065	Frt LH Tyre Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp	-	-	_
1108	991752	Frt RH Fender Protector		+	_
1109	991740	Frt RH Fender Inner Shield	12	+	
1110	991884	Frt RH Mudflan		+	-
1111	992087	Fet RH Wheel Rim		+	
1112	994025	Frt RH Rim Cover		+	
1113	993065	Frt RH Tyre Frt Windscreen Glass			
1115	992117	Fit Windscreen Rubber	-	4	_
1116	992108	Frt Windscreen Moulding	-	+	-
1117	992098	Frt Windscreen Seplant	-	+	-
1118	991019	ERP Bracket	-+	+	-
120	991020	ERP Unit			
-	992142	Frt Wiper Arm Frt Wiper Blade	_	1	
-	995045	Wiper Panel Garnish		+	_
123	991126	Firewall Panel	-	+	-
124	90753	Dashboard Assy	-	+-	-
125	92232	Glove Box Cover	-	+	-
126	92231	Glove Box Compartment	-	-	-
127 5	94483	Steering Wheel Airbay		+	4
128 5	94485	Steering Wheel Airbay Sensor	_	+	-
123 3	90749	Dashbourd Airbag		1	1
130 5	90750	Dashboard Airbay Sensor		T	
131 9	90029	Airbug Control Unit		1	
132 9	01022	Fri Driver Sent			
134 9	01800	Frt RH Seat Belt Assy		1	
	95182	Frt Passenger Scat Frt LH Seat Belt Assy.	-	-	-
36 9	90247	Sticker -	-	+-	-
		-	-	1.	-
-				4	. +1
				1_	1

Rear Portion

NAC 1137		Item	CON	AC	Qt
1138	993626	Rear Number Plate			
1139	993027	Rear Number Plate Base			
1140	003633	Rear Number Plate Garnish			
1141	002058	Rear Number Plate Lamp Rear Bumper	7		_
1142	003005	Rear Bumper	DD		
1143	003017	Rear Bumper Upper Rear Bumper Lower			
1144	.003024	Rear Bumper Side			
1145	993103	Pear Dumper Side			_
1146	002241	Rear Bumper Tow Cover			
1147	992341	Rear Bumper Clips	Nec		I
	992976	The state of the state of			
1148	993068	Rear Bumper Side Retainer RH	BR		1
1149	993045		-	-	1
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1154	993040 993036	- Comper reduction			
1155	993026				
1156					
1157	993023	Rear Bumper Reflector R/L		7	2
1158					
-	994023	Reverse Sensor	short		T
1159	993327	Rear End Panel	DD		T
1161	993339	Rear End Panel Top Garnish	CPY		1
1162	000333	Rear End Panel Inner Trim	COUNTRY		
1163	003051	Boot Compartment Inner Trim			
1164	993031	Rear LH Taillamp	7		
-1165	993859	Rear LH Taillamp Gazzish brocket Rear LH Taillamp Panel	1.		
1166	995116	Rear RH Taillamp			_
1167	993853	Rear RH Taillamp Garnish brode	CRY	_	1
1168	993859	Rear RH Taillamp Panel		-	-
1169	993554	Rear Apron Panel	_	-	-
1170	992895	Bootlid	in la	_	-
1171	991328	Bootlid Emblem	pp	_	1
1172	990356	Bootlid Handle	Nec	_	1
1173	995250	Bootlid Moulding	-	_	
1174	990376	Bootlid Reflector	SCH		1
1175	995222	Bootlid Lamp LH		_	
J176	992899	Bootlid Lamp RH		_	
1177	995243	Bootlid Lock	FRU	-	-
1178	990377	Bootlid Rubber	CKY	-	-
1179	990382	Bootlid Hinge R/L	R		2
1180	993877	Bootlid Spoiler	1		-
1181	994543	Tailgate			-
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle		-	-
1184	994640	Taileate Moulding	-	-	-
1185	994545	Tailgate Garnish			-
1186	994648	Tailgate Reflector :	_	-	
1187	994549	Tailgate Lamp		-	-
1188	994646	Tailgate Protector			-
1189	994676	Tailgate Wiper Arm	- 70		-
1190	994677	Tailgate Wiper Blade			-
1191	994679	Tailgate Wiper Nozzle			-
1192	994555	Tailgate Wiper Motor			-
1193	994602	Tailgate Glass	_	-	-
1194	994606	Tailgate Glass Rubber	-	-	-
1195	994604	Tailgate Glass Moulding		-	_
1196	994607	Tailgate Glass Sealant		_	
1197	994629	Tailgate Class Sealant			
1198	994651	Tailgate Rubber	N. Call		
1000	27-1031	Telland INDOER			
1199	0046111				
1199	994611	Tailgate Hinge Tailgate Dumper			

NAC	INC	Item	CON	40
1202	.993784	Spare Tyre Board	CON	AC
1203	994328	Spare Tyre Panel	7	-
1204	995065	Spare Tyre	-	_
1205		Spare Tyre Lock Screw	-	_
1206		Spare Tyre Cover	-	
1207	995323	Triangle Breakdown Sign	_	_
1208		CD Changer Assy	_	
1209	990164	Antenna -		_
1210				CI
1211	990534	Centre Exhaust Pipe Assy		
	990532	Centre Exhaust Mounting		-
1212	993364			
1213	993357	Rear Exhaust Chrome Pipe		-
1214	993361	Rear Exhaust Mounting		-
1215	993358	Rear Exhaust Heat Shield		-
1216	995223	Rear LH Chassis Member		
1217	993165	Rear RH Chassis Member		
1218	993436	Rear LH Fender	R	
1219	993449	Rear LH Fender Protector		
1220	993420	Rear LH Fender Inner Panel		
1221	993431	Rear LH Fender Inner Trim	-	-
1222	993415	Rear LH Fender Inner Garnish	-	-
1223	993425	Rear LH Fender Inner Shield	-	-
1224	993621	Rear LH Mudflap	-	-
1225	993933	Rear LH Wheel Rim	-	-
1226	994025	Rear LH Rim Cover	-	-
1227	995065	Rear LH Tyre	-	-
1228	993456	Rear RH Fender	R	
1229	993450	Rear RH Fender Protector	1	
1230	993420	Rear RH Fender Inner Panel		
1231	993431	Rear RH Fender Inner Trim		
1232	993415	Rear RH Fender Inner Garnish		
1233	993425	Rear RH Fender Inner Shield		
1234	993622			-
1235	993934	Rear RH Wheel Rim		_
1236	994025	Rear RH Rim Cover		-
1237	995065	Rear RH Tyre	-	-
1238	995162	Rear Fender Extension Panel I H	-	-
1239	993491	Rear Fender Extension Panel RH		
1240	993430	Rear Fender Inner Top Gamish		-
1241	993073	Rear Fender 1/4 Glass		
1242	993452	Rear Fender 1/4 Glass Rubber		
1244	993453	Rear Fender 1/4 Glass Sealant Rear Windscreen Glass		
1245	903076	Rear Windscreen Glass		
1246	993961	Rear Windscreen Rubber		
	002055	Rear Windscreen Moulding		
1247	333322	Rear Windscreen Sealant	000-22	
1248	994729	Third Brake Light		
1249	993385	Rear Fender Air Grille		
1250	992167	Fuel Lid	-	
1251	992168	Fuel Neck		
1252		Fuel Tank		5
1253	992184	Puel Tank Bracket		
1254	992191	Fuel Tank Float		_

1254 992191 Fuel Tank Float 111357 990247 Sticker

Rear wheather Strip Rour Spare Tyre Foodm

CUT



https://www.sgcarmart.com/used_cars/listing.php?BRSR=20&MOD=Toyota+Vios&RPG=20&AVL=2&VEH=0&RGD=10&ORD=RGD_ASC

Used Toyota Vios Car & Used Cars & Vehicles Singapore - sgCarMart



Toyota Vios 1.5A G (COE till \$23,800 \$7,280 /yr 11-Her-2006 1,497 ← 167,000 km Sedan 03/2023)

Available

(CONSTRUCTOR)

Available

Well Maintained, Loans Available, With Lowest Interest Rates, High Trade In Welcome, Cell Now To Book An Appointment To View This Beauty. Viewing Strictly Appointment Based.

Posted: 27-Nov-2019 Tags: 2008 Toyota Vos. 2008 toyota vios. Toyota Vos. toyota vios. Toyota Vios. toyota vios.



Toyota Vios 1.5A E (COE till \$21,000 \$6,330 /yr 28-Har-2008 1,497 cc 150,000 km Sedan 03/2023)

Look No Furtheri Best Value For Your Money, Direct Owner's Beautful Red, Har 2008 Toyota Vios E Auto, Selling Due To Lipgrading To New Car. Low Fuel Consumption, Low Maintenance, Original Paintwork Condition And Well Taken Care By Owner, Servicing Done With R...

Posted: 09-Oct-2019 Tags: 2508 Teyota Vios, 2003 toyota vios, toyota Viosa Vi



Name your price, sell your car

Sell by consignment-hassle free with no obligations to sell!



Toyota Vios 1.5A E Sports \$41,800 / \$4,960 /yr 08-May-2008 / 1,497 cc 132,000 km Sedan (CDE till 05/2028)

Available

Best Selling Brand And Model In The Market, Well Maintained And Regularly Serviced By Precious Owner, Low In Depreciation, Value For Money, Flexi Loan Scheme Available, Call Now For More Enquires.

Postect 09-Nov-3019 Tags: 2008 Toyote Was, 2008 toyota was, Toyota Vas, toyota vas, Toyota, Vas, vas, Used Toyota



Toyota Vios 1,5A J (COE till \$23,700 \$6,890 /yr 12-May-2006 1,497 cc - Sedan 05/2023)

Available

Excellent Fuel Efficiency Showroom Condition, Economical And Reliable Japanese Sedan, No Repairs Required, Do Not Mass, Bank And In Nouse Lean Available: Trade In Welcome, Call To Discuss, Act Fast!

Protect: 18-Nov-2019 Tegs: 2006 Toyota Vios, 2008 toyota Vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A J (COE till \$20,800 \$6,040 /yr 13-May-2006 1,497 tc 05/2023)

Available

High Spec J Model. Sport Model Body Kit, Stock Condition, No Modification, Premium Grooming Provided, Bank And In House Full Loan Available. STA/Vicom Evaluation Welcome. Trade In Welcome. Kindly Contact Our Seles Advisor For Viewing And Test Drive.

Protect: 02-Dec-2019 Tags: 2008 Tuyuta Vios, 2006 coyota vios, Toyota Vios, Suyota Vios, Tuyota, Vios, Vios, Vios, Used Toyota



Toyota Vios 1.5A E Sports (COE till 05/2023)

\$24,800 \$7,090 /yr 06-Jun-2008

1,497 cc 143,000 km Sedan

Available

1 Year In House Warranty, High Loan Available, Free 2 x Servicing, Warranty Not By 3rd Party Workshop, Company Renew CDE Cars Based On Car Condition, Price Stated Above Is Actual Selling Price, New Paintwork, Accident Free, STA Or VICOM Evaluation Are Welco...

Posted: 01-Dec-2019 Fags: 3008 Toyota Visa, 2008 toyota visa, Toyota Visa, toyota Visa, Toyota, Visa, Visa,



Toyota Vios 1.5A E (COE till \$22,800 \$6,380 /yr 30-Jun-2008 1,497 cc 183,058 km Sedan 06/2023)

Available

1 Year Warranty Cover Engine And Gear Box By Our Authorized Worleshop, Servicing Just Done, Well Naintain By Previous Owner, Can Arrange For STA Evaluation, Drive With Peace Of Mind! High Trade-In Up To \$2K More And Flexible High Loan Available, Please Call/Wh...

Accendore Autolution Pte Ltd

PDSTell 22-Nov-2019 Facts 2009 Telebite Vics, 2005 toyota vice, Toyota Vics, toyota vice, Toyota Vics, Vice, Vice,



Toyota Vios 1.5A E (COE till \$52,800 \$6,020 /yr 08-Sep-2008 1,497 cc 72,401 km Sedan

Available

Low Mileage, Most Reliable Japanese Sedan, Fuel Efficient. Well Maintained, Unit In Excellent Condition! In House Finance Available! Call For More Enquiries!

Posteri. 19-Oct-2019 Tags: 2008 Teyeta Vins, 2009 boyeta vins, Toyota Vios, toyota vins, Toyota, Vios, vins, Used Toyota



Toyota Vios 1.5M E (COE till \$24,800 \$7,270 /yr 16-Sep-2008 1,497 cc 135,000 km Sedan 04/2023)

Posterit 10-Oct-3019 Tags: 2008 Toyota Vice, 2015 toyota vice, Toyota Vice, toyota vice, Toyota, Vice, vice, Liked Toyota

Available

THE PARTY

100% Full Loan At 100% Approval Rate! 100% Head Turner With Everything 100% Done Up By 100% Car Lover, Sports Rims, Bucket Seats, Collover, Exhaust And Superb Sound System All Go Together With The Car. You Will Never Meet Another Vios Like This! Trade In...



Available

WEST TOTAL

Toyota Vios 1.5A 3 (COE till \$23,800 \$6,150 /yr 16-Oct-2008 1,497 cc 134,000 km Sedan er, 1 Careful Owner, New Paint, Under Warranty. Well Maintained, Seldom Used, Accident-Free, Undergone A 120 by Our In House Mechanics Peace Of Mind! Loan \$18800 x 35 Months, Monthly \$386, Interest Rate From 2.98%, C...

Na Leong Trading Enterprise Fosted: 29-Nov-2019 Tags: 2008 Toyota Vios, 2008 toyota wos, Toyota Vios, toyota vios, Toyota, Vios, V

Postnd: 02-Dec-2019 Tags: 2008 Toyota Vios, 2008 toyota wos, Toyota Vios, toyota vios, Toyota, Vios, Vios, Vies, Used Toyota



Toyota Vios 1.5A E (COE till \$21,068 \$5,890 /yr 18-Nov-2008 1,497 cc 88,900 km 96/2023)

Sedan

Available

Engine And Transmission In Good Condition, No Noise, Jerks Nor Any Gitches, Brakes Pads, Tyres Relatively New.

Toyota Vios 1.5A E (COE till \$40,600 \$4,410 /yr 26-Dec-2008 1,497 cc 205,000 km Seden 12/2028)

Available (CONGROMENT)

(COTTO COTTO

ignment Code: A236, Picolbie And Attractive Loan Available To Choose From, Trade-In Available For Your Carl No Hidden Costs, For ser Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

...CLAIM SUBFOLDER...(Pending for Survey Report)

	Notified	Est Submitted	Adi Assigned	Adj Rpt	Adi	Submitted	Ins Auth'ed	Status	
-	29 Nov 2019 Edit Reg	Est Submitted	28 Nov 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimate	5\$0	0.00 ew Rpt	ing radii co	Pending for Survey Report Cancel Case	
	Main	R	eference	Claim	Details		Documents	٦.	Show All
CLAIM SU	BFOLDER DE	TAILS				[Created	by adjuster]		
Insured:	Mohamad	Hafiz Bin Juma	II, Co. Reg. No.: -						
Main Claimant:	GO AH TE	E, ID: S253044	1A						
Vehicle Reg No.:	SJG611	SJG6113M				27/11/2019 14:00 - :59 [136 Months and 18 Days From LTA Reg Date (Man Yr)			e (Man Yr)]
Claim Type	TP / 511	TP / 5118053711SG				1900027991 (Comprehensive)			
Vehicle Reg No. (Insured):		SKA7744E							
Ç				The second secon	ess:				
Repairer:	D Motory	verkz Pte Ltd (H	Q) NO. 280 Woodla	nds Industrial E5	#01-03	Harvest @ W	oodlands, 757322 Wo	oodlands - Tel	:
Handling Insurer:	Day 25 000 5 2 4 5						y MdNoor, Norsiah)		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 6	256-3561 [Hai	ndled by C	I SUN PIN	[Final Rpt due	09/12/201	.9]
ASSOCIAT	TED MAIL RE	CEIVED					View A	II Compos	se Case Mai
 AIG_SG 	(29/11/2019)	: Request To Up	load TP GIA Repo	rt					
ALL ASSO	CIATED TAS	sks ⁼				View All	Search Tasks Crea	te New Task	Complet
Due Dat	e Priority	Type Tasi	k Group Subje	ct Handler	Assig	ned By	Completed On	Created O	n Done

Claim Documents

*SJG6113M (5118053711SG) [SKA7744E] TP GO AH TEE Nov 27 2019 2:50PM [Mohamad Hafiz Bin Jumali] D Motorwerkz Pte Ltd

Pho	tos/Images		3 per p	3 per page	
lo	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
	03/12/19 09:42	Chassis Number	0	Load JPG	Y
2	03/12/19 09:42	Odometer Reading	0	Load JPG	V
3	03/12/19 09:43	General View	0	Load JPG	V
1	03/12/19 09:43	General View	0	Load JPG	V
5	03/12/19 09:43	General View	6	Load JPG	V
5	03/12/19 09:43	General View	0	Load JPG	2
,	03/12/19 09:43	General View	0	Load JPG	V
3	03/12/19 09:43	General View	0	Load JPG	V
9	03/12/19 09:43	General View	0	Load JPG	V
10	03/12/19 09:43	General View	63	Load JPG	V
11	03/12/19 09:43	General View	6	Load JPG	V
12	03/12/19 09:43	General View	0	Load JPG	V
13	03/12/19 09:43	General View	0	Load JPG	8
14	03/12/19 09:43	General View	0	Load JPG	2
15	03/12/19 09:43	General View	0	Load JPG	V
16	03/12/19 09:43	General View	6	Load JPG	2
17	03/12/19 09:43	General View	6	Load JPG	V
18	03/12/19 09:43	General View	0	Load JPG	V
19	03/12/19 09:43	General View	0	Load JPG	2
20	03/12/19 09:43	General View	0	Load JPG	5
21	03/12/19 09:43	General View	0	Load JPG	E.
22	03/12/19 09:43	General View	0	Load JPG	2
23	03/12/19 09:43	General View	0	Load JPG	2
24	03/12/19 09:43	General View	0	Load JPG	2
25	03/12/19 09:43	General View	0	Load JPG	6
26	03/12/19 09:43	General View	0	Load JPG	5
27	03/12/19 09:43	General View	0	Load JPG	5
28	03/12/19 09:43	General View	0	Load JPG	5
29	03/12/19 09:43	General View	0	Load JPG	6
30	03/12/19 09:43	General View	0	Load JPG	5
31	03/12/19 09:43	General View	0	Load JPG	8
32	03/12/19 09:43	General View	0	Load JPG	2
33	03/12/19 09:43	General View	0	Load JPG	5
34	03/12/19 09:43	General View	0		5
35	03/12/19 09:43	General View	0		5
36	03/12/19 09:43	General View	0		5
37	03/12/19 09:43	General View	0	Load JPG	6
		General View	0	Load JPG	5
38	03/12/19 09:43	General View	0		8
39	03/12/19 09:43		0		6
40	03/12/19 09:43	General View	0		8
41	03/12/19 09:43	General View	0		-
42	03/12/19 09:43	General View	0	COUG ST G	8

Pho	Photos/Images		3 per p	3 per page 🔻	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	to calculate Aspectation for
44	03/12/19 09:43	General View	0	Load JPG	V
45	03/12/19 09:43	General View	0	Load JPG	☑
46	03/12/19 09:43	General View	0	Load JPG	V
47	03/12/19 09:43	General View	Ð	Load JPG	$\overline{\mathbf{A}}$
48	03/12/19 09:43	General View	0	Load JPG	\square
49	03/12/19 09:43	General View	0	Load JPG	V
50	03/12/19 09:43	General View	0	Load JPG	V
51	03/12/19 09:43	General View	0	Load JPG	V
52	03/12/19 09:43	General View	0	Load JPG	\mathbf{Z}
53	03/12/19 09:43	General View	0	Load JPG	V
54	03/12/19 09:43	General View	0	Load JPG	\square
55	03/12/19 09:43	General View	0	Load JPG	V
56	03/12/19 09:43	General View	0	Load JPG	\square
57	03/12/19 09:43	General View	0	Load JPG	V
58	03/12/19 09:43	General View	0	Load JPG	V
59	03/12/19 09:43	General View	0	Load JPG	V
60	03/12/19 09:43	General View	0	Load JPG	V
61	03/12/19 09:43	General View	0	Load JPG	\square
62	03/12/19 09:43	General View	0	Load JPG	V
63	03/12/19 09:43	General View	0	Load JPG	V
64	03/12/19 09:43	General View	0	Load JPG	V
65	03/12/19 09:43	General View	0	Load JPG	\mathbf{Z}
66	03/12/19 09:43	General View	0	Load JPG	V
67	03/12/19 09:43	General View	0	Load JPG	V
68	03/12/19 09:43	General View	0	Load JPG	\square
69	03/12/19 09:43	General View	0	Load JPG	V
70	03/12/19 09:43	General View	0	Load JPG	V
71	03/12/19 09:43	General View	0	Load JPG	V
72	03/12/19 09:43	General View	0	Load JPG	\square
73	03/12/19 09:43	General View	0	Load JPG	V
74	03/12/19 09:43	General View	0	Load JPG	\square
75	03/12/19 09:43	General View	0	Load JPG	\square
76	03/12/19 09:43	General View	0	Load JPG	\mathbf{Z}
77	03/12/19 09:43	General View	0	Load JPG	V
78	03/12/19 09:43	General View	0	Load JPG	V
79	03/12/19 09:43	General View	0	Load JPG	V
80	03/12/19 09:43	General View	0	Load JPG	₩.
81	03/12/19 09:43	General View	0	Load JPG	V
			paration	- Indiana	E
Do	Documentation		1 per	page v	
No	Finalized On 29/11/19 09:24	AIG Asia Pacific Insurance Pte. Ltd. (SG) OI GIA REPORT	6	Thumbnai Load PDF	Prin

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			V

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG19021075/QSD3E2

Date:

05/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900027991

Claimant Vehicle No: SJG6113M

Insured Vehicle No: SKA7744E

Date of Loss:

27/11/2019

TP Nature of Claim:

Claim No: 5118053711SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJG6113M

Make & Model:

TOYOTA VIOS, 1.5 E (A)

Engine No: Chassis No: Odometer:

1NZX778941

210866 km

MR053HY9305071442

Reg. Date:

09/07/2008 (Man. Year: 2008)

Red

Colour: Engine Capacity: 1497 cc

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/50 R15

Rear Tyre Size:

195/50 R15

Front Left Side:

Goodyear 5 mm

Rear Left Side: Rear Right Side: Goodyear 5 mm Goodyear 5 mm

Front Right Side: Goodyear 5 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

28/11/2019

Date Inspected:

29/11/2019 Inspected At:

D Motorwerkz Pte Ltd (HQ)

NO. 280 Woodlands Industrial E5, #01-03 Harvest @ Woodlands

Singapore 757322

Estimated Period of Repair:

9.0 days

Adjuster: OI SUN PIN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

			-11	D
ĸе	comi	men	aea	Parts

No.	Qty Part N	o. Particulars	Condition	Repairer's	Amount
1	1	*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1	*FRT NUMBER PLATE BASE	Broken	0.00 F	*- F
3	1	*FRT BUMPER	Repair	0.00 F	*-F
4	1	*FRT BUMPER REINFORCEMENT	* Check	0.00 F	*- F
5	1	*FRT GRILLE LOWER MOULDING	Cracked	0.00 F	*- F
6	1	*REAR BUMPER	Dented	0.00 F	*- F
7	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
8	1	*REAR BUMPER SIDE RETAINER RH	Broken	0.00 F	*- F
9	2	*REAR BUMPER REFLECTOR R/L	* Check	0.00 F	*- F
10	1	*REVERSE SENSOR	Shorted	0.00 F	*- F
11	1	*REAR END PANEL	Dented	0.00 F	*- F
12	1	*REAR END PANEL TOP GARNISH	Crushed	0.00 F	*- F
13	1	*REAR LH TAILLAMP	* Check	0.00 F	*- F
14	1	*REAR LH TAILLAMP BRACKET	* Check	0.00 F	*- F
15	1	*REAR RH TAILLAMP	Crushed	0.00 F	*- F
16	1	*REAR RH TAILLAMP BRACKET	* Check	0.00 F	*- F
17	1	*BOOTLID	Dented	0.00 F	*- F
18	1	*BOOTLID EMBLEM	Necessary	0.00 F	*- F
19	1	*BOOTLID MOULDING	Scratched	0.00 F	*- F
20	1	*BOOTLID LOCK	Crushed	0.00 F	*- F
21	2	*BOOTLID HINGE R/L	Repair	0.00 F	*- F
22	1	*REAR LH FENDER	Repair	0.00 F	*- F
23	1	*REAR RH FENDER	Repair	0.00 F	*- F
24	1	*REAR WEATHER STRIP	Cut	0.00 F	*-F
25	1	*REAR SPARE TYRE FOAM	Crushed	0.00 F	*- F
26	1	*SPARE TYRE PANEL	* Check	0.00 F	*- F
F=Fr	anchise part		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >