

ASS. REC. BY:

REF: AG /11/11/11Kennerth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 02 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SE 1444CYr Regn: 11 / 11Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: BMW730iL

c.c.

2996Colour: M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 173423

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAKB 22080C951196Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 245/50R18(BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mm

Rear

R/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 20/11/19D.O.I. 29/11/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to1st: +3.49 (880) + 4.093 88 501/2

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

F - RS

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 573721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TANG HEE KHOON
BLK 203A COMPASSVALE ROAD #07-19
SINGAPORE 541203

Attention : THE OWNER
Contact : 97911162

Estimate : ES006852

Date : 29/11/2019
Vehicle Num. : SLE1444C
Make/Model : BMW 730Li-2011
Chassis/Eng# : WBAKB22080C951196/04397837N521
Accident Date : 20/11/2019
Claim No. :
Reference :
Policy No. :

Not Authorized
11 Pay 83650
Running After Rep
2 days
11 Pay 83650

S/N Quantity Particular Unit Price Amount S\$

- NETT ITEMS :
1. 1 REAR BUMPER
 2. 6 REAR BUMPER CLIP
 3. 1 REAR BUMPER REINFORCEMENT
 4. 1 REAR BUMPER CENTRE GUIDE
 5. 1 REAR BUMPER LOWER INNER ADAPTOR
 6. 2 REAR BUMPER BRACKET
 7. 2 REAR BUMPER SIDE RETAINER
 8. 2 REVERSE SENSOR
 9. 1 REAR END PANEL

Nett Total S\$:
5.00% Discount S\$:

LABOUR :
RUST PROOFING TREATMENT
SPRAY PAINT DAMAGED AREA AFFECTED
TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR
CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS

Labour Total S\$:

Buy cm

1,876.00	✓
12.50	✓
75.00	✓
738.00	✓
366.00	✓
421.00	✓
186.00	✓
372.00	✓
267.00	✓
534.00	✓
263.70	✓
527.40	✓
671.00	✓
5,780.40	
289.02	
5,491.38	
100.00	✓
900.00	300
950.00	250
1,950.00	

SingDollars : Seven Thousand Four Hundred Forty-One & Cents Thirty-Eight Only

Total S\$: 7,441.38

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LKK Auto Consultants hence notify the Repairof the following:
• To return by before later spray painting
• To display damaged parts during recovery
• To provide the full scope of repair
• Third party survey is on a "No Win No Fee" basis
• No charge and handling is allowed
• Supplementary (extra) labour is allowed and is subject to final approval from Insurance Company
Authorised by Repairof
Signature
Date



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TANG HEE KHOON
BLK 203A COMPASSVALE ROAD #07-19
SINGAPORE 541203

Attention : THE OWNER
Contact : 97911162


Supplementary Estimate : ES006853

Date : 24/11/2019
Vehicle Num. : SLE1444C
Make/Model : BMW 730LI-2011
Chassis/Eng# : WBAKB22080C951196/04397837N52I
Accident Date : 20/11/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	NETT ITEMS :		
2.	1	REAR BUMPER LOWER LIP	CM 625.00	
		REAR PANEL LOWER COVER	CM 325.00	
		Nett Total S\$:		950.00
		5.00% Discount S\$:		47.50
				902.50

SingDollars : Nine Hundred Two & Cents Fifty Only

Total S\$: 902.50


COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TANG HEE KHOON
BLK 203A COMPASSVALE ROAD #07-19
SINGAPORE 541203

Attention : THE OWNER
Contact : 97911162

Estimate : ES006852

Date : 29/11/2019
Vehicle Num. : SLE1444C
Make/Model : BMW 730LI-2011
Chassis/Eng# : WBAKB22080C951196/04397837N521
Accident Date : 20/11/2019
Claim No. :
Reference :
Policy No. :

Not Authorised
11/11/19
Resurvey After Repair
2 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	NETT ITEMS :		
2.	6	REAR BUMPER		
3.	1	REAR BUMPER CLIP		
4.	1	REAR BUMPER REINFORCEMENT		
5.	1	REAR BUMPER CENTRE GUIDE		
6.	2	REAR BUMPER LOWER INNER ADAPTOR		
7.	2	REAR BUMPER BRACKET		
8.	2	REAR BUMPER SIDE RETAINER		
9.	1	REVERSE SENSOR		
		REAR END PANEL		
Nett Total S\$:				5,780.40
5.00% Discount S\$:				289.02
				5,491.38
LABOUR :				
RUST PROOFING TREATMENT				
SPRAY PAINT DAMAGED AREA AFFECTED				
TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR				
CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS				
Labour Total S\$:				1,950.00

SingDollars : Seven Thousand Four Hundred Forty-One & Cents Thirty-Eight Only


COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

Total S\$: 7,441.38

LKS Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 956A

Vehicle Details

Vehicle No.: SLE1444C
Vehicle to be Exported: Yes
Intended Deregistration Date: 02 Dec 2019
Vehicle Make: B.M.W.
Vehicle Model: 730LI AT ABS D/AB 2WD 4DR NAV HID SR
Primary Colour: Grey
Manufacturing Year: 2011
Engine No.: 04397837N52B30AF
Chassis No.: WBAKB22080C951196
Maximum Power Output: 190.0 kW (254 bhp)
Open Market Value: \$73,495.00
Original Registration Date: 16 Nov 2011
First Registration Date: 16 Nov 2011
Transfer Count: 1
Actual ARF Paid: \$73,495.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Nov 2021
PARF Rebate Amount: \$40,422.00

Intended COE Rebate Details

COE Expiry Date: 15 Nov 2021
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$73,600.00
COE Rebate Amount: \$14,372.00
Total Rebate Amount: \$54,794.00

The information contained herein is correct as at 02 Dec 2019

OK

21/11/19
Your password will expire in 13 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION REQUEST - SLE1444C vs SJW2939P (OI) on D.O.A.: 20/11/2019

From: Hor, Yinnul

To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)

Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni

Sent: 11/29/2019 2:19:03 PM

Hi,

Please refer to the enclosed request from **Complete VMS PTE LTD**.

Claim no : 3132273500SG003

Case Owner : Loh Chee Heng

If you have any queries/concerns, please let us know.

Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yim Rui (Viviane)

AIG

FNOL Adjuster I

Singapore FNOL | Claims Operations - Auto

Tel: 8001206558 | Ext: 1002208

Yinnul.Hor@aig.com | www.aig.sg

From: lihui@completevms.com.sg [mailto:lihui@completevms.com.sg]

Sent: Friday, November 29, 2019 1:57 PM

To: Hor, Yinnul

Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; lihui@completevms.com.sg

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJW2939P AND SLE1444C ON 20/11/2019

Without Prejudice

Dear OIC,

Please arrange Mr Kenneth Kong (LKK Auto Consultants Pte Ltd) to conduct survey.

Thank you & Best Regards,

Gan Li Hui (Ms)

Complete VMS PTE LTD

Block 176 Sin Ming Drive, #03-14

Sin Ming Autocare Complex, Singapore 575721

Tel: 6455 0012 Fax: 6554 0012

From: Hor, Yinnul

Sent: Fri, 29 Nov 2019 05:52:37 +0000

To: lihui@completevms.com.sg

Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJW2939P AND SLE1444C ON 20/11/2019

Without Prejudice

Your Reference : SLE1444C

Our Reference : 3132273500SG003

22/11/19 @ 29/11/19

P: Li Hui
V: IN
S: Kenneth

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1032208
Yinrul.Hor@aig.com | www.aig.sg

From: Gan Li Hui [mailto:lihui@completevms.com.sg]
Sent: Friday, November 29, 2019 11:25 AM
To: ClaimsDocManagement
Subject: [EXTERNAL] NOTICE OF ACCIDENT: SLE1444C Your ref: SJW2939P

This message is from an external sender; be cautious with links and attachments.

Without Prejudice

Dear Sir,

ACCIDENT INVOLVING SLE1444C AND SJW2939P ON 20/11/2019 ALONG BKE TOWARDS SLE AT ABOUT 17:30 HRS.

We act for TANG HEE KHOON owner of vehicle no. SLE1444C with instruction to repair the vehicle.

Please be informed that the said vehicle can be inspected at:-

Venue Complete VMS Pte Ltd

176, Sin Ming Drive,

#03-14,

Singapore 575721

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you. Please note that there will also be a storage charge of \$60 per

day on the 2 day notice period commencing from the date of this letter.

Thank you & Best Regards,

Gan Li Hui (Ms)

Complete VMS PTE LTD

Block 176 Sin Ming Drive, #03-14

Sin Ming Autocare Complex, Singapore 575721

Tel: 6455 0012 Fax: 6554 0012

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 5 December 2019 4:40 PM
To: Lily Leow
Subject: ACCIDENT INVOLVING SLE 1444C AND SJW 2939P ON 20/11/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/Madam,

ACCIDENT INVOLVING SLE 1444C AND SJW 2939P ON 20/11/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Claim Audit

- AUDIT TRAIL

1	29 Nov 2019 16:51	Cim Dtl Modified	Claimant's Name: -> -.	[A] HOW MEI KWAN
2	29 Nov 2019 16:51	Cim Veh Model Changed	(204808) HONDA VEZEL 1.5 (A).	[A] HOW MEI KWAN
3	29 Nov 2019 16:51	Cim Created	Reg No: SLE1444C. Acct Date: 2019/11/20. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: COMPLETE VMS PTE LTD (HQ)	[A] HOW MEI KWAN
4	29 Nov 2019 16:51	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	29 Nov 2019 16:51	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/10	[A] HOW MEI KWAN
6	29 Nov 2019 16:51	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	29 Nov 2019 16:51	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[T] Merimen Administrator
8	29 Nov 2019 16:52	Label Added	(19):Fastlane.	[A] HOW MEI KWAN
9	29 Nov 2019 16:52	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] HOW MEI KWAN
10	02 Dec 2019 17:33	Cim Registration Modified	Init.Est.:8,000 - 9,000->7,000 - 8,000.	[A] HOW MEI KWAN
11	02 Dec 2019 17:33	Cim Veh Model Changed	(204808) -> (205062) BMW 730LI 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A).	[A] HOW MEI KWAN
12	15 Feb 2020 16:28	Adj Rpt Initiated		[A] Asher Sng Rong Yi
13	15 Feb 2020 16:28	Insured Phone No Updated	[None] -> [+6587783636]	[A] Asher Sng Rong Yi
14	15 Feb 2020 16:28	Cim Dtl Modified	Claim Conclusion: -> 1.	[A] Asher Sng Rong Yi
15	15 Feb 2020 16:28	Cim Dtl Modified	JPJ Reg. Date: -> 2011/11/16.	[A] Asher Sng Rong Yi
16	15 Feb 2020 16:28	Cim Details Notified		[A] Asher Sng Rong Yi
17	15 Feb 2020 16:46	Adj Mandate Request	Cur.Req:4334.50:LIABILITY: 100% B:27 OLD REAR ENDED TP	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

2364415	02 Dec 2019 16:08:06	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SLE1444C	SJW2939P	11.77
2439638	15 Feb 2020 16:28:42	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLE1444C	SJW2939P	11.77

Print Received Message

This mail is associated with :

***SLE1444C (3132273500SG)**
[SJW2939P]
TP
TANG HEE KHOON
Nov 20 2019 12:00AM
[AMA RENTAL PTE LTD]
COMPLETE VMS PTE LTD

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 17/02/2020 08:20 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4334.50) - SLE1444C - Claim Handler: Loh, Chee-Heng

Approved:4334.50.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2019 Edit Reg		29 Nov 2019 00:00 Edit Adj Rpt	\$3,650.00 Edit Estimates	\$3,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: AMA RENTAL PTE LTD , Co. Reg. No.: 201708966M, Tel: +6587783636									
Main Claimant: TANG HEE KHOON , ID: S1640956A									
Vehicle Reg. No.: SLE1444C		Date of Loss: 20/11/2019 00:00 - :59	[96 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type: TP / 3132273500SG		Policy/Cover Note No.:	[Third Party Only]						
Vehicle Reg. No. (Insured): SJW2939P		Policy No. (Claimant):	D19MPC0002458						
		Excess:							
Repairer: COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Claimant's Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/12/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (17/02/2020): Alert - Adj Mandate Approved (\$4334.50) - SLE1444C - Claim Handler: Loh, Chee-H... - AIG_SG (02/12/2019): TP GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE1444C (3132273500SG)
[SJW2939P]
TP
TANG HEE KHOON
Nov 20 2019 12:00AM
[AMA RENTAL PTE LTD]
COMPLETE VMS PTE LTD

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#) |
 [Upload Video](#) |
 [Upload Audio](#)

View View in Browser

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/02/20 16:43	General View		Load JPG	☒
2	15/02/20 16:43	General View		Load JPG	☒
3	15/02/20 16:43	General View		Load JPG	☒
4	15/02/20 16:43	General View		Load JPG	☒
5	15/02/20 16:43	General View		Load JPG	☒
6	15/02/20 16:43	General View		Load JPG	☒
7	15/02/20 16:43	General View		Load JPG	☒
8	15/02/20 16:43	General View		Load JPG	☒
9	15/02/20 16:43	General View		Load JPG	☒
10	15/02/20 16:43	Odometer Reading		Load JPG	☒
11	15/02/20 16:43	General View		Load JPG	☒
12	15/02/20 16:43	Chassis Number		Load JPG	☒
13	15/02/20 16:43	Reinspection Photo		Load JPG	☒
14	15/02/20 16:43	Reinspection Photo		Load JPG	☒
15	15/02/20 16:43	Reinspection Photo		Load JPG	☒
16	15/02/20 16:43	Reinspection Photo		Load JPG	☒
17	15/02/20 16:43	Reinspection Photo		Load JPG	☒
18	15/02/20 16:43	Reinspection Photo		Load JPG	☒
19	15/02/20 16:43	Reinspection Photo		Load JPG	☒
20	15/02/20 16:43	Photo After Spray		Load JPG	☒
21	15/02/20 16:43	Photo After Spray		Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/11/19 16:52	ACKNOWLEDGEMENT EMAIL TO AIG DD 29.11.2019		Load PDF	
2	29/11/19 16:52	EMAIL FROM AIG DD 29.11.19		Load PDF	
3	03/12/19 10:39	TP ESTIMATE - MARKED		Load PDF	
4	03/12/19 10:39	TP GIA REPORT		Load PDF	
5	05/12/19 16:41	LETTER TO OI		Load PDF	
6	15/02/20 16:45	TP LOD		Load PDF	
7	12/03/20 10:37	WORKSHOP INVOICE		Load PDF	
8	12/03/20 10:37	AUTHORISATION TO ACT FORM		Load PDF	
9	12/03/20 10:37	Release Voucher		Load PDF	
10	12/03/20 10:37	GIA SEARCH		Load PDF	
11	12/03/20 10:37	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	02/12/19 16:10	OI GIA REPORT		Load PDF	
2	27/12/19 15:46	TP GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJW2939P (Insd veh)	Model:	BMW 730Li 3.0 AT ABS
	SLE1444C (TP veh)		D/AB 2WD 4DR NAV HID SR
Date of Accident:	20/11/2019		(A)

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	8,927.95
Final Repair Cost	:	\$	3,905.50
Loss of Use	:	\$	400.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	29.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,334.50

4.00 days at \$100.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	COMPLETE VMS PTE LTD	:	\$ 4,334.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

12 Mar
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021128/KEA3Q2

Date: 12/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No: SLE1444C

Insured Vehicle No: SJW2939P

Date of Loss: 20/11/2019

Nature of Claim: TP

Claim No: 3132273500SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE1444C

Make & Model: BMW 730LI, 3.0 AT ABS D/AB 2WD 4DR NAV
HID SR (A)

Engine No: 04397837N52B30AF

Reg. Date: 16/11/2011 (Man. Year: 2011)

Chassis No: WBAKB22080C951196

Colour: Metallic Grey

Odometer: 173423 km

Engine Capacity: 2996 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R18

Rear Tyre Size: 245/50 R18

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,393.88	4,004.63	2,389.25	37.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	550.00	1,400.00	71.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,343.88	4,554.63	3,789.25	45.41
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	8,343.88	3,650.00	4,693.88	56.26
+ GST 7.00/7.00% (S\$)	584.07	255.50	328.57	56.26
Nett Amount (S\$)	8,927.95	3,905.50	5,022.45	56.26
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		4,334.50		

INSPECTION

Date of Assignment: 29/11/2019

Date Inspected: 29/11/2019 Inspected At:

COMPLETE VMS PTE LTD (HQ)
176 Sin Ming Drive #03-14 Sin Ming
Autocare Complex
Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	1,876.00 FN	*1,876.00 FN
2	6		*REAR BUMPER CLIP	Necessary	75.00 FN	*75.00 FN
3	1		*REAR BUMPER REINFORCEMENT	Repair	738.00 FN	*- FN
4	1		*REAR BUMPER CENTRE GUIDE	Cracked	366.00 FN	*366.00 FN
5	1		*REAR BUMPER LOWER INNER ADAPTOR	Cracked	421.00 FN	*421.00 FN
6	2		*REAR BUMPER BRACKET	Repair	372.00 FN	*- FN
7	2		*REAR BUMPER SIDE RETAINER	Serviceable	534.00 FN	*- FN
8	2		*REVERSE SENSOR	Shorted	527.40 FN	*527.40 FN
9	1		*REAR END PANEL	Repair	871.00 FN	*- FN
10	1		*REAR BUMPER LOWER LIP	Cracked	625.00 FN	*625.00 FN
11	1		*REAR PANEL LOWER COVER	Cracked	325.00 FN	*325.00 FN

F=Franchise part. N=NettItemDisc.

Sub Total (\$\$)	6,730.40	4,215.40
- Nett Item Discount on N Items 5.00/5.00% (\$\$)	336.52	210.77
Total Parts (\$\$)	6,393.88	4,004.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RUST PROOFING TREATMENT	New	100.00	0.00
2	SPRAY PAINT DAMAGED AREA AFFECTED	New	900.00	300.00
3	TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	New	950.00	250.00
Gross Labour Cost (S\$)			1,950.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >