

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC3/MSG19021196/USP312

MSU

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 7235Eat Workshop m/s SP.

of

Insured: SMN 6972C

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 80k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLW 7235EYr Regn: 2118

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: KIA carensc.c. 1685Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 34620

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAH4815VJ7199265

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55-216

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or nexen

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 30/11/19D.O.I. 2/12/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/12/19 LTA 49315
L/S \$5500 confirmed with Alu. Jmmt
(\$ 9,672.00 Red 64%)

RECEIVED 27 DEC 2019

27/12/2019

Date/Time, File Pass to?

27/12/19

1) Type Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation: 200

Photos

Others

TOTAL

211

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$ 5,500/- 45)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 4 December 2019 8:50 am
To: motorsurvey@sg.msig-asia.com
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 30/11/2019 , SLW 7235E (TP VEHICLE), SMN 6972C (OI VEHICLE)
Attachments: TP GIA REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLW 7235E at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 02/12/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

CLEARANCE **SALE** NOW ON!
40% OFF ALL SELECTED ITEMS.



Locus Habitat
SINGAPORE

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Renewal COE Toyota Wish.



2.88% P.A, \$0 Admin, Monthly
From \$688, 2 Years Warranty
Engine And Gearbox.
GV Credit StarAd

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

1 vehicles

Kia Carens

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Kia Carens		Any	Any	2018	Any	Any	Any	Available
	Kia Carens	Diesel 1.7A EX	\$87,800	\$9,020 /yr	18-Jul-2018	1,685 cc	17,693 km	MPV	Available
Fuel Type: Diesel (Euro 5 Engine and Above) New Model! 1 Careful Owner! Low Fuel Consumption. Low Deprecation! Bank And In House Full Loan Are Available At Low Interest Rate... Starise Automobile Posted: 08-Nov-2019 Tags: 2018 Kia Carens, 2018 kia carens, Kia Carens, kia carens, Kia, Carens, carens, Used Kia									

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Kia Carens, Kia Carens Singapore, used Kia Carens Singapore, used Kia Carens, used vehicles Singapore or even buy used Kia Carens Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 691I

Vehicle Details

Vehicle No.: SLW7235E
Vehicle to be Exported: No
Intended Deregistration Date: 02 Dec 2019
Vehicle Make: KIA
Vehicle Model: CARENS 1.7 DCT DIESEL 5DR FWD
Primary Colour: Blue
Manufacturing Year: 2018
Engine No.: D4FDGH221224
Chassis No.: KNAHU815VJ7199265
Maximum Power Output: 104.0 kW (139 bhp)
Open Market Value: \$19,264.00
Original Registration Date: 28 Feb 2018
First Registration Date: 28 Feb 2018
Transfer Count: 0
Actual ARF Paid: \$19,264.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Feb 2028
PARF Rebate Amount: \$14,448.00

Intended COE Rebate Details

COE Expiry Date: 27 Feb 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,322.00
COE Rebate Amount: \$34,867.00
Total Rebate Amount: \$49,315.00

The information contained herein is correct as at 02 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/12/2019 16:01
Date Of Accident	30/11/2019 18:05
Exact Location Of Accident	FOCH RD TWDS JALAN BESAR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW7235E
Insured/Policyholder	
Name Of Registered Owner	HOW MEI YU (HOU MEIRU)
NRIC No	S8517691I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91780876
Alternative Phone No	OFFICE-91780876

Vehicle Particulars

Manufacturer	KIA
Model	CARENS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800020062
Cover Note Number	

Driver

Name of Driver	CHUA KIAN WANT(CAI JIANYUAN)
NRIC No	S8306754C
Date Of Birth	09/03/1983
Occupation	INDOOR
Date Of Driving Pass	20/05/2005
Driving Experience	14 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94517806
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 525B PASIR RIS ST 51 #12-569
Postcode	512525
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : HOW MEI YU GENDER: : FEMALE
Passenger 2	NAME: : CHUA JIE YING QUINTON GENDER: : MALE
Passenger 3	NAME: : LAUREN TAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMN6972C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHUA KIAN WANT(CAI JIANYUAN)

Approximate Age

Injuries Sustain NECK N BACK

Injured person in which vehicle? SLW7235E

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Date of Accident : 30/11/19 Accident Time: 6:05pm (24-HR-Format)
Accident Place : Foch rd towards Jalan Besar.
Vehicle No. (Car Plate No.) : SLW 7235F Make/Model: _____
Insurance Company : AIG Policy No: _____
Owner or Company Name /IC No. : How Mei Yu . S8517691 I .
Owner or Company Contact No. : 91780876 Owner's Hp _____ Company Tel _____
DRIVER'S Name / IC No. : Chua Kian Went . S8306754C
DRIVER'S Date Of Birth : 09/03/1983 DRIVER'S License Pass Date _____
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: _____
DRIVER'S Address : Blk 525B Pair Ris St 51 #12-569
S 512525 .
DRIVER'S Contact No./ Alt No. : 1) 94517206 2) _____
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address : _____
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): yes Driver & 3 passengers .
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): Driver : Neck & Back Pain

Other Party Driver's Particular (if any)

Vehicle No: 3MN6972C	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

*** NEW - Passenger's name & gender:**

How Mei Yu (F)

Chua Jie Ying, Quinton (M)

Lauren Tan (F)

Chua

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A: SLW 7235 E

B: SMN 6972 C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/11/19 at about 6:05pm. I was traveling
 straight along Roch Rd towards Jalan Besar.
 reversed and
 suddenly vehicle B approached into my lane and
 hit my vehicle.

Note: He was travelling against the traffic.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
LKR
2/12/18
4dy. 2/5 @ 5500/

VEHICLE NO: SLW 7235E

QTY	PARTICULAR
1 PCS	BONNET
1 PCS	FRONT BUMPER 695
1 PCS	FRONT BUMPER LOGO
2 PCS	FRONT BUMPER SIDE RETAINERS @\$48.00
1 SET	FRONT BUMPER CLIPS
1 PCS	FRONT BUMPER CENTRE GRILLE
1 PCS	FRONT BUMPER LOWER SKIRTING
1 PCS	FRONT BUMPER BEAM
1 PCS	FRONT BUMPER SPONGE 166.00
1 PCS	FRONT BUMPER FOG LAMP O/S 315.00
1 PCS	FRONT BUMPER FOG LAMP GARNISH O/S 205
1 PCS	FRONT GRILLE
1 PCS	HEADLAMP O/S 1715.00
1 PCS	FRONT SUPPORT PANEL 645.00
1 PCS	FRONT FENDER O/S 620
1 PCS	FRONT FENDER INNERSHIELD O/S
1 SET	FRONT FENDER INNERSHIELD CLIPS O/S
1 PCS	FRONT SHOCK ABSORBER O/S
1 PCS	FRONT LOWER ARM O/S
1 PCS	FRONT KNUCKLE ARM O/S
1 PCS	FRONT KNUCKLE ARM BEARING O/S
1 PCS	FRONT SPORT RIM O/S

17	\$1,421.00	X
00/2011	\$981.00	
17	\$68.00	X
0/5 Bent	\$96.00	12C
new	\$50.00	
7m	\$341.00	
00/2011	\$680.00	
17	\$425.00	X
2011	\$282.00	
one	\$450.00	
2011	\$405.00	
one	\$466.00	
one	\$2,100.00	
one	\$966.00	
Bent/3uc	\$525.00	
2011	\$211.00	
new	\$50.00	
17	\$392.00	X
17	\$388.00	X
17	\$365.00	X
17	\$250.00	X
17	\$1,250.00	X
	\$12,162.00	

10%

LABOUR CHARGES
TO CHECK WIRING
TO REFILL AIR CON GAS
TO SPRAY RUST PROOFING
TO CONDUCT WHEEL ALIGNMENT
TO DISMANTLE & REFIX FRONT UNDERCARRIAGE
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	30
	\$120.00	100
	\$80.00	30
17	\$100.00	X
17	\$180.00	X
	\$980.00	650
	\$1,500.00	600
TOTAL	\$15,172.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Handling of litigation(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

6112
0910.8

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19021196/USF3N2

Date: 06/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29110539

Claimant Vehicle No : SLW7235E

Insured Vehicle No : SMN6972C

Date of Loss: 30/11/2019

Nature of Claim: TP

Claim No: 613367

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW7235E

Make & Model: KIA CARENS, 1.7 D DCT 5DR FWD (A)

Engine No: D4FDGH221224

Reg. Date: 28/02/2018 (Man. Year: 2018)

Chassis No: KNAHU815VJ7199265

Colour: Blue

Odometer: 34620 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Nexen 7 mm

Rear Left Side: Nexen 7 mm

Front Right Side: Nexen 7 mm

Rear Right Side: Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,162.00	5,500.80	6,661.20	54.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	1,410.00	1,600.00	53.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,172.00	6,910.80	8,261.20	54.45
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	15,172.00	5,500.00	9,672.00	63.75
+ GST 7.00/7.00% (S\$)	1,062.04	385.00	677.04	63.75
Nett Amount (S\$)	16,234.04	5,885.00	10,349.04	63.75

INSPECTION

Date of Assignment: 11/12/2019

Date Inspected: 02/12/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 06 Jan 2020)

Parts: M1-MPV KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLW7235E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,421.00 F	*- FL
2	1		*FRONT BUMPER	Dented/Torn	981.00 F	*695.00 FL
3	1		*FRONT BUMPER LOGO	Not Necessary	68.00 F	*- FL
4	1		*FRONT BUMPER SIDE RETAINERS	O/s Bent	96.00 F	*48.00 FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
6	1		*FRONT BUMPER CENTRE GRILLE	Twisted	341.00 F	*341.00 FL
7	1		*FRONT BUMPER LOWER SKIRTING	Deformed/Torn	680.00 F	*680.00 FL
8	1		*FRONT BUMPER BEAM	Repair	425.00 F	*- FL
9	1		*FRONT BUMPER SPONGE	Torn	282.00 F	*166.00 FL
10	1		*FRONT BUMPER FOG LAMP O/S	Cracked	450.00 F	*315.00 FL
11	1		*FRONT BUMPER FOG LAMP GARNISH O/S	Torn	405.00 F	*205.00 FL
12	1		*FRONT GRILLE	Cracked	466.00 F	*466.00 FL
13	1		*HEADLAMP O/S	Cracked	2,100.00 F	*1,715.00 FL
14	1		*FRONT SUPPORT PANEL	Cracked	966.00 F	*645.00 FL
15	1		*FRONT FENDER O/S	Bent/Buckled	525.00 F	*525.00 FL
16	1		*FRONT FENDER INNERSHIELD O/S	Torn	211.00 F	*211.00 FL
17	1		*SET FRONT FENDER INNERSHIELD CLIPS O/S	Necessary	50.00 F	*50.00 FL
18	1		*FRONT SHOCK ABSORBER O/S	Not Necessary	392.00 F	*- FL
19	1		*FRONT LOWER ARM O/S	Not Necessary	388.00 F	*- FL
20	1		*FRONT KNUCKLE ARM O/S	Not Necessary	365.00 F	*- FL
21	1		*FRONT KNUCKLE ARM BEARING O/S	Not Necessary	250.00 F	*- FL
22	1		*FRONT SPORT RIM O/S	Not Necessary	1,250.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	12,162.00	6,112.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	611.20
Total Parts (\$\$)	12,162.00	5,500.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REFILL AIR CON GAS	New	120.00	100.00
3	TO SPRAY RUST PROOFING	New	80.00	30.00
4	TO CONDUCT WHEEL ALIGNMENT	New	100.00	0.00
5	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE	New	180.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	980.00	650.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	600.00
Gross Labour Cost (\$\$)			3,010.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >