

ASS. REC. BY:

REF: CS/AGI/9021198/ksf3 n2

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Ratilla Ivy of AGI Date/Time: 2.12.2019 11.12g.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SME 1773R Insured: SLD 3825Dat Workshop n/s Estem Performance Tel: 8799 0066of 385 Sin Ming Drive SingaporePolicy No: _____ Claim No: C1004253/KY

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29.11.2019
(Client's Record)CA / REV / REP. / REV 24 HRS sup H.O.D. Endorsement: _____Date/Time: 2.12.19 12p.m Person Contacted: Carman Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SME 1773R - X</u>
<u>17/12</u>	<u>B 2445.60 email & Carman</u>
	<u>C \$2,260.88 Red - 48%.</u>

ASS. REC. BY:

REF: 162/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.13M

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SME 1773R Yr Regn: 09, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle cc 1498

Colour:

M.D. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

84825

T/Radio: Insured / Std / NI / NA

Eng No:

C/No:

GP7 - 1218053

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

Road Stone F. 185/60R15

R: Yokohama

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

3

mm

Rear

R/Bal.

4

mm

L/Bal.

3

mm

L/Bal.

4

mm

D.O.A.

29/11/19

D.O.I.

2/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 20 DEC 2019

Date/Time, File Page 107

20/12/19

1) Type

Date/Time, File Return 107



: Preli. Report



: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

: Fuel

: Others

: TOTAL

TOTAL

250

Report Format :

Lump Sum (I.B.) (\$ 2,445.60 A/P)

Niyitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Monday, 2 December 2019 11:22 AM
To: SUR; Admin-D (LKKAuto)
Cc: Justin Wong
Subject: FW: REQUEST FOR PRI SURVEY SME1773R || C10004753/KY

Hi Team,

We would like to arrange TP PRS for SME1773R.

Name of workshop : Esteem Performance Pte Ltd
Address : 385, Sin Ming Drive Singapore 571718
Tel : 8799 0066
Fax : 6259 3326

Please confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Carmen Lim <carmen@esteemperf.com.sg>

Sent: Friday, 29 November 2019 5:49 PM

To: Claims <claims@budgetdirect.com.sg>

Cc: serence ctc <serence@esteemperf.com.sg>; jenny chong <jenny@esteemperf.com.sg>

Subject: REQUEST FOR PRI SURVEY SME1773R

Dear Sir / Madam,

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES
(NIMA)**

We act for Esteem Leasing Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no SME 1773 R

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : 385, Sin Ming Drive Singapore 571718

Tel : 8799 0066

Fax : 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

Thank you



Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division

Esteem Performance Pte Ltd

M: 8799 0066

P: 6484 1221

E: carmen@esteemperf.com.sg


5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/11/2019 09:44
Date Of Accident	29/11/2019 09:50
Exact Location Of Accident	JUNCTION OF JALAN ISHAK AND LORONG MARICAN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME1773R
Insured/Policyholder	
Name Of Registered Owner	ESTEEM LEASING PTE LTD
Co Reg No	201807215D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96355963
Alternative Phone No	OFFICE-64841221
Vehicle Particulars	
Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5110341793 (CLASSIC)
Cover Note Number	
Driver	
Name of Driver	YEO KIAN SENG
NRIC No	S1486260I
Date Of Birth	19/12/1961
Occupation	OUTDOOR
Date Of Driving Pass	22/06/1982
Driving Experience	37 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96355963
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 134 SIMEI STREET 1 #04-172
 Postcode 520134
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : PASSENGER
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TAMPINES NORTH NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 461 TAMPINES STREET 44 #01-56 , POSTCODE: 520461 ,
 COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-7818999 - FAX NO: 67838603
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: CANNOT BE UPLOADED
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLD3825D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver ZAINI BIN HASSAN
 NRIC/Passport Number S0200217E
 Contact Number 90102451

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	YEO KIAN SENG
Approximate Age	57
Injuries Sustain	4 DAYS MC
Injured person in which vehicle?	SME1773R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 134 SIMEI STREET 1 #04-172
Postcode	520134

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer as police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20191129/2117

1 of 3

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20191129/2117

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/11/2019 16:03	Vide Report No.:	Station Diary No.: 26
--	------------------	--------------------------

Informant's Particulars

Name of Informant: YEO KIAN SENG			Address: APT BLK 134 SIMEI STREET 1 #04-172 SINGAPORE 520134		
ID Type / ID No.: NRIC NO / S14862601			Contact No.: Home/Office: Mobile: 96355963		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 57	Date of Birth: 19/12/1961	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 29/11/2019 09:50	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 JALAN ISHAK LORONG MARICAN				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLD3825D	Car	HONDA		Grey		0
SME1773R	Car	HONDA	SHUTTLE	Blue	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SME1773R	NTUC Income Insurance Co-Operative Limited	5110341793-000044	13/06/2019	12/06/2020



**SINGAPORE
POLICE FORCE**



T/20191129/2117

2 of 3

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20191129/2117

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ZAINI BIN HASSAN	ID No.	S0200217E
Related Vehicle	SLD3825D (Car)	Contact No.	90102451
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	YEO KIAN SENG	ID No.	S1486260I
Related Vehicle	SME1773R (Car)	Contact No.	96355963
Hospital/Clinic	W Y TEH FAMILY CLINIC AND SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	29/11/2019	Date Discharge	29/11/2019
No. of Days granted Medical Leave	04	Degree of Injury	NIL

Brief Details.

On 29/11/2019 at about 9.50 a.m, I was driving my car registration number SME1773R along Jalan Ishak towards Jalan Eunus. As I bypass junction of Jalan Ishak and Lorong Marican, a car registration number SLD3825D came out of Lorong Marican. The front part of the car hit the left side of my car. My car was badly dented at the side. Subsequently I went to clinic and was give 4 days MC.



**SINGAPORE
POLICE FORCE**



T/20191129/2117

3 of 3

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20191129/2117

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

SI SHAHRIN BIN ABDULLAH

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt ONG YONG HOCK

Contact No.: 65476436

Signature Of Informant:

Date/Time:

29/11/2019 16:03

Classification Of Case:

Authentication Stamp

NP168

SINGAPORE
POLICE FORCE

SIGNATURE

Budget Direct



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SME 1773 R

*Not Authorized
Resurvey B4p1m*

Parts	(a) Cost / List Price Items	\$	2,258.10
	Plus/Less 20%	\$	451.62
	Total of Cost / List	\$	1,806.48
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	480.00
Total Parts Cost		\$	2,286.48
Labour		\$	2,420.00
Total		\$	4,706.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be returned and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	<u>Kenneth</u>
Company	:	<u>LKK</u>
Survey conducted on	:	<u>21/2/19</u> at _____
<u>Remarks By Surveyor</u>		
(a)	The repair of this vehicle is <u>authorized</u> / is not authorized until further notice.	
(b)	Recommended Days of Repair	: <u>05</u> day(s)
(c)	Resurvey	: Required / <u>Not Required</u>
(d)	Excess	:\$ _____
(e)	Signature of surveyor	: <u>Lc</u> Date: <u>21/2/19</u>



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :	SME 1773 R	Submit By :	Carmen Lim
Make & Model :	HONDA SHUTTLE	Year Manufacture :	2018
Chassis No. :	GP71218053	Engine No. :	

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH rear door	1	\$899.50		✓
2	LH rear door hinge top	1	\$68.50		X
3	LH rear door hinge bottom	1	\$68.50		X
4	LH rear door lock	1	\$195.80		✓
5	LH rear door checker	1	\$65.00		X
6	LH rear door weatherstrip	1	\$109.50		X
7	LHR door glass outer moulding	1	\$42.70		X
8	LHR power window motor	1	\$195.00		X
9	LHR power window regulator	1			
10	LH side skirt	1	\$383.60		✓ X
11	LH side skirt clip	10	\$35.00		✓ X
12	LH rear rim	1	\$480.00	S.N	5050
13	LH rear hub cap	1	\$195.00		✓
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI19021198/Ksf3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 23-12-2019	
		Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLD 3825D	Veh. Inspected	SME 1773R
Policy No.		Coverage (\$)	0.00
Claim No.	C10004753/KY	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	02/12/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71218053	Colour	METALLIC DARK BLUE
Odometer	84825	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	ROADSTONE	3 mm
L/H Front Tyre	185/60 R15	ROADSTONE	3 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	4 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/11/2019	Inspection Date	02/12/2019
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 1773R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LH REAR DOOR	BENT	899.50	899.50
1	LH REAR DOOR HINGE TOP	TO REPAIR SEE LABOUR	68.50	-
1	LH REAR DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	68.50	-
1	LH REAR DOOR LOCK	TO REPAIR SEE LABOUR	195.80	-
1	LH REAR DOOR CHECKER	TO REPAIR SEE LABOUR	65.00	-
1	LH REAR DOOR WEATHERSTRIP	SERVICEABLE	109.50	-
1	LHR DOOR GLASS OUTER MOULDING	SERVICEABLE	42.70	-
1	LHR POWER WINDOW MOTOR }	SERVICEABLE	195.00	-
1	LHR POWER WINDOW REGULATOR }	SERVICEABLE	-	-
1	LH SIDE SKIRT	SERVICEABLE	383.60	-
10	LH SIDE SKIRT CLIP	NOT NECESSARY	35.00	-
1	LH REAR HUB CAB	MISSING	195.00	195.00
	LESS 20% DISCOUNT		-451.62	-218.90
			1,806.48	875.60
SPECIAL NETT ITEMS				
1	LH REAR RIM (LOCAL PURCHASE)(SN)	DENTED	480.00	50.00
			480.00	50.00
LABOUR				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(LHF DOOR,LHR DOOR,LHR FENDER,LH SIDE SKIRT).INCLUSIVE OF THE REPAIR OF LH REAR DOOR HINGE TOP,LH REAR DOOR HINGE BOTTOM,LH REAR DOOR LOCK AND LH REAR DOOR CHECKER.		1,000.00	550.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(LHF DOOR,LHR DOOR,LHR FENDER,LH SIDE SKIRT).		1,000.00	800.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT DOOR TRIM,DOOR GLASS,WINDOW REGULATOR,DOOR LOCK TO ASSIST WORK LOAD.		150.00	60.00
	TO DO WHEEL ALIGNMENT.		120.00	60.00
	TO TUFF COAT.		100.00	30.00
			2,420.00	1,520.00

Report Ref No. CS/AGI19021198/Ksf3n2



GRAND TOTAL		4,706.48	2,445.60
RECOMMENDED COST OF REPAIRS			2,445.60

Report Ref No. CS/AGI19021198/Ksf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.