

ASS. REC. BY:

REF: CS3/A1419021202/BY d3b

Special Instruction:

Surveyor: LIM

Meunmen

ASSIGNMENT (Office)

From (Person): Jennifer Chen

of

A14

Date/Time: 02/12/2019

Estimated Cost:

Bill to:

OD-TP-WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 4882Y

Insured:

SMD 6099B

at Workshop m/s

Eng Shing Mechanical

Tel:

6453 7380

of

160 8th Ming Drive # 06-21

Policy No:

Claim No:

376213646159

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/11/2019

CA / REV / REP. / REV 24 HRS

Date/Time: 206pm @ 2/12/19

Person Contacted:

Mr. Tan

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (X)

SLT 4882Y-X

SMD 6099B-X

Dismantle recovery - 05/12/19

After print - 10/12/19

23/12/19

Submit DAR.

ASS. REC. BY:

REF:

AIG

## ASSIGNMENT

From

PRS

Date:

4/12/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLT 4882Y

at Workshop m/s

Eng Shing Mechanical

of 160 Sin Ming Drive # 06-21

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

65,000/2

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLT 4882Y

Yr Regn:

30/10/2015

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW

C.C

1426

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

47719

T/Radio:

Insured / Std / NI / NA

Eng/No:

36079358B37D15A

C/No:

WBA1V72070V249858

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55/16

R: 205/55/16

BS / DUN / EXNOVA / ☒ FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/11/19

D.O.I.

4/12/19

Survey held at

Eng Shing Mechanical

Des. of Damages:

Frt / Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 23 DEC 2019

MV

65,000/2

PV

42,571/2

NV

19,429/2

Retim Lin  
6/12/19

Date/Time, File Pass to?



: Preli. Report

1) 13/12/19



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others:

TOTAL

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Report Format:

DAR

Lump Sum / LBR (\$)


120

11

191

Your password will expire in 10 days. [Click here to change it.](#)

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICL...**

From: Chan, Jennifer-WM  
To: Admin A, assignments  
Cc: Fong, Andy-SY, Fan, Winnie-LW  
Sent: 12/2/2019 1:38:29 PM  
Attachments:  9211 - AIG PRI 20191202095625.pdf

---

Hi LKK,

Kindly assist to survey.

Thanks & regards  
Jennifer Chan

---

**From:** Hor, Yinrul  
**Sent:** Monday, 2 December, 2019 11:27 AM  
**To:** mail@oraclelaw.sg  
**Cc:** Fong, Andy-SY; Chan, Jennifer-WM; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni  
**Subject:** aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMD6099B AND SLT4882Y ON 30/11/2019

Without Prejudice

Your Reference : SB/PO/Acc/2019-9211  
Our Reference : SMD6099B

Dear Sir/Madam,

We refer to your email below. We disagree with the list of your nominated surveyors.  
Pursuant to Appendix C of Pre-Action Protocol for NIMA cases, citation 2.9. We will proceed to appoint our in house surveyor for the pre-repair inspection.

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
FNOL Adjuster I  
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208  
[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Oracle Law Corp [mailto:mail@oraclelaw.sg]  
**Sent:** Monday, December 02, 2019 11:07 AM  
**To:** Hor, Yinrul  
**Subject:** [EXTERNAL] RE: Our Ref: SB/PO/Acc/2019-9211 Your Ref: SMD 6099B

**This message is from an external sender; be cautious with links and attachments.**

Dear Yinrul,

**PRE-REPAIR INSPECTION**

**ACCIDENT INVOLVING SLT 4882Y & SMD 6099B ALONG UPPER THOMSON ROAD ON 30-11-2019 @ 7.15 P.M.**

Please refer to attachment the contents of which are self-explanatory for your kind attention and immediate action.

Regards

Alvin Ong



• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11

The Alexcier, Singapore 159929

Telephone: 6538 6250 Facsimile: 6538 1860

---

**From:** Hor, Yinrul [mailto:Yinrul.Hor@aig.com]

**Sent:** Monday, 2 December 2019 10:13 AM

**To:** Oracle Law Corp <mail@oraclelaw.sg>

**Cc:** Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chan, Jennifer-WM <Jennifer-WM.Chan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>

**Subject:** PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMD6099B AND SLT4882Y ON 30/11/2019



This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2019-12-08 21:13 EST to read your message.  
After that, open the attachment.

[More Info](#)

**Disclaimer:** This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

# Oracle Law Corporation

• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11  
The Alexcier, Singapore 159929  
Telephone: 6538 6250 Facsimile: 6538 1860  
Email: mail@oraclelaw.sg

## FACSIMILE TRANSMISSION

To	: AIG Asia Pacific Insurance Pte Ltd	Date	: 2 <sup>nd</sup> December 2019
Attention	: Motor Claims	From	: Mr Stanley Bay / Miss Pauline Ong
Your Ref.	: Insurer of SMD 6099B	Our Ref.	: SB/PO/Acc/2019-9211
Facsimile	: 6835-7416	No. of Pages	: 4 (including this page)

## **IMMEDIATE ATTENTION**

Dear Sirs

### **PRE-REPAIR INSPECTION**

**ACCIDENT INVOLVING SLT 4882Y & SMD 6099B ALONG UPPER THOMSON ROAD ON 30-11-2019 @ 7.15 P.M.**

We act for the owner of vehicle registration no. **SLT 4882Y**.

We are instructed by our client to notify you of the above accident involving our client's said vehicle and your insured's vehicle registration no. **SMD 6099B** driven at the material time. A copy of our client's Singapore Accident Statement is enclosed herein.

As a result of the above accident, our client's said vehicle was damaged. Before our client proceeds to repair his damaged vehicle, please let us know **within the next (2) working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. **If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair his said vehicle without further reference to you.**

Please note that this notification does not in any way prejudice our client's right nor shall it be deemed as a waiver of any of his rights, as such our client's rights are expressly reserved.

Yours faithfully



*Mr Stanley Bay / Miss Pauline Ong*  
Enc

### Details of Repairers

Eng Shing Mechanical Works  
160 Sin Ming Drive  
#06-21 Sin Ming Autocity S(575722)  
Tel No.: 6453-7380 ; Fax No. 6252-4129

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/12/2019 15:46
Date Of Accident	30/11/2019 19:15
Exact Location Of Accident	ALONG UPPER THOMSON ROAD NEAR OUTSIDE THOMSON CC
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT4882Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ENG JIAT CHENG
NRIC No	S1164260H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94756701
Alternative Phone No	OFFICE-94756701

### Vehicle Particulars

Manufacturer	BMW
Model	116 D
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096192563-01
Cover Note Number	

### Driver

Name of Driver	TAN YU SHENG
NRIC No	S8524894D
Date Of Birth	02/09/1982
Occupation	INDOOR
Date Of Driving Pass	13/10/2004
Driving Experience	15 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94756701
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 453 SIN MING AVENUE #16-563 SINGAPORE
Postcode	570453
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LEE YAN LIN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD6099B
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	PRIVATE CAR
Name of Driver	ONG TENG KHOON
NRIC/Passport Number	S0178139A
Contact Number	96649359
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 02/12/19  
09:11

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(near outside Thomson CC)

I was driving along Upper Thomson Road, towards Novena, on 30/11/2019, about 1915hrs. I was on left most lane, going straight. A car on my right, SMD 6099B, cut into my lane, I sounded the horn <sup>but he continued</sup> and he knocked into the right passenger door of my car and scraped all the way to the right back bumper.

We stopped at the side of the road to exchange contacts and take photo. The driver of SMD 6099B said that he was turning to Marymount MRT to pick his wife. Hence, he would needed to take the left lane.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 02/12/19  
9.12

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Photo



## MOTOR CAR (RH)

Vehicle No: SLT 48824

### Right Portion

[illegible][illegible]

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	260H
<b>Vehicle Details</b>	
Vehicle No.:	SLT4882Y
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Dec 2019
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCHBACK DSC LED
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	36079358B37D15A
Chassis No.:	WBA1V72070V249858
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,802.00
Original Registration Date:	30 Oct 2015
First Registration Date:	30 Oct 2015
Transfer Count:	1
Actual ARF Paid:	\$11,723.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2025
PARF Rebate Amount:	\$8,792.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,301.00
COE Rebate Amount:	\$33,779.00
<b>Total Rebate Amount:</b>	<b>\$42,571.00</b>

The information contained herein is correct as at 06 Dec 2019

OK

Dep 10,340/yr  
862/mth

MV 65,000/2  
PV 42,571/2  
NY 19,429/2

  
6/12/19

**SUSS**  
SINGAPORE UNIVERSITY  
OF SOCIAL SCIENCES



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Bmw 5 Series 523i Sunroof July 2011.



Very Well Maintain Interior And  
Exterior. Very Safe Buy, Selling  
Close To Scrap.  
Direct Owner: StarAd



Browse by Category ▼

◀ Back ( 1 2 ) Next ▶








Sort by Date Posted ▼

20 results/page ▼

23 vehicles

BMW 116d

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>BMW 116d</b>		Any	Any	<b>2015</b>	Any	Any	Any	All
	<b>BMW 1 Series 116d</b>		<b>\$69,800</b>	<b>\$11,410 /yr</b>	<b>13-Aug-2015</b>	<b>1,496 cc</b>	<b>38,000 km</b>	<b>Hatchback</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) 1 Owner, Low Mileage Agent (PML) Unit, Low Depre, 1.98% Interest, Buy From Reputed Company, All Credit Profile Welcome, 100% Loan Available, Free 2 Years Warranty And Servicing Package. Hamilton Autohub Pte Ltd Posted: 03-Dec-2019 Tags: 2015 BMW 116d, 2015 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW									
	<b>BMW 1 Series 116d</b>		<b>\$67,800</b>	<b>\$10,610 /yr</b>	<b>30-Sep-2015</b>	<b>1,496 cc</b>	<b>47,000 km</b>	<b>Hatchback</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) 100% Loan Available! Offer Bank Interest Rate From 1.98%! 1 Owner PML Unit. Free 1 Year Warranty With Certified 120 Points Test Report With Detailed Chassis Inspection. Drive Off With A Peace Of Mind. Extremely Fuel Efficient Engine Delivers 24Km/L With Up To 1... Dynamic Motoring Posted: 03-Dec-2019 Tags: 2015 BMW 116d, 2015 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW									
	<b>BMW 1 Series 116d</b>		<b>\$65,999</b>	<b>\$10,340 /yr</b>	<b>29-Sep-2015</b>	<b>1,496 cc</b>	<b>58,000 km</b>	<b>Hatchback</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) Very Affordable German Hatchback! Certified Premium Pre-Owned Multi Points Check For Peace Of Mind Drive Away. Exceptionally Frugal Fuel Consumption! Well Maintained By Previous Owner With Regular Servicing! Be Seen In This Sporty Black German Engineered Hatch... Premium Automobiles Posted: 02-Dec-2019 Tags: 2015 BMW 116d, 2015 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW									
	<b>BMW 1 Series 116d</b>		-	<b>N.A</b>	<b>15-Sep-2015</b>	<b>1,496 cc</b>	-	<b>Hatchback</b>	<b>SOLD</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) Offer Best Interest Rate With High Loan! Hurry Please Call For Availability, High Loan Discussion Or Viewing Appointment! Please Call Sales Person! Immediate Transfer Of Ownership Upon Collection. Benefit Auto Enterprise Pte Ltd Posted: 02-Dec-2019 Tags: 2015 BMW 116d, 2015 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW									
	<b>Rear Spoiler</b> BMW F10 523i 535i Rear Spoiler. PU material, Slim and Sleek Design, good fitment. More info about this product								
	<b>BMW 1 Series 116d</b>		<b>\$65,800</b>	<b>\$10,550 /yr</b>	<b>31-Aug-2015</b>	<b>1,496 cc</b>	<b>68,000 km</b>	<b>Hatchback</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) 1 Owner BMW 116 With Black Interior. PML Unit Guaranteed Condition, 100% Loan Available, Hurry! Car Available In Showroom For Viewing Now. Contact For More Details. Posted: 01-Dec-2019 Tags: 2015 BMW 116d, 2015 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW									
	<b>BMW 1 Series 116d M-Sport</b>		<b>\$74,940</b>	<b>\$11,970 /yr</b>	<b>30-Sep-2015</b>	<b>1,496 cc</b>	-	<b>Hatchback</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) Warranty With PML Extended! 100% Loan Available! Tip Top Condition! Brand New Wrap! Price Reduced! 1 Direct Owner Sale. Still Under Agent Warranty For Peace Of Mind. Fully Serviced And Maintained By Agent. Low Mileage. Accident Free. Comes With Free Bidded Num... Auto Inn Posted: 27-Nov-2019 Tags: 2015 BMW 116d, 2015 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW									

Compare

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Dec 2019 <a href="#">Edit Reg</a>		02 Dec 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Ong Teng Khoon, Co. Reg. No.: -		
Main Claimant:	ENG JIAT CHENG		
Vehicle Reg. No.:	SLT4882Y	Date of Loss:	30/11/2019 00:00 - :59 [49 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3762136461SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SMD6099B	Policy No. (Claimant):	
		Excess:	
Repairer:	Eng Shing Mechanical Works (HQ) 160 Sin Ming Drive, #06-21 Sin Ming Autocity, 575722 Sin Ming - Tel: 64537380		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 11/12/2019]		
Claimant's Solicitor:	ORACLE LAW CORPORATION - Tel: 65386250		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (05/12/2019): TP GIA report

## ALL ASSOCIATED TASKS












































[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SLT4882Y (3762136461SG)  
[SMD6099B]  
TP  
ENG JIAT CHENG  
Nov 30 2019 12:00AM  
[Ong Teng Khoon]  
Eng Shing Mechanical Works

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
2	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
3	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
4	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
5	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
6	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
7	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
8	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
9	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
10	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
11	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
12	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
13	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
14	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
15	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
16	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
17	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
18	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
19	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
20	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
21	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
22	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
23	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
24	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
25	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
26	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
27	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
28	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
29	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
30	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
31	23/12/19 10:23	Chassis Number														Load JPG	<input checked="" type="checkbox"/>			
32	23/12/19 10:23	Odometer Reading														Load JPG	<input checked="" type="checkbox"/>			
33	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
34	23/12/19 10:23	General View														Load JPG	<input checked="" type="checkbox"/>			
35	23/12/19 10:24	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
36	23/12/19 10:24	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
37	23/12/19 10:24	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
38	23/12/19 10:24	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
39	23/12/19 10:24	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
40	23/12/19 10:24	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
41	23/12/19 10:25	After Repair Photo														Load JPG	<input checked="" type="checkbox"/>			
42	23/12/19 10:25	After Repair Photo														Load JPG	<input checked="" type="checkbox"/>			
43	23/12/19 10:25	After Repair Photo														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	23/12/19 10:25	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
45	23/12/19 10:25	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
46	23/12/19 10:25	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
47	23/12/19 10:25	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
48	23/12/19 10:25	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
49	23/12/19 10:25	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
50	23/12/19 10:25	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
51	23/12/19 10:25	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19021202/BQD3E2  
Date: 26/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
Claimant SLT4882Y Insured Vehicle No : SMD6099B  
Vehicle No : SLT4882Y  
Date of Loss: 30/11/2019 Nature of Claim: TP Claim No: 3762136461SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT4882Y  
Make & Model: BMW 116D, 1.5 D 5DR HATCH LED (A) Engine No: 36079358B37D15A  
Reg. Date: 30/10/2015 (Man. Year: 2015) Chassis No: WBA1V72070V249858  
Colour: White Odometer: 49719 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/12/2019  
Date Inspected: 04/12/2019 Inspected At: Eng Shing Mechanical Works (HQ)  
160 Sin Ming Drive, #06-21 Sin Ming  
Autocity  
Singapore 575722  
Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Dented	0.00 F	*- F
2	1		*REAR RH DOOR RUBBER	Necessary	0.00 F	*- F
3	1		*REAR BUMPER	Broken	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER RH	Distorted	0.00 F	*- F
5	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
6	1		*REAR RH FENDER	Repair	0.00 F	*- F
7	1		*REAR LEFT WHEEL (LOCAL REPAIR)	Scratched	0.00 F	*- F
8	1		*SIDE SKIRT	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >