

ASS. REC. BY:

REF: CS3/A191902/206/Hsd387 Special Instruction:

Surveyor: Hock AnnASSIGNMENT (Office)- MWFrom (Person): Jennifer Chanof ACADate/Time: 2/12/2019 @ 11:43am

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

FBP 3933 E

Insured: _____

SKR 951E

at Workshop in/s _____

GP Motoring

Tel: _____

9061 8091

of _____

282 Macpherson Road

Policy No: _____

Claim No: _____

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 19/11/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 1:52pm @ 2/12/19

Person Contacted: _____

KenVehicle: IN/OUT

Date/Time

Action/Instruction Follow up (X)FBP 3933 E - XSKR 951E - X2/12/19 - survey5/12/19 - pending survey- later repair pending

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBP 3733E

Yr Regn:

27/03/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA GDR (AEROX)

c.c. 155

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

18354 km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MH35G4640KJ053669

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110/80/R14

R:

140/70/R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

mm

L/Bal.

mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

DAN / ON

Repair days

4 days

MV - 7600

PV - 3230

NV - 4300

RECEIVED 03 DEC 2019

Date/Time, File Pass to?

03/12/19

1)

Typist

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Phone

Others

TOTAL

Rep. Form:

PRS



Lump Sum / L.E.D. C:

11

191

Your password will expire in 10 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE ...

From: Chan, Jennifer-WM
To: Admin A, assignments
Cc: Fong, Andy-SY, Fan, Winnie-LW
Sent: 12/2/2019 11:43:58 AM
Attachments:  PRI FBP3933E.pdf  PRI FBP3933E.PDF

Hi LKK,

Kindly assist to survey.

GP Motoring Pte Ltd
282 Macpherson Road
Singapore 348607
Mobile :9061-8091
Fax: 6909-9284
Contact person: Mr. Ken Sim

Thanks & regards
Jennifer Chan

From: Hor, Yinrul
Sent: Monday, 2 December, 2019 9:49 AM
To: zul@juseq.com.sg; Alfred Ng
Cc: Fong, Andy-SY; Chan, Jennifer-WM; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKR951E AND FBP3933E ON 19/11/2019

Without Prejudice

Your Reference : JEQ/FBP3933E/GP (zl)
Our Reference : 0437420579SG003

Dear Sir/Madam,

We refer to your email below. We disagree with the list of your nominated surveyors.
Pursuant to Appendix C of Pre-Action Protocol for NIMA cases, citation 2.9. We will proceed to appoint our in house surveyor for the pre-repair inspection.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinrul.Hor@aig.com | www.aig.sg

From: alfred_ng@juseq.com.sg [mailto:alfred_ng@juseq.com.sg]

Sent: Friday, November 29, 2019 5:37 PM

To: Hor, Yinrul

Subject: [EXTERNAL] ACCIDENT INVOLVING FBP3933E AND SKR951E ON 19 NOV 2019

This message is from an external sender; be cautious with links and attachments.

Your ref:0437420579SG003

Our ref: JEQ/ FBP3933E/GP

Dear Yinrul,

We refer to your email today.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1. Absolute Appraisal Services Pte Ltd;
2. Sincere Appraisal Services;
3. Mc Coy Appraiser Pte Ltd;
4. Delta V Consultant;
5. Prominent Appraiser Pte Ltd;
6. Advance Automotive Consultancy Pte Ltd;
7. Pal's Appraiser Pte Ltd;
8. S K Auto Consultants;
9. Prudent Adjustors Services;
10. CL Appraiser Pte Ltd;

Please be informed that if the above mentioned surveyors is not agreeable by you, our clients' motor vehicle is available for pre-repair inspection at the under-stated workshop:-

GP Motoring Pte Ltd
282 Macpherson Road
Singapore 348607
Mobile :9061-8091
Fax: 6909-9284
Contact person: Mr. Ken Sim

With Regards

Alfred Ng
Executive
Legal Division
On behalf of Mr. Michael Yap
M/s JusEquity Law Corporation
No. 133 New Bridge Road
Chinatown Point
#10-03 Singapore 059413

Tel : 6536 9339

Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

From: Yinrul.Hor@aig.com

To: zul@juseq.com.sg ,alfred_ng@juseq.com.sg

Cc: Andy-SY.Fong@aig.com ,Winnie-LW.Fan@aig.com ,NoorMariesa.AbuKassim@aig.com ,Syazairdina.Azlan@aig.com ,yokeshi.chan@aig.com ,ShengYang.Lim@aig.com ,Aashweenjeetkaur.Mithoosingh@aig.com ,Theerthan.Parthiban@aig.com ,Divyashni.Subramaniam@aig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKR951E AND FBP3933E ON 19/11/2019

Date: Fri, 29 Nov 2019 07:15:00 +0000

Without Prejudice

Your Reference : JEQ/FBP3933E/GP (zl)

Our Reference : 0437420579SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster I

Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208

Yinrul.Hor@aig.com | www.aig.sg

From: zul [mailto:zul@juseq.com.sg]

Sent: Friday, November 29, 2019 2:55 PM

To: Hor, Yinrul

Cc: 'Alfred Ng'

Subject: [EXTERNAL] ACCIDENT INVOLVING FBP3933E & SKR951E ALONG SEMBAWANG ROAD ON 19.11.2019 O ref: JEQ/FBP3933E/GP (zl)

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

Please refer to our notice of accident.

Regards,

Zul

JusEquity Law Corporation

133 New Bridge Road #10-03

Chinatown Point

Singapore 059413

Tel: 6536 9339

Fax: 6536 5368

E-mail: zul@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

133 New Bridge Road #10 – 03, Chinatown Point, Singapore 059413

Telephone (65) 6536 9339,

Email : claims@juseq.com.sg

Fax : (65) 6536 5368 (Litigation & Conveyancing)

website : www.juseq.com.sg

Our Ref: JEQ/FBP3933E/GP (zl)

Your Ref: SKR951E

29 November 2019

KHOO KEE CHAI GODFREY
303 Canberra Road #05 – 33
Singapore 750303

By Post Only

AIG ASIA PACIFIC INSURANCE PTE LTD
Singapore

By Fax: 6835 7416 Only

Dear Sir

ACCIDENT INVOLVING FBP3933E AND SKR951E ON 19.11.2019

We act for the owner of vehicle no. FBP3933E.

We hereby notify you of a road traffic accident on **19 November 2019** at about **0735 hrs**, along Sembawang Road towards Gambas Avenue involving our client's vehicle and vehicle registration no. **SKR951E** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 27/11/2019 18:35

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2019 18:18
Date Of Accident	19/11/2019 07:35
Exact Location Of Accident	ALONG SEMBAWANG ROAD TOWARD GAMBAS AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBP3933E
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD RAZI BIN JOHARI
NRIC No	S8301072Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83066449
Alternative Phone No	OFFICE-83066449
Vehicle Particulars	
Manufacturer	YAMAHA
Model	GDR155A (AEROX)-155CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	D19MTMC01002399
Cover Note Number	
Driver	
Name of Driver	MUHAMMAD RAZI BIN JOHARI
NRIC No	S8301072Z
Date Of Birth	02/02/1983
Occupation	INDOOR
Date Of Driving Pass	25/01/2019
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83066449
Fax Number	
Contact Number	OFFICE-83066449
EMail Address	NOEMAIL

Address BLK 501C WELLINGTON CIRCLE
#03-68
Postcode 753501
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : NOORASHIKIN BINTE HAMZAH
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name 10 UBI AVENUE 3
Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT AND SETCH PLAN. THANK YOU

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKR951E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver KHOO KEE CHAI
NRIC/Passport Number
Contact Number 94898468

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBP3933E

Were seat belts worn?

NO

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renewate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name:

SKETCH PLAN



oob = FBP 3933 E /  = SKR 951 E Along Sembawang Road towards Chembas Ave.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report T/20191126/2094.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

I/We declare the foregoing particulars are true in every respect.



**SINGAPORE
POLICE FORCE**



T/20191128/2094

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408866
Tel No: 65470000

1 of 3

Report No. T/20191128/2094

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/11/2019 14:39		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MUHAMMAD RAZI BIN JOHARI			Address: APT BLK 501C WELLINGTON CIRCLE #03-68 MONTREAL SPRING SINGAPORE 753501		
ID Type / ID No.: NRIC NO / S8301072Z			Contact No.: Home/Office: Mobile: 91081437		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 02/02/1983	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name:
Occupation: OTHERS			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 19/11/2019 07:35	Type of Location:
Location: Along Road 1 SEBBAWANG ROAD INFRONT OF SPC PETROL KIOSK				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBP3933E	Motorcycle	YAMAHA	GDR155A (AEROX)	Black	Slightly Damaged	1
SKR951E	Car				Seriously Damaged	0

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date	
FBP3933E	TENET SOMPO INSURANCE PTE. LTD.	D19MTMC0100239 9	27/03/2019	26/03/2020	



**SINGAPORE
POLICE FORCE**



T/20191126/2094

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3
Report No. T/20191126/2094

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMMAD RAZI BIN JOHARI	ID No.	S8301072Z
Related Vehicle	FBP3933E (Motorcycle)	Contact No.	91081437
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	19/11/2019	Date Discharge	19/11/2019
No. of Days granted Medical Leave	14	Degree of Injury	Serious
Driver			
Name	KHOO KEE CHAI	ID No.	NIL
Related Vehicle	NIL	Contact No.	94898468
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE, TIME AND LOCATION, I WAS RIDING MY MOTORCYCLE ON MY WAY TO WORK WITH MY WIFE WHEN I COLLIDED WITH A MERCEDES CAR. I WAS DRIVING ON THE LEFT LANE OF 3 LANES. THE MERCEDES CAR CAME FROM UTMOST RIGHT. HE SIGNALLED FROM THE RIGHT TO CENTRE LANE AND SUDDENLY MADE A SHARP TURN TOWARDS SPC PETROL KIOSK WITHOUT NOTICING THAT I WAS IN THE RIGHT OF WAY. I THEN COLLIDED INTO THE CAR AS THE CAR DIDNT GIVE ME ALLOWANCE TO BRAKE. I THEN ASKED THE DRIVER WHAT HAPPENED AND HE TOLD ME THAT HE DID NOT SEE ME AS IT WAS A BLIND SPOT. AMBULANCE CAME AND I WAS CONVEYED TO KHOO TECK PUAT HOSPITAL. I SUFFERED A RIB FRACTURE, ABRASIONS TO THE LEG, LIPS AND BOTH ARMS.

THATS ALL
IO IVAN
TEL 65476170



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20191126/2094

3 of 3

Report No. T/20191126/2094

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
MUHAMMAD MOINUR RAHMAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sgt 2 HO JIEKANG, IVAN
Contact No.: 65476170

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
26/11/2019 14:39

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature:

Your password will expire in 10 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION REQUEST – SJT7667G vs SLM1378T (OI) on D.O.A.: 29/11/2019

From: Hor, Yinnul
To: 'assignments@kkauto.com', Admin A (admin-a@kkauto.com)
Cc: Fong, Andy-SY; Chan, Jennifer-WM; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam,
Sent: Monday, 2 December 2019 11:51:12 AM
Attachments: [image.png](#); [lock.pdf](#); [QIA REPORT PDF](#); [QIA REPORT PDF](#)

Hi,

Please refer to the enclosed request from **Teamwork Garage Pte Ltd**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Mohamad Taufik** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL / Claims Operations – Auto

Tel: 6001206556 | Ext: 1002208
Yinnul.Hor@aig.com | www.aig.sg

From: Darren [mailto:claims@teamworkgarage.com]
Sent: Monday, December 02, 2019 11:35 AM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chan, Jennifer-WM; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM1378TAND SJT7667G ON 29/11/2019

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

Hi Yinnul,

Kindly appoint LKK Taufik.

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Hor, Yinnul
Sent: Monday, 2 December 2019 10:46 AM
To: claims@teamworkgarage.com
Cc: Fong, Andy-SY; Chan, Jennifer-WM; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM1378TAND SJT7667G ON 29/11/2019



This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2019-12-08 21:46 EST to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. If you have received this email in error or simply delete it.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	072Z
Vehicle Details	
Vehicle No.:	FBP3933E
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Dec 2019
Vehicle Make:	YAMAHA
Vehicle Model:	GDR155A (AEROX)
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	G3J8E0099842
Chassis No.:	MH3SG4640KJ053669
Maximum Power Output:	-
Open Market Value:	\$2,369.00
Original Registration Date:	27 Mar 2019
First Registration Date:	27 Mar 2019
Transfer Count:	1
Actual ARF Paid:	\$356.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Mar 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,469.00
COE Rebate Amount:	\$3,230.00
Total Rebate Amount:	\$3,230.00

The information contained herein is correct as at 03 Dec 2019

OK



(1)

Make or Model

Type

Any

Price From

Any

Price To

Any

Class

Any

Q SEARCH

VIEW ALL (/LISTING/NEWBIKES/LISTING/SELL/)



REPORT ERROR (/LISTING/LISTING/ERROR/NEWBIKES/228/)

SHORTLIST

Share

© SHAR (WHA) SAPP (/SHORTLIST/HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/NEWBIKES/SELL/YAMAHA-YAMAHA-AEROX-155/228/)

Yamaha Aerox 155

Brand	Yamaha (/listing/newbikes/brand/yamaha/)
Model	Yamaha Aerox 155
Engine Capacity	155
Class	2B
Type of Vehicle	Scooters

Price: SGD\$9042

new 4th
less 15%
= \$7685

DETAILS

Brand New Yamaha Aerox 155 ABS! Comes With 12 Months Unlimited Mileage Agent Warranty! 42nd Anniversary Special!
Downpayment from \$42!

USED YAMAHA FOR SALE

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2019 18:18
Date Of Accident	19/11/2019 07:35
Exact Location Of Accident	ALONG SEMBAWANG ROAD TOWARD GAMBAS AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBP3933E
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD RAZI BIN JOHARI
NRIC No	S8301072Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83066449
Alternative Phone No	OFFICE-83066449

Vehicle Particulars

Manufacturer	YAMAHA
Model	GDR155A (AEROX)-155CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	D19MTMC01002399
Cover Note Number	

Driver

Name of Driver	MUHAMMAD RAZI BIN JOHARI
NRIC No	S8301072Z
Date Of Birth	02/02/1983
Occupation	INDOOR
Date Of Driving Pass	25/01/2019
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83066449
Fax Number	
Contact Number	OFFICE-83066449
EEmail Address	NOEMAIL

Address	BLK 501C WELLINGTON CIRCLE #03-68
Postcode	753501
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NOORASHIKIN BINTE HAMZAH GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT AND SETCH PLAN. THANK YOU

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR951E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KHOO KEE CHAI
NRIC/Passport Number	
Contact Number	94898468

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBP3933E

Were seat belts worn? NO

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name:

SKETCH PLAN



000) = FBP 3933 E /  = SKR 951 E

Along Sembawang Road
towards Grambas Ave.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report T/20191126/2094

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]



**SINGAPORE
POLICE FORCE**



T/20191126/2094

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20191126/2094

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/11/2019 14:39		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MUHAMMAD RAZI BIN JOHARI			Address: APT BLK 501C WELLINGTON CIRCLE #03-68 MONTREAL SPRING SINGAPORE 753501		
ID Type / ID No.: NRIC NO / S8301072Z			Contact No.: Home/Office: Mobile: 91081437		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 36	Date of Birth: 02/02/1983	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name:
Occupation: OTHERS			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 19/11/2019 07:35	Type of Location:
Location: Along Road 1 SEBBAWANG ROAD INFRONT OF SPC PETROL KIOSK				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBP3933E	Motorcycle	YAMAHA	GDR155A (AEROX)	Black	Slightly Damaged	1
SKR951E	Car				Seriously Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBP3933E	TENET SOMPO INSURANCE PTE. LTD.	D19MTMC0100239 9	27/03/2019	26/03/2020



**SINGAPORE
POLICE FORCE**



T/20191126/2094

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191126/2094

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMMAD RAZI BIN JOHARI	ID No.	S8301072Z
Related Vehicle	FBP3933E (Motorcycle)	Contact No.	91081437
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	19/11/2019	Date Discharge	19/11/2019
No. of Days granted Medical Leave	14	Degree of Injury	Serious
Driver			
Name	KHOO KEE CHAI	ID No.	NIL
Related Vehicle	NIL	Contact No.	94898468
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE, TIME AND LOCATION. I WAS RIDING MY MOTORCYCLE ON MY WAY TO WORK WITH MY WIFE WHEN I COLLIDED WITH A MERCEDES CAR. I WAS DRIVING ON THE LEFT LANE OF 3 LANES. THE MERCEDES CAR CAME FROM UTMOST RIGHT. HE SIGNALLED FROM THE RIGHT TO CENTRE LANE AND SUDDENLY MADE A SHARP TURN TOWARDS SPC PETROL KIOSK WITHOUT NOTICING THAT I WAS IN THE RIGHT OF WAY. I THEN COLLIDED INTO THE CAR AS THE CAR DIDNT GIVE ME ALLOWANCE TO BRAKE. I THEN ASKED THE DRIVER WHAT HAPPENED AND HE TOLD ME THAT HE DID NOT SEE ME AS IT WAS A BLIND SPOT. AMBULANCE CAME AND I WAS CONVEYED TO KHOO TECK PUAT HOSPITAL. I SUFFERED A RIB FRACTURE, ABRASIONS TO THE LEG, LIPS AND BOTH ARMS.

THATS ALL

IO IVAN

TEL 65476170



**SINGAPORE
POLICE FORCE**



T/20191126/2094

3 of 3

Report No. T/20191126/2094

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000


CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / MUHAMMAD MOINUR RAHMAN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 26/11/2019 14:39
Officer In Charge Of Case: TP / GIT / Sgt 2 HO JIEKANG, IVAN Contact No.: 65476170	Classification Of Case: 
Authentication Stamp NP168	



Sampo Insurance Singapore Pte. Ltd.

30 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048023
Tel: 6461 6555 - Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 15565450E | GST Reg. No.: U00063105

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1969
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D19MTMC01002399
Insured : MUHAMMAD RAZI BIN JOHARI
Motor Vehicle (Regn No.) : FBP3933E
Cover : Third Party, Fire & Theft
Policy Commencement Date : 27 MARCH 2019 15:55
Policy Expiry Date : 26 MARCH 2020 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$300 - Section I
Named Driver 1 : MUHAMMAD RAZI BIN JOHARI
Named Driver 2 : HAIRI BIN HASNAN
HIRE PURCHASE OWNER : GP MOTORING PTE LTD

* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

MUHAMMAD RAZI BIN JOHARI, HAIRI BIN HASNAN

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purposes and
 (a) by the Insured in person in connection with his business or profession or
 (b) in connection with the Insured's business or profession

The Policy does not cover

- (i) Use for hire or reward
- (ii) Use for racing, pacemaking, reliability trial or speed-testing
- (iii) Use for the carriage of goods (other than samples) in connection with any trade or business
- (iv) Use for any purpose in connection with the Motor Trade

Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Vehicle within 24 hours of the accident or by the next working day thereof.

For list of Accident Reporting Centres, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6461 6555.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Transport Act, 1957 (Malaysia); and (2) the policy terms, conditions and exceptions of the Motorcycle Policy (Ref MCY-MTMC.02)

Sampo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 27 MARCH 2019 15:58

IMPORTANT NOTICE

- Keep the Certificate in your Motor Vehicle.
- Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- On the sale of the Motor Vehicle or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If this Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- This Policy will cease to be valid once the Motor Vehicle has been sold to another person. The Policy is not transferable to the new owner of the Motor Vehicle.

Intermediary Code & Name : 11E07901 & ENSURE PTE. LTD. (MOTORCYCLE) CI Code: MY3 _JDZRH4J4TBLMPAJ

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Dec 2019 Edit Reg		02 Dec 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	Khoo Kee Chai Godfrey, ID: S15565961, Tel: +6594898468								
Main Claimant:	MUHAMMAD RAZI BIN JOHARI, ID: S83010722								
Vehicle Reg. No.:	FBP3933E	Date of Loss: 19/11/2019 07:00 - :59 [7 Months and 23 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 0437420579SG	Policy/Cover Note No.: 2100399293 (Comprehensive) Coverage: 16/01/2019 - 15/01/2020							
Vehicle Reg. No. (Insured):	SKR951E	Policy No. (Claimant):							
		Excess:							
Repairer:	GP MOTORING PTE LTD (HQ) 282 Macpherson Road, 348607 Macpherson - Tel: 67464240								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 11/12/2019]								
ASSOCIATED MAIL RECEIVED									
		View All Compose Case Mail							
• AIG_SG (03/12/2019): TP GIA report									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBP3933E (0437420579SG)
[SKR951E]












































TP






































MUHAMMAD RAZI BIN JOHARI

Nov 19 2019 7:00AM















































[Khoo Kee Chai Godfrey]




































GP MOTORING PTE LTD

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
Photos/Images						3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print		
1	03/12/19 09:55	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>		
2	03/12/19 09:56	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>		
3	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
4	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
5	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
6	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
7	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
8	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
9	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
10	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
11	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
12	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
13	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
14	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
15	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
16	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
17	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
18	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
19	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
20	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
21	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
22	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
23	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
24	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
25	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
26	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
27	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
28	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
29	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
30	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
31	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
32	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
33	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
34	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
35	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
36	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
37	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
38	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
39	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
40	03/12/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>		
41	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>		
42	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>		
43	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
62	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
63	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
64	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
65	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
67	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
68	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
69	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
70	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
71	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
72	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
73	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
74	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
75	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
76	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
77	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
78	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
79	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
80	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
81	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
82	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
83	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
84	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
85	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
86	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
87	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
88	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
89	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
90	03/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
91	03/12/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
92	03/12/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
93	03/12/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
94	03/12/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
95	03/12/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
96	03/12/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
97	03/12/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
98	03/12/19 09:58	General View	Load JPG	<input checked="" type="checkbox"/>
99	03/12/19 09:58	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
100	03/12/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
101	03/12/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
102	03/12/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
103	03/12/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
104	03/12/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
105	03/12/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
106	03/12/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
107	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
108	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
109	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
110	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
111	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
112	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
113	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
114	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
115	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
116	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
117	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
118	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
119	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
120	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
121	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
122	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
123	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
124	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
125	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
126	06/12/19 08:58	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
127	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
128	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
129	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
130	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
131	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
132	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
133	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
134	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
135	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
136	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
137	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
138	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
139	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
140	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
141	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
142	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
143	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
144	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
145	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
146	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
147	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
148	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
149	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
150	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
151	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
152	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
153	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
154	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
155	06/12/19 08:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
156	06/12/19 08:59	Reinspection Photo		<input checked="" type="checkbox"/>
157	06/12/19 08:59	Reinspection Photo		<input checked="" type="checkbox"/>
158	06/12/19 08:59	Reinspection Photo		<input checked="" type="checkbox"/>
159	06/12/19 08:59	Reinspection Photo		<input checked="" type="checkbox"/>
160	06/12/19 08:59	Reinspection Photo		<input checked="" type="checkbox"/>
161	06/12/19 08:59	Reinspection Photo		<input checked="" type="checkbox"/>
162	06/12/19 08:59	Reinspection Photo		<input checked="" type="checkbox"/>
163	06/12/19 08:59	Reinspection Photo		<input checked="" type="checkbox"/>
164	06/12/19 08:59	Reinspection Photo		<input checked="" type="checkbox"/>
165	06/12/19 08:59	Reinspection Photo		<input checked="" type="checkbox"/>
166	06/12/19 08:59	Reinspection Photo		<input checked="" type="checkbox"/>
167	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
168	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
169	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
170	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
171	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
172	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
173	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
174	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
175	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
176	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
177	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
178	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
179	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
180	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
181	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
182	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
183	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
184	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
185	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
186	06/12/19 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
187	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
188	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
189	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
190	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
191	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
192	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
193	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
194	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
195	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
196	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
197	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
198	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
199	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
200	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
201	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
202	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
203	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
204	06/12/19 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
205	10/12/19 10:16	After Repair Photo		<input checked="" type="checkbox"/>
206	10/12/19 10:16	After Repair Photo		<input checked="" type="checkbox"/>
207	10/12/19 10:16	After Repair Photo		<input checked="" type="checkbox"/>
208	10/12/19 10:16	After Repair Photo		<input checked="" type="checkbox"/>
209	10/12/19 10:16	After Repair Photo		<input checked="" type="checkbox"/>
210	10/12/19 10:16	After Repair Photo		<input checked="" type="checkbox"/>
211	10/12/19 10:16	After Repair Photo		<input checked="" type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
212	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
213	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
214	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
215	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
216	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
217	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
218	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
219	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
220	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
221	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
222	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
223	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
224	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
225	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
226	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
227	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
228	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
229	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
230	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
231	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
232	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
233	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
234	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
235	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
236	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
237	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
238	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
239	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
240	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
241	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
242	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
243	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
244	10/12/19 10:16	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
245	10/12/19 10:17	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	03/12/19 15:05	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19021206/HSDE2

Date: 10/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100399293
Claimant
Vehicle No : FBP3933E **Insured Vehicle No :** SKR951E
Date of Loss: 19/11/2019 **Nature of Claim:** TP **Claim No:** 0437420579SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBP3933E
Make & Model: YAMAHA GDR155A (AEROX), 155cc **Engine No:** G3J8E0099842
Reg. Date: 27/03/2019 (Man. Year: 2019) **Chassis No:** MH3SG4640KJ053669
Colour: Black **Odometer:** 18354 km
Engine Capacity: 155 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 110/80 R14 **Rear Tyre Size:** 140/70 R14
Front Left Side: IRE 6 mm **Rear Left Side:** IRE 6 mm
Front Right Side: 0 mm **Rear Right Side:** 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/12/2019
Date Inspected: 02/12/2019 **Inspected At:** GP MOTORING PTE LTD (HQ)
 282 Macpherson Road
 Singapore 348607
Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Scratched	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Cracked	0.00 F	*- F
3	1		*FRONT BRAKE DISC	* Check	0.00 F	*- F
4	1		*FRONT BRAKE CALIPER	* Check	0.00 F	*- F
5	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
6	1		*FRONT FORK INNER TUBE	Crushed	0.00 F	*- F
7	1		*FRONT FORK OUTER TUBE	Crushed	0.00 F	*- F
8	2		*FRONT FORK BRACKET	Crushed	0.00 F	*- F
9	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
10	1		*FRONT FORK GARNISH	Cracked	0.00 F	*- F
11	1		*FRONT HEADLAMP	Cracked	0.00 F	*- F
12	1		*FRONT HEADLAMP BRACKET	Crushed	0.00 F	*- F
13	1		*FRONT HEADLAMP FAIRING	Crushed	0.00 F	*- F
14	2		*FRONT WING MIRROR	Cracked	0.00 F	*- F
15	1		*FRONT LH SIGNAL LAMP	Scratched	0.00 F	*- F
16	1		*FRONT RH SIGNAL LAMP	Cracked	0.00 F	*- F
17	1		*METER CASING	Cracked	0.00 F	*- F
18	1		*ERP BRACKET	Crushed	0.00 F	*- F
19	1		*ERP UNIT	Damaged	0.00 F	*- F
20	1		*COWLING STAY	Cracked	0.00 F	*- F
21	1		*STEERING STEM	* Check	0.00 F	*- F
22	1		*STEERING CONE	Crushed	0.00 F	*- F
23	1		*HANDLE BAR	Crushed	0.00 F	*- F
24	2		*HANDLE BAR GRIP	Scratched	0.00 F	*- F
25	1		*HANDLE BAR BALANCER LH	Scratched	0.00 F	*- F
26	1		*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F
27	2		*HAND BRAKE LEVER	Cracked	0.00 F	*- F
28	2		*SIDE FAIRING LH / RH	Cracked	0.00 F	*- F
29	2		*SIDE FAIRING TOP GARNISH LH / RH	Cracked	0.00 F	*- F
30	2		*SIDE FAIRING INNER GARNISH LH / RH	Cracked	0.00 F	*- F
31	1		*FAIRING SHIELD	Cracked	0.00 F	*- F
32	1		*FRONT TOP FAIRING INNER GARNISH	Cracked	0.00 F	*- F
33	1		*FAIRING TOP GARNISH	Cracked	0.00 F	*- F
34	1		*CENTER FAIRING	Cracked	0.00 F	*- F
35	1		*RADIATOR	* Check	0.00 F	*- F
36	1		*RADIATOR COWLING	* Check	0.00 F	*- F
37	1		*SIDE STAND	Scratched	0.00 F	*- F
38	1		*MAIN STAND	Scratched	0.00 F	*- F
39	1		*REAR FOOT REST	* Check	0.00 F	*- F
40	1		*REAR FOOT REST BRACKET	* Check	0.00 F	*- F
41	1		*EXHAUST MUFFLER COVER	Scratched	0.00 F	*- F
42	1		*FRT RIM	Bent	0.00 F	*- F
43	1		*REAR BOX	Scratched	0.00 F	*- F
44	1		*EMBLEM	Necessary	0.00 F	*- F
45	1		*STICKER	Necessary	0.00 F	*- F
46	1		*REAR AIR FILTER OUTER HOUSING L/H	Scratched	0.00 F	*- F
47	1		*REAR GEAR BOX OUTER HOUSING L/H	* Check	0.00 F	*- F
48	1		*REAR GEAR BOX OUTER HOUSING COVER L/H	Scratched	0.00 F	*- F
49	2		*FRT BOTH SIDE STEP PANEL GARNISH	Crushed	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >