



TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H

REPAIR PERFORMA INVOICE

AIG INSURNACE

Vehicle number	SJT7667G
Make / Model	MITSUBISHI LANCER
Chassis number	JMYSRCY2AAU000358
Accident date	29/11/19
Reference	1911-40

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER	682.7 702.60 de
1	REAR BUMPER BEAM	114.00 bb
1	REAR BUMPER TOW COVER	85.00 m/z
2	REAR BUMPER SIDE RETAINER	232.80 LH-X, RH de 116.40
2	REAR BUMPER REFLECTOR	207.00 LH-X, RH de 1103.50
1	REAR BUMPER REINFORCEMENT	270.00 bb
1	REAR END PANEL	485.7 769.60 ? bt
1	REAR END PANEL TOP GARNISH	255.7 316.80 ? de
2	BOOTLID LAMP	680.00 X nn
2	BOOTLID HINGE	187.20 Rx
1	BOOTLID WEATHERSTRIP	186.00 ? fu
1	BOOTLID LOCK	78.00 bb
1	BOOTLID LOCK STRIKER	30.00 Rx
1	BOOTLID INNER TRIM	201.60 X nn
1	REAR RH FENDER	939.60 Rx
1	SPARE TYRE TOP BOARD	512.60 X nn
2	TAILLAMP @ 548 each	1164.00 LH-X, RH-X 548
	Bootlid XR.	
		6676.80
	Less 10 %	667.68
	Subtotal	6009.12
	Balance C/F	6009.12
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1	REAR NUMBER PLATE BASE	80.00 45 con
1	REAR NUMBER PLATE	80.00
1 SET	REAR BUMPER CLIP	40.00 30 con
1 SET	REAR REVERSE SENSOR	600.00 200, 200 de
2	REAR BUMPER LIP	500.00 LH-X, RH-X 250
1	BOOTLID (CARBON FIBRE)	2000.00 X nn
1	JOINT SEALANT	150.00 ? 40
	Subtotal	3290.00
	Balance C/F	9299.12

565

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	9299.12
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	120.00 50
3	REMOVE AND RENEW REAR REVERSE SENSOR	120.00 30
4	REMOVE AND STRAIGHTEN REAR EXHAUST	120.00 60-plu X
5	PANEL BEATING ON AFFECTED AREAS	1200.00 700
6	SPRAY PAINTING ON AFFECTED AREAS	1000.00 700
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
	Subtotal	2770.00
	Grand total	12069.12

Tanpin 9749544
 'WP'
 Lampsun 02/12/19 @ 3pm
 Resurvey after repair
 Tanpin @ Lampsun
 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: