

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/07/2019 13:34
Date Of Accident	12/07/2019 00:35
Exact Location Of Accident	BUKIT BATOK AVE 6 X BUKIT BATOK ST 23
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH7331G
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS HYBRID 4G
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	KHOO KEE CHOON
NRIC No	SXXXX970I
Address	BLK 260 BOON LAY DRIVE #10-527

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	1

Circumstances of Accident

REFER POLICE REPORT NO: t 20190712 2037 * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY4542L
Vehicle Make/Model/Colour	
Name of Driver	UNKNOWN
Insurance Company Name	

DETAILS OF INJURED PERSON 1

Name	KHOO KEE CHOON
Injured person in which vehicle?	SH7331G

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/7/2019@12:00hrs

Lisa

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

As attached

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer to the Police Report No:
T/20190712/2037
A-SH 7331G
B-GY 4542L
After the accident, I felt pain my back, RH hand and shoulder, and 5 days mc given by doctor.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/7/2019@12:00hrs

Lisa

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

East
Section of Bukit Batok Ave 6
and Bukit Batok St 23



~~Suppl~~
12/7/19

KHOO KEE HOON

UIC: 0537970/I

Sketch Plan Pg. 4



**SINGAPORE
POLICE FORCE**



T/20190712/2037

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190712/2037

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/07/2019 10:48	Vide Report No.: J/20190712/0020	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars			
Name of Informant: KHOO KEE CHOON		Address: APT BLK 260 BOON LAY DRIVE #10-527 BOON LAY CREST SINGAPORE 640260	
ID Type / ID No.: NRIC NO / S05379701		Contact No.: Home/Office: Mobile: 98618218	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 70	Date of Birth: 30/05/1949	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 12/07/2019 00:35	Type of Location:
Location: Junction of Road 1 and Road 2 BUKIT BATOK STREET 23 BUKIT BATOK EAST AVENUE 6 BUKIT BATOK STREET 23 BUKIT BATOK EAST AVEUNE 6				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SH7331G	Car	TOYOTA	PRIUS 5DR HATCHBACK (AUTO)	Blue		0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190712/2037

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3
Report No. T/20190712/2037

CONTINUATION OF REPORT

Driver			
Name	KHOO KEE CHOON		ID No. S05379701
Related Vehicle	SH7331G (Car)		Contact No. 98618218
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

ON THE STATED DATE TIME AND LOCATION

I WAS TRAVELLING IN MY TAXI OF PLATE NUMBER SH7331G AT THE JUNCTION OF BUKIT BATOK ST 23 AND BUKIT BATOK EAST AVEUNE 6, THE TRAFFIC LIGHT IS GREEN IN MY FAVOUR SO I PROCEEDED. SUDDENLY, A VEHICLE (UNKNOWN PLATE NUMBER) HIT ONTO MY RIGHT REAR OF MY VEHICLE.

494542 L Sup 2019

I AM VERY SURE THAT THE TRAFFIC LIGHT WAS GREEN IN MY FAVOUR. I WAS CONVEY TO NG TENG FONG HOSPITAL AND WAS GIVEN 5 DAYS OF MEDICAL LEAVE. MY TAXI WAS BADLY DAMAGE WITH THE AIRBAG BLOWN.

VIDE INCIDENT NUMBER: J/20190712/0020

Sketch Plan Pg. 6



**SINGAPORE
POLICE FORCE**



T/20190712/2037

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190712/2037


CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / EUGENE AW WEI XUAN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Staff Sgt SUFIYAN BIN KHAIRI Contact No.: 65476390

Signature Of Informant: 
Date/Time: 12/07/2019 10:48
Classification Of Case:  SINGAPORE POLICE FORCE
Signature: <u>Eugene</u>

Authentication Stamp
NP168

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



9/18/2019

Gmail - Notice of accident



hui wang enterprise <huiwang576@gmail.com>

Notice of accident

5 messages

Hui Wang Enterprise Pte Ltd <huiwang576@gmail.com>
To: Motor Claim - III <motorclaim@iil.com.sg>

Sat, Jul 13, 2019 at 11:41 AM

Dear Sir,

We are instructed by Hui Wang Enterprise Pte Ltd to notify you of a road traffic accident on 12/07/19 at about 0030HRS at Junction of bukit batok ave 6 & bukit batok st 23 involving our client's vehicle registration number GY4542L and your insured SH7331G. A copy of the Singapore accident statement/ traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Winson Tan

Hui Wang Enterprise Pte Ltd

Blk 5 Defu Lane 10

#01-576

S539186

DID: 62864541



GY4542L ACCIDENT REPORT.PDF
2014K

Motor Claim - III <motorclaim@iil.com.sg>
To: Hui Wang Enterprise Pte Ltd <huiwang576@gmail.com>

Mon, Jul 15, 2019 at 9:26 AM

Dear Sir / Mdm,

We acknowledge receipt of your email.

Enquire Vehicle & Owner Information (Vehicle No. SH7331G As At 29 Aug 2019 / 18:12:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CCL.190804 HWE

Current Owner Details

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SH7331G

Make Description/Model: TOYOTA / PRIUS 5DR HATCHBACK (AUTO)

Insurance Company Name: INDIA INT'L INS PTE LTD

Print

OK

> Back to OneMotoring

Land Transport Authority

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 13 Jul 2019 / 10:50:39

Receipt Date/Time : 13 Jul 2019 / 10:50:39

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190713-000425

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
	Result of Insurance Enquiry - SH7331G As at 12 Jul 2019/00:00:00 Insurance Co: INDIA INTL INS PTE LTD			
1	Insurance Enquiry - SH7331G Enquiry Fee 20190713104853531605	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20190713104918940		Direct Debit: eNETS Debit (Internet Banking)	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



輝皇企業私人有限公司 HUI WANG ENTERPRISE PTE LTD

BLK 5, DEFU LANE 10, # 01-576, SINGAPORE 539186

TEL: 6286 4541, 6283 0717 FAX: 6281 0647

No 21882

Co. Reg. No. 201426468N

囉厘，貨車出租，車輛檢查，修理，噴漆，打嗎呷等
LORRY, VAN RENTAL, VEHICLES INSPECTION, REPAIRING, SPRAY PAINTING, PANEL BEATING, INSURANCE CLAIM, ETC.

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULARS } I/We _____ I/C No: _____
If Different From Section 1 } of _____ Tel No: _____

hereby confirm having agreed to hire this day from Messrs Hui Wang Enterprise Pte Ltd the undermentioned NEW/USED Vehicles at the rental fees as shown below and I agree that I shall be responsible for the first payment of \$2,000.00 / \$3,000.00 for any loss and/or damaged caused to the said vehicle and I shall be responsible to pay Messrs Hui Wang Enterprise Pte Ltd the value of the vehicle in the event of the Vehicle being CONFISCATED or any loss resulting from THEFT or DESTRUCTION of the said vehicle whether or not such damage or loss is caused by negligence or by any breach by me of the terms and conditions of hire, hereinafter mentioned and printed.

Vehicle Regd. No. 車號	GBJ 1599 G		(Diesel) Petrol
Section 1 Hirer's And / Or Driver's Particulars 租車者 \ 駕駛員個人記錄	日期及取車時間 Date & Time Out:	12/7/19	11:25am
Name 名	日期及還車時間 Date & Time In:	25/7/19	9:20am
Address 地址	天數 Days @ \$	150	
HONG LIM COMPLEX, SE. 050531.	星期 Weeks @ \$		
駕駛執照 Dr/Licence No: I/C No: G 65431914. Tel No: 9237 8401	月 Months @ \$		
截止日期 Expiry Date	Date Of Birth	總數 Nett-Total	
Replacement Veh. Regd. No. (Diesel / Petrol)	按權金 Deposit		
日期及取車時間 Date & Time Out:	Refund		
日期及還車時間 Date & Time In:	Balance To Pay		
* Note: A repossession fee of S\$100.00 will be charged on repossess vehicles	Cash / Cheque		
NOTICES: ACCIDENT EXCESS: S. 2500 22 69 NO INSURANCE COVERAGE FOR YOUNG (BELOW ...), OLD (ABOVE ...) AND IN EXPERIENCED DRIVERS. 請注意水箱里的水及引擎里的黑油須每天檢查。 Please check Radiator Water & Engine Oil daily. 半途汽油不足，遺失鑰匙等，若須服務者另付額外費用。 Extra charges are required for those vehicle that run out of petrol, lost of key and etc. Interest rate of 1.5% will be charged on overdue payments	出車油箱 Fuel Tank OUT	E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F	
	加額費用 Total Additional Charges		

IMPORTANT!

I / We declare that the usage of renting the above mention Vehicle are not to be used for illegal purpose, including offences in connection with thefts, uncustomed goods, drugs dealings or trafficking or smuggling.

Signature of Hirer

I/We hereby accept the terms and conditions herein and overleaf which I have read and understood or have been read over and explain to me and understood by me. I/We hereby declare that the particulars of the Hirer and licence given above are correct in every respect and that I am the holder of a valid driving licence enabling me to drive the above-mentioned vehicle and not disqualified from driving.

Remarks: Bill 10 Days (3Days Pat 7Days (per))



Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4
#06-46 Synergy @KB
Singapore 417800
Hotline: 6385 1171

Our reference: 19-7-8389
Date: 28/7/2019

INVOICE NO. 8389

Hui Wang Enterprise Pte Ltd
c/o Hui Wang Enterprise Pte Ltd
Blk 5 Defu Lane 10
#01-576
Singapore 539186

Registration No. **GY4542L**

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 577.00
Total amount			<u>\$ 577.00</u>

Please kindly cross all cheques made payable to " Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

L. L. Tan (Ms)
Principal Consultant



Impact Analysis Consultant

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4
#06-46 Synergy @KB
Singapore 41780
Hotline: 6385 1171

Our reference: 19-7-8389

Date: 28/7/2019

c/o Hui Wang Enterprise Pte Ltd
Blk 5 Defu Lane 10
#01-576
Singapore 539186

Dear Sirs

RE: Road Traffic Accident on 12/7/2019
Hui Wang Enterprise Pte Ltd

In accordance with your instructions received in this office on 12/7/2019, we made arrangements to examine the vehicle on 12/7/2019 at above-mentioned address. The following data was recorded:


Vehicle details

Make	Toyota	Registration	GY4542L
Model	Hiace	Chassis	KDH2000004383
Colour	Silver	Gearbox	Manual
Odometer	354877km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	195R15C	85% Delium
Front right	195R15C	85% Delium
Rear left	195R15C	80% Ultima
Rear right	195R15C	80% Ultima

Impact Direction & Area of Damage:



Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$5,600.00 and 7 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Our reference 19-7-8389
Date 28/7/2019
Page 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As Inspected	Repairer's Estimate	Our Adjustment
<u>List Items:</u>				
Front bumper	1	deformed	512.50	512.50 /
Front bumper side bracket @\$35.00	2	necessary	70.00	70.00 /
Front bumper reinforcement	1	bent	528.60	528.60 329.6
Front panel	1	bent	925.40	925.40 /
Front panel logo	1	necessary	53.50	53.50 /
Front radiator grille	1	damaged	471.20	471.20 280.9
Front head lamp @\$652.30	2	defaced/cracked	1304.60	1304.60 /
Front corner panel @\$233.10	2	repair,refinish	466.20	0.00 R
Front radiator grille reinforcement	1	damaged	122.40	122.40 89.2
Front support panel	1	bent	625.40	625.40 /
Front support panel top garnish @\$65.00	1	damaged	130.00	130.00 65
Front panel brace lock	1	damaged	198.45	198.45 89.6
Front radiator	1	dented/bent	1024.50	1024.50 /
Front door step outer garnish @\$120.00	2	deformed	240.00	X 240.00 SVC
Sub- Total cost			6672.75	6206.55
Percentage discount : 25%			1668.19	1551.64
Sub-Total costs for parts			5004.56	4654.91 5370.2
<u>Special Nett Items:</u>				
Front number plate	1	damaged	50.00	50.00 15
Front bumper clips	1 set	necessary	30.00	30.00 /
Sub-Total costs for parts			80.00	80.00 45
Parts Repair				
*	*	*	0.00	0.00
Sub- Total costs			0.00	0.00
Total costs for parts			5084.56	4734.91

Our reference 19-7-8389

Date 28/7/2019

Page 3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	25	\$ 1,125.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$ 700.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 30.00
Wiring and bulb checking	\$ 45.00	0.5	\$ 22.50
*	*	*	\$ -
Total labour cost			\$ 1,877.50

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.


600
500
/
/
1152.5
5225.15
20/02 4150
6962.06
5 Days.

Our reference 19-7-8389
Date 28/7/2019

Section C: Summary Table of Total Repair Cost

Damaged Parts Assessment (See section A)		\$4,734.91	
		\$946.98	
Further discount	20%		
Recommended cost of parts		\$3,787.93	(1)
Labour Cost Calculation (See section B)		\$1,877.50	(2)
Total Repair Cost (Round off to hundred)		\$5,600.00	(1) + (2)

We would recommend a sum of \$5,600.00 and 7 working days for repair.
No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.



Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)
B.Eng. (Hons, NUS)
Diploma.Mechanical Engineering
NTC-2 Automovite Technology
Sr.MIES, Institution of Engineers, Singapore (#20100091)
MATAI, Maryland Association of Traffic Accident Investigators
IAARS, International Association of Accident Reconstruction Specialists
PMC of Singapore Business Advisors & Consultants Council



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III19012435/Gqf3s2-1	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 12-02-2020	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7331G	Veh. Inspected	GY 4542L
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19070308	Excess (\$)	0.00
Assign From	STANLEY LAI	Assign Date	30/11/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE 2.5	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	KDH2000004383	Colour	SILVER
Odometer	354877	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	DELIUM	6 mm
L/H Front Tyre	195 R15	DELIUM	6 mm
R/H Rear Tyre	195 R15	DELIUM	6 mm
L/H Rear Tyre	195 R15	DELIUM	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/07/2019	Inspection Date	15/07/2019
Survey held at	HUI WANG ENTERPRISE BLK 5 DEFU LANE 10 #01-576 SINGAPORE 539187		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GY 4542L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	512.50	512.50
2	FRONT BUMPER SIDE BRACKET @ \$35.00	NECESSARY	70.00	70.00
1	FRONT BUMPER REINFORCEMENT	BENT	528.60	329.60
1	FRONT PANEL	BENT	925.40	925.40
1	FRONT PANEL LOGO	NECESSARY	53.50	53.50
1	FRONT RADIATOR GRILLE	DAMAGED	471.20	280.90
2	FRONT HEAD LAMP @ \$652.30	DEFACED / CRACKED	1,304.60	1,304.60
2	FRONT CORNER PANEL @ \$233.10	TO REPAIR SEE LABOUR	466.20	-
1	FRONT RADIATOR GRILLE REINFORCEMENT	DAMAGED	122.40	89.20
1	FRONT SUPPORT PANEL	BENT	625.40	625.40
2	FRONT SUPPORT PANEL TOP GARNISH @ \$65.00	DAMAGED 1PC ONLY	130.00	65.00
1	FRONT PANEL BRACE LOCK	DAMAGED	198.45	89.60
1	FRONT RADIATOR	DENTED / BENT	1,024.50	1,024.50
2	FRONT DOOR STEP OUTER GARNISH @ \$120.00	SERVICEABLE	240.00	-
	LESS 25% DISCOUNT		-1,668.19	-1,342.55
			5,004.56	4,027.65
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	DAMAGED	50.00	15.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
			80.00	45.00
<u>LABOUR</u>				
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL.		1,125.00	600.00
	PUTTY AND SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		700.00	500.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		30.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING AND BULB CHECKING.		22.50	22.50
			1,877.50	1,152.50
GRAND TOTAL			6,962.06	5,225.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,150.00

Report Ref No. CS3/III19012435/Gqf3s2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.